

Mr. John Ryne. Postlake

1916

£ s d

Oct. 19	mason 2 hrs. about oven			1	2
23	mason 9/2 hrs. piping oven			5	6 1/2
24	mason 9/2 hrs. do.			5	6 1/2
25	mason 3 1/2 hrs. rebuild furnace			2	0 1/2
27	mason 9/2 hrs. do.			5	6 1/2
28	mason 6 hrs. do. put bricks in oven at Dairy House			3	6
	5 barrels mortar			5	0
	25 bricks			1	2
	1 1/2 pecks cement 2/3 2 bks washed gravel 6.			2	9
	1 furnace pan			19	0
	1 door grating			4	9
	4 fire bricks			10	
	1 cast iron fire cheek			1	3

£ 2 18 1

Said

Miss Rose Edith Martin

1916

Aug 16	Self 9 hrs. make door & jambs		5 3
17	" 7 hrs. hang door & fix jambs		4 1
"	Mason 4 1/2 hrs. take out doorway		5 6 1/2
18	" 4 1/2 hrs. wall up jambs & lintel		5 6 1/2
19	" 6 hrs. make path & get turf		3 6
22	Self 2 1/2 hrs. put on fastenings		1 5 1/2
24	" 1 hr. paint door		7
31	" 2 hrs. fix night latch & paint door		1 2
Nov. 6	1 1/2 hrs. ease door		" 10 1/2
	15-9 of 4x3 deal jambs	7 1/2	10 0
	2 dowels		3
	24-0 of 7x1 match	3 1/4	7 10 1/2
	8-0 of 7x1 ledges	3	2 0
	nails		" 4
	1 pair 16" Tee hinges & screws		1 8
	4-0 of 9x3 lintel		4 0
	1 1/2 pecks cement		2 3
	1 barrow mortar		1 0
	1 bucket sand		" 3
	4 gals. tar 1/8 2 barrows sea gravel 2/7		4 3
	1-6 Tower bolt		9
	1 Norfolk handle		10
	2 lbs. paint		1 4
	1 Night latch		6 0

 $\frac{1}{4}$

3 10 9 1/2

Paid

Mr. Best Stamp

1916

£ p d

July	14	1 split key & straighten by neck pin			8
Aug	30	1 1/2 hrs. put castors on chair 2 chair castors			9 14
Sep.	19	sharp & cut of 1 hand saw 6°			13
Oct.	12	6 1/2 hrs. put new side bar to blade	^		33
	13	1 1/2 hrs. do			9
		1. 5 x 3/8, 1. 4 x 3/8, 1. 2 x 1/4 bolts 1°			5 1/2
		5-0 of 6 x 2 ash side			18
		5-2 of 3 x 1 elm bar	6-5/2 ✓		4
		put in pane glass putty 11°			11
		paint out name & put in name 1/-			10
		put on lamp bracket 4 screws 4°			4
	13	3 1/2 hrs. clean off paint shafts	^		19
	18	2 hrs. do			10
		2 lbs. paint	1/2	8 1/2	15
		solder kettle 4°			4
Nov.	3	9 1/2 hrs. put up partition	^		49
	4	6 hrs. do			30
	6	2 hrs. paint do			10
	8	2 hrs. do			10
		64-0 of 7 x 3/4 match		2 3/4	148
		10-0 of 2 x 3 deal		2 3/4	23 1/2
		4-6 of 1 x 3 "			6
		2-3 of 2 1/2 x 1 1/4 "			3
		6-9 of 7 x 3/4 "		2 1/2	15
		3-12 T. hinges & screws			10 1/2
		1 lb. nails		3 1/2	3 1/2
		1-6 bolt & screws 6°			7
		4 lbs. paint		8 1/2	210
		solder kettle			4
	16	3 staples for draft 9°			0
			1-14-5 1/2 ✓		
			£	2	12 0

Taid

Mr. Alfred Stamp

1916

£ p d

		forward 182		1	2	15
Sep.	19	take out, repair put in cow stable				9
Oct.	12	sweep chimney put up damper chain			1	9
		2 yds. damper chain				6
	30	3 hrs. put in glass rease window			1	6
		2 panes glass. putty			1	5
		to 1 hook & eye				2
Nov.	21	5 1/2 hrs. repair pig ladder			2	9
		q-o of 2x1 oak				6
	22	messon 9 hrs repair floor			5	3
		2 1/2 pecks cement	116		3	9
		4 buckets pea gravel				8
		sharp meet saw				5
Dec.	6	2 pairs of brake blocks			3	0
Jan	3	new tyre on waggon wheel 3 lbs. 4 3/4 5			12	31
		take off put on wheel			1	0
				£	2	18 5
		Credit by old lead 40 lbs at 7/11 per cwt				7 5
				£	2	11 0
		paid				

Mr G. Goss

1916

Aug 9	3 hrs.	get out stock	1/6
10	9 1/2 hrs.	make wheel	4/9
11	9 1/2 hrs.	do	4/9
12	6 hrs.	do	3/-
14	3 1/2 hrs.	do	1/4
16	2 hrs.	do	1/0
17	3 hrs.	do	1/6
18	2 hrs.	do	1/0
		14 spokes	10/6
		7 ash felloes	3/6
		paint + varnish	1/-
		7 iron davel	3
		7 stock r turning	1/6
21	2 1/2 hrs.	wheel	1/3
	2 hrs.	stripe	1/0
		type wheel	3/6 ✓
		2 new nose bands	2/- ✓

take off type + box
from old wheel

loping

Aug.	To making a new trap wheel	1	16	0
	To taking off old wheel, take off type + box		2	3
	2 new nose bands		2	0
	tying wheel		3	6

£ 2 3 9

Paid

Miss Lucy Martin, Sydney Cottage.

1926

£ o d

July 4	mason 9 $\frac{1}{2}$ hrs. repair roof		5 6 $\frac{1}{2}$
6	mason 6 hrs. do.		3 6
8	mason 4 $\frac{1}{2}$ hrs. paint skylight		2 7 $\frac{1}{2}$
	4 12 x 24 plates $\frac{1}{8}$ 12 nails	3	1 11
	6 strips lead		" 9
	7 lbs. paint	8 $\frac{1}{2}$	4 11 $\frac{1}{2}$
	1 lb. putty		2
10	mason 2 $\frac{1}{2}$ hrs. paint skylight		1 5 $\frac{1}{2}$
	1 $\frac{1}{2}$ lbs. paint		1 1
18	2 hrs. make boards 11-		" "
	5 boards 6 x 5 x $\frac{1}{2}$ each 11-		2 9
Aug 22	mason 9 $\frac{1}{2}$ hrs. rehang passage window		4 9
24	mason 6 hrs. repair handle bolt paint		3 3
	door open in glass		" "
	2 sash pulleys screws		1 0
	2 5 lb sash weights		3 4
	2 cords rebands		1 0
	3 panes glass		1 9
	putty & 2 lbs. paint		1 6
Oct. 11	mason 7 $\frac{1}{2}$ hrs. take out clean boiler tank & W.C. valve		4 4 $\frac{1}{2}$
	repair boiler tank carriage, new bottom		13 0
14	mason 5 $\frac{1}{2}$ hrs. fix tank		3 2 $\frac{1}{2}$
	mason 2 hrs. rehang door		1 0
	1 leather collar 1 lead collar, red lead		1 0
	1 brass back nut		" 10
	copper wire for W.C.		6
	1 pair 2 $\frac{1}{2}$ butts screws		" 6
	repair cistern of range carriage		4 9
21	mason 2 hrs. fix cistern		1 2
25	Self mason open out range		1 3
Nov. 1	mason 6 hrs. about range forward	7	3 15 5

£ 0 8

		forward		3	15 5
Nov.	14	mason gln. with plumber shield wall in cupboard			5 3
		Plumbers time rail pines put in boiler pipe			12 0
	15	mason gln. repair roofs			5 3
		2.0 of 1/4 lead pipe			1 6
		1 barrel mortar			1 0
		6. 11x22 slates			2 3
		4. 12x24 "	5		1 8
		5 ft. copper wire			5
		4 strips lead, 25 plate nails			10

boiler
about 2-10-0

Paid

1/2

5 5 7

Mrs. Bessie Glauwill

1916

£ o d

Nov 22	man 6 hrs. repair jambs put new sill to front door			3 0
	2-9 q 4x3 oak sill	5		1 3
	2-9 q 2x1 1/2 deal			3
	2-6 q 3x3/8 plps			2
	2 squares 1/2 8 pence 2 ^o paint 2 ^o			1 4
				<hr/>
				6 0

Paid

Mr. W. Glauwill Ford Farm

Dec. 6	man 9 1/2 hrs. fit & repair envelopes			4 9
7	man 9 1/2 hrs. do.			4 9
8	man 9 1/2 hrs. repaired gates 13			4 9
	6 lbs. unified nails			1 9
				<hr/>
				16 0

Paid Jan 29 1917

1916 Wares & Pans.

£ o d

Nov 28	1 hr put in pane glass	}		6
	1 pane glass putty			9
Dec 5	2 ropes		40	
9	1 pair brake blocks		16	

Paid

£

69

Dr. Furnivall

Nov 27	Self 4 1/2 hrs repair carriage shaft		30
	2 plates iron		6
	4. 3 x 1/4 bolts		6
Dec 11	Self 4 1/2 hrs repair carriage shaft		30
	2 plates iron		6
	4. 2 x 1/4 bolts		6

Paid

£

80

20-1-17

Mr. J. Ackland, Churchwarden, Baltimore

1917			
Jan 20	To two Bell Ropes		1 13 0
	Carriage		9

Paid

1 13 9

sent to Mr. H. Grant
Baltimore

Mr. Harold Ware

£ o d

1916

Dec	2	Self 8 hrs. repair & clean washing machine		4	8
	3	" 2 hrs.		1	0
	4	" 2 hrs.		1	0
	6	" 2 hrs.		1	0
		4 - 1 1/2 x 3/8 bolts		-	8
		1 por of black paint, green paint		-	9
		5-3 q 2 x 3/4 match	2 3/4	1	2 1/2
		1-q of 3 1/2 x 3/4 "			2 1/2
		1-q of 5 1/4 deal			5
		2 - 1 1/2" screws			1

£ 11 0.

Dec.	15	sweep chimney at Mrs Carter		1	0
	18	man 8 hrs repair window put in glass		4	0
		" mason 7 1/2 hrs whitewashing & coloring		4	4 1/2
	19	mason 9 1/2 hrs. take out & repair stove		5	6 1/2
		Self 7 1/2 hrs. color kitchen		4	4 1/2
		2 panes glass putty		1	7
		1-3 q 1 1/2 x 1 1/2 deal			2
		14 lbs. Halls green	6	7	0
		1/2 pk. plaster, 1 bck. lime		1	3
		25 bricks, 1 1/5 barrow mortar, 5 fire bricks		3	8
		4 stove screws			4

1917	Feb.	5	mason 9 1/2 hrs. whitewash & color staircase		5	6 1/2
		6	man 1 1/2 hrs. plaster panes		1	5 1/2
			" 2 1/2 hrs. repair roof do.			6
			1/4 peck plaster, 4 1/2 bucket sand			6
	Apr.	12	self 6 hrs. color staircase		4	0
		13	self 4 hrs. do.		2	8
			7 lbs. green distemper	6	3	6
			10 lbs. white do.	6	5	0

Mar.	5	beetle stem			1	0
Paid July 4, 1917				£	3	8 10

1916 Mr. H. Knott

£ p d

Aug	15	9 1/2 hrs. take off trap wheels & shafts		49
	23	9 1/2 hrs. put in shafts		49
	"	1 1/2 hrs. do.		8
	24	3 hrs. do.		18
	25	6 1/2 hrs. do.		33
	26	6 hrs. do.		30
	28	9 hrs. do.		46
	30	1 screw.		1/2
		4. 3 x 1/4, 4. 2 1/2 x 1/4, 2. 5 x 3/8 bolts, 1. 3 1/2 x 7/16		12
		6-3 of 7 x 3/4 deal bottom		14
		9-0 of 8 x 2 1/2 ash shafts	10	76
		1 leather collar		9
		1 lb. paint	1-14-6	8
		tyre 2 wheels 7/-		70
		repair 2 trease hooks 6", 1 tail pin, 2 staples	2-3-0 1/2	16
Sep	6	1 barrow mortar 4/-		10
		2 pecks cement 2/9		29
Oct.	2	mason 9 hrs. fix reed maker		53
		4 pecks cement		56
		4 bolts & plates		46
	6	9 1/2 hrs. put in new waggon shafts		49
	7	2 hrs. do.		10
		9-3 of 4 x 3 ash shafts	5/-	43
		1 lb. paint	10/8	8
				<hr/>
				3 12 8 1/2

Mr. H. Knott

1916

May	10	man horse 1 day ploughing	4	1	
	11	man horse 1 day do.	11	3	
June	22	man 2 hrs. haymaking			10
Aug	17	man after 2 p.m. cut wheat barley			19
	18	man after 2 p.m. cut wheat			19
	28	man cut corn			30
Sept	25	man threshing			50
Oct	9	man 3 1/2 hrs.			19
	10	man 1 day "		4	310

1918

Feb	25	man horse 1 day draw manure 7/2		2	
June	18	man horse housing hay			70
	19	do. do.			70

183

1916

Mrs. Stokes, Sen (Trustees)

£ p d

Oct.	4	mason 9 hrs. repair roof Hawkins Pyke		53
	5	do 6 hrs.		36
		25 double roll tiles	3½	7 3½
		59 pantiles	2½	12 3½
		8-0 of 4x3 prop	5	34
		4-0 of 4x2 "	3½	12
		nails 2°		.. 2
	9	mason 5½ hrs. repair wall put in step		3 2½
	12	" 4 hrs. repair grate Mr James		24
		2 shute bolts. 3 pieces iron 6x1½x¼ "		.. 8
		4 pecks cement		60
		2 buckets gravel		.. 3
		1 double roll tile		3½
		piece zinc 2 ft. at R. Davey		10
	27	man. 7 hrs. make pit barge boards		36
	28	man 5 hrs. do		26
		29-0 of 9x1	5	121
		13-0 of 2x1.		10
		2 lbs. nails		.. 7
		tar varnish		10
		7-6 of 7x¾	2½	17
		1-4 of 7x1	3	.. 4
		3-9 of 2x¾		.. 3½
		½ lb. nails		2
Nov.	6	repair lock of door at Pyke		.. 9
Nov.	9	man 2 hrs. paint shuting		10
	13	man 9½ hrs. pit shuting		49
		mason 3 hrs. do.		19
		6 shute screw, 4. 2½ screws, putty		.. 6
		1-3 of 4x3 deal, 6½ 1½ lbs. paints 4.		16½
		4. 6 ft. 12/6 1. 4 ft. of 4 gutter 2/3		14 9
		1 nozzle, 1/8 2 stop ends 10"		26
		6 holdfasts		26
		forward	7 1/2	4 19 10.

	forward		4	19	10
Nov	24	man 9 $\frac{1}{2}$ hrs. repair rails Globe Hill		4	9
	27	man 9 $\frac{1}{2}$ hrs. "		4	9
	28	man 8 $\frac{1}{2}$ hrs. "		4	3
	29	man 9 $\frac{1}{2}$ hrs. "		4	9
	30	man 9 $\frac{1}{2}$ hrs. "		4	9
Dec.	1	man 5 hrs. "		2	6
		18-9 of 3+3 oak rails	4 $\frac{1}{2}$	7	0
		6-6 of 7x1 pale	3 $\frac{1}{2}$	1	11
		2 screws. 1 lb. paint 8 $\frac{1}{2}$		-	9
		3-6 of 2 $\frac{1}{4}$ x1 pale, 5-6 of 1x1		-	6
		2 catches. 4 $\frac{1}{2}$ latch 6 $\frac{1}{2}$		-	10
		1. 3 $\frac{1}{4}$, 1. 4 $\frac{3}{8}$ bolts		-	3
		9-0 of 4x4 2 oak post	8	6	0
		2-9 of 2+3 deal weather board		-	8
		1 hook & twist		1	1
Nov.	25	mason 5 $\frac{1}{2}$ hrs. stop in cement chimney		3	2 $\frac{1}{2}$
	28	mason 7 $\frac{1}{2}$ hrs. do		4	4 $\frac{1}{2}$
	29	mason 5 $\frac{1}{2}$ hrs. do		3	2 $\frac{1}{2}$
		5 pecks cement		7	6
		1 $\frac{1}{2}$ barrels sand		-	9
		3 buckets gravel		-	4 $\frac{1}{2}$
			7	8	40
		Repairing two gates at S. Seales		5	0
		Paid	7	8	90

Mrs. Stokes, Penn

1916

£ o d

Nov. 21	3½ hrs. repair roof	Mrs. Wilder	1	11½
	6 pantiles	"	1	3
	2 fire bricks			5
Dec. 1	4½ hrs. repair & tar parlour		2	3
	tar & nails	6 ^p .	2	6
Oct. 10	solder pan	2 ^p .		2

paid

£ 6 6 2

Mr. Joseph Banney

Nov. 21	7½ hrs. make of brake block		3	9
	7½ lbs. iron		1	10
	6. 1¼" screws			2
	1-b of 5 + 2½ ash			8

paid

£ 6 5

Mr. C. H. Stamp, Woodbury House

1916

Oct	12	1 1/2 hrs. put in glass			9
		1 pane glass			9
		putty			1
Nov	29	5 hrs. chip out catches from posts sharp chisel	} 3/6		3 1/2 4 1/2
Dec.	1	9 1/2 hrs. repair field gate			4 9
		1 hr. do			6
	2	7 1/2 hrs. do			3 9
	4	3 hrs. do			1 6
		4-6 of 7x3 oak tail	10		3 9
		7-0 of 3x3 deal head + rails	4 1/2		2 6
		4-3 1/2" r 2. 4 1/2 x 3 1/8 bolt. 1. 8 x 1 1/2 bolt. 3 1/2" nail			1 3
		2 doz. 2 1/2" put. nails			2
		paint			4
		2 catches & 2 1/2" wedges rifting in post 2/9			4 9
1917	17	man 3 hrs. collaring & riving trap wheels			1 9
		2 small collars r iv			9
		tyring 2 wheels			7 0
		riving wheels & rivets r cap			2 6
Oct.	11	new bolt in shears			9

1 1/2

2 1 1

Miss Glanville: Rydon Farm

1916

£ s d

Nov	9	2 hrs. repair towel rail			
"		3 hrs. line & paint trunk			1 6
		flannel etc for trunk & pack	} 3/-		9
		paint & letter trunk			
	24	6 1/2 hrs. repair chest drawers	3-3		3 3
	25	6 hrs. do.	3-0		3 0
	27	9 hrs. do.	4-6		4 6
	28	2 hrs. do.	1-0		1 0
	29	8 hrs. do.	4-0		4 0
	30	1 1/2 hrs. do.	9		9
		4-0 of 9x1 deal	1-8		1 8
		2-0 of 2x1 "	1		1
		glue & varnish	6		6
		fit key to locks	6		6
Dec.	9	2 1/2 hrs. pin lock	1-3		1 3
	11	2 1/2 hrs. do.	1-3	£ 1-1-9	1 3

£ 1 4 9

Paid

Dr. Stokes

1916

£ p d

Nov 24	messon 8 hrs. repair roof at Mr. Davy's		4	8
	6- 11x22 plate		2	6
	4 panels			10
	25 nails, 4' 8-0 of copper wire 8 ³		1	0
Sep 7	3 hrs. take out & re-leather pucker at Couches	}	1	9
	leather slabs			9
	Trap & journey to Woodbury Rd		4	0
		£	15	6

Col. Mansfield

Oct 24 Carting two loads wood from Black Hill 8 6

Paid Jan 29. 1917

S. Thomas R. D. Council

1916

Aug 25	2685	11 1/2 hrs. make barn wheel new tyre wood	} 10/-	59
30		3 hrs. put on afle blocks & repair barn		30
Dec 11		man 3 1/2 hrs. fix pells at Rydon Brook		13
12		man 9 1/2 hrs. do. 6 spikes		16
		<u>Paid</u>		196

Rev. R. Newman. Hawkridge Rectory

1917	Feb 5	To 5 bellropes each 60-0 long at 16/6	4 2 6
		Paid Feb 5. 1917	

C. Davy Log

F o a

1917

Jan. 1	man 8 hrs. batten plaster drawing room walls		4 8
	mason 8 1/2 hrs.		4 11 1/2
2	man 9 1/2 hrs. 5/6 mason 9 1/2 hrs 5/6		11 1
3	man 9 1/2 hrs. mason 9 1/2 hrs.		11 1
4	man 9 1/2 hrs mason 9 1/2 hrs		11 1
5	mason 5 1/2 hrs		3 2 1/2
8	man 5 1/2 hrs fix picture rail, paint floor		3 2 1/2
10	mason 8 hrs. whiten ceiling		4 8
11	Self 7 hrs. paint room		4 8
12	Self 6 hrs do		4 0
15	Self 6 hrs do		4 0
18	Self 9 hrs. do paper		6 0
19	Self 4 1/2 hrs enameling		3 0
24	put down carpet		1 6
	130-0 of 2x1 batten		8 0
	10-0 of 2x3 deal	2 3/4	2 3 1/2
	20-0 of 7x4 floor	3	5 0
	2-0 of skirting		7
	3 lbs. lath nails		2 0
	1 bag plaster		8 2
	4 barrows sand 1/4 1 bck. putty lime 1/2		1 10
	4 bales saw laths	4-	16 0
	tho. mats		- -
	7 lbs. white distemper		3 0
	6 lbs. paint	8 1/2	4 3
	5 lbs. nails	3 1/2	1 5 1/2
	3 pieces wallpaper + postage		15 2
	1 pck. paste		6
	3 pints enamel		11 0
	1/4 lbs. size		3
Feb. 8	4 hrs. put in glass, 2/4 putty 2'		2 6
	2 panes plain 11- 1 pane figured 10'		1 10
	forward	7	8 0 11 1/2

£ c d

		forward	8	0	11½
Mar.	1	2 hrs. ease dining room door		1	6
	6	sharpen saw			6
Feb.	19	carting 2 loads manure		3	0
	28	carting lime from Topsham		4	6

£ 8 10 5½

Paid. May 4. 1917

Mr. Edgar Ware, Woodbury

1917

£ o d

Feb	5	6 1/2 hrs. put in felloe in wheel			3	9
		1 felloe				6
		tyring wheel			3	6
		painting lades			2	6
Mar	30	10 new body of waggon as contract		12	0	0
	6	sharp saw				6
	18	Hauling timber to Remouth			10	0
	14	do			10	0
	16	do			10	0

 £ 14 0 9

Paid. May 15. 1917

Mr. W. Page. Venmore Farm.

1917

£ s d

Feb.	26	take of trap spring, repair scroll iron 2 bolts, 4 ^o , 3, nub, 3 ^o , 7 hrs, 4/1	4 8
"		man 9 1/2 hrs. repairs	5 6 1/2
	27	do.	5 6 1/2
	28	do.	5 6 1/2
Mar	1	do.	5 6 1/2
	2	do.	5 6 1/2
	3	" 6 hrs. do.	3 6
	5	" 9 1/2 hrs.	5 6 1/2
	6	" 9 1/2 hrs.	5 6 1/2
	7	" 9 1/2 hrs.	5 6 1/2
	8	" 9 1/2 hrs.	5 6 1/2
	10	" 6 hrs.	3 6
	12	" 9 1/2 hrs.	5 6 1/2
	13	" 9 1/2 hrs.	5 6 1/2
	14	" 9 1/2 hrs.	5 6 1/2
	15	" 9 1/2 hrs.	5 6 1/2
	16	" 9 1/2 hrs.	5 6 1/2
	17	" 6 hrs.	3 6
	19	" 9 1/2 hrs.	5 6 1/2
	20	" 9 1/2 hrs.	5 6 1/2
	21	" 9 1/2 hrs.	5 6 1/2
	22	" 9 1/2 hrs.	5 6 1/2
	23	" 9 1/2 hrs.	5 6 1/2
	24	" 6 hrs.	3 6
	26	" 9 1/2 hrs.	5 6 1/2
	27	" 9 1/2 hrs.	
		altering 4 hooks & turnstiles	1 0
		2 latkes 1/4. ✓	1 4
		3. 2 1/4 bolts ✓	3
		20 lbs. cut nails	5 10
		5 lbs. post. rose nails	1 8
		forward	6 19 9

£ o d

forward
 12 gate staples
 2 catches ✓
 3 square staples ✓
 6 - 3 x 3/8 bolts ✓
 18 - 2" screws
 5 lbs paint
 4 - 2 x 5/16 bolts ✓
 10 - 0 of 2 x 1 button

6 19 7
 1 6
 .. 6
 .. 9
 1 0
 4 2
 3 4
 .. 3
 7

£ 7 7 10 1/2

Paid Apr. 30. 1917

Mr. S. C. Miller, Woodbury

1917

F o d

Jan. 8	man 6 hrs. repair pony cart		3 6
	1 plate iron 4", 2 bolts 4"		. 8
	1" q of 2 1/2 x 3 ash		. 7
	3 rivets, repair lade eye, new tip iron		1 3
22	mason 9 1/2 hrs. build food mixer		5 62
23	mason 9 1/2 hrs. do		5 62
	45 rd. corner bricks		4 0
	175 bricks		9 7
	2 bags cement	7/.	14 0
	3 barrels mortar		3 0
	1 1/2 barrels sea gravel		. 9
Mar. 6	sharp & cut saw		. 9
	sharp handsaw		. 6
17	glue up table		. 9
19	repairing table, 1 square 4 screws		1 6
28	repair wardrobe		. 6
Jan 30	repairing chain harrow, 50 links		. .
	3 weights, new end to spreader		1 4 10
			<hr/> 3 17 3

Paid May 5 - 1917

Rev. W. Geary Kivker. Coryton Rectory, Devon

1917

Mar. 26 To 2 bellropes at 16/6 ea
Carriage

1 13 0

9

1 13 9

Paid, May 10, 1917

Rev. J. Newman, Woodleigh S. Devon

Apr. 24 To 3 bellropes at 16/6 ea.
Carriage paid on

2 9 6

8

Paid, June 11/1917

£

2 10 2

Mrs. H. H. M. Pecke, Glade Barton, Payhembury

June 1st To new lorry waggon blades dis.

£ 0 0

30 10 0

10 0

30 0 0

Paid, June 18, 1917

Mr. T. Glanville.

1917

June 1	9 1/2 hrs. ring waggon wheel			5 6 1/2
2	7 hrs do.			4 1
	2 spokes			8
	4-6 of 9 x 2 1/2 ash	11 ^p		4 1 1/2
	paint			3
	1 new tyre 36 lbs.	£1-9-8	5 ⁻	15 0
12	7 hrs. repair spring cart, part			4 1
17	9 1/2 hrs. new side + front			5 6 1/2
18	9 1/2 hrs. rail, new pair shafts			5 6 1/2
19	9 1/2 hrs. + paint 2 coats			5 6 1/2
	2 hrs.			+ 2
20	5 1/2 hrs.			
22	9 1/2 hrs.			5 6 1/2
23	9 1/2 hrs.			
24	7 1/2 hrs.			
25	6 1/2 hrs.			
26	4 1/2 hrs.			
29	4 1/2 hrs. 8 1/2 hrs.			2 9 7
	17-6 of 12 x 1 elm.		3	3 0
	8-6 of 3 x 2 1/2 ash		4 1/4	4 4 1/2
	1. 2 1/2 x 3/8, 1. 3 x 3/8, 2. 1 3/4 x 1/4 bolts, 4 screws			6
	1 iron plate, 4 ^p , 1-0 of 1 1/2 x 1 1/2 ash			7
	2 shafts			16 0
	6. 3 1/2 x 1/2, 4. 6 x 1/2, 2. 4 x 1/2 bolts			2 5
	1 back chain			2 3
	8 1/2 lbs. paint			6 4 1/2
	2 large & 2 small collars			4 0
	lettering cart			5 0
	2 long staple 1/6, 2 crooks 1/6, 3 rings 9 ^p			"
	4 washers, 4 ^p			3 7
	repair scroll iron + couplings			2 9
	1 link			2
	forward £5-0-7.		£	6 10 3

1917

		forward		6	10	3
Feb	21	man q ¹ / ₂ hrs. hang gates			5	6 ¹ / ₂
	22	man q ¹ / ₂ hrs. do.			5	6 ¹ / ₂
		3 gate hooks & eyes			3	0
		6 staples. 1 rasp			1	0
		nails				2
					<hr/>	
Paid. Aug 9. 1917			£	7	5	6
				<hr/>		

June 11.

C. Davy Esq. Knoll Cottage

1917

Apr. 16	Self 8½ hrs. whitewash bathroom, W.C. staircase, Kitchen etc			58
17	Self 7½ hrs. "			50
18	Self 7½ hrs. "			50
19	Self 4 hrs. "			28
20	Self 7½ hrs. paper bedroom			50
	6 pieces wallpaper 13/6 carriage 6"			140
	1 pkt. paste 6" ¼ lb. size 3"			9
	20 lbs. white distemper	6		100
	14 lbs. buff. "	5½		65
	4-6 of 3½ x ¾ deal			8
	plaster, white lime etc			6
	2 laths 2", nails 1", paint 6"			9
Apr. 3	cleaning out cesspit			110
27	2 hrs easing door			16
May 29	man 7½ hrs. make bench jaws			44½
	5-0 of 2 x 1½ oak			26
	12. 1" screws			2
	3. iron squares			16
	1. 1¼" bench screw			110
	1 iron stop pin chain			30
June 4	2 men 9½ hrs. ea. fencing in garden			111
5	2 men 9½ hrs. ea. do.			111
6	2 men 9½ hrs. ea. do.			111
7	2 men 9½ hrs. ea. do.			111
8	2 men 9½ hrs. ea. do.			111
9	2 men 5 hrs. ea. do.			510
	man cutting hedge			20
	1 post 12-0 long 4x4 oak	6¾		69
	6 do. 6-0 long ea. 4x4 36/4	6¾	1	03
	45 do. 6-0 " " 2x3 27 c/p.	2¾	3	110½
	12 do. 5-0 " " 2x3 60	2¾		139
	forward	1	12	174

June

	forward		12	17	4
	4 lbs. staples	10		3	4
	3 lbs. pat. nails			1	0
	18 lbs of wire	7½		11	3
	50 yds of 48x2 netting		1	12	0
	50 yds of 36x1½ "		1	4	6
	10 yds of 48x2 "	7		5	10
	1 coil fine wire				8
	23-0 of 2x1 battens			1	6
	20. 1" screws				3
	1 pair 2" back flaps				6
	1 hasp & 2 staples				6
19	3 hrs. make read boxes	1-9			
20	9 hrs. do	5-3			
21	3 hrs. do	1-9			
	80-0 of 7x¾ floor 2¾	18-4			
	nails	5- 1-7-6			
	10 portable boxes at 2/9		1	7	6
27	self 5 hrs. fit boarding felting			3	4
	54-0 45-0 of 7x¾ match		27/8	12	11
	8 yds of felting			4	0
	9-0 of 2x1				7
	9-0 of 2x¾				6
	nails				6

Paid. July 11. 1917

19 8 0

Master W. Hosford

1917

apr. 26	7½ hrs. make 17 ft flag pole stand		50
	12:0 of 4x4 oak	6¾	69
	1 bolt, ¼" 8 coach screws ¼"		20
	1 cap. 6" 6. 1½" screws 2"		8
	4½ lbs. white paint		34½

179½

Paid July 11. 1917

Woodbury Churchwardens

1917

Jan. 4	5 hrs. put in new chime cords		39
	4½ lbs. chime cord		90
	1. 5½ x 3/8 bolts		3

£

130

Paid July 18. 1917

Miss Lucy Martin, Sydney Cottage

1917

£ s d

Jan.	10	1 1/2 hrs. eazing door	1	0	10 1/2
Feb.	13	Self 3 1/2 hrs. put in glass case cupboard door & fit board in cupboard	2	4	
		2 pails 10 x 14 putty	2	3	
		1 piece elm 2'-0" x 10" x 1/2"		4	
Mar	2	Self 3 hrs. put in new pucker	2	0	
		1- 3" pucker	1	6	
		1 leather slack	1	0	
	4	new end to rake handle	1	0	
Mar	5-6, 17.	To carting 8 tons 17 cwt coal from Station	1	7	0
		man packing coal		8	0

 £ 2 6 5

Paid, Aug. 4, 1917

1917 Mr. J. S. Pyne, Radbrooke, Cullompton

£ a d

Jan.	12	man 1 1/2 hrs take off cast shaft			10 1/2
	15	2 men 9 1/2 hrs ea put in shaft, & new front board & rail			11 1
	16	1 man 6 1/2 hrs. do			3 9 1/2
		1 crooked shaft			17 6
		4-9 of 2 x 3 ash			1 3
		3-0 of 1 1/2 x 1 1/2 "			4 1/2
		3-6 of 1 3/4 x 1 elm	3-		11
		18 rivets, & repair front board iron			2 9
		paint 6.			6
		2 keys & 1 ring staple			10
		repair ironwork of shaft			10
Feb.	20	man 7 1/2 hrs repair lades		2-1 0 1/2	4 4 1/2
		4-3 of 1 5/8 x 1/2 elm			10
		5-6 of 3 x 1 elm			4
		2. 2" & 2. 3 1/2 x 3/8 bolt.			6
		1/2 lb. paint			5

Paid. July 9. 1917

£ 2 7 8

Mr. B. Stamp. Woodbury

1917

Jan.	16	1 1/2 hrs. make draft 1 draft staple	1 2
	20	man 3 hrs. alter step of trap & put on tail spring 1 new spring 1. 2 1/2 x 3/8 bolt. 2 screws 1 saw handle & put on bottom of range	1 9 1 6 2 1 3 3 0
Feb.	23	1 1/2 hrs put in afe handle	.. 10 1/2
Mar.	24	2 meat crooks rifting	.. 6
	26	solder separator spout	.. 4
Apr.	11	man 2 1/2 hrs. repair foot corp 12. 1 1/4" screws	1 5 1/2 3 1/2
	20	link in chain	.. 2
	24	man 3 hrs. make draft 1 new pin	1 9 9
May	4	new lynch pin of wheel	1 0
	5	1 hr. take off front board of trap repair front board iron new piece	7 2 3
	7	fit do.	9
	5	1 pint linseed oil	19
	9	1 1/2 do.	13 1/2
	11	1 1/2 do.	13 1/2

 7 1 2 10

Paid July 19, 1917

Warehouses (Tanners)

1916

Dec.	29	mason 2 hrs. put in glass plate.			1 2
		3 glass plates			4 6
		12 p. copper wire, 10 screws			1 2
1917 Jan.	31	man 8 hrs. hack out glass pip shunting			4 11 1/2
Feb.	2	man 9 hrs. pip shunting stake out skylight			5 6 1/2
	3	man 5 hrs. put in glass			3 2 1/2
		24 slunk screws, 24 C.S. nails			1 6
		1. 5" stop end, 6" 1-0 of 1 1/2 R.W. Pipe			" 9
		5 lbs. putty for glass shunting			10
	13	man 9 hrs. pip shunting, stair head, beams under roof r.s. & lead on bruiser roof			5 6 1/2
	14	man 9 hrs. do.			5 6 1/2
		man 2 1/2 hrs. do.			1 5 1/2
	15	man 9 hrs. do.			5 6 1/2
	16	man 9 hrs. do.			5 6 1/2
	17	man 5 hrs. do.			3 2 1/2
		28-0 of 2x1 battens bruiser roof			2 1
		6-0 of 2x3 " do.	2 3/4		1 4 1/2
		2 lbs. nails "			7
		lead 72 lbs. "	5 1/2	1	13 0
		1. 4 1/2" outlet. shunting			1 9
		15 C.S. nails "			4 1/2
		6. 3" pipe nails "			3
		repair holofast "			1 0
		22-0 of 3x2 beams under iron roof	2 3/4		5 1
		3-6 of 10 1/2 x 1 1/4 elm bread			
		3-6 of 8 1/2 x 1 elm riser } Sp.	3		1 3
		paint for shunting			9
		lead in gutter over office 70 lbs.		1	12 1

Paid July 4, 1917

£	6 10 0 1/2
---	------------

Mr W. Glanville. Ford Farm

1917

Jan. 16	make drapr. 1 staple			1 2
Apr 13	man qt. lms. make hurdles			5 65
	nails			6
	$55.6 + 4.6 = 249.9$			
	$28.9 \times 10.6 = 302.0 - 551.9$	6/6		1 159
June 21	1 notch board			3 6

 £ 2 6 5

Paid, Aug 24 1917

1917 Wm. S. Miller

Feb. 12	man hrs. put new prints to wagon shafts	36
	3-3 of 2x3 ash	10
	paint 2 ^o . hoop iron 3 ^o claws 2 ^o .	7
	1. 3 x 3/8 bolt	2
	repair bolts of shafts	6
Apr 20	2 shaft wangs putting in	23
	1 false link	3
May 9	Self color kitchen, staircase glim.	60
	14 lbs. Halls distemper	70
25	put handle in hook	9
		<hr/>
		\$ 11 10

Paid. July 7. 1917

Mr. E. Burden

May 12	To new body of barrow, ring wheel	
	1 new spoke + new tyre	136
June 20	To putting new side leg to barrow	36
		<hr/>
		\$ 170

Paid Oct. 31. 1917

St. Thomas Rural District Council

1917

£ s d

Feb. 16	6 hrs. repair barrow		3	6
	4-6 q 2 x 3 ash		1	1½
	1-9 q 15 x 1 elm			6½
	4-0 q 9 x 1 - back bracket			9
	½ lb. nails, ½ lb. paint	6/5.		6
June 19	To 2 notice boards. painted & covered with galv'd. sheet iron on oak posts To fixing one in Black Hill Pit		1	15 0
				2 0

£ 23 5

Paid. July 16. 1917

Mr. G. Pyne. Rosedale

May 22	To garden light			7 0
	To frame for light painting light		1	0 0

£ 17 0

Paid. July 11. 1917

1917 Mr. J. Fyne. Postlake

£ s d

Feb.	27	To washing stool		5	3
Mar	7	man 6 hrs. put in waggon shaft		3	6
	8	man 5 hrs. do		2	1
		8.6 of 3 + 3 1/2 ash shaft	6 1/2	4	8
		paint			6
		repair shaft iron	11 1/3		6
June	4	To garden light		1	0
		To frame for light painting light		1	0
				<u>£</u>	<u>2 5 6</u>

Paid. July 25. 1917

Mr. W. Down. Vennor

1917

F o d

Mar 2	man q ² hrs. put new tip stick, new horse piece & plates to perhaps & new front board to east			5 6 ¹ / ₂
3	man 6 hrs. do.			3 6
	3-6 of 13x1 elm			1 0
	4-6 of 4 ¹ / ₂ x3 oak	6 ¹ / ₂		2 6
	4 iron plates 16 lbs. 2 ^o			2 8
	8 4" ¹ / ₄ r y. 4 ¹ / ₂ x ³ / ₈ bolts ¹ / ₈			3 0
	3-0 of 1 ¹ / ₂ x1 ¹ / ₂ ash tip			6
	2 rings ³ / ₂ r 13 rivets 1/1			1 4
	paint			6
	2 plates iron 6 ¹ / ₂ lbs. 1 ¹ / ₂ hrs.			2 3

1 1 2 9 ¹/₂

Paid. July 30. 1917

Mr. S. Cornish, Colhills

1917

Mar	27	9½ hrs.	ring waggon wheels			
	28	7 hrs.	do.			
Apr.	4	9½ hrs.	do.			
	5	9½ hrs.	do.			
	7	5 hrs.	do.			
	10	9½ hrs.	do.			
	11	2 hrs.	do.			
	12	9½ hrs.	do.			
	13	3½ hrs.	do.			
	14	1½ hrs.	do.	66½	1 18 9	
		12.	3-4 felloes	1-0½	12 6	
		6.	3-2 felloes	1-0	6 0	
		3	spokes		1 0	
		3 new tyres	158 lbs	4½ 5½	3 5 10	
Mar	29	2 hrs.	repair waggon	}		
	30	3½ hrs.	do.			
	31	6 hrs.	do.			
Apr	2	9½ hrs.	do.			
	7	2 hrs.	do.		23 hrs	13 5
	11	8 hrs.	paint do.	}		
	12	1 hr.	do.			
	14	2 hrs.	do.			
	24	4 hrs.	do.			
	25	5 hrs.	do.			
	27	7 hrs.	do.		48 hrs	
	28	3 hrs.	letter do.			
May	2	2 hrs.	paint			
	3	7 hrs.	do.			
	4	5 hrs.	do.			
	5	2 hrs.	do.			
	7	2 hrs.	do.			
		9 lbs. red paint	6/9	9 lbs. blue	6/9	1 8 0
						13 6

Mr. S. Cornish

£ s d

1917

May 7	To painting & cleaning lorry waggon 2 coats paint		2	1	6
	To repairing lorry waggon, new tail board, part new bottom, 12 bolts, 1 roller pin & links, 2 ring eyes 2 side board harps staples & crooks time 13/5½		1	7	3
	12 bolts	11-			
	18 screws	4			
	nails	3			
	5-3 of 7 x 1½ elm	1-1½			
	9-6 of 16 x 1 elm	3-2			
	repair 2 plates	7			
	wash waggon	1-9			
	1 pin & 3 links	2-3			
	2 ring eyes	1-0			
	2 harps, 6 staples, &c	2-4	13/9½		
	To ringing 3 waggon wheels putting in 3 new spokes 3 new tyres 15 lbs at 5 ^d 4½		2	18	3
			2	19	3
			8	5	0
12	2 lbs. blue paint				16

Paid. July 24. 1917

£ 9 7 9

Mr. George Kerlake

1917

Mar	29	man 6 $\frac{1}{2}$ hrs. repair casement	3	9 $\frac{1}{2}$
		6. 1 $\frac{1}{4}$ screw paint	3	
Apr	3	man 9 $\frac{1}{2}$ hrs. repairs	5	6 $\frac{1}{2}$
May	3	man 10 $\frac{1}{2}$ hrs. painting	6	2 $\frac{1}{2}$
		1 sheet glass paper	1	
	14	1 lb. red paint	9	
June	11	man 9 $\frac{1}{2}$ hrs. about window sashes	5	6 $\frac{1}{2}$
	12	man 9 $\frac{1}{2}$ hrs. do.	5	6 $\frac{1}{2}$

Paid Jan 26. 1918

 1 7 7

Mr. S. Pile, Rydon hills

Apr.	2	4 $\frac{1}{2}$ hrs. fit handrail, wardrobe	2	7 $\frac{1}{2}$
		2 - 3 $\frac{1}{2}$ 2, 2 $\frac{1}{2}$ + 2, 2 $\frac{1}{2}$ screws	3	
		2 doz. brads. 3 - 0 of 3 x 1 deal	4	2

 3 3

Paid Aug 27. 1917

Mr. Henry Clauill

1917

Apr. 12

1 hr. put plate on cart shaft
 1 plate iron 10 lbs. fitting plate 4 hrs. 1.5
 2. 4¹/₂ + 3 4 x 3/8 bolt. 6

7
 4 6 1/2
 10 1/2

Paid Sep. 1. 1917

1

60.

Apr. 26

Woodbury School (Council)
 fixing bellrope

20

Paid July 13. 1917

Apr. 28

Mr. Walter Skinner
 4 hrs. put felloe in wheel
 1 felloe. 1 davel
 1/2 hr take off tyre
 1 new tyre 3 lbs

24

8

4

5

12 11

1

16 3

Paid Oct. 4. 1917

Mr. W^m Sage Venmore.

1917

Apr 17	2 1/2 hrs. make hay knife handle	1 5
"	making a new top end to hay knife	3 0
23	man 6 hrs. making 3 horse drags	3 6
24	man 5 1/2 hrs. do.	3 2 1/2
24	repairing bolts across of drags, making 3 new clips fixing clips on drags	6 0
May 21	man 9 1/2 hrs. repairs Venmore	5 6 1/2
22	do. 9 1/2 hrs. repairs Willycombe	5 6 1/2
23	do. 9 1/2 hrs do	5 6 1/2
24	do. 9 1/2 hrs do	5 6 1/2
25	do. 9 1/2 hrs do	5 6 1/2
26	do. 6 3/4 hrs do.	3 6
	4 4 x 3/8 ⁸ 1 4 1/2 x 2/8 bolts Venmore	.. 8
	1 4 1/2 ²⁴ 18 4 ³¹ 18 3 x 2/8 ²³ Willycombe	5 5
	18 fake staple	2 0
	4 lbs. cuts	1 0
	2 lb. pat. nails	8
June 19	repairing roller handle, 1 handle, 5 bolts new iron 7 lbs. time 6 1/2 hrs. paint	8 0

 3 6 4

Paid July 19. 1917

Mr. Edgar Ware, Woodbury

£ s d

Apr.	30	take off chop around wheel 1 new tyre 4 lbs.	5		9
May	29	man 9 ¹ / ₂ lbs repair lades			5 6 ¹ / ₂
	31	man 5 ¹ / ₂ lbs do.			3 2 ¹ / ₂
		5-3 of 9x2 ash side	9		4 0
		4-0 of 3x1 elm			.. 3
		3-0 of 2x2 ash			.. 3
		7- 2x1/4 bolts			7
		3. 4 ¹ / ₂ , 2. 6 ¹ / ₂ + 1. 5 ¹ / ₂ + 3/8 bolts			1 3
		paint			.. 6
		lengthen lade iron (3 lbs iron 9 ¹ / ₂)			1 6
June	1	man 9 lbs repair carriage of waggon			5 3
		1-6 of 3 ¹ / ₂ x 2 ¹ / ₄ ash			.. 6
		alter repair ironwork of waggon			3 0
		4 small harness rings			1 0
	25	3. 1 ¹ / ₂ x 3/8 bolts 1 nut			4
			7	2	5 0

Mr. Joseph Ramsey

1917

May	1	man 3 1/2 hrs. re box wheel			23
June	11	man 6 hrs repair glass			36
		4 lbs. putty			8
		6. 1" screws			1 1/2
		1 plate iron			.10 1/2
					<hr/>
Paid July 17, 1917			£		75.

Mr. F. Watts Carrier B. Salterton

May	7	14' 0" x 1' 9" x 1' elm 24' 6"			61 1/2
-----	---	--------------------------------	--	--	--------

Mr. John Stooke, Woodbury, Salterton

1917

May 8	4 hrs. repair trap, + new wing board	+	2 7 $\frac{1}{2}$
9	4 hrs. do.	+	2 4
10	9 $\frac{1}{2}$ hrs. do.	+	5 6 $\frac{1}{2}$
11	6 hrs. clean off trap	✓	3 6
16	3 $\frac{1}{2}$ hrs. do.	}	" "
17	5 $\frac{1}{2}$ hrs. do.		✓
18	9 $\frac{1}{2}$ hrs. put new tailboard on.	+	5 6 $\frac{1}{2}$
19	7 hrs. paint + stain	✓	4 1
	2. 5 + 3/8 ⁵ , 2, 3 + 3/8 bolts ³ , 4. 2 $\frac{1}{2}$ x 3/8 ^{5 to}	✓	1 1 $\frac{1}{2}$
	2. 1 $\frac{1}{2}$ + 5/16, 8. 1 $\frac{1}{4}$ + 1/4 "	+	10
	12. 1" screws	+	2 2
	whitewood for tailboard	+	4 3
29	9 $\frac{1}{2}$ hrs. paint + size	✓	5 6 $\frac{1}{2}$
30	9 $\frac{1}{2}$ hrs. do.	✓	5 6 $\frac{1}{2}$
31	7 $\frac{1}{2}$ hrs. do.	✓	4 4 $\frac{1}{2}$
	1 new wing board	+	10
June 4	strip trap	✓	8 0
5	3 hrs. varnish trap	✓	1 9
7	5 hrs. do.	✓	2 11
8	8 hrs. do.	✓	4 8
9	2 hrs. do.	✓	1 2
	1 pint varnish	✓	3 6
	paint	✓	2 3
	re-typing 2 wheels	+	7 0
	riveting step 1/2 + alter spring 6	+	1 6
	1 bolt + thumb screw for seat	+	1 0
	To cleaning, painting wheels, springs, chaps inside of trap, striping wheels + varnishing trap 2 coats		2 12 6
	To cutting + shooting types		7 0
	To putting new tailboard, 1 new wing board, new cross bar + thumb screw for seat, new bolts + repair step		1 6 0
		£	4 5 6

Paid Sep 21 1917

Executor of late Mr. J. J. Glanville, Rydon Farm,

1917

May 11	To making an elm shell and an outer			
12 + 17	Coffin of ^{unpolished} Oak with heavy brass mountings taking the Coffins to Reminster and carrying out the funeral arrangements of the late Mr. J. J. Glanville		10	10 0
	To Hearse & mourning Coach & Drivers		4	5 0
	To Vicars, Clerks & Serrons Fees			9 0
	To six bearers		1	10 0
	To engraving & painting 69 letters to painting 165 letters, to cleaning & painting, and to taking out & refixing headstone			1 7 6
			£	18 11 6

Paid. Oct. 20. 1917

Miss Acland. The Firs. Woodbury

1917

May	14	man 9 $\frac{1}{2}$ hrs. ring trap wheel		5 6 $\frac{1}{2}$
	15	man 4 $\frac{1}{2}$ hrs do.		2 7 $\frac{1}{2}$
	16	man 1 $\frac{1}{2}$ hrs do.		10 $\frac{1}{2}$
		7 felloes		5 3
		paint		" 6
		tyring 2 wheels	£ 1-1-4	7 0
		To milking stool		2 3

 $\frac{1}{2}$

1 4 0

Paid Feb. 1. 1918

Mr. Robert Pile. Bagmoor Farm

1917

May 21	qhrs. clean & whiten ceiling			
22	qhrs. clean varnish paint windows			
23	qhrs. varnishing			
24	qhrs. hang paper			
25	qhrs. varnish floor re color porch 45hrs)	1	10	0
	7lbs. white distemper		3	6
	2lbs. luff for porch		1	0
	2lbs. paint		1	6
	1/2 gal. Oak Varnish		7	6
	2 tins Bonumilk, 1/3 1 pint turps		2	3
	size 3, paste 11-		1	3
	8 pieces wallpaper 2/3		18	0
	20 yards border		7	0
	plaster for porch		..	6
	6 picture hooks nails putty		..	6
		<u>1</u>	<u>3</u>	<u>13</u>
	To milking stool			<u>2</u>
				<u>3 15 6</u>

Paid. Oct. 26. 1917

1917 Mr. Alfred Stamp

Jan	24	2 box ions	30
Feb.	10	new hoop on standard	29

Paid. July 5. 1917 59

Feb	9	Col. Marefield 2 seams wood	70
-----	---	--------------------------------	----

Paid. July 5. 1917

		Rev. R. H. Heely	
March		To cleaning & varnishing trap as contract.	1 10 0
		To felloeing wheels do.	3 15 0
Apr.		To striping trap	5 0
		.. To full to seat & new cloth back	1 1 0
		.. To thumb screw bolts & 2 plates of iron to seat striping	4 3

Paid. July 13. 1917

7 4 15 3

Mr. John F. Glanville, Rydman Farm

1917

June 11	man 1 1/2 hrs. repair bottom of waggon	-	
12	man 9/2 hrs.	do. r screw up.	-
13	man 9/2 hrs.	do. wash waggon	-
14	man 7 hrs.	wash & paint	X
15	man 6 hrs.	paint	X
	" 3 1/2 hrs.	repair lades	-
16	man 4 hrs.	paint lades	+
18	man 2 hrs.	about wheels	-
	" 9/2 hrs.	paint waggon	+
19	man 5 1/2 hrs.	do.	+
20	man 8 1/2 hrs.	do.	X
21	man 11 1/2 hrs.	do.	X
22	man 2 hrs.	do.	X
25	man 3 hrs.	put together	+
	57 hrs. paint waggon		1 13 3
	9 lbs. red, 6 lbs. lead, 5 1/2 lbs. blue paint	20 1/2 lbs	15 1/2
	3 lbs putty		6
	letter waggon	2-12-1 1/2	3 0
	26 hrs. repair bottom of waggon, repair lades		15 2
	r screw up waggon + side rails		3 1/2
	11-0 of 15 x 1 elm	13-9	" 4 1/2
	4-6 of 6 x 1/2 elm		" 4
	1 lb. nails		" 5
	10-6 of 2 x 1/2 ash for lades	7 1-6-4	" 6 1/2
	2-3 1/2 x 3/8 bolts, 3 1/2 3-1 1/2 x 5/16 bolts 3°.		1 6
	repair bolt, hook, I.S. roller ring		3
	1 split key		1 0 5
	new tyre 4 q lbs		3 0
	tyre wheel		

Paid. Jan. 9. 1918

2-12-0
 1-2-0
 1-0-5
 3-0
 7-4-5

Messrs. Albr. Squires Ltd. South Street, Exeter,

1917

July 4

1/2 elm
 3 boards 10-6 long $16\frac{1}{2} \times \frac{1}{2}$ ea. = 43-3
 1 do. 11-6 " do. 15-9
 2 do. 14-0 " do ea = 40-0-99-0
 99 feet paper at 2^o

16 6

7/8 elm
 1 board 6-9 long $18\frac{1}{2} \times 7/8$ = 10-4
 1 do 6-9 " $19\frac{1}{2} \times 7/8$ = 10-11
 2 do. 6-9 " $20\frac{1}{2} \times 7/8$ ea. = 23-0
 6 do. 6-9 " $21 \times 7/8$ ea. = 70-6
 2 do. 6-9 " $21\frac{1}{2} \times 7/8$ ea. = 12-1-26-10

1 11 8

126-10 of 7/8 elm 3^o
 1 board 11-3 long $18 \times 7/8$ = 16-10
 1 " 11-3 long $19 \times 7/8$ = 17-9
 1 " 11-3 long $20 \times 7/8$ = 18-9
 2 " 11-3 long $20\frac{1}{2} \times 7/8$ = 38-4
 3 " 11-3 long $21 \times 7/8$ = 59-0
 4 " 11-3 long $21\frac{1}{2} \times 7/8$ = 80-4
 231-0

231-0 paper at 3^o

2 17 9

1/2
5 5 11

Paid Sep. 13. 1917

July 20-17

Mr. S. Roberts, Jeanes Farm, Bradford-on-Turn

1917

July 11	To six bellropes at 16/6 ea. 50 pr. long Carriage	4 19 0	1 10
---------	---	--------	------

£	5 0 10
---	--------

Paid. Sep. 21. 1917

Mr. H. Tucker, Canonwells, Woodbury

June 29 or July 13	man 42 ¹ / ₂ hrs. ring 2 trap wheels & put in 4 spokes	1 4 9 ¹ / ₂
	14. 2 ¹ / ₂ spokes fellows 7°	8 2
	4. spokes	1 4
	2 lbs. paint	1 6 ¹ / ₂
	2 new tyres 64 lbs. at 5 ^d	1 6 8
	15 hrs. alter step of trap	1 0

1-15-1917

3 3 4

Paid. Oct. 25. 1917

Mr. S. G. Miller

1917

Mar.	13	4 hrs. clean governess car (\$)	2-8		
	14	3 hrs. do.	2-0		
	15	9 1/2 hrs. repair trap door & traps around body, & alter springs	5-6 1/2		
	16	9 1/2 hrs. do.	5-6 1/2		
	17	5 1/2 hrs. do.	3-2 1/2		
	21	8 hrs. paint trap (\$)	5-4		
	22	3 hrs. do. (\$)	2-0		
	23	4 hrs. do. (\$)	2-8		
	24	4 hrs. do. (\$)	2-8		
	26	2 hrs. do. (\$)	1-4		
	31	1 hr. do. (\$)	8		
Apr.	3	8 hrs. varnish (\$)	5-4		
	5	8 hrs. upholster (\$)	5-4		
	7	6 hrs. - wood varnish (\$)	4-0	2	8 3/2
		Red Paint 4/- Quaker Green 3/-			1 5 1/2
		1 square screens			7 0
		1 1/2 pints Varnish			4 6
		screwing bolts			4 3
		Striping trap 3-11-6			8 6
		Making 2 Cushion Covers, 1-4-3 c.p. add 3/6		1	7 9
		15-0 of brass beading 57- c.p.			6 0
		Restuffing 2 long cushions			6 6
				<hr/>	
				5	11 9

Paid July 30. 1917

Mr. S. G. Miller

1917

Apr.	23	sharpen small saw				4
May	5	straighten + repair wing boards of trap				33
	9	sharpen saw				6
	14	2 1/2 hrs. put zinc in door + window				15 1/2
		9 sq. ft. of perforated zinc	3 lbs.	1/5		43
		4 doz. 1/2" nails				2
	19	7 lbs. cut nails				24
	30	6 planks wood				90
						<hr/>
						113 1/2

Paid. July 30. 1917

Mr. W. H. Stamp. Venmor

1917

I o d

Jan. 29 th	29 lbs. ring trap wheels			16	11
Feb. 1	7-6 of 2x9 ash felloes 1 spoke	9		5	7 $\frac{1}{2}$
	2 tyres 62 lbs.	5	1	5	10
Feb. 3	16 $\frac{1}{2}$ lbs. making trap		4	15	11
Mar. 7	2 bent sides			14	9
	14 $\frac{1}{2}$ doz. screws	1 ^o		2	5
	timber			11	6
	50 bolts various sizes			8	4
	2 brass chapt stops			3	3
	2 tailboard fasteners			4	0
	screws for do			5	6
	2 brass handles			5	6
	1 quart petrol				8
	1 leaf in spring			9	0
	2 lamp iron + ends			2	0
	new cushion seat back + full		2	10	0
	whip socket			2	0
	paint + varnish			6	0
	striking			7	6
	1 tail lamp			3	6
	1 pair steel butts			1	0
	1 pair jap ^d breeching staples				8
	smith 39 lbs. alter + make ironwork q ^o		1	9	3
	29 lbs. new iron 3 ^o			7	3
	1-6 of chain				6
				15-16	-4 $\frac{1}{2}$
	To ring trap wheels, new tyres, 1 spoke making new ralle body + seat, new leaf in spring, part new ironwork, new brass chapt stops, handles + tailboard fasteners new whip socket, tail lamp + painting striking		13	6	6
	To making 2 new cushions, forming box and seat back with best green cloth		2	10	0

Mr. W. H. Stamp Venmore

1917

£ s d

Mar 7	man 8 ¹ / ₂ hrs. repair shackles of pig ear	4	11 ¹ / ₂
	smith 6 ¹ / ₂ hrs do	4	10 ¹ / ₂
	9 lbs new iron	2	3
	6. 4 ¹ / ₂ + 1/2 bolts	1	6
	4. 4 ¹ / ₂ + 3/8 bolts		9
	altering step of pig ear 1 ¹ / ₂ hrs	15	4
May 9	1 red lamp glass		6
June 26	6 do.	2	6
	putting plug in waggon wheel	1	0
28	repairing trap lamp	1	0
	8 hrs. put new body to barn	4	8
29	7 ¹ / ₂ hrs do	4	4 ¹ / ₂
	5-0 of 2+3 ash	1	3
	8-0 of 12+1 elm	2	0
	2-3 of 15+1 elm		8 ¹ / ₂
	1 lb. nail		4
	2 lbs. paint		1
	repair 2 bolts q. 2 new eyes 1/6. 2 ring 8 ¹ / ₂	2	11
	14 ¹ / ₂ planks wood at 2/.	1	9
	6 do. at 1/6		9
		13	6
		2	10

Paid. July 13. 1917

£ 19 12 7

Mrs. Marshall. Oakhays

1917

June	12	Pour & Trap	to Station		1 9
	16	do.	Exmouth	10 a.m. to 6 p.m.	4 6
	21	do.	Exeter	10 a.m. to 7 p.m.	5 6
	23	do.	Station		1 9
July	13	do.	Exton	4 to 6-30 p.m.	2 0
	17	do.	Station		1 9
	18	do.	Station		1 9
	20	do.	Exmouth	2 p.m. to	4 0
	23	do.	Comberton Wear	3 p.m. to 7 p.m.	4 0
	25	do.	Station		1 9
	27	do.	Exmouth	10 a.m. to 5 p.m.	4 6
	28	do.	Woodburn Saltston		1 9
Aug	2	do.	Exmouth		4 6
	3	do.	Exton Station	3-30 to 6 p.m.	2 0
	7	do.	Exeter	10-30 to 6-30	5 6
	9	do.	Station		1 9
	21	do.	Station		1 9
	27	do.	Exeter	1 p.m. to 8 p.m.	5 6
	29	do.	Topsham		2 0
	"	do.	Station		1 9
	31	do.	Exmouth		4 6
Sep.	3	do.	B Saltston		5 0
	7	do.	Exmouth	10-30 to 6 p.m.	4 6
	10	do.	Exeter	10-30 to 7 p.m.	5 6
	15	do.	Exmouth	3-19-3	4 0

Paid. Sep. 25. 1917

4 3 3

Mr. Joseph Ramsey

Aug 1	9 $\frac{1}{2}$ hrs. put in post, beam, hang doors + repair jambs		5 6 $\frac{1}{2}$
2	6 hrs. do. do.		3 6
	4 spikes 1/2 2 square staples 6 $^{\circ}$ 1 catch 3 $^{\circ}$		1 9
	1 $\frac{1}{2}$ lbs cut nails 12 counter sunk nails		8 $\frac{1}{2}$
	1 iron square		6 $\frac{1}{2}$
	12-0 of 2x1 battens		9 $\frac{1}{2}$
	11-0 of 9x3 deal beam 1/1 $\frac{1}{2}$		12 4
	18-0 of 4x4 oak post 6 $\frac{3}{4}$		10 0
	making stay for beam		1 0
	4-0 of 4x3 oak sill 5 $\frac{1}{2}$		1 10
			<hr/>
			1 18 0 $\frac{1}{2}$

Paid. Oct. 26. 1917

Mr. A. Havill. Mallocks Woodbury

£ s d

1917

June 1	man's time 23 hrs making body of waggon			
July 3	putting new pillars to carriage repair			
	lades + paint waggon wheels		6	14 9
	timber pains bolts		3	17 0
	14 bolts 13 lbs. 98 lbs. of iron 3 ^d		1	4 6
	ironwork 20 lbs. 74 hrs making		2	0 4 1/2
	coal			5 0
	12 rivets 1/2 2 tail pins chains staples 1/6			2 6
	1 plate for draghoe 1/2, 12 nails 1/2.			2 0
	2 ring eyes			1 6
			14	7 7 1/2

To making ^{painting} a new body of waggon

12 0 0

To putting 2 new bearing pieces on
front back carriages, new iron sweep
ring on front carriage, painting
wheels, carriage shops 2 coats paint

2 10 0

£

14 10 0

Paid. Oct. 10. 1917

Mr. W. Glanville, Ford Farm, Woodbury

1917

July	4	To milking stool			2 6
Aug	5	2 hrs. repair trap			1 2
	7	8 1/2 hrs. do.			4 11 1/2
		2. 3 x 5/16 ³ , 2. 2 x 5/16 ² , 1. 1 1/2 x 5/16 ¹ bolts			.. 6
		2. 3 x 3/8 ³ , 1. 1 1/2 x 1/4 bolts			.. 4
		6. 1 1/4" screws			.. 2
		2 leather collars			3 3
		2 seat straps			1 0 1/2
		3 doz. tacks, 9" hoop iron			5
		2 shaft stops 1/10 2 breechin staples 1/5			3 3
		5 1/4 hrs clean + paint trap varnish		4 1	11 6
		paint, 6/10 varnish 4/6			18 6
		striping	7 2-12-6		7 6
		2 umbrella straps			1 6
		To making 2 cushions, trimming seat			
		back 2 sides + driving box			2 10 0
Oct.	23	To 2 milking stools.			5 0

6 7 0

Paid, Jan 3, 1918

Mr. W. Sage. Vermont. Woodbury

(1917)

July	6	man 7 $\frac{1}{2}$ hrs repair lade			4 4 $\frac{1}{2}$
	7	man 6 hrs do			3 6
		6-3 q 7x2 ash	7		3 8
		5-0 q 2x4 ash			1 8
		17-0 q 2x $\frac{1}{2}$ ash rap			9
		2- 3 $\frac{1}{2}$ x $\frac{3}{8}$ bolts ^{3$\frac{1}{2}$}			8
		3- 3x $\frac{3}{8}$ bolts ^{4$\frac{1}{2}$}			5
		nails, 1 staple rework for pin			
	10	man 3 $\frac{1}{2}$ hrs make lade			2 0 $\frac{1}{2}$
	11	man 9 $\frac{1}{2}$ hrs do			5 6 $\frac{1}{2}$
		6-6 q 2x7 ash	7		3 9
		5-3 q 10x1 elm 4-6 or 3"			1 1 $\frac{1}{2}$
		4-0 q 9x $\frac{1}{2}$ elm			6 $\frac{1}{2}$
		1- 3 $\frac{1}{2}$ x $\frac{3}{8}$ bolt			2 $\frac{1}{2}$
		nails paint 13 q $\frac{1}{2}$.. 6 $\frac{1}{2}$
Sept-	24	9 $\frac{1}{2}$ hrs put in new shaft in cart			5 6 $\frac{1}{2}$
	25	9 $\frac{1}{2}$ hrs repair bottom & put plate of iron on the shaft		
					5 6 $\frac{1}{2}$
	26	2 hrs do repaint shaft			1 2
		8-3 q 4 $\frac{1}{2}$ x3 ash shaft	7 $\frac{1}{2}$		5 0
		3-9 q 2x2 ash stand	4		4 8
		3-3 q 9x1 elm bottom			7 $\frac{1}{2}$
		2-3 q 5x $\frac{1}{2}$ elm rail			2
		2-0 wire 1 do nails			3
		1-4 $\frac{1}{2}$ 1, 5 $\frac{1}{2}$ x $\frac{3}{8}$ bolts			5
		1 lb. paint			.. 8
		ring staples for rest stand			.. 8
		cutting shuting 2 tyres			8 0
			1		2 17 4 $\frac{1}{2}$

Paid, Dec. 28, 1917

1917 C. Davy, Esq. Knoll Cottage, Woodbury.

£ p d

July	10	23-0 g. 11x1 deal	6	11	6
Aug	10	5 hrs. put piece flue in range		3	4
		1 piece of flue		3	0
		3. 1 1/2" screws			2
		plaster			3
	22	sharpen saw			6
Sep	1	3 hrs repair wire fence		2	0 1/2
		6 yds. of wire			6
	15	10 cub. of logs		15	0

£ 16 3

Paid. Oct. 10. 1917

Mr. Alfred Stamp.

1917

June	8	piping damper	1	4
July	11	3 hrs. collar waggon wheels	1	9
		1/2 lb. leather for collars		3
		oil for 4 wheels		3
	12	3 1/2 hrs. fix locks on deck scupboard	2	0 1/2
		1 deck lock		2 6
		1 scupboard lock		3 0
Aug	24	7 1/2 hrs. put in post change gate	4	4 1/2
		1 new twist		2 3
sep.	18	new axle stem		1 4
July	12	sharp meat saw		6
			1	1 7

Paid. Oct. 16. 1917

Miss B. Glanville, Broadway, Woodbury

1917

7 p d

July 19 Self 8 1/2 hrs. fit new sill + jamb + make change new door hardware

4 11 1/2
5 8
1 5 1/2
+ 8

20 Self 2 1/2 hrs. do. 1 paint door

30-0 of 7x3/4 mesh

2 3/4

6 10 1/2

7-3 of 7x1 ledge

3 3/4

2 0

6-3 of 4x3 deal jamb

6

3 1 1/2

3-0 of 4x3 oak sill

6

1 6

1 iron square + 4 screws

6

1 6" Tower bolt screws

8

1 lb. nails

4

1 pair 12 Teething screws

1 6

1 lb. paint

8

14-0 of 1 1/2 x 3/4 deal steps

7

7 1/2

1 4 2 1/2

Paid, Jan. 7, 1918

Mr. S. G. Miller, Woodbury

I o d

1917

July	23	7 hrs. repair hay tuner		4	1
		5-6 of 1 ³ / ₄ x 1 ³ / ₄ ash	1 ¹ / ₂		8
	27	sharp X cut		1	0
		sharp hand saw			6
Aug	1	6 hrs. fence out-rick		3	6
		3 ¹ / ₂ lbs. put. nails			12
	3	sharpen digger			3
	7	laying mattock		2	0
	8	2 hrs. box car wheel			12
		new stock bond on wheel 3 lbs. of 2 hrs. of 6		2	3
		repairing draft ironwork 6 hrs. 6 ¹ / ₂ 4 lbs. new iron 1 ¹ / ₂		7	0
	15	4 hrs. repair studs boarding in out house		2	4
		7-0 of 2 x 4 deal	4	2	4
		4 ¹ / ₂ lbs. nails			2
Sep.	17	1 hr. take up spindle sucker of pump			7
	19	new end to pump handle, new large bolt			
		new pin key. put new end on sucker		4	10
	22	fix handle & spindle			7
		new spindle leather		4	0
	20	2 hrs. prepare fellos		1	2
	21	7 ¹ / ₂ hrs. put 3 fellos in wheel		4	4 ¹ / ₂
	22	1 hr. paint wheel			7
		3 fellos in 5 ¹ / ₆ pairs 1 ¹ / ₂	7/9		17 ¹ / ₂
		type 1 wheel		3	0
	25	2 hrs. put in pane of glass		1	2
		2 panes of glass 2 oz. glass		6	6
		putty threads			4
July	27	3 seams of wood		4	6
	10	alter wagon brake put on plates 2 bolts	2 hrs 1 ¹ / ₂		20

Paid Nov. 5. 1917

338

Col. Masefield, Springhayes, Woodbury

1917

Aug 20	45-0 of 7x1 floor	3/4	12 3
Sep 20	To re-rubbering one pair of brougham wheels with #clincher tyres e.p. 2-15-6 carriage 2-0		3 7 6
	To taking off + putting on wheels on carriage		2 6
20	82-0 of 7x1 floor	3/4	1 2 3
		<u>1</u>	<u>5 4 6</u>
	Paid. Oct. 10. 1917		

Mr. Talbot, Stallecombe House

1917

July 20	22 1/2 hrs. make reverse 4-9-6 oak gate		13 0
	4 sets of oak for 9-6 gates 2-8-0		2 8 0
	bolts 4/- screws 4/-		5 0
			<u>3 6 0</u>
	To 4-9-6 oak at 17/-		3 8 0

Paid. Oct. 19. 1917

Mr. Fred Stamp, Woodbury

1917

£ . d

July	4	Man 6 hrs. put new points & to shaft		3	9 1/2	
	5	do. 6 hrs. do		3	6	
	7	do. 2 hrs. do		1	2	
d)		3 doz clark 4 x 3 x 3/8 bolts 6"			9	
		2-6 of 6 x 3 ash	9		1 10 1/2	
		6-6 of hoop iron	0		6 1/2	
	12	19 hrs. paint cart leaf			12 8	
		6 lbs. paint	7 1-9-3 1/2	10	5 0	
	20	3 hrs. ringing cart wheels			18 1	
lv	28	12-3-10 x 3' ash felloes	}	1/2	12 0	
		1 lb paint			7 1-10-9	8
		2 new 2 1/4 x 5/8 tyre 112 lbs at 5¢		2	6 8	
	27	3 1/2 hrs. straightening axle			2 0	
Aug	21	30 1/2 hrs. put in new pair shafts & some piece			17 9 1/2	
lv	25	10-6 of 12 x 3 1/2 ash	}	1/4	18 4 1/2	
		1 home made nail			2 lbs paint	1 5
		2 long staples, 2 crooks, 2 staples				" "
		2 screwing bolts			2-1-1	3 6
		part new tail eye & pin				1 0
					7-10-9	7

Mr W. Summerfield

1917

£ s d

July	18	2 hrs. re-leather sucker	1-2	}			
		new leather clouts	9			2	0
		new pin rkey					9
Aug	23	To 2 windows frames as contract			2	12 0	
		6 hrs. put on counterails	3/6	}			
		7-0 of 7x3 deal	9		5/3		
		5 lb. nails			3		9 0
	31	11-0 of 2x3 paper		3		2 9	
Sep	14	6 hrs. make 2 doors	3-6	}	1	0 3	
		timber for one door 1" thick	16-9				16 5
		4 hrs. make small door	2-4				
		timber for 3/4 door	7-5				9 9
	24	Horse man 1 day carting gravel				10 0	
June	11	1 1/2 hrs. re-leather sucker		}			
		leather clouts					2 0
					£	5 8 6	
Nov.	24	2 hrs. fit up pump sucker	1/3			1 3	
		1- 3/4 sucker, 1/4 leather clouts	1/4			2 9	
		new end to sucker iron	1/4			1 0	
	26	man 2 hrs. repair pump & leather spindle				1 3	
	27	man 9 hrs. rehang door of shed				5 7 1/2	
		4. 1" screws. 6 washers				3	
		1 hook				1 0	
		2. 3 1/2 + 1/2" bolts				4	
	28	making a new large pump. bolts. 1 pin rkey. new end to sucker iron. + fit same to pump	6/4			6 0	
		3 hrs. leather sucker rfit it				1 10 1/2	
		1. 3" sucker				1 9	
		new leather clouts				1 0	
					£	6 12 7	

Mr. T. Gilman. The Brewery.

1917

£ s d

Aug 2	2 hrs. take off pit catch spring			1	2
	new top cap to spring piping			7	10
11	6 hrs. box wheel of trap			3	6
13	8 hrs. repair + screw up trap			4	8
	1. 1", 2. 2 1/4" + 1. 3" x 1/4 bolts. 1-2 x 5/16 bolts				9
	4. 1" screws				1
	type 1 wheel				3
	5 1/2 hrs. clean paint trap + varnish	} £ 2-12-6		1	11
	paint 6/8 varnish 4/6				10
	stripping				7

£ 3 14 0

Paid. Oct-18-1917

Messrs. Alb. Squires Ltd. South Street. Exeter

1917

£ p d

Oct.	12	To 8 boards 10-6 long $1\frac{3}{4} \times \frac{1}{2}$ ea.	96p.		
		To 12 boards 12-6 long $1\frac{3}{4} \times \frac{1}{2}$ ea.	171p.		
		To 1 board 12-0 long $1\frac{3}{4} \times \frac{1}{2}$ ea.	12p. 9.		
			279-9		2 6 6

Paid Jan. 19. 1918

Mrs. Lucy Martin. Sydney Cottage

July	9	To new ^{sucker} leather & slack to pump			4 6
	4	new end to pump sucker iron			1 6
					<hr/> 6 0
Dec.	24	Horse start 1 day carting gravel & earth			11 0
1918	Mar	26 To unloading truck of coal			2 0 0
	+ 27				2 2 $\frac{1}{2}$
1917	Dec.	17 man 3 $\frac{1}{2}$ hrs. put in glass & repair lock			1 7 $\frac{1}{2}$
		1 pane of glass & putty			1 2 $\frac{1}{2}$
1918	Feb.	2 man 3 hrs. put in glass & door knob			1 10 $\frac{1}{2}$
		1 pane glass $17\frac{1}{2} \times 12\frac{1}{2}$			1 0 $\frac{1}{2}$
		$\frac{1}{2}$ lb. putty			1 $\frac{1}{2}$
		1 door knob.			1 0 $\frac{1}{2}$
Apr.	9	1 flashlight cord & piping			1 6

Paid April 19. 1918

£ 3 6 0

Mr. W. H. Stamp, Higher Vermont

1917

£ 2 d

July 5	man 9 1/2 hrs. fix up stile	5 6 1/2
	3 lbs. nails, 1 1/2 2 spikes 6"	1 7 1/2
18	9 1/2 hrs. screw up clips of trap & put 2 felloes & 2 spokes in wheel	5 6 1/2
19	6 hrs. do.	3 6
20	5 hrs. do.	2 11 1/2
23	3 1/2 hrs. do.	1 11 1/2
	cut short 2 types	7 0
	2 2" felloes, 1 2 spokes 8"	1 8
Sept. 24	3 hrs. take off fix spring	1 9
	repair top lap of spring	3 6
	1 small leather collar	6
	forward to 255	£ 1 15 6 1/2

Mr. B. Stamp, Woodbury

Aug. 23	new plate of iron fix to reaper	4 6
	1 crook for rake	6
Oct. 4	repair chair	1 0
	new flat iron	2 6
11	sharp saw	9
Dec. 22	making draps	1 4
	1 clip for draps	1 5
	Paid Jan 4, 1918	12 0
Dec. 19	1 1/2 hrs put in twobill stem	1 0

Rev. J. B. Housman. Farringdon Rectory

1917

		To a/c. rendered		18
July	26	2 hrs. make barge scapping		12
		10-9 of 2x ³ / ₄ floor	3	27 ¹ / ₂
		10-9 of 2x ³ / ₄ "	3 ¹ / ₂	32 ¹ / ₂
		nails 2 ^o . paint 6 ^o		8
	31	2 ¹ / ₂ hrs. taking out sash		16 ¹ / ₂
		Pony & trap fetching do.		26
	"	4 hrs. make sash		24
Aug.	1	9 ¹ / ₂ hrs. do.		56 ¹ / ₂
	2	9 hrs. do.		53
	3	Horse Waggons deliver window barge cap		40
	"	9 ¹ / ₂ hrs. fit window		56 ¹ / ₂
	4	6 hrs. do. barge scapping		36
	7	9 ¹ / ₂ hrs. repair floor		56 ¹ / ₂
		9-0 of 2 ¹ / ₄ x 1 ¹ / ₂ deal sash		16
		2-9 of 2 x 1 ¹ / ₄ "		3
		8-0 of sash bar		6
		1 fastener screws		10
		3 panes of glass 9 ¹ / ₄ x 12 ¹ / ₄ "		16
		2 lbs. putty ⁵ / _o clots, 1 2 lbs. paint 1/8		22
		33-0 of 7 x 1 floor		97 ¹ / ₂
		3 lbs. nails		10
		examining window 2/6		26
		pony trap fetch; paint jobs & tools		26
Sep.	17	repairing music rack		26

 3 10 1.

Paid, Dec. 21 1917

Mr. J. Pyne. Poellake

1917

July 30	12 lbs. ring waggon wheel put on	11/6	7 0
	6. 2' elm fellows small		1 6
	1 spoke 3 ^d . paint 3 ^d		6
	put on tyre		2 6
Aug 16	4 lbs. repair chum cover	}	2 4
	2 screws. 1 piece of beech		2
	1 new bolt put to chum screw, 2 rivets 4-		1 6
Sep 16	9 lbs. make swath board	8/10	5 3
	3-6 of 10 ² x 1 elm		10 2
	6. 1 ¹ / ₄ screws 1 ¹ / ₂ , paint 3 ^d .		4 2
	7 rivets		6
	2 plates of iron filling		1 4
19	collaring, rolling trap wheels		1 9
3	2 lbs. tin wheels		1 0
4	2 1/2 lbs. do		1 3
17	man haymaking		3 0
Oct. 20	To 8 bushels of barley at 62/9		3 2 9

 7 4 14 1

Paid. Oct. 29. 1917

Mr. J. Pyne, Postlake Farm, Woodbury

1917

Aug.	29	To easing doors, repairing locks, put hinges				
10		moulding on chest, new locks on doors, &				
Sep	13	whitening, coloring, painting varnishing				
		staircase passage				
	29	9 1/2 hrs.	Sep. 1	6 hrs	6 1/2 hrs	10 1/2 hrs
		8 1/2 hrs.	2	9 1/2 hrs	7 1/2 hrs	11 1/2 hrs
	30	9 1/2 hrs.	-	7 1/2 hrs	" 8 hrs	7 1/2 hrs
		8 1/2 hrs.	4	9 1/2 hrs	8 1/2 hrs	13 1/2 hrs
	31	9 1/2 hrs.	5	9 1/2 hrs	" 4 hrs	
		8 1/2 hrs.	6	9 1/2 hrs	10 1/2 hrs	
		<u>54</u>		<u>51 1/2</u>	<u>45</u>	<u>30</u>
		180 1/2 hrs. at 7°				5 5 3/2
		30 lbs. green distemper				6 15 0
		10 lbs. white do.				6 1/2 5 5
		4 lbs. white paint				10 3 4
		2 lbs. brown paint				" "
		5 1/2 pints Oil & Turp. } 26 1/2 lbs. at 7°				1 1 0
		1 gal. Varnish				12 6
		1 pair chest hinges screws				1 2
		1 pane of glass putty				1 0
		2 locks staples screws				5 6
		1 box staple				1 1
Oct.	17	put lock on trap house door, 1 plate 5 screws				1 3
						<u>8 12 4 1/2</u>

Paid. Oct. 29. 1917

Mr. G. Pyne. Rosedale. Olyst & Mary

1917

July 12	2 straps for trap shaps.	20
Aug 14	6 hrs. repair shaps of trap	36
	repair wing boards, & leather on shaps	26
	re-rubbering 1. 4' 5" trap wheel with	" " "
	1 1/2" wired on rubber tyre	376
Oct. 3	lacing windows, clean out copper	30
4	4 hrs make 3 sheep brackets.	28
	32-0g 2x1 battens	24
	1/2 lb nails	3
24	1 rear lamp 5/3 r bracket, 2-1x1/4 bolts 1/3	66

 1 4 10 3

Paid
1917

Miss Hooper. Woodbury

July 31	2 hrs. put new sucker & leather to pump	12
	1 sucker, 1/2, 1 leather, 1/2 cloth 2'	24

 1 36

Paid. Nov. 1. 1917

Mr. Edgar Ware.

1917

		To acc. rendered	2	50
July	3	To making breechin crooks springs, 4 links r fitting on chains 8/-	"	"
				80
	31	9 hrs. make machine draft put in hooks in gates + repair corn hutch		5 6 1/2
		3-9 of 4 x 1 1/2 ash 2 3/4	} 1/8	10 3/4
		3-3 of 2 1/2 x 1 1/2 ash 2 1/2		4 1/2
		1 gate hook + eye		16
		4-4 of 7 x 1 floor for hutch		15
		2 doz. 2 1/2" nails patls.		2
				3 3 3 1/2
Ware, Sons. millers				
Aug.	2	3 hrs. repair hangings of cart		20 1/2
		1-3 1/2 + 3/8 bolts 2" 3-5 x 1/2 bolts 9"		11
		1-0 of 3 x 1 elm. 1 doz. nails 2 1/2		3 1/2
		8 hrs. make new cart hanging 5/4 lbs. iron 1/3		67
		new tail chain ring 6". 12 smiths nail 6"		10
	3	8 1/2 hrs. collar waggon wheels, alter brakes r make brake blocks		4 1/2
		smith 2 hrs. alter brakes		18
		2 leather collars 2/- 1 brake block		24
	15	4 hrs. repair r rehang field gate		24
		1 eye with wings, r plate r 4 nails		20
		1-2 1/2. 1. 3" 1/4 2-4 x 3/8 bolts		7
		12-2 1/2" pat. nails. 1 trap of wood		4
Sep.	18	35 pieces of positives at 4"		118
				1 16 8

Paid. Oct. 30 1917

Mr. T. Jenning, Woodbury Salterton

£ s d

1917

Aug. 14	6 ¹ / ₂ film repair trap			3	9	1/2
	4- 3 ¹ / ₂ + 1, 2 ¹ / ₂ x 3/8 bolts					8 1/2
	8 lls. of iron for plates			2	0	

Paid Nov. 6. 1917

£

6 6

Mrs. Marshall Oakhayes

Sep. 17	Topmy trap 1+	17ulwell Station			2	6
19	do.	Station			1	9
22	do.	Exmouth			4	6
26	do.	B. Salterton			5	0
27	do.	Exmouth			4	6
28	do.	Exeter			5	6
Oct. 1	do.	Exmouth			4	6
4	do.	Exeter			5	6
9	do.	Exmouth			4	6
10	do.	Station (2)			3	6
15	do.	Grandale			2	6
16	do.	Exeter			5	6
19	do.	Exmouth			4	6
27	do.	Exeter			5	6

2 19 9

Credit for shoe

10

Paid Oct 30. 1917

£

2 18 9

Mrs. Marshall. "Oakhayes" Woodbury

1917

£ . d

June	19	To repairing waterbarrow			40
Aug	23	man 3 hrs. make bands for trees		↑	20
	24	smith 6 hrs. do			36
		man 4 hrs. do.			24
	27	smith 9 hrs. making piping bands			53
		man 7 1/2 hrs. do.			41
	28	smith 7 hrs. do			41
		man, 4 hrs. do.			24
		68 lbs. of old type		2	184
		4 lbs. new iron			14
		bolts 8 lbs.	2-0-3	↓	40
	27	sharp. & cut saw			10
Sep.	21	3 1/2 hrs. make porch bottom			24
		42-0 of 7 x 3/4	3 ²	} 17-6	106
		15-0 of 2 x 3	3 ²		39
		nails & creosote	10 ²		16
	26	2 men 7 1/2 hrs. ea. re-piping wire fence			89
	27	2 men 9 1/2 hrs. ea. "			111
	28	2 men 9 1/2 hrs. ea. "			111
	29	2 men 6 hrs. ea.			70
Oct.	1	2 men 9 1/2 hrs. ea.			111
	2	2 men 9 1/2 hrs. ea.			111
		140 of 9 1/2 x 4 oak blocks	1/4		188
		new piece of strand wire			86
		7 lbs new iron for ^{new} stands			24
		20 lbs. of types for bottom of stands		2 ⁰	34
		1 lb. nails			5
		6 bricks			6
	4	soldering 2 stew pans			10
Paid Oct. 30. 1917					£ 7 17 7

Mr T. Wood. Bridgeport Farm. Woodbury

1917

Aug	27	9 $\frac{1}{2}$ hrs. make wheels			
	28	8 $\frac{1}{2}$			
	29	9 $\frac{1}{2}$			
	30	9			
	31	8 $\frac{1}{2}$			
Sep	1	2			
	10	3 $\frac{1}{2}$ 50 $\frac{1}{2}$ hrs. at 7 ⁰		1	9 5 $\frac{1}{2}$
		28 oak spokes		1	4 0
		1 pair Rock Elm stocks		10	0
		2 pairs of stock rings		6	0
		14 dowels			10 $\frac{1}{2}$
		1 pair of new tyres 8 blls at 5 ⁰		1	15 10
		felloes 14. 2 $\frac{1}{2}$ ash			7 0
	12	7 hrs. box wheels	5-17-3		4 1
	13	9 $\frac{1}{2}$ hrs. alter steps & repair dash board		+	5 6 $\frac{1}{2}$
	14	8 hrs. clean paint trap			4 8
	15	6 hrs. do.			3 6
		3-6 of 9x1 elm tread		+	7 $\frac{1}{2}$
		1-6 $\frac{1}{2}$ x $\frac{1}{2}$, 1-2x $\frac{1}{16}$, 2. 1x $\frac{1}{4}$ bolts		+	6 $\frac{1}{2}$
		6-1 $\frac{1}{2}$ screws		+	2
		2 lbs. paint			1 10 $\frac{1}{2}$
	18	7 hrs. paint trap			4 1
	19	6 hrs. "			3 6
	22	4 hrs. "			2 4
	24	6 $\frac{1}{2}$ hrs. "			3 9 $\frac{1}{2}$
	25	5 hrs. varnish trap	3-0-2 6-10 2-13-4		2 11
Oct.	1	6 hrs. do.			3 6
	3	2 hrs. do.			1 2
	4	5 $\frac{1}{2}$ hrs. put together stripping trap			3 2 $\frac{1}{2}$
		2 lbs. paint blue pink varnish			12 0 3 9 3 0

Paid. Jan 24. 1918

$\frac{1}{2}$ 8 17 5

1917

Mr. W. Down. Higher Fenmoor

£ s d

\$ep.	7	7 1/2 hrs. put 2 fellows in cart wheel	4	4 1/2
	8	2 hrs. do	1	2
		2. 3' elm fellows 1/-	1	0
		2 dowels 2 ^d		2
	11	9 1/2 hrs. repair body of cart put on plate of iron on cart	"	"
		1- 2" ^{1 1/2} 3. 4 1/2 x 5/16 bolts 6 ^d	"	5 6 1/2
		1- 2 1/2" ^{1 1/2} 1- 5 x 3/8 ^{2 1/2}	"	7
		6- 1 1/4" screws	"	4
		1 new tyre 78 lbs. at 5 ^d	1	10 5
		cut ratchet 1 tyre		3 6
		1 stock hasp & 2 staples, 2 plates of iron	"	"
		1 long staple ratchet, 1 link, 1 plate for top rail & 1 plate for tip stock	"	"
				8 0
	18	repair tip eye of cart & nails in tail iron	"	"
				2 6

£ 2 17 9

Paid Nov. 21. /17

Mr. John Cornick, Woodbury

£ p d

1917

June 2 To repairing barrow, putting in
new side, 1 plate of iron, 2 wheel axes
both screws

6 10

Paid.

Mr. Hubert Laphorn, Holbeton

July 21 To six muffles for bell at 4/9

1 8 6

Paid

Mr. Frank Sellick

April Ploughing ^{2/6}, working dam ^{1/-}, planting ^{3/-}
H June three hve ^{1/6}, round hve ^{1/-}.

9 0

Paid, Jan. 1918

Mr. Rowe, Bungahwa

May 5 1 load of manure carting

6 0

Paid, Jan 21. 1918

Mr. A. Hault Mallards

1917

Oct. 1-189

3 1/2 hrs. repair trap. put in new side rail
 new turned pegs, new collars to wheels
 repair front board bottom & put on new steps
 2 large & 2 small leather collars
 2 doz. C-S. nails 1/2" 2 doz. 1 1/2" wire nails 2"
 1-9 of 3 1/2" x 3/4" deal floor
 3-3 of 9 1/2" x 3/4" "
 1. 2 1/2" x 5/16" + 2. 3 1/2" x 1/2" bolts 4"
 2. 1 1/2" screws 1 plate of iron 1/2 lb. 3
 2-0 of 2 x 1 elm
 1 new double step
 7 turned pegs
 1 ash rail

18 45
 4 0
 8
 4
 10
 7
 4
 2
 11 6
 1 6
 1 6

with 2 1/2 hrs. fitting of the running tyres
 tyreing 2 wheels

1 10 1/2
 7 0

56 hrs. clean, paint & varnish trap
 3 lbs. lead color
 quaker green
 varnish

1 12 8
 2 4
 6 0
 3 0

striping

1/2 2-16-0

12 0

1/2 5 5 0

244 Paid

Mr. W. Page - Vermont

1917

7 2 2

Oct. 2	9 $\frac{1}{2}$ hrs.	repair at Vermont		5 6 $\frac{1}{2}$
3	9 $\frac{1}{2}$ hrs.	do.		5 6 $\frac{1}{2}$
4	9 $\frac{1}{2}$ hrs.	Bassets		5 6 $\frac{1}{2}$
5	9 $\frac{1}{2}$ hrs.	do.		5 6 $\frac{1}{2}$
6	6 hrs.	do.		3 6
		2 gate hooks.		1 4
		2 staple		3
		3 - 4 $\frac{1}{2}$ x $\frac{1}{2}$, 3 - 3 $\frac{1}{2}$ x $\frac{3}{8}$ bolts ^{5$\frac{1}{2}$}		1 2 $\frac{1}{2}$
		13 $\frac{1}{2}$ lbs. cut nails	4 $\frac{1}{2}$	"
		2 lbs. put "	4 $\frac{1}{2}$	5 10
		6 - 2" screws		3
8	9 $\frac{1}{2}$ hrs.	Bassets		5 6 $\frac{1}{2}$
9	9 $\frac{1}{2}$ hrs.	"		5 6 $\frac{1}{2}$
10	9 $\frac{1}{2}$ hrs.	"		5 6 $\frac{1}{2}$
11	9 $\frac{1}{2}$ hrs.	"		5 6 $\frac{1}{2}$
12	9 $\frac{1}{2}$ hrs.	"		5 6 $\frac{1}{2}$
13	6 hrs.	Vermont		3 6
		1 catch		3
		4 lbs. cut nails	4 $\frac{1}{2}$	1 6
15	9 $\frac{1}{2}$ hrs.	Bassets		5 6 $\frac{1}{2}$
16	9 $\frac{1}{2}$ hrs.	"		5 6 $\frac{1}{2}$
17	9 $\frac{1}{2}$ hrs.	"		5 6 $\frac{1}{2}$
18	9 $\frac{1}{2}$ hrs.	"		5 6 $\frac{1}{2}$
19	9 $\frac{1}{2}$ hrs.	"		5 6 $\frac{1}{2}$
20	6 hrs.	Hatches		3 6
		6 - 2 $\frac{1}{2}$ x 5/16 bolts		7 $\frac{1}{2}$
		6 $\frac{1}{2}$ lbs cut nails	4 $\frac{1}{2}$	2 5 $\frac{1}{2}$
		23-0 of 2x1 battens		1 8 $\frac{1}{2}$
22	9 $\frac{1}{2}$ hrs.	Hatches		5 6 $\frac{1}{2}$
23	9 $\frac{1}{2}$ hrs.	"		5 6 $\frac{1}{2}$
24	9 $\frac{1}{2}$ hrs.	Roosthouse		5 6 $\frac{1}{2}$
26	9 $\frac{1}{2}$ hrs.	"		5 6 $\frac{1}{2}$
		forward	7 $\frac{1}{2}$	6 5 8

		forward		6	5	8
Oct.	27	6 hrs. Rookhouse			3	6
		4. 8" spikes			1	0
		sharpen 4 spikes				4
		screwing 8 bolts			1	4
		2 staples				3
		2 lbs. nails				9
	29	9 1/2 hrs. Rookhouse			5	6 1/2
	30	9 1/2 hrs. "			5	6 1/2
	31	9 1/2 hrs. "			5	6 1/2
Nov.	1	9 1/2 hrs. "			5	6 1/2
	2	9 1/2 hrs. "			5	6 1/2
	3	6 hrs. "			3	6
		18 lbs. cut nails	4 1/2		6	9
		3. 4 1/2 x 3/8 bolts				7
		12. 1 1/4 screws				2
		1. 4" coach screws				3
		4 holdfasts for roof			5	3
	5	9 1/2 hrs. shed			5	6 1/2
	15	9 1/2 hrs. Bridge			5	6 1/2
	16	9 1/2 hrs. "			5	6 1/2
	17	6 hrs. "			3	6
		2 lbs. nails				9
		8. 1" & 2. 1 1/2" screws.				2 1/2
		1 square staple				B
	19	9 hrs. Venmore			5	7 1/2
	20	9 hrs. Bards			5	7 1/2
	21	9 hrs. "			5	7 1/2
	22	9 hrs. "			5	7 1/2
	23	9 hrs. Bridge			5	7 1/2
	24	20 5 1/2 hrs. "			3	6
		6 lbs. nails, 2/3				2
		1. 4 x 1/2 coach screws	3			6
		forward	7		11	12 6
						15 7

£ s d

		forward	11	12	6
Nov	26	q hrs. Bridge		5	7½
	27	q hrs. "		5	7½
	28	q hrs. "		5	7½
	29	q hrs. "		5	7½
	30	q hrs. "		5	7½
Dec.	1	5½ hrs. "		3	6
		13 panes of glass at 3 ^d		3	3
		4 do. at 3 ^d		1	0
		2-0 of 5x1½ deal			9
		1 large staple for yard door			4
		3 lbs. pulley			7½
		42. 1¼" screws			10½
		1. 3x¼ bolt, paint 4 ^d			5½
		1. 2" hinge & 4 screws			4

£ 13 11 9
1 16 0

Credit by loads manure

£ 11 15 9

Paid

Mr. & G. Miller

1917

Jan.	5	do		5 0
Jan.	9	Horse 1 day	plough	5 0
	12	do	"	5 0
	13	do	"	5 0
Feb.	27	do	1/2 day	2 6
Mar.	1	Horse to	Boystock	2 0
	2	do.	breeder	5 0
	23	do.	1 day plough	5 0
	24	do.	1 day "	5 0
July	24	Horse	cut grass	6 0
	28	man, Horse	haymaking	10 0
Sep.	5	Hawkins	threshing 3/4 Tark do 3/-	6 0
	18	man Horse	1 day work errish	10 0
	22	do.		10 0
	25	do.		10 0
	28	do.		10 0
Nov.	27	man Horse	plough to to 11 a.m. x	
	28	man Horse	do. 1 day	10 0
	29	do.	1 day	10 0
	30	do.	to 3 p.m. x	10 0

6 6 6

Jan. 23 Had your horse 1 day 5/-
 Mar. 2 do. cob 1 hour 1/-

6 0

£

6 0 6

Paid

Omitted Jan 5. horse 1 day 5/-

Mr. J. G. Miller

1917

o d

Oct.	5	1 shoe on cot			1 0 $\frac{1}{2}$
	7	1 lb. nails			3 $\frac{1}{2}$
Nov.	6	9 $\frac{1}{2}$ hrs. put door in dairy shelf			5 6 $\frac{1}{2}$
	7	9 $\frac{1}{2}$ hrs. do			5 6 $\frac{1}{2}$
	8	2 $\frac{1}{2}$ hrs. do			1 5 $\frac{1}{2}$
		2-0 of 10x1 elm brackets			5
		2-0 of 7x1 deal			7 $\frac{1}{2}$
		1 pair 2-bulb. 12. $\frac{3}{4}$ " percs			.. 6
		1 fastener			.. 6
		1 lb. nails, cloth, r paint			6
	16	sharpen saw			6
Dec.	20	put clock on pump			6

 17 6 $\frac{1}{2}$

Paid \$7-0-0 Feb. 9. 1918

 6 5 6

 7 3 0

Mr. Alfred Stamp.

1917

Oct.	4	alter staples of shafts			..	9
	5	repair furnace door 2 plates iron & 8 bolts			3	10
	10	repair fender			2	6
	11	sharp 2 saws			1	0
	16	altering lamp irons 1/2 2 bolts 2 1 lamp plate 2			1	4
	31	new handle to iron			1	6
Nov	7	8 1/2 hrs. ring 2 waggon wheels	✓		5	4
	8	9 1/2 hrs. do	✓		5	11 1/2
	9	7 1/2 hrs. do	✓		4	8 1/2
		5-0 x 1-6 x 2 1/2 ash felloes 11/10 1/2	✓		8	6 1/2
	12	2 new tyres 83 lbs.	5	1	14	7
	9	1 1/2 hrs. repair front carriage of waggon	✓			11
	10	6 hrs. do	✓		3	9
	12	2 hrs. clean off paint wheels	✓		1	3
	13	10 hrs. clean off repair waggon brakes & put on wheels	✓		6	3
		4. 5 1/2 x 3/8 bolt. 2 1/4	✓		1	10
		4. 6 1/2 x 3/8 bolt. & repair ironwork of waggon	✓		3	3
		1 new plate of iron for front carriage	1 ✓		1	3
		3-3 of 3 1/2 x 2 ash blocks 2 1/2	✓			8
	8	2 1/2 hrs. make of pit roller brackets		}		16
		4 brackets				4
		4. 2 1/2 & 4. 2 screws				2
Dec.	12	sharp saw			..	6
Nov.	12	man horse plough 1 day			10	0
	15	do. do.			10	0
	19	do. do.			10	0
					6	18 1/2

Credit by

Horse 2 days Oct 26 & 27

10 0

Paid Jan. 11 / 18

C. Dairy - Esq. Knoll Cottage

1917

£ r d

Oct.	22	1 load manure			6	0
		carting do.			2	3
Nov.	14	Horse Cart 1 day carting earth			11	0
	16	do. do.			11	0
	20	Horse Waggon to Exeter			11	0
	21	100 stakes & Carting			1	5 0
Dec.	10	5 loads manure			1	10 0
		carting do.			11	0
	13	1 load of firewood	5-17-3		10	0
Oct.	5	2 lb. buff paint			1	8
	15	2 men 1 1/2 hrs. ea. measure chimney			2	0
	23	2 men 9 hrs. ea. make & fix chimney top			12	0
		1 sheet galv. steel 9/7			11	6
		nails				6
		mortar, 2 bricks	£ 1.7.6		1	6
Nov.	21	grinding hatchet				6
	14	6. 11x22 slates			2	6
Oct.	22	6. 11x22 slates			2	6

7 11 11

Paid. Jan 4/18

St. Thomas Rural D. Council

1917

Oct. 22	5-0 of 4x4 oak	6 ⁹	2 6
24	6-0 of 9x3 "	10 ⁴	5 1 ¹ / ₂
	6-0 of 4 ¹ / ₂ x3 "	5 ⁴	2 7 ¹ / ₂
	6-6" nails		3
31	5-9 of 4x4 oak	6	" "
	6-0 of 4x4 " = 11-9		5 10 ¹ / ₂
	6-6 of 4x3 ¹ / ₂ "	5 ¹ / ₄	10 1
	6-3 of 4x3 ¹ / ₂ "		
	10-3 of 4x3 ¹ / ₂ " = 23-0		
	6-3 of 3x3 ¹ / ₂ " = 2 9-3	4	2 1
	10-9 of 17x3 ¹ / ₂ elm 2/9 wire	11 ¹ / ₂	12 1
	40 ¹ / ₂ sq. ft. of slabs 1 ¹ / ₂		5 1
	2 lbs. nails		7
Dec. 18	1 6p. straight edge		2 0

28 3¹/₂

Paid Jan 23 1918

Rev. Donald W. Jackson. Dowland Vicarage, Dolby

1917

£ . s . d

Dec. 18 To 1 bell rope 60 feet 1 0 0

Paid Jan. 2 - 1917

J. Ackland Esq. Cutten, Poltimore,

Nov 13 To 4 lbs. chime cord 120 feet 3/- 12 0
Postage 7

Paid Jan 11/18

12 7

Mr. R. Hulland, ~~Hulland~~ Kingsnypston

Dec. 28 5 lbs chime cord 150 ft for 3 ropes 3/- 15 0
Postage .. 8

Paid

15 8

Mr. & G. Sheppard, Churchwarden, Lympstone

Dec. 20 To repairing chiming cords & screwing
up bell fittings in Lympstone Church 9 0
3. 40 ft. bell ropes £1-2-6 ea 3 7 6
1 can of oil 6
8 1/2 lbs. of chime cord for 4 ropes 3/- 1 5 6

Paid Jan. 11/18

£ 5 2 6

Miss Wright, Exton

1917

Oct	5	To drawing 2 loads of furze	12 0
	6	do. 1 do	6 0
	8	do. 1 load of poles	6 0
	30	do. 1 load of poles	6 0
Nov	8	do. 2 loads of furze	12 0

Paid

 2 2 0

Mr. George Wilson, Woodbury, Salterton

Nov	6	To 2 new trap wheel tyres 40 lbs	1 0 0
		To rivetting tyres	2 0

Paid

 1 2 0

Mr. Edgar Ware

1917

£ s d

				£	s	d
			forward	3	3	3½
Oct.	18	repair lade			1	0
	24	man 9½ hrs. make 2 gates			5	6½
	27	1 lb. of 2½ pat. nails			..	5
	29	man 9½ hrs. fence in Broad Park			5	6½
	30	man 9½ hrs. do.			5	6½
Nov.	2	man 9½ hrs. repairs shed			5	6½
	3	man 6 hrs. do.			3	6
		8 lbs. nails Broad Park	2 4½		3	0
		3. 4½ + ½ coach screws				9
		3 lbs. nails for shed	2 4½		1	1½
		3 lbs. spikes do	6 ^o		1	6
	10	lettering 62 hlds at 1½ ^o			7	9
Dec	4	To soldering tinner spent & fixing it in tinner			..	18
	24	new bottom to cider bucket			3	6
	29	4 hrs. repair cider mill put up job			2	8
	30	man 2½ hrs. fix job hang door			4	8
		1 lb 23 pat. nails			..	7½
		6 spikes, 1/6 1 hook 1/6			2	6
				7	5	10 1½
					6	0 1½

Paid Jan 22. 1918

Mrs. Wills, Greyside, Woodbury

1917

£ s d

Aug. 8	To putting on new tyre & rivetting 20 lbs. at 6	10	0
+ 9	12 rivets	1	0
	11 1/2 hrs. put in new felloe & spoke in wheel.	6	8 1/2
	1 felloe & 12 spoke	18	6
Nov. 20	To putting castor on chair, 4 screws	"	9
Dec. 22	To putting 3 bolts in pump	1	0
27	1 shoe	"	9
	To new pair of springs, new pair of Warner wheels with 1 3/8 Clincher rubber tyres & new pair of shafts as quotation	11	0 0
	To cleaning, varnishing, & painting body of trap	"	"
		10	0
Oct. 15	To fetching trap from Venmore	2	6
		£	12 13 0

Paid Jan. 12. 1918

Mr. Newham. Coombe Park.

£ s d

1917

Oct. 10	9 1/2 hrs.	put ⁴ new fellows in wheel, new point	5	6	9
12	9 1/2 hrs.	plate of iron to shaft repair bottom and tailboard	5	6	7
		wood, 6 bolts, 12 screw, 4 fellows, plate of iron			
		tyring 1 wheel		4	6
				4	0

Paid Jan. 22. 1918

£ 19 7

Mr. Fred Stamp, Woodburn

To acc. rendered

7 10 9 1/2

Oct. 16	7 1/2 hrs.	put in new apple case	4	4	1/2
17	9 1/2 hrs.	do.	5	6	1/2
		3-3 of 7x5 elm case	8	3	1/4
		2-9 of 2x4 "	2		5 1/2
		1 doz. nails, 1 ^o 2 square washers, 2 ^o 1/2 lb. paint			8
		2 new apple bolts		2	6

16 - 1 1/2

8 6 9 1/2

Credit by Trap

1 0 0

Paid

£ 7 6 9

Rev. Dr Tulford

£ o d

1917

Nov.	9	cleaning W.C valve			10
	14	3 hrs. put in sash cord			10 $\frac{1}{2}$
		8-0 of sash cord	2/9		10 $\frac{1}{2}$
Paid Jan. 25. 1918					
					39

Mr. J Bamsey

Nov.	13	man 6 hrs. put new brake blocks and iron shang door			41
		1-3 of 4 $\frac{1}{2}$ x 2 $\frac{1}{2}$ ash			6
		4 screws & pins			3
		2 brake block iron ylls			36
Paid Jan. 25. 1918					
					84

Mr. Harold Ware

Nov.	16	2 hrs. 21 st 4 hrs. 26 th 3 hrs. 27 th 1 hr.			9 $\frac{1}{2}$
		29 th 1 $\frac{1}{2}$ hrs. Dec-3 rd 3 hrs. 14 $\frac{1}{2}$ hrs.			10 $\frac{1}{2}$
		3 lbs. putty			80
		glass			36
		4 lbs. paint			
Paid Jan. 18. 1918					
					116

Mr. Gordon Ware

1917

Nov	20	3 hrs. repair shaft of waggon, putting in new brake blocks, & altering brake iron	1	60c
	21	7 hrs. do	4	4 1/2
		4. 3/2 x 7/16 bolts		9
		3-0 of hoop iron ³ , 2 doz. clunk ² , 2 C.S. nails ^{1/2}		5 1/2
		1 wheel cap		10
		3-0 of 2 x 3 ash shaft ⁹ , 1-3 of 2 x 5 ash blocks		13 1/2
		1 new crook, 1 long staple, repair breechin crook, cut & shoot nose bands of wheels	"	"
				53
	29	repairing damper of stove & part new frame & chain		50
			<u>£</u>	<u>19 3 1/2</u>
Paid Feb. 2. 1918				100

Mr. W. Newton, Rushmoor

Dec.	7	2 1/2 hrs. widen shaft		17
		2 pieces of wood 3 ^d		3
		tyring wheel		39
		repair 4 bolts, 1 new tail pin, take off & put on wheel	"	"
				23
			<u>£</u>	<u>7 10</u>
Paid Jan. 21. 1918				

Mr. Robert Pile, Bagmore Farm

1917

Nov.	28	7 hrs. repair side of waggon & put new bottom, repair shafts & rs		
	29	3 hrs. do do		
Dec.	3	9 hrs. do do		
	4	4 1/2 hrs. do do		
	5	5 hrs. do do	28 1/2 hrs.	17 10
		2 plates of iron for shafts	10 lbs	26
		1 drag shoe crook , 2 - 2 x 3/8 bolts		25
		8 - 3 x 3 - 9 x 1' elm bottom	3 1/2 pr. or 3'	79
		1 1/2 lbs. nails		7 1/2
		8. 1 1/2 x 1/4 bolts.		8
		5. 4 x 3/8 bolts.		10
		2 plug hasps staple, 2 lynch pins,		
		2 plates of iron for rail board, 1 bolt, 3 keys		
		2 rivets, 1 plate crook for drag shoe		92
				<u>197</u>
Nov.	28	5 hrs. washing & clearing waggon		
	30	4 hrs. painting		
Dec.	1	4 hrs. "		
	3	4 hrs. "		
	4	4 hrs. "		
	5	2 hrs. "		
	6	4 1/2 hrs. "		
	7	3 hrs. "		
	11	6 hrs. "		
	14	4 hrs. "		
	15	3 1/2 hrs. "		
	17	2 hrs. "	4 hrs.	184
		20 lbs. paint	q ²	150
		3 lbs. putty	2-4-3	6

Mr. R. Pile, (continued)

Dec	5	9 hrs. make new front carriage				
	4	4½ hrs. do				
	6	9 hrs. do				
	7	9 hrs. do				
	8	5½ hrs. do				
	10	9 hrs. do				
	11	9 hrs. do				
	12	5½ hrs. do	60½		1	17 10
		13-6 of 3x4½ ash		6¼		7 0
		4-0 of 3x1 oak				4
		4-3 of 10½x3 elm		8		2 10
		4-0 of 5x5 "		6¼		2 1
		2-4" 4 2, 3½" x 3/8" & 1-8x½ bolt ⁶				1 1½
		4. C-S nails				1
		repair clips of front carriage & bolt				3 0
		repair bolt, 2 new nuts	2-15-3½			1 0
Dec.	12	3½ hrs. make lades				
	13	9 hrs. "				
	14	9 hrs. "				
	15	4½ hrs. "				
	17	5½ hrs. "				
	18	7½ hrs. "				
	19	3 hrs. "				
	22	4 hrs. "	46 hrs.		1	8 9
		3 roller eyes & spalls & 4 lade crooks 15 lbs at 7°				8 9
		8 nails for rollers, screwing bolts 3 nuts				1 7
		1 hook for lade pin				. 3
		13-6 of 2x11 ash				11 3
		½ lb. nails, 15, 3½ x 3/8 ^{2 1/2} , 4 4½ ⁹ , 4, 3, 5, 2½ ⁶		10		3 11
		2 rollers & turning	2-18-0			1 6

Mr. Robert Pile, Bagmoor

1917

£ s d

Nov.		To putting new bottom in waggon, putting 2 plates of iron on side of waggon, 2 plate of iron on shaft, 1 drag shoe crook.			
Dec.		2 Lynch pins, 2 plug hasps staples 3 split keys		1	19 7
		To making a new front carriage		2	15 3
		To making a new pair of lades		3	0 0
		To cleaning painting waggon		2	15 0
1918 Feb.	11	To making a new body of butt car all new ironwork, putting a new axle case, new cross bar, altering shaft put new point to shaft & altering axles painting wheels & shaft		10	0 0
March		To repairing lades & shovels, wire bond & cleaning painting waggon		3	10 0
Feb.	12	repairing butterworks			10 6
	14	put in beetle stem			- 9

24 11 1

1 oak	11-0	gir 14"	15-0		
1 do.	13-0	gir 13½"	16-0	31-0 at 1/9	2-14-3
1 elm	12-0	gir 14"	16-3		
1 "	14-0	gir 13½"	17-9		
1 "	11-0	gir 11"	9-0		
1 "	12-0	gir 14"	14-3	59-3 8"	2-0-0

paid

£ 19 16 10

Nov. G. Gress

1917

£ s d

Nov. 30	2 men 4 hrs. ea. put covering on traps	5 0
9	man & horse taking up potatoes	10 0

Feb. 8/1918

£

15 0

J. B. Ashford, Esq., 1 Victoria Terrace, Essex

Dec. 3	2 men 9 hrs. ea. put in posts & hang gate in Thom meadow	11 3
4	man 6 hrs. putting up rails	3 9
	Horse cart take down gate rails & posts	2 0
	1. $\frac{3}{4} \times \frac{3}{8}$ " 2. $4\frac{1}{2} \times \frac{3}{8}$ bolts	9
	3 lbs. nails post.	1 3
	7-6 of 8 x 8 oak post $\frac{1}{4}$ c	13 5
	1 chisp & 2 staples	4
	6 Smiths nails	6

Paid June 1918

£

1 13 3

Mr. W. C. Abbott

1917

£ p d

Dec.	4	3½ hrs. repair trap wheel, alter lamp iron r pit spring r repair tailboard			2 2½
	5	8 hrs. do. 1 spoke 4. 1½", 2. 1¼", 3. ¾" screws 1 plate of iron new scroll iron repair me put on tyre alter lamp iron			5 0 0 6 0 4 3 ½ 3 6 1 0 4 0 2 0
Dec.	18	4½ hrs. make manger			2 10
		2-q of 13x1 elm	9 ⁰	}	
		2-q of 11x1½ "	9		
		2-q of 15½x1½ "	10½		
		2-3 q of 12x1½ "	9½		
		1 lb. nails			3 2 6

18/10

£ 1 5 4

Paid. Jan 29 1918

Mrs Dagworthy, Woodbury & Alton \pounds . . .

Dec-13	$\frac{1}{2}$ hr. measure window			6
19	6 hrs. make s'p' mullion to window			3 9
	4-0 of 2x4 deal			1 0
	nails & paint	5/6		3
20	8 hrs. repair lades			5 0
21	5 hrs. put tail in waggon			3 1 $\frac{1}{2}$
25	5 $\frac{1}{2}$ hrs. do.			3 5 $\frac{1}{2}$
24	9 hrs. do.			5 7 $\frac{1}{2}$
27	3 $\frac{1}{2}$ hrs. do.	19/5		2 2 $\frac{1}{2}$
	10-6 of 2x1 fir lades		3 ^o	2 7 $\frac{1}{2}$
	3-9 of 9x $\frac{1}{2}$ elm "			7 $\frac{1}{2}$
	$\frac{1}{2}$ lb. nails			2 $\frac{1}{2}$
	5-0 of 3x 3 $\frac{1}{4}$ elm tailpiece		2/4	11
	6. 3 $\frac{1}{2}$, 10 $\frac{1}{2}$ 3. 2 $\frac{1}{2}$ x 3/8 bolts			1 2 $\frac{1}{2}$
	paint			6
	hook, rivet, alter ratchet catch for lades			" 10
	repair ironwork of waggon sides, 1 bolt			" "
	1 new tailboard eye, + 4 strap plates			4 9
	1 ring, 2-6 of chain, 1 staple r			" "
	repair bolts 3 new nuts 2 hrs.			2 6
			\pounds	1 19 1 ^o

Paid

Mr William H Stamp

1917

£ o d

		forward from 238		1	15	63	
Oct.	15	1 1/2 hrs. take off spring	}				
	22	1 1/2 hrs. put on spring					1
		repairing spring				3	
	31	7 1/2 hrs. make new tailboard for pig cart	}			4	
Nov.	1	9 1/2 hrs. do					5
		7-0 of 2x6 ash			5 1/2		3
		3-3 of 15x3/4 elm					1
		7. 2 1/2 x 1/4 bolts					10
		4 lb. nails & paint	16 to			1	
	5	1 new tyre 45 lb. 5 1/2				0	
		cut & shoot 1 tyre				3	
		4 hrs. take off collar wheel				2	
		2 large. 2 small collars	in			4	
	19	7 1/2 hrs. put on new spring				4	
	20	6 hrs. do. wheel				3	
		new spring clip 1/2. 2 spike plate 1/2				2	
		4 1/2 hrs. drilling springs 3/4				3	
		new pair 3-0. 4 lap ellipse springs				16	
Dec.	28	8 1/2 hrs. put up fence posts				5	
	29	2 1/2 hrs. do				1	
		1 1/2 lb. nails				7	
						3	
Mar.	18	3 men 9 1/2 hrs. ea. put up fence				17	
	19	3 men 3 1/2 hrs. ea. "				6	
	20	3 men 9 1/2 hrs. ea. "				17	
		4 lbs. nails				1	
		2 lbs. wire staples				1	
		11 rails				2	
		1. 4 1/2 x 3/8 bolts				3	
Apr.	11	2 men 6 hrs. ea.				7	
		2 lbs. staples				1	
						8	
						0	
						0	

Paul

Mrs Marshall, Batehays

1917

£ s d

Mar 26	repairing long shears	2	0
Oct. 30	Pony & Trap to Esmenth	4	6
	Pony & Trap to Station	2	0
Nov. 21	new screw to mower	1	0
"	Pony cutting grass	1	0
	Toler	4	6
carried to page 263		15	0

Mr Frank Selluk, Woodbury, Salterton

Mar 26	8 hrs. making stone hammers	6	0
	<u>Paid</u>		

Mr. Frank Brockington

Mar 31	repairing guard of saw	4	0
"	1 pint castor oil	1	0
Nov. 8	repairing draw chain	3	4
	<u>Paid. Feb. 3. 1918</u>	8	4

1917 Mr. R. B. Parsford, Builder, Remouth

Sept	26	To six burrow wheels as per contract	at 12/6	3	15	0
		To extra for 2" rims tyres instead of 1 1/2"	at 1/6		9	0
			£	4	4	0
		Paid Jan. 11. 1918				

Rev. D. W. Jackson, Dowland Vicarage Dolton

Jan	14	To 1 bell rope 60 feet long: 1-11-12-14		1	0	0
		Postage				8
		Postage on Dec. 18. 1917				8
			£	1	1	4

Rev. J. O. Openshaw, Kentishum Rectory,

Jan	14	To 2 bell ropes ea 60 ft. long		2	0	0
		Postage				10
			£	2	0	10
		Paid. Apr. 19. 1918				

Messrs. Alb. Squires Ltd. South Street Exeter
£ 0 0

1917

Jan. 24 To 774-6 super of 1/2" elm board at 2 1/2 8 1 5

Paid

Mr. F. Elliott, Pearson Farm Beaford

1918

Jan. 31 To 3 bellropes each 60 feet long
Carrriage 3 0 0
1 10

Feb. 11. 1918

Nett.

£

3 1 10

July 21. Rev. J. Mercer Cox. The Vicarage, Plympton St. Mary
To examining & reporting on the
condition of Plympton St. Mary Church
Bells

Rail Fares

1 11 6

14 0

Paid

£

2 5 6

Mr. R. T. S. Greenbade, East Rowley, Romanelough

Feb. 15 To fit bellropes ea. 50 ft. long

6 0 0

Paid, Feb. 15. 1918

Paid 15/2/18

Mrs H Stokes Senr.

1917

£ s d

Jan.	15	repair coalscuttle	2	0
Feb.	2	2 seams wood	7	0
Aug.	15	solder kettle pan		9
Sep.	21	solder can		4
Oct.	16	2 score of apples	3	0
Mar.	22	rest for grate.	1	9
May	16	4 1/2 hrs. fix curtain pole	2	7 1/2
Apr.	11	5.0 of 2 1/2 buttons		4
		4 hrs. repair parlour	2	4
		3.0 of 4 1/2 deal		3
		18.1 screws		3

1 0 7 1/2

Mrs Stokes Senr. Wilder Stokes & Smethes

Jan	24	3 hrs put fire bricks to stove Cole	1	9
		3 fire bricks		6
		1 bucket mortar		4
		1 fire lump		13
June 16 Apr.	22	rest for grate new lock ^{2 1/4} fix ^{1 1/2 hrs} at R Smethes	3	8
Sep.	13	9 1/2 hrs whitewash room at Cole	5	6 1/2
		lime 1/-		10

14 0

Trustees (late H. Stokes)

1917

£ s d

Jan	8	repair lock at Mrs Sykes			1	0
	24	3 1/2 hrs. repair grate do			2	0 1/2
		3 pie bricks				9
		1 bucket mortar				4
		1. 9" square				3
Mar.	1	put new end to pump handle do.			4	10
	6	put new sucker leather to pump do.			4	6
May	16	4 hrs. color kitchen + smears			2	4
Apr.	16	7 lbs. green distemper	6		3	6
		3 1/2 lbs. white	6 1/2		1	9
	1	plaster				3
June	6	about cistern			1	6
Aug.	9	4 hrs. make pit W. E. n. s. r James			2	4
		3-9 of 1 1/2 x 1 elm			1	5
		3-0 of 2 x 2				4 1/2
		6. 2 screws				2
	10	6 hrs. clear shuting Globe Hill			3	6
	28	6 hrs. repair roof at Leach's James			3	6
		2 Roman tiles				8
		4 slate nails				1 1/2
Sept.	17	3 hrs 1/4 new leather 3 1/2 edack for pump Globe Hill			5	3
	18	8 hrs. repair casement Clarence			4	8
	19	3 hrs. do.			1	9
		1-8 of 7 x 1 1/2 deal			1	0
		1 pane glass putty				1 1/2
	25	7 1/2 hrs. case up pump			4	4 1/2
		16-0 of 7 x 1 match	4 1/2		5	8
		3-0 of 3 x 2				9
		1-0 of 1 1/2 x 1				6
		6. 2 screws				2
		paint 1/2 lb.				5
Nov.	9	3 hrs. do.				1 9

forward

£ 3 2 7

£ o d

		forward		3	2	7
Oct. 26	4½ hrs.	put in gate post	Hawkins		2	10
27	2½ hrs.	do.			1	7
	5-0	of 4x4 oak		0/4	2	10
	2-6	of 4x2½ oak		4/4	-	11
		½ lb. paint			-	5
		1 staple, 3. 1½" screws			-	3½
		3 5 hold fasts 2/6 10 screws 4 ^o			2	10
30		new flue + damper for T. Pykes			8	6
				£	4	2 9½

1917
 Loyal Sydney Lodge of Oddfellows

Sept	27	4 hrs repair of cupboard	24
	28	8 hrs ..	48
	29	1 1/2 hrs ..	10 1/2
		6-1" 6-1 1/2" screws 3 1/2" 2 deal ropes 4"	7 1/2
		paint	16
		<u>Paul</u>	
			100

1918 H. Langford Brown Esq. Huder House, Kingskenwell £ s d

Apr. 4 To 4 lbs. of chiming cords 3/- 13 6
Postage - 7

Paid April 6. 1918 £ 14 1

J. T. H. Bastard. Esq.
Harley Cottage
S. Breward

April 5 To six Bell Ropes each 60-0 long for S. Breward Church carr. paid at £ 1-8-0 8 8 0

Paid April 12. 1918

1918 C. Davy, Esq.

£ s d

		Omitted from last ac. 6-11x22 slates		2	6
Jan.	3	laying matlock		2	0
	16	shaper saw			9
Feb.	11	mason labourer level out ground, laying	
16	16	a brick path + 2 gate steps 2-13-9 r 43,	2	18	0
		750 bricks	2	3	5
		carting bricks from Exmouth		16	6
		175 182 bricks white or 1 1/2 ea.	1	2	9
		2 bags cement		17	0
		carting bricks cement from Exeter		11	0
		2 loads sand 3/0 r carting 3/1 f. 14-8		6	0
		2-11+22 plate		..	10
		6 nails, 3 strips lead		..	9
	13	mason 2 hrs. cut off sleepers of bank		1	3
	14	mason 4 1/2 hrs. prepare gate posts		2	10
	15	mason 9 1/2 hrs. fix posts & hang gate		5	11 1/2
	16	mason 4 hrs. do.		2	6
	25	mason 4 hrs. paint posts & put on springs		2	6
		12-0 of 4x4 oak posts		6	9
		1 coil spring		2	3
		plate of iron recur		..	4
		paint		..	6
		grinding hatchet		..	6
Mar	4	Self 3 1/2 hrs. stripping & raising wall	
16	8	whitening ceilings & changing wallpaper	1	5	6
		10 pieces wallpaper or 5/-	2	10	0
		1 pket paste, 1/2 lb. size, paint & plack		1	6
		6 lbs. white distemper		3	6
Mar	11, 12 + 13	mason labourer take out foundation
		build pier & dwarf wall	1	3	0
		325 bricks carting 4/- for 50	1	6	0
		4 barrows of mortar, 3 1/2 pecks cement, & gravel		11	6
		forward		17	7 10 1/2

		forward	17	7	10 ¹ / ₂
Jan.	25	Horse cart 1 day drawing		11	0
	29	do. 1 day		11	0
Feb.	11	do. 3/4 day		8	3
	13	do. 1/2 day		5	6
	20	do. 3/4 day		8	3
	27	do. 1 day		11	0
Mar.	4	do. 1 day to beets		11	0
	12	do. 1/2 day to Topshan		5	6
		150 stakes		2	0
Apr.	5	Carting 1 load stone from Topshan & 1 load of gravel			
			22	7	9

Paid May 1/15

$\frac{1}{2}$

 23 7 1¹/₂

Mr. W. Page. Venmore

1917

Dec.	28	8 hrs. repair cart		50
"	29	4 hrs. do.		210
1918 Jan.	1	7 hrs. do.		48 1/2
	2	9 hrs. do.		57
	3	9 hrs. do.		57
	4	2 1/2 hrs. do.		17
		2. 2 x 5/16, 2 1. 4 x 5/16, 2 1/2 1. 3 1/2 x 3/8 bolt-2		6 1/2
		8. 1' screws. 1 lb. nails paint		10
		3-6 of 2 x 2 ash rail		7
		16 sq ft of 1' elm bottom	30	50
		4-9 of 3 x 3/4 oak tail	42	19
		repair iron bolt. 1 new bolt 1-19	3	13
		new harness hook 9° new tip eye 1/3 new ring staple	6	26
		repair tail plate, 1 plate. 6 nails, ✓		14
	4	12 hrs. make new lade		710
		6-0 of 9 x 2 1/2 ash	11	56
		5-6 of 11 x 1 fir		13
		4-0 of 9 x 1/2 elm	17/6	8
		6. 4 x 3/8 bolt. 1' 1/2 lb. nails 3° 1 lb paint 10°		23
	7	8 1/2 hrs. alter front carriage of waggon r		54
		new tail pin, staple chain		6
		new washer, lengthen topping pin		"
		new split key 10/1 ✓		44
	28	11 hrs. repair winnow		610 1/2
		6-0 of 7 x 1 fir		10
		canvas sheets		6
		1 false link 8/6		2
Mar.	30	5 hrs. repair comb - table		3 1/2
		6 screws. 2° 1 leg 5° 3/9		7 1/2
Paid June. 1918				
3 14 1 1/2				3 19 2 1/2

Mr. Edgar Ware

1918

£ o d

Jan	1	new towel roller			1 0
Feb.	27	9 hrs. hang gates			5 11½
	28	5 hrs. do.			3 1½
Mar.	1	9 hrs. do.			5 11½
	2	5½ hrs. do.			3 1½
		8½ lbs. put. nails			3 6½
		52.0 of 4x1 oak bars	1½		6 6
		6 hooks ^{3/16} - 9 eyes ^{5/16}			8 9
		3 sharp staples			1 0
		3 bolls. 6° - 8 staples 8d.			1 2
		repairing gate ironwork			1 6
	8	9 hrs. repair hang gates			5 11½
	9	3 hrs. do.			1 10½
		3 bolls. 6°			6
		8.9 of 2x3½ oak top bar	3		2 2
		15.0 of 4x1 oak	1½		1 10½
		17.6 of 8x1 fir	2		2 11
	11	7 hrs. hang gates			4 4½
Jan.	18	haul horse take timber to be made			11 0

 3 12 3½

Paid, April 16. 1918

Mr. Walter Skinner

£ o d

Jan 7	1 hr. measure window				7 1/2
8	8 1/2 hrs. prepare sill	}			
9	1 1/2 hrs. "				6 3
	10-0 of 7 x 3 deal		11		5 10
	10-0 of 2 x 3 1/2 "		4		3 4
15	9 hrs. fitting				5 7
16	9 hrs. do.				5 7
	3-0 of 2 1/2 x 3 1/2 deal		4		1 0
	4-0 of 2 x 3 1/2 "				1 4
	12. 1 1/4" screws, 5. 1 1/2" screws				3
	1 lb. nails				5
21	9 hrs.				5 7
22	9 hrs.				5 7
23	9 hrs.				5 7
	4-6 of 2 x 3 rafter				1 1 1/2
	5-0 of 2 x 1				4
	10-0 of 7 x 3 1/4 floor		4		3 4
	6 lbs putty				1 1
29	3 hrs. paint fix bar				2 1
	2 lbs. paint				1 8
	To iron spike rail				13 0
					<hr/>
					3 9 7.

Mr. A. Stamp.

Jan.	7	sharpen 2 saws		10
Mar.	14	sharpen saw		6
	27	repairing bed	}	
		2, 3 1/2 x 3/8 coach screw		10
Apr.	16	sharp saw		6
Paid				
				30

15 Sholes in a/c. with Mr. A. Stamp

Mar.	7	1 horse 1 day		
	8	do.		
	9	do.		
	15	1/2 day		
	20	1 day		
	21	1 day		
	22	1 day		
	23	1 day		
	25	1 horse 3 hrs.		
	26	1 horse 1 day		
	27	1 horse 4 hrs.	Paid	
Apr.	3	4 hrs.		

1918

Mr. W. Summerfeld

£ o d

Jan	19	To door r jams		2	15	0
		To painting 2 coats			3	6
	28	man 6 hr. repairing at Morris's Cottage			3	9
		1- 12 Tee hinge r 12 screws			1	0
		2 panes glass				6
		1 stop.				5
		putty r nails				4
Feb.	4	9/2 hrs. make r fix pump casing to heater			5	11 1/2
	5	9/2 hrs do			5	11 1/2
		5-9 of 10 x 1 1/2 oak	7		3	4
		15-6 of 11 x 1 deal	7		9	0
		8. 2" screws				3
		1/2 lb. paint 1/2 lb. nails				8
Mar.	4	man 9/2 hrs Mr. P. Stokes			5	11 1/2
	5	man 9/2 hrs do			5	11 1/2
Paid						
				£	5	17

Travis Sons (millers) Woodbury

Jan.	21	2 hrs. repair front of wagon			1	4
		3. 1/2 x 9/16 bolts.				4
		wood paint				3
		new iron stay r repair 2	5/6		3	7
Feb.	25	sharpen r set saw			1	6
				£	7	0

Messrs. Jarman. Bros.

1917

Dec.	18	man & horse	hauling timber to clyst S. Mary	11 0
	19	do.	"	11 0
	20	do.	"	11 0
1918 Jan	11	do.	"	11 0
	12	do.	loads from "	11 0
	17	do.	"	11 0
	23	do.	scumth	5 6
Apr.	4	do.	clyst S. Mary	5 6
Paid May 2/18				
				£ 3 17 0

Mr. John Sprague, Woodbury

Feb.	25	Curving manure line	from Topsham	7 6
Mar	21	man & 2 horses	ploughing	15 0
	22	do.		15 0
	23	do.	sowing barley	15 0
	25	do.	do.	7 6
Mar.	5	man & 2 horses	wheel dragging	15 0
Paid				
				£ 3 15 0

Mrs Marshall. Oakhays

1915

£ s d

		book forward from page 255			15 0
Jan.	16	Pony Trap to Station			2 0
	23	do. Lenneth			4 6
	24	do. Station			1 9
	30	do. Otterton			3 6
	"	202-6 of 1/2" elm board at 2 1/2 ^o		2	2 2
Feb.	4	Pony Trap to Station			1 9
	12	do.			1 9
	18	1 new fork handle & tip			1 6
	25	new wheelbarrow		1	15 0
	28	6-6 of 2x3 paper	3		1 7 1/2
Mar	4	17-0 of 2x3 "	3		4 3
		71-0 of 1x7 deal floor	3 1/2	1	0 8 1/2
		17-0 of do.	3 1/2		4 11 1/2
		36-6 of 3/4" match	3 1/2		10 8
		7-3 of 17x1/2" elm 10 1/4" sq ft. at 2 1/2			2 2
Apr	15	2 lbs. putty			6
		<u>paid</u>			
				£	7 13 9 1/2

Mr. W. Newton. Rushmore

£ s d

Jan.	28	tyracing wheel			2 6
		<u>paid</u>			

Mr. S. Skinner, Corniche, Woodbury

1918

£ a d

Feb.	14	1 1/2 hrs. wash wheel			10
		6 hrs. put spokes in wheel			39
15		8 1/2 hrs. ring wheel			54
16		4 1/2 hrs. do.			210
		5 spokes			18
		6. 3x3 ash felloes		1/2	70
		1 new tyre 7 lbs.		1	97
18		2 hrs. clean off paint	wheel 1-3-4 tyre 1-9-7		13
		paint			6
16		.1 hr. put plate on shaft			8
		repair tailboard iron, 3 rivets			19
		2 plates of iron + 5 bolts for shaft	10/5		73
		new crook for back chain + S & I link			9
Mar.	6	8 1/2 hrs. put new shaft to cart		✓	54
	7	9 1/2 hrs. do.		✓	5 11 1/2
	9	5 hrs. put in cart bottom			3 12
	11	2 hrs. do			13
		1 hr. fix sideboards			7 1/2
		10-0 of 10 1/2 x 3/4 ash shaft		✓	147
		2. 7 + 1/2 bolts		✓	7
		40 pr. paper of 1" elm	bottom 15/5 shaft 1-9-7		100
		1 lb. pat nails			5
		paint		✓	6
		2 crooks. 1 link + repair ironwork		✓	28

Paid

£ 58 4 1/2

Mr. Henry Glanville, Webbers Farm

1918

£ s d

Feb 26	2 men q ² hrs. ea.	hang gates	11	10 ¹ / ₂
27	2 men q ² hrs. ea.	"	11	10 ¹ / ₂
28	2 men q ² hrs. ea.	"	11	10 ¹ / ₂
Mar 1	2 men q ² hrs. ea.	"	11	10 ¹ / ₂
2	2 2 men 5 ² hrs. ea.	"	6	10 ¹ / ₂
	2 hooks		1	2
	17 eyes		9	11
	4 harp staples		1	4
	10 staples		1	3
	2 q ¹ spikes			6
	4 lbs nails			18

Paul

£ 3 10 2¹/₂

Mr. W. Down, Venmore

Mar 15	man q ² hrs.	hanging gates 1 ⁵	5	11 ¹ / ₂
	nails		..	5
	2 harp staples		..	8
	1 staple 1 ⁰	1 gate eye 7	.	8
	sharpen hooks	eyes	"	9
				8 5 ¹ / ₂

Paul

1918

Mr. W. Glanville, Ford Farm.

£ s d

Jan.	24	2 1/2 hrs. - take off spurs on chaps			
Feb.	11	9 1/2 hrs.			
	13	9 hrs.			
	16	8 hrs. 30 hours			18 9
		2-0 of 1 3/4 + 3/4 inch			3
		10. 1 1/4 screws			3
		1 pair ash chaps		1	2 0
		1 pair chaps tips			1 3
		new part to trap for old ^{old} traps			3 6
Paid Apr 24/18					
				£	2 6 0

Mr. Harold Ware. The Beeches.

Feb.	13	5 hrs. repair bird cases			
	14	3 hrs. do.			
	15	1 hr. do.			6 9
		1 pane glass			1 6
		packs. paint + glue			6
					8 9
Mar	4	To making a new body of wheel barrow + ring wheel + new tyre + eyes			1 12 0
Paid May 2 1918					
				£	2 0 9

Mr. J. F. Glanville, Rydon Farm

1918

£ p d

Jan. 24	5 hrs. boxing cart wheel 1 old box	5/-	3	1 1/2
Mar. 21	fixing lamp iron on milk can		1	0
Paid, May 2 1918		£	6	0

1918

Mr. G. Goss, Woodbury

£ p d

Jan 9	roughing horse		1	6
Mar 15	ploughing 3 allotment		7	6
16	setting manure		10	0
20	sowing oats		7	6
Apr. 6	new handle spin for pump		3	3
Paid		£	19	9

Mr. B. Stamp, Woodbury

1918

£ s d

Feb.	4	solder Kettle	• 4
		repair hoop of butter tub	2 0
	8	solder separator spout	• 4
	11	Thrs. repair shaft of trap, step, shackles collar wheels	4 4½
		1. 2. 2. 2½ x 3/8 + 2. 2 x 1/4 bolts	6
		2 large & 2 small leather collars	3 0
		leather stacks	6½
		sowing on leather on shaft	2 0
	23	1 nailpin & chain staples	• 6
	26	4½ hrs. make draft for drag	2 10
Mar	5	sharp saw	• 6
	12	1 link	• 3
	27	painting cupboard B.	4 6
Apr.	16	solder Kettle	• 4
Feb.	18	man horse, had man horse in shed	• •
	19	man horse do.	• •

Stamp

9½

 1 2 0

Mr. R. Piles, Bagmore

1918

		Ironwork for cart 6 lbs.	↑	14	0
		Time making 72½ hrs.	↑	2	8 4
		18 rivets	↑		16
		4 plates	↑		4
		2 Lynch pins	↑		4
		2 tail pins	↑		2
		plug harp.	↑		6
		Time making 174½ hrs.	↑	5	1 9½
		Timber bolts	↑	2	4 6
		9 lbs. paint	↑		7 6
Feb	11	To making a new body of lutt cart all new ironwork, putting a new axle case, new cross bar, altering shafts & put new point to shaft, and altering axles & painting wheels & shafts	↑	10	0 0
March		Waggon	↑		
		Time 70½ hrs.	↑	2	4 0
		6. 1¼ x ¼, 1-5 x 3/8 bolts	↑		8½
		10-6 of 2 x ½ elm	↑		5
		1-5 x 3/8 14 lbs. paint	↑	10	11 8
		2 split keys	↑		6
		cut short wire bands	↑		4 4
		To repairing lades, & cleaning & painting waggon & shooting wire bands of wheels	↑	3	10 0
Feb.	12	13 hrs. repair lutt worker	↑		8 1½
		5-0 of 1¼ x 4 beech	↑		5
		28. 1½, 2-2½, 1-3 screw	↑		9½
		1 bolt	↑		1 2
			10/6 v		
	14	put in lutt stem	↑		9

Carried back to page 253

Mr. J. G. Miller

£ o d

		To Mr. Summersfelds acc.	1	0	3
Jan	12	2 oak grating frames		6	0
Feb.	12	repair & varnish chair		2	0
	21	sharp saw			7
Feb-Mar		64 hrs. repairing & painting waggon	2	0	0
		material		5	11
		washing waggon		5	0
		18 lbs. paint		15	0
		£ 3. 6. 0			
Mar.	16	put bolts in spring of pony waggon			16
April		To making a new body of pony cart			
		altering ironwork, ringing wheels			
		2 new tyres, put point to shaft			
		+ painting shafts		8	50
				<hr/>	
			£	13	14
				<hr/> <hr/>	

Paid. May 2. 1918

1918 Miss Acland. The Firs, Woodbury £ p d

Feb. 9	To 1. 3-6 rabbit hutch	1	2	6
April 11	To 2. 5-0 hutches	2	15	0

Paid
 out of pocket at 5/6
 1919

£	3	17	6
		3	9
£	4	1	3

Mr. C. H. Stamp. Buckler & Topsham

Apr. 4	6 1/2 hrs. repair trap shaps		4	0
	1 plate of iron		1	6
	4 - 2 + 1/4 bolts		4	4
	3 - 1 1/2 screws		1	1
	2 leather collars		4	4
	oil		3	3

Paid

£	6	6
---	---	---

Mr. T. Wood, Bridgepit Farm.

Feb. 19	9 1/2 hrs. make ladder		11	10
20	9 1/2 hrs. do.		9	9
	3 iron rods		3	8
	22 rounds		1	0
	paint		1	0

Paid.

£	17	3
---	----	---

Mr. Harold Ware. The Beeches

1918

£ s d

Mar. 15 7 hrs. repair & rehang doors at Mr. Bamsey
 10 screws 2^d. 1. Taper bolt 8^d
 1 catch. 1 staple
 3-0 of 2¹/₂ + 1¹/₂ oak. 1 stop block

4 4¹/₂
 10
 3
 9¹/₂

Paid May 2 / 18

£

6 3

Miss Fulford. The Priory

Apr. 15 new bottle handle + new ring 1/4
 19 2 hrs. put up sash cord
 1 cord + repair

2 0
 2 9

Paid Apr 23 1918

£

4 9

Mr. J. Bamsey. Woodbury

Feb. 26 making riving board to front door
 Mar 13 To taking off & altering brake blocks
 + 14 putting new ends with clips. plates &
 blocks.
 Mar 15 2 1/2 hrs. repair glass
 5 panes glass
 putty

2 6

 1 2 6
 1 7
 2 6
 3

Paid May 2 1918

£

1 9 4

1915 Rev. G. J. Jeppery, Merion. Dolton £ s d

Apr. 29 To 13 lbs. of chime cord at 3/6 2 5 6
 To 6 hand rubbers 7 6

Paid

£ 2 13 0

Rev. B. Wheeler, Halwell Devon

Apr. 29 To 6 turned patrices at 2/6 15 0

Mr. John Tyne, Postgate, Woodbury

1918

£ s d

April

To making a new Varished body of
mill cast complete with springs
cranked, axles & fitting over wheels

16 0 0

Paid 11/6/18

Rev. H. W. Millett, The Glebe House, Littleham

£ s d

May 6

To 6 1/4 lbs. chime cord for Littleham Church
at 3/6

1 2 0

Paid

Trustee (late H. Stokes)

1918

7 p a

Jan 25	9 ¹ / ₂ hrs. repair porch pump, new clock.	Claremont	7	3 0 ¹ / ₂
29	solder water pipe at Mr. James			5 11 ¹ / ₂
	W. Sumner fields hill, repair ceiling			3 0
25	8 hrs. fix plumbing for window	Claremont		3 6
26	2 hrs. do.			5 0
	plumbing		1	1 3
	7 plumb screws, 7 12-2 screws			4 0
	1 lb. putty, 4 pipe nails			1 1
29	2 hrs. paint window			6
30	4 ¹ / ₂ hrs. "			1 3
31	9 hrs. "			2 9 ¹ / ₂
Feb 23	5 ¹ / ₂ hrs. do.			5 7 ¹ / ₂
25	5 ¹ / ₂ hrs. do.			6 10 ¹ / ₂
	2 ¹ / ₂ lbs. green 2/1, 2 ¹ / ₂ lbs. lead color 4/1			4 2
	1 lb. white 10, 1 lb. putty 3			1 0
Mar 27	4 hrs. fix chimney cow			3 0
	1. Sculls, cow			15 0
Apr 3	new rubber on cisten	Mr. James		2 0
20	1 ¹ / ₂ hrs. repair plumbing			1 0
2	repair lock at R. Daves			1 0
			7	4 11 0 ¹ / ₂
				4 11 0 ¹ / ₂

Mrs Stokes Sen. (Coler & Smeeths)

1916

£ s d

Feb.	1	9 hrs. painting			5 3
	2	1 1/2 hrs. do.			10 1/2
	6	9 1/2 hrs. do.			5 6 1/2
	7	9 1/2 hrs. do.			5 6 1/2
	8	9 1/2 hrs. do.			5 6 1/2
	9	5 1/2 hrs. do.			3 2 1/2
		10 lbs paint			8 4
		2 lbs putty			4
		7-0 of 2 x 1 1/4 deal			7

£ 1 15 2 1/2

Mrs. Stokes Sen. (Private acc)

Jan.	1	1 new pulley bottom to stove			4 6
Feb.	2	3 hrs. fit handrail			2 1
		2 iron handrails & screws	5/9	}	3 8
	15	36 plate nails for fruit tree			
Mar.	28	4 1/2 hrs. fit wire netting			3 0
Apr.	2	6 hrs. do.			4 0
		17 yds. 4 pr. netting		7	10 0
		17 1/2 yds. plain wire.			1 6
		11 yds. 2 pr. netting			6 0
		18 plate nails, 8. 4 pat.			6
		9 iron stands			9 0
		9 nails, 6 staples, 9 holdfasts.			3 0
	15	repair coal scuttle			1 9

£ 2 9 6

Expenses of late Mr. W. Summerfeld

1918

£ s d

May 24	Horse cart to Backenhayes			5	0
Aug 21	do. Exmouth to Elford 2 loads			15	0
Sep 3	do. do. Exton			7	6
4	do. do. Yard			6	0
16	do. do. Elford			10	0
Oct 1	do. do. do			10	0
14	3 fire bricks				9
Nov 11	Horse cart to Elford			5	6

£ 2 19 9

Mr. W. Tolman

£ s d

Sep 26	man off horse 3 1/2 hrs.			6	0
Dec 7	do. 2 1/2 hrs.			4	3
18	do. 1 hr.			1	9
	3 fire bricks				9
	1 fire check				19
	25-6 of 18x1 1/2 elm = 38-3 at 1 1/2			14	4
	10-0 of 14x1 elm 11-8				
	9-0 of 12x1 " 9-0				
	12-0 of 14x1 " 14-0				
	12-0 of 15x1 " 15-0 49-8 at 3-0			12	5

£ 2 1 3

1 12 6

£ 3 13 9

13 weeks Rent at 2/6

Settled Dec. 30/18

1918 Rev. Canon Boles. Newton St. Cyres £ o d

Dec. 27 To six leather clapper muffles with straps buckles at 5/- £ 1 10 0

Paid Jan. 3. 1919

Dec. 23 Rev. Preb. Benson, Withenidge To two bellropes for 5th & 6th bells at Withenidge Church. ea. 60-0 long Carriage 2 16 0 1 0

Paid Jan. 4. 1919 £ 2 17 0

Dec. 23 Rev. J. H. H. Wollamby, Stowford To six bellropes each 60-0 long for Stowford Church at £1-8-0 ea. Carriage 8 8 0 3 9

Paid Jan. 2. 1919 £ 8 11 9

1918 Rev. H. C. Jenner. Bradford Vicarage, Taunton £ p d

Dec. 6	To main line & railpurs examining			
12	bells, To main line, railpurs & overhauling			
18	+ screwing up bells fittings in Bradford Church Tower			
	Railpurs & trap hire		1	8 6
	Time lodgings		1	6 0
			<hr/>	
		Nett. Cost.	2	14 6
		add 25% p.		13 9
			<hr/>	
	Paid. Jan. 2. 1919	£	3	8 3
			<hr/>	

Rev. R. G. Crump. Crump Orchard

Jan. 20	To 2 3 bellropes, each 60 ft. long			
	Paid. Jan. 30. 1919			
May 23	To 3 bellropes each 60 ft. long		4	4 0
	Carriage			2 3
	Paid. June 2. 1919		4	6 3

H. M. Sperling, Esq. Coombe Trenchard. Lew Down
 1919 £ s d

Jan. 30 To six bellropes each 60 ft. long
 at £1-8-0 each
 Carriage

8 8 0

2 5

£ 8 10 5

Paid

Mr. R. B. Parsford, Exeter Rd. Withycombe

Feb. 28 To 2 bell ropes for Withycombe Church
 Carriage

2 16 0

1 0

£ 2 17 0

Paid

The Churchwardens of Thorveston

Apr. 11 To man's time + rail fares
 screwing up Thorveston Church Bells
 2 clapper leathers, 1 can of oil

1 1 6

Rev. J. de B. Forbes, Hemsworth

Apr. 16 To two men's time, rail fares +
 carriage of chain blocks & for repairs
 to tenor bell + screwing up bell
 fittings in Hemsworth Church Tower

3 2 6

Paid Apr. 25. 1919

Mr. B. Stamp

1918

June 28	Horse & man 8 hrs. 12	12 0
	4 1/2 hrs. overtime 9.	3 4
July 29	man cutting out.	6 0
Aug 1	man 5 hrs.	3 0
3	Horse & man	12 0
	2 hrs. overtime	1 6
12	man horse	6 0
	3 1/2 hrs. overtime	2 8
13	man 4 1/2 hrs.	3 0
17	Horse & man	12 0
Sep. 19	Horse & man 3 1/2 hrs.	5 3
Nov. 18	Horse & man	12 0
26	4 bags powder 8.	8 0
Dec. 30	Horse & man	12 0
31	Horse & man	12 0
1919 Jan. 1	man 4 hrs.	3 0
29	man & horse	12 0
30	do.	12 0
31	do.	12 0

7 799

Contra. acc. 8-1-6
7-9-9
11-9

Settled up. to
March 20. 1919

Mr. C. Summerfield.

1919

£ o d

Feb.	4	Horse & Cart 1 day lime & sand	12	0
	14	Cart gravel from beneath	7	6
	15	1 load bricks	6	0
	20	do.	6	0
	28	bricks to Aylesbeare	12	0
Mar.	5	do.	12	0
	11	do.	12	0
	12	do.	12	0
	20	fetching poles, bricks & bls.	9	0

Paid Apr. 9. 1919

£ 48 6

Mr. J. Pyne

1918

Nov.	23	boy 3 days			
Dec.	7	3 days			
	21	3 days			
1919					
Jan.	11	4 days			
	18	3 days			
	25	2 days			
Feb.	15	2 days			
	22	1 day			
Mar.	1	4 days			
	8	2 days			
	15	2 days			
Nov.	21	1918 wheat 1 1/2 bushels	15/9		15 9
Mar.	22	3 days			
	29	2 days			
April	5	1 day	35 days		

Paid up 5 Calf
to April 1919

	1	15	0
£	2	10	9
		16	6
£	3	7	3

1919 Exors. of late Mr. Josias Down

Apr. 3	To making a polished elm Coffin with brass mountings and carrying out the funeral arrangements for the late Mr. Josias Down	9	5	0
	Hearse	2	5	0
	Six bearers	1	10	0
	Vicar's Clerks Fee		3	6
	Sextons Fee		10	0
		£	13	13 6

Paid May 26. 1919

Jarman Bros

1918

£ p d

Sep.	6	Cart gravel from Remouth			7	6
Dec.	23	Horse Waggon to Exeter			12	0
1919						
Jan	21	Cart gravel from Remouth			7	6
Feb.	3	Horse Waggon to Exeter			12	0
Mar.	15	do. Remouth			7	0
	21	Cart 3 loads sand			4	6

Paid Apr. 5/19

£ 2 10 6

Apr.	4	Man & 2 Horses ploughing			1	1	0
	8	Horse Waggon to Remouth				7	0
	19	Chain Harrow Roll fields 2 days			1	4	0
May	12	Horse Waggon to Remouth				7	0
	17	do. to Clyst				6	0
	30	Load gravel from Remouth				7	6
June	2	Man & 2 Horses working field			1	1	0
	3	do.			1	1	0
	11	do.			1	1	0
	12	Load sand from Remouth				7	6
	17	$\frac{1}{2}$ journey Clyst & Man				3	0
	18	Man & Horse 3 $\frac{1}{2}$ hrs. haymaking				7	0
	19	do. 1 day				12	0
	27	Cart load from Exeter				7	0

£ 8 12 0

May	10	4 iron window squares				14	0
-----	----	-----------------------	--	--	--	----	---

£ 9 6 0

276 Harry Stokes

1918 Invo a/c with Mr. Alf Stamp

July	1	man 1 day + 3 1/2 hrs overtime haymaking	6 0
Aug.	8	man 3 hrs.	
Sep.	9	horse 1 day	5 0
1919 Mar.	22	man horse ploughing	12 0
	24	do	12 0
	31	horse 1 day	5 0
Apr.	14	do.	5 0
	28	do.	5 0
May	5	do.	5 0
			£ 2 15 0

Mr. Alf Stamp

July	25	help tie oats				
Aug	5	tie wheat 3 hrs.				
"	28	horse 1 day			5 0	
	29	do.			5 0	
	30	do.			5 0	
Oct	22	do.			5 0	
	23	do.			5 0	
	24	do.			5 0	
	31	do.			5 0	
Nov.	13	do.			5 0	
	14	do.			5 0	
	15	do.			5 0	
¹⁹¹⁹ Mar	25	man horse cart			12 0	
	26	do.			12 0	
	27	horse 1 day			5 0	
	28	do.			5 0	
Apr	2	horse 1 day			5 0	
	4	do.			5 0	
	22	man & horse 1 day (chain harrow)			12 0	
	23	do.			12 0	
May	2	horse 1 day	} call 3 days, 2 days			
	6	do.				
	7	do.				10 0
June	2	do.			5 0	
	3	do.			5 0	
	4	do. 1/2 day			2 6	
	5	1 day			5 0	
	11	1 day			5 0	
					7 10 6	
					2 15 0	
					4 15 6	

©. Davy Esq Knoll Cottage

1918

£ s d

May	15	clearing drain							29
Oct.	5	carting manure							23
	21	carting turf							90
	31	" manure							16
Nov-	26	" turf							30
1919 Feb.	5	" manure							27
Mar.	7	" "							19
	17	" gravel							100
	21	do.							26
Mar.	3	8 hrs.	10 ⁵	8 hrs					
	4	8 hrs.	11 ⁵	8 hrs					
	5	8 hrs.	12 ⁵	8 hrs.					
	7	8 ¹ / ₂ hrs.	13 ⁵	5 hrs					
			14 ⁵	4 ¹ / ₂ hrs					
			15 ⁵	6 hrs.					
			17 ⁵	9 hrs.					
			18	2 hrs.					
			32 ¹ / ₂	50 ¹ / ₂	83 hrs.	4-			4 3 0
		9 lbs. ^{stone} white paint							9 0
		12 lbs. ^{stone} color & undercoating				21 lbs.			13 0
		1/2 gal. enamel							17 6
		7 lbs. green paint							7 0
		14 lbs. Halls distemper							8 2
		1 lb. putty							. 3
		1/4 pk. plaster							1 0
		1 tin Brunswick black							. 6
		5 pieces wallpaper							1 10 0
		1/2 pk. paste 10 ⁵ 1/4 lb. putty 2 sheets paper 3 ⁵ / ₂							1 8
		can pebbles planks etc.				8-14.5			1 0
		4 lbs. buff distemper							2 4
									10 9 9
		Credit by 25 yds. of br. netting c.p. 32/-							10 8 0
		1/4 lb. do.							

distemper
bath bed room
kitchen
paint
enamel
putty
paper

paid 1919
Apr 9

Apr 10, 1919

Rev. T. S. Fox, The Vicarage, Shebbear

1919

Apr. 10	To six bellropes each 70 feet long at £1-11-6 per rope				9	9	0
		Carrriage				3	9
	<u>Paid</u>		bell	£	9	12	9

Rev. S. Boylan-Smith, Bondleigh

May 7	To 4 bellropes at £1-8-0				5	12	0
		Carrriage				2	3
				£	5	14	3

Rev. J. D. H. Patch, The Vicarage, Ilminster

June 27	To five bellropes ea. 60 ft. long				7	0	0
		Carrriage				3	2
					7	3	2

Mr. W. Thomas

May 13	To repairing trap traps					6	9
--------	-------------------------	--	--	--	--	---	---