

May 27. 1919

1919 The Churchwardens of Ashburton (Mr. A. Wilson, Fairleigh) £ s d

Mar. 20	To inspecting bells & rail faces	1	7	0
Apr. 28	To mens line, screwing up bell			
to May 3	frame fittings, putting new leathers to clappers, repairing ironwork, & cleaning out lower rail faces, carriage of tools chain blocks &c	9	15	0
		<hr/>		
		£	11	20
		<hr/>		

The Churchwardens of Lapford
(F. Moulton-Barratt Esq)

£ s d

June	To inspecting Lapford bells & mens line & railway faces screwing up the fittings &c	3	3	0
------	---	---	---	---

H. Maddick, Esq. Velwell, Torves.

June 26	To 8 bell ropes ea. 60-0 long for Torves Church at £ 1-8-0 ea.	11	4	0
	Carriage		2	6
		11	6	6

H. F. Telford Esq. The Priory.

1919

£ s d

May	29	4 1/2 hrs.	do.			4	6	
	30	9 1/2 hrs.	make doors			9	6	
	31	6 hrs.	do.			6	0	
June	2	9 1/2 hrs.	do.			9	6	
	3	8 hrs.	do.			8	0	
		94-0	of 7x1 match	5	1	19	2	
		20-0	of 7x1 ledge	6 1/2		10	10	
		12-0	of 7x3/4 brace	3 3/4		3	9	
		7-6	of 3x1 stop	3		1	10 1/2	
		2 lbs.	nails	6		1	0	
		9 lbs.	paint	1 1/2		10	6	
		2.	8" Tower bolts & screws	1 1/2		2	4	
		2	pairs hooks & studs			7	6	
		4	bolts & screws			1	3	
		1.	6" dead lock staple			2	3	
		1	spike .3			1	3	
			1 stop block 1/-					

5 19 2 1/2

9 1/2

Paid. July 2. 1919.

£

6 0 0

Rev. Dr. Telford. The Priory

May	5		re-leather jacket			2	6	
	31	5 hrs.	put in 3 sack cords	5/-				
		1 1/2 hrs.	cord	1/6		6	6	

Paid. July 2. 1919

£

9 0

Mr. S. G. Miller

1919

F o d

Apr. 2	6 hrs. repair spring mutton	6/-	}			
	9-0 of 2x3 oak $3\frac{1}{4}$	2/9				
	1 doz. staple, wire & varnish	3				9 0
May 19	To new pair of Heavy Oak Gates				6 6 9	
May 19	sharpen saw				7	
May 12	6 $\frac{1}{2}$ hrs. painting		}			
	4 lbs. paint	5-0				
June 14	8 $\frac{1}{2}$ hrs. hang gates & put back part.	8-6				
1	8 $\frac{1}{2}$ hrs. do.	7-10				
5	9 $\frac{1}{2}$ hrs. do.	9-6				
	7 $\frac{1}{2}$ hrs. do.	6-5				
May 21	13 $\frac{1}{2}$ hrs. take out old hooks ✓	13-6				
June 6	9 $\frac{1}{2}$ hrs. hang & paint gates	9-6				
	4 lbs. paint	5-0				
	2 small staples	3				
	1 stop block	1-0				
	1 new twist ✓	9-9				
	2 hooks ✓	4-6				
	8 bolts $\frac{3}{4}$, wedges $\frac{1}{3}$, lead 21-	6-7				10
	taking out old hooks from part.					13 6
	1 new bottom twist & 2 hooks.				14 3	
	10 time hanging gates, refixing 3 part, putting in new hooks, painting gates 2 coats, 8 bolts, 2 staples & stop block				3 6 1	
7	6 hrs. repair & rehang paint gate at main Road	6/-	}			
	4-0 of 2x1 larch	1/4				
	2 lbs. paint	3/8				11 0
10	repairing lade				3 3	
					<u>12 3 8</u>	

1919 Rev. A. P. Hudson, Hantsham Rectory £ s d

July 11	To 3 bell ropes ea. 60 ft. long at £1-8/- Carrriage	4 4 0 1 6
		<hr/>
		£ 4 5 6

Rev. E. D. Southcomb, Rose Ash Rectory

July 15	To 2 bell ropes ea. 60 ft. long at £1-8/- Postage	2 16 0 1 0
		<hr/>
		£ 2 17 0

Rev. W. R. H. Arundell, South Pool Rectory

July 10 & 11	To man's time 24 hrs. screwing up bells putting in ropes 15 24 hrs. Rail fares, wedges, Smith lodgings wedges getting tools 15 Oil	1 10 0 17 9 1 0
		<hr/>
		£ 2 8 9

Mr. Alfred Stamp.

1919

£ o d

May 13	9 $\frac{1}{2}$ lbs. paint paper room			
14	9 $\frac{1}{2}$			
15	16 $\frac{1}{2}$			
16	19			
17	6			
19	11			
20	8			
24	2			
27	3	84 $\frac{1}{2}$	at 1/-	4 4 6
	26 lbs. paint			113 1 12 6
	2 iron r f screws for deck			10
	2 lbs. putty			8
	2 sheets glass paper			3
	8 pieces wallpaper 2/34			18 8
	1 pkt. paste powder 11- $\frac{1}{4}$ lb. pine			1 6
	3-6 of 7 x $\frac{3}{4}$ match			1 2
	4-6 of 5 x 1			1 6
	9. 1 $\frac{1}{2}$ screws			3
	1 square r 4 screws for couch			1 2
	2 panes of glass			2 6
	Mr. Summerfields bill, whitening ceiling, sweeping chimney, r f 8-5-6			1 0 0
20	put bolt in spring of waggon			1 0
May 8	sharp 2 saws			1 4
29	tyring waggon wheel			5 0
	repair bottom of waggon			1 3
June 24	sharp saw			8
25	cut r short 2 trap wheels			12 0
	28 rivets for dr.			9 4
	Repair dash board. 2 bolts			1 0
	repair scales			1 6
				1
				9 18 7

Col. Mansfield

1919

£ o d

May 14	Carting 2 loads gravel			60
June	To cleaning, varnishing & striping trap & re collaring wheels		5	00
		£	5	60
June 2	To repairing cutlery box			26
		£	5	86

Mr. F. Elliott, Pearson Farm, Beaford

July 18	To 3 bellowses ea. 60 p. long at £1-8-0 Carrriage		4	40
				16
		£	4	56

Mr. J. Pyne. Postlake, Clevel. & Mary. 7 o d

1919

May

To repairing trap, new front board,
repair tail board, new hinges, 4 bolts screws,
new back step, 2 new dash board inner
plate of iron on shaft

1 50

1 pair brass tailboard fasteners

50

To cleaning, re-painting, striping &
varnishing trap

4 100

To re-covering 3 cushions, back of
seat, box & fall of trap 9-12-6

3 126

June

To repairing dogcart, new tail piece
part new bottom, new tailboard
fasteners, new whip socket

1 ~~8~~ 6

To re-rubbing two wheels

4 150

To cleaning, staining, striping
& varnishing dogcart

4 100

Apr. 16

man 1 day thrashing

66

720 150

Mr. W. Down

May 16	To new type blls. at 7°	2	0	10
	new toy crook, repairing stay, repair			57
	2 bolts, new mudguard			2 15 0
	To painting cart			
		<u>£</u>	<u>5</u>	<u>15</u>

Mr. H. Ware, The Beeches

May 13 + 14	To cleaning up and touching up parts of motor	1	2	0
28	To making, hanging & painting new garden gate & turret for Cottage	1	4	0
June 13, 14, 15, 16	3 1/2 hrs. fixing bridge	1	15	0
	14-0 of 2x7 oak	11		12-10
	30-0 of 2x12 oak	1/6		2-5-0
	26-6 of 3 1/2 x 3 1/2 oak	9 1/2		1-1-0
	3-6 of 4x4 oak	11-		3-6
	10 larch poles			<u>4-2-4</u>
	6 lbs. nails			3-0
	4. 5 1/2 x 7/16 bolts. 6. 2 1/2 x 1/4 bolts.			2-5
	repairing iron stay & latch of gate	6-17-9		2-6
		<u>£</u>	<u>9</u>	<u>39</u>

Mr. Edgar Ware.

1919

Apr. 29	repairing pump	5 0
May 3	repairing wheel	6 6
16	1 new tyre 46 lbs. at 7?	1 6 10
		<hr/>
		£ 1 18 4
		<hr/> <hr/>

Mr. James Handford.

May 8	repair coal scuttle	2 3
27	lying pick	2 6
June 3	sharp pick	5
10	do. 2	10
19	lying pick	2 6
24	sharp pick	5
30	do.	5
		<hr/>
		£ 9 4
		<hr/> <hr/>

Mr. S. Cornish. Coshills

June 22	To repairing tip iron of cart, repairing tailboard iron, 6 rivets, 1 nut	7 3
---------	--	-----

Mr. B. Stamp

1919		£	p	d
Apr. 3	put in 2 wheel handles		3	0
May 7	repair plough clip		1	3
9	repair headptk of plough			10
	$\frac{1}{2}$ cost of straightening beam			13
26	2 horsehoe knives		10	6
	filing do. sharpen 2 feet & repair clips		4	9
June 6	2 handles & rings		2	0
June 19	repair wheel of hay rake		19	3
	3 pints linseed Oil			46
		£	2	76

Mr. C. Stamp

May 5	re-leather sucker		3	0
May 19	new handle for pump		5	0
	new top for sucker rod & 2 new bolts			
	& piping		6	0
June 18	putting in pane of glass		2	6
		£	16	6

Dr. F. S. Stokes

1919

£ s d

May 9+10 To repairing plaster & coloring
end of ~~the~~ Knoll & windows of Knoll
Cottage 2 10 0

Apr. 25 Mr. A. Haire Higher Malletts
To putting in 11 panes of glass
at Cottage 14 3

Mr. C. Summerfield

Apr. 24 10 gals. tar 5 0

June 30 20.0 of 2x3 paper 6 8

Apr. 2 ploughing 2 allotments 6 0

3 sowing do. 6 0

10 Horse Cart (day carting lime sand 12 6

May 8 Rolling out 2 0

13 Horse Cart (day carting lime sand 12 6

17 mend hoop 2

£ 27 10 80

Mr. G. Pyle. "Rosedale" Clevel St. Mary

£ p d

May 2	To repairing tailboard of trap & cleaning	4	6	
to 21	staining & varnishing trap	3	10	0
June	To re-rubbing 1 wheel	3	7	6
	To touching up shops & repairing dash board		5	0
	To carting 2 loads gravel		12	0
		£	7	19 0

Mr. Joseph Pyle. Hoggsbrook

May 9	To ring 1 trap wheel & spokes felloes	1	1	0
	To tyreing 2 wheels		12	0
	To putting 22 rivets in tyres at 4 ^d .		7	4
	To screwing up springs & after, repairing brass front rail & oiling putting on wheels		7	0
		£	2	7 4

Mr. W. Stamp. Vermont

1919

£ p d

May 14 9 1/2 hrs. putting up bridge
6 spikes

9 6
2 6

12 0

Woodbury School

May 17 1 1/2 hrs take out glass }
20 1 1/2 hrs. put in } 3/-
1 pane glass 3/2
putty 4

6 6

Miss Vinter. Woodbury Saltm

June 20 To collaring & oiling trap wheel

5 0

Mr. J. J. Glanville. Ryan Farm

Mr. F. Stamp

I o d

May 28	tyring 2 car wheels		16 0
	putting plate of iron on shaft. 2 bolts		1 6
	altering long staple & making plate		2 0
29	tyring 1 car wheel		8 0
	2 Lynch pins		2 0
	2 false links		4
June 19	do.		1 0
" 19	1 1/2 hrs. take off wheels &	1-4 1/2	
20	9/2 hrs. repair do.	8-8 1/2	
21	6 hrs. do. do.	5-6 1/2	
23	9 1/2 hrs. do. put plates of iron	8-8 1/2	
	& tips of cars		
	4 spokers, 2 1/8 3, 3 1/2' fellows, 3/4 pair of	7-0	
	2 rivets in hubboard eyes & 4 plates & 8	7-0	
	nails for tips of cars	2-4	1 13 8
	tyring 2 wheels		16 0
			<hr/> 4 10 4
	2 new car wheel skids 2-17-6		5 15 0
July 4	evening		1 0
	8 false links		1 4
9	setting & drilling car wheels		4 0
Sep. 29	wedging car wheel		1 6
Dec. 30	1 new bottom to skid 7/6 r'p'ing 3/.		10 6
			<hr/> 10 13 10

Mrs. Marshall, Oakhays

1918

Dec.	11	Pony r trap	Station	26
	18	do.		26
	31	do.		36
1919				
Jan.	14	do.		26
Feb.	3	do.	(2)	50
	7	do.	reeter	60
	22	do.	remouth	50
Apr.	8	do.	Station	26
	26	do.	do.	30
May	6	do.		26

 1 15 0

S. Thomas Rural District Council

1919

£ s d

Aug. 18	To repairing barrow & tyreing wheel			6	3
Sep. 27	To 16-0 of 11x4 oak	Brook	at 9/-c.	2	2 8
	15-0 of 9x4 oak	"	9/-c.	1	13 9
	27-0 of 4x4 oak	"	8/-c.	1	4 9
	13 spikes	"			4 4
	man 4 hrs. cut out sweeps B				4 0

£ 5 15 9

Rev. Dr. Fulford, The Priory.

1919

£ o d

June 25	100 hrs. make, hang & paint entrance gates.		5	0	0
	30.0 of 4x3 deal	11/-	1	10	0
	28.0 of 3x3	9 1/2	1	2	2
	9.0 of 4x2	6 1/4		4	8
	35.0 of 7x1	6		17	6
	2 lbs. priming			2	2
	4. 4x3/8 bolts				
	8. 3 1/2 x 3/8 bolts				3 0
	2 lbs. paint			2	4
	2 small staples				2
	4 lbs. paint			5	0
	2 new hanging staples			2	9
	repair ironwork	£ 9. 15. 0		5	3
July 24	4 hrs. repair skirting			4	0
	3.0 of 6x1 deal	5		1	3
	piece of oak 3"				3
	nails 2"				2
Aug. 14	8 1/2 hrs. repair skirting, verandah & jambs			8	6
15	9 1/2 hrs. do.			9	6
16	6 hrs. do.			6	0
	6.0 of 6 1/2 x 1 floor	5		2	6
	6.0 of 1 1/2 x 3/4				6
	12.0 of 7 x 3/4 match	4		4	0
	2.0 of 2 x 3	4			8
	1.3 of 4 1/2 x 4			1	6
	1. 18" Tee hinge			1	6
	12. 1 1/2" screws, 12. C.S. nails				5
	3.9 of 3 x 3 oak sill	6		1	10 1/2
	3 squares			2	0
	1/2 lb. paint				7 1/2
	1 lb. nails				6
	forward			2	5 9

	forward		2	5	9
Aug. 18	5 hrs. make fix luntels			5	0
	4-9 of 13x3 oak luntel	2/3		10	9
	4-0 of 8x3 "	1/6		6	0
	4-0 of 3x1 deal			1	0
	1 square			1	3
	1 stay	3-10-3			6
Aug. Sep	238 hrs. painting outside of The Priory		11	18	0
	62 lbs. paint	1/2	3	12	4
	3 quarts Linseed Oil	3/7		10	9
	1 pint Terebinte			2	3
	3 lbs. putty			1	0
	12 sheets glass paper			1	0
		£	16	5	4
	Repair Gates		3	10	3
			9	15	0
		£	29	10	7
	Paid. Oct. 14/19				

Mr. Harold Ware.

July	7	9 $\frac{1}{2}$ hrs. repair iron hinge & leather stove doors		9	6
	8	9 $\frac{1}{2}$ hrs. do. roof, fencing & garden door		9	6
	9	7 hrs. do.		7	0
		5.0 of 9x1 deal	8 $\frac{1}{2}$	36	$\frac{1}{2}$
		guide for door		1	6
		1 latch & guide		1	3
		new part to stage		2	3
		1 lb. nails, 6 lb. wire nails, 10 ^p .		1	4
		$\frac{1}{2}$ lb. paint, 7 ^p 6, 1 $\frac{1}{2}$ " screws, 1 $\frac{1}{2}$ staple 1 $\frac{1}{2}$			10
		2.0 of 6 $\frac{1}{2}$ x3 oak		1	2
		7.0 of 2x1 battens			9
		2 holdfasts			10
Aug	5	9 $\frac{1}{2}$ hrs. piling bridge		9	6
	6	9 $\frac{1}{2}$ hrs. "		9	6
		7-6 + 4-0 of 3" oak plank 30 pr. super 40		3	26
		5.3 of 4x3 oak	8		36
		4.0 of 3 $\frac{1}{2}$ x3 "	7		24
		3.6 of 4x3 deal	8 4 $\frac{1}{2}$		24
		8.6 of 4x2 deal	5		36 $\frac{1}{2}$
		3.0 of 6 $\frac{1}{2}$ x1 "			13
		3 lbs. nails, 1 lb. 1 lb. paint 1 $\frac{1}{2}$ 2 nails 3 ^p			211
	7	10 $\frac{1}{2}$ hrs. put new part piece to waggon		10	6
		5.3 of 3x3 $\frac{1}{2}$ oak	7		31
		20. c.s. nails 5 ^p paint	7		10
		repairing ironwork 12/6			126
			<u>£</u>	8	41

Woodbury Churchwardens

1919

Aug.	6 hrs. overhauling & re-fitting bearings & fittings of bells. & putting stunt to roof of tower		4	5	0
	3- 2" screws, 4 washers				4
	4-6 of 5 + 4 1/2 inch stout	1/5 1/2		6	7
	1- 7" spike				6
	Castor oil, 11- sweet oil, 11- candles			2	3
	taking over & fetching gear			1	6
	8 hrs. take down & paint flag pole			10	0
	5 lbs. paint, 5/10 2 lbs. pulley 8			6	6
July 12	4 hrs. fit flag line	}		4	6
	1 new flag line			5	6

 £

 6 2 8

Mr. J. Clavill. Rydu Farm.

1919

June 30	25 lbs. ring broad wheel		1	2	4
	6. 4 1/2" elm felloes	4-		6	0
	2 new 4" tyres 154 lbs.	7 ⁰⁰	4	9	10
	6 dowels				6
	paint			1	0
	1 staple for wheel				3
			<hr/>		
			5	19	11
			<hr/> <hr/>		

5 19 11

Mr. Collier

July 7	15 lbs. take off ring, put on wheel			15	6
	5. 2" ash felloes			5	0
	new 1 1/2 x 1/2 tyre 20 lbs.	7 ⁵⁰		12	6
			<hr/>		
			1	13	0
			<hr/> <hr/>		

1 13 0

Mr. Samuel Skinner

Sep. 8	To cleaning, staining & varnishing Greeness Car			3	10	0
			<hr/>			

3 10 0

Mr. Best Stamps

July 10	sharp saw		9
7	2 box ions 5 lbs.		50
31	4 1/2 hrs. alter front board of trap		46
	alter innwork		30
	alter step		20
	6. screws		3
Aug	new canvas To cleaning, painting & varnishing dog trap	4	10 0
	To re-rubbering 2 wheels	4	5 0
21	new draft pin		1 2
Sep 24	repair photo frame & put in glass		1 6
		£	9 13 2

Woodbury Public Hall Co. Ltd.

July 21	8 hrs. repair chairs		80
	18. 2" screws		6
Sep 15	3 hrs. repair door & gate		30
	2. 3 + 1/4 bolts. 3. 2" + 4. 1 1/4" screws		6
		£	120

Mr. B. Harding

1919

Sep 13	To painting car	3 0 0
	To new front board	5 6
		<hr/> 3 5 6 <hr/>

Sep 13	Mr. C. H. Stamp, Topeka	
	To painting & lettering car	3 0 0
	To new tailboard & repair bottom	1 5 0
	To repairing axle bolts	1 0
		<hr/> \$ 4 6 0 <hr/>

Mr. D. Channon, Greendale Dairy

June 25	17 lbs. repair 2 wheels		17 0
	3. 2 1/2" ash felloes		3 9
	1 spoke		.. 8
	tyring 2 wheels	14/-	14 0
	2 rivets	4. ^o	4
		1-15-9	
	To making new body & shafts for market trap. + painting & stripping		14 10 0
			<hr/>
			£ 16 5 9
			<hr/> <hr/>

Mr. W. Hawkins, Black Hill

Aug.	34 lbs. ring cast wheels 11 ²		1	11	2	
	12. 3x3 ash felloes tyring 2 wheels	2-6-0		15	0	
	29½ lbs. put new tips to shafts, repair front & tailboards & re-ty wheels 11 ²		1	7	0	
	5-0 of 3x3 ash	7		2	11	
	2-3x3/8 bolts				5	
	3-2x1/4				3	
	3-2½x3/8				5	
	4-1¼ screws, hoop iron re-ty				6	
	2 Keys for lip eyes				6	
	cutting & shooting 2 stock loads, 2				.	
	new strap plates, 1 plate iron, 2 new				.	
	ends & nuts for shaft staples 8 lbs ½ 2-0-6			8	6	
	To painting cart		3	0	0	
			<u>1</u>	8	0	6

1919 Mr. J. Handford

July	5	sharp pick		6
	11	do		6
	14	lying pick		26
Aug	1	sharp pick		6
	6	do		6
	25	do.		6
		repair pick		3
	27	sharp pick retrace up eye		9
	29	soldering can		9
Sep	17	repair pick		6
	18	lying pick		26
	24	do.		26

1123

Mr. Edgar Ware

Aug	1	tyring 2 waggon wheels		140
	30	repairing hook		16
Sep.	11	2 hrs. make draft, repair ironwork		50
	19	6 hrs. repair field gate	5/-	
		1 new top bar	2/6	
		5 bars & braces	6/3	
		2 lbs. 2 1/2" put nails	3 ³	140

11146

Mr. J. G. Miller

July 24	2 lbs. put in glass 1 lb. putty	}			2 6
Sep. 18	9 1/2 lbs. put in glass. paint window 5 pip plumbing			11-	8 8 1/2
19	9 lbs. do.			8 3	
20	3 1/2 lbs. do.			3 2 1/2	
22	1 1/2 lbs. put in pump sucker			1 4 1/2	
	3 lbs. paint			3 6	
	3 lbs. putty, glass paper			1 2	
	12. C.S. nails			3	
	6 shutt screws			4 1/2	
	3 panes 21 oz. glass			18 0	
	3 shutt cramps			2 0	
	re-leathering pump sucker			2 6	
			£	2 11 10.	

Rev. Henry Hammond
The Rectory, Stockleigh Pomeroy

Sep 19	To 4 bell ropes ea. 60 ft. long at Carriage			5 12 0
				2 3
			£	5 14 3

Wm A. Fitzwarren Smith, Ferrants.

Aug 8	33 hrs. make waggon shaft		1	13	0
	9-6 of 12 x 2 1/2 ash	118		15	10
	repair shaft ironwork 2 hrs.			2	0
	repair bolts, 2 plates, 2 wangs			4	2
	alter & repair iron	2-18-0		3	0
	4 1/2 hrs. repair wheels			4	6
	1. 2 1/2" felloe ash			1	0
	tyring 1 wheel			5	0
	3 new tyres 94 lbs. 7 1/2"		2	18	9
	take off wheels 1 hr			1	0
	repair waggon 9 1/2 hrs			9	0
	4 washers, 2 6 nuts, 6 2. 4 x 3/8 bolts 6			1	2
	part new eye, 4. 3 nuts, 3 0-			1	3
	1 square staple 3 0- 2 keys 6 0-			9	5
	1-6 of 3 x 1 deal				
	4 large, 2 small collar, raling 1-3-6			10	0
	To cleaning & painting waggon 3 coats.		4	10	0
	To 1 seat board			3	0
	To 3 hoops on cart			1	6
			£	12	5 3

Mr. Samuel Cornish

Aug. 17	1 new waggon wheel tyre $2\frac{1}{4}$ " 49 lbs. 7 ⁰	1	8	7
20	tyring 2 trap wheels		14	0
	repairing step of trap		3	0
	oiling & putting on wheels		2	0
		$\frac{1}{2}$	2	77
Mr. T. Geanill, Brewery				
Aug. 25	28 hrs. put in new trap shafts		1	58
	1 pair bent ash shafts		1	00
	3-0 of 2x1 $\frac{1}{2}$ ash bar		..	6
	8. 2 $\frac{1}{2}$ x $\frac{1}{4}$, 4. 2x $\frac{1}{4}$ bolts. 6. 1 $\frac{1}{2}$ screws		1	15
	1 lb. paint		1	3
	2 shaft tips		1	3
	repair & alter steps, 2 hrs.		2	6
	4 bolts.		1	0
	1 new step plate		1	3
	tyring 1 wheel		7	0
		$\frac{1}{2}$	3	16

Messrs. Jarman Bros.

July	11	repair hp of stove			1	3
	5	Take range from Station to Halfway			8	0
	7	man & 2 horses working field		1	2	6
Sep.	5	$\frac{1}{2}$ load from beneath			4	0
	26	man & 2 horses working field		1	2	6
	30	Horse Wagon to beaker			1	0

£ 3 12 3

Mr. C. Summerfield

Aug	14	Man & horse 1/2 hr. hounding rats	3 0
	18	2 loads sand	4 0
	20	Topsham for lime	7 0
	28	2 loads bricks from Exmouth	14 0
	29	Topsham for lime	7 0
	30	3 loads sand	6 0
Sep.	3	2 loads bricks	14 0
	18	Topsham for lime	7 0
	20	3 loads sand	6 0
July	3	repair window stay	. 6
Sep.	8	1 bolt for pump	1 2

£ 3 9 8

Mr. J. Pyne, Bellakee.

1919

£ s d

July	7	repair trap wheel bolt.			..	6
	17	7 hrs. put in glass. ^{take of} repair locks r.			7	0
		5 panes glass			3	0
		2 lbs. putty			..	8
		repairing lock, new part to window stay			3	0
Aug	9	1 pair breechin staples & piping			2	3
	19	1 nail pin chain			1	0
	20	tyring 1 wheel 2 type			7	0
		1 new type 1 1/2 x 1/2 33 lbs. 7 1/2		1	0	7 1/2
	22	3 hrs. repair ash board & put on shepp clip.			3	0
		1 clip			1	0
	25	12 hrs. put in 1 felloe, & chip around wheels & paint wheels		
		1 ash felloe			11	0
		1 1/2 lbs. paint			1	0
		2 new types 2 1/2 x 1/2 97 lbs. 7		2	16	7

£ 5 19 1 1/2

C. Dany. Esq. Knoll Cottage

£ s d

1919

June 25	cleaning out cesspit			15	0
July 11	repair mower			1	6
30	lock spring				6
				<hr/>	
			£	17	0

Lieut. Col. Marshall. Oakhayes

July 31	Pony trap to Station			2	6
Aug. 17	1 sheep stop			1	0
Aug. 29	Carting chairs			4	0
Sep. 2	do.			4	0
15	Pony trap to Station			2	6
16	do. Lympstone			3	0
24	do. Station			2	6
				<hr/>	
			£	19	6

Mr. W. Sage. Venmoor.

1919

F o d

Aug 14	2½ hrs. 2/6. 1. 4½ + 3/8 bolts, 3°			
	5-0 of 3½ + 1 elm, 10° nails 2° for lade			3 9
Sep. 4	fellu settle 1/6			
5	5 hrs. repair settle			
6	6 hrs. do.			
17	3 hrs. do.			
18	5 hrs. do. 19 hrs.	19-0		
	floor board, 2 turnbuckles, screws & nails	11-0		1 10 0
	16½ hrs. clean paint & grain settle	16-6		
	3 lbs. paint	3-6		
	-varnish	2-6		1 2 6
17	man 9½ hrs.			
18	9½ hrs.			
19	9½ hrs.			
20	6 hrs. 34½ hrs. 11½°			1 18 7½
	2 strap plates, 2 bolts & plates			6 0
	4. 6 + 3/8 bolts & washers			1 4
	17-0 of 2 x 1 battens			2 1½
22	9½			
23	9½			
24	9½			
25	9½			
26	9½			
27	6 - 53½ hrs. 11½°			2 9 0½
	9 lbs. pat. nails			4 6
	5 lbs. cut nails			2 1

7 13 2
~~7 16 7½~~
 7 12 11½

Mr. C. Summerfield (Lower Bagmoss).

Sep	15	4 hrs	making Mr. C. seat brackets			
	18	4½	door + jambs, + window			
	19	8 hrs.	frame + light for			
	23	9½ hrs.	Lower Bagmoss.			
	24	4½ hrs.				
	25	2 hrs.				
Oct	7	9½ hrs	42 hrs.		2	20
		materials			2	13 4
					<hr/>	
					£	4 15 4

H Stokes in ap. with Mr. A. Stamp

1919

July	7	1 horse 1 day			
	25	do			
	30	do.			
Aug	20	do.			
	22	do.			
	27	do.			
Sep.	1	do.			
	15	do.			
	16	do.			
	22	do.			
	24	do.			
	25	do.			
	26	do.			
	29	do.			
Oct.	3	do.			
	8	do.			
	9	do.			
	14	do.			
	15	do.			
	16	do.			
	17	3 hrs.			
Nov.	5	$\frac{1}{2}$ day			
	6	1 day			
	7	$\frac{1}{2}$ day			
	17	1 day	23 $\frac{1}{2}$ day.	6/.	7 1 0

Mr. A. Stamp

Aug 2	sharp saw	✓		9
25	6 hrs. make door joints	}		60
26	1½ hrs. do.			16
28	1½ hrs. fix dr.			16
	17-0 of 4x3 deal		11½	163½
	2 nails			3
	1 lb. paint			12
	6 slips		1-7-2½	6
	1 square for desk + 4 screws			7
Sep 3	sharp 2 saws			16
	6 hrs. repair garden door			60
4	9½ hrs. do.		96	
5	4½ hrs. do.		46	
	5-9 of 2x8 deal	11	63	
	4-0 of 7x¾ match	4	14	
	20-6 of 2x4 for brackets, 6 nails	5	87	
20	6 hrs. make door	7	60	
22	6 hrs. do. hang garden door		60	
24	3 hrs. repairs		30	
25	9½ hrs. "		96	
26	9½ hrs. "		96	
27	6 hrs. "		60	
	40-0 of 7x1 match	5	168	
	10-0 of 8x1 ledge	8	68	
	4-6 of 7x¾	4	16	
	1 lb. nails		6	
	1 pair 18" H. Tee hinges		50	
	18. 1¼ screws		4½	
	1 Norfolk latch complete		19	
	18. R. H. screws		4½	
	1½ lb. paint	2-0-7	19	
	2 gate latches + 24 screws.		86	
	forward	£	793½	

		forward		7	9	3½
sep	29	7½ hrs.			7	6
	30	9½ hrs.			9	6
Oct.	1	19 hrs.			19	0
	2	19 hrs.			19	0
	3	19 hrs.			19	0
	4	10 hrs.			10	0
		6. 4½ x 3/8 bolt			1	6
		1. 2½ x 1/4 "				1
		18. 1½" clouts				4½
		1 pair 4" butt. hinge			1	2
		3 plates iron, 3 holdfasts			3	6
	6	9½ hrs.			9	6
	8	7 hrs.			7	0
	9	8½ hrs.			8	6
+	10	9½ hrs.			9	6
	11	3 hrs.			3	0
		3 lbs. nails			1	6
		2 lbs. paint			2	4
		18. 0 of 4x2 oak post. for fence	5		7	6
		1 staple. 1 bolt			1	3
	13	6½ hrs.			6	6
	14	9½ hrs.			9	6
	15	5 hrs.			5	0
		4 large washers for door			3	0
		11-0 of 7x1 red deal	6½		6	0
		4-9 of 7x3/4 "	5		1	10
		2 lbs. nails			1	0
		9-0 of 7x1 match	5		3	9
		2 lbs. paint			2	4
		4-0 of 2x7	1-		4	0
		1. 3½ x 3/8 bolt				3
		50-0 of 4x3 oak	8		2	0
		forward	£		18	13
						2

	forward		18	13	2
	12-0 of 4x4 oak	11		11	0
	7-6 of 6x6 oak	2 1/2		16	3
Oct. 17	9 1/2 hrs. painting			9	6
18	6 hrs. "			6	0
20	5 hrs. "			5	0
21	9 1/2 hrs. "			9	6
22	9 1/2 hrs. "			9	6
23	9 1/2 hrs. "			9	6
25	1 1/2 hrs. "			1	6
	2 hrs. letter gates			2	0
	13 lbs. paint			15	2
	2 1/2 lbs. putty				10
	2 sheets glass paper	3-8-8			2
25	4 hrs. take down cisterns			4	0
31	13 hrs. piping cisterns			13	0
	2 new cisterns	13/-	1	6	0
	1 valve rubber				6
	3 lead washers	2-3-9			3
Oct. 9	6 1/2 hrs. put new side to barrow			5	5
10	1 1/2 hrs. do.			1	3
	1 new ash side	11/-		2	0
	1/2 lb. nails				4
	tyring barrow wheel			2	0
			7	26	3 10

Lieut. Col. Marshall, Oakhays

1919

Sep.	2	1 hr. measure fence in Lane			
	23	15½ hrs. fit do.			
	24	17 hrs.			
	25	19 hrs.			
	26	19 hrs.			
	27	12 hrs.			
	29	15½ hrs.			
	30	19 hrs.			
Oct.	1	16½ hrs.			
	2	14½ hrs.			
	3	19 hrs.			
	4	12 hrs.			
	6	13½ hrs. 19 3½ hrs.	9-13-6	9	13 6
	7	7-6 of 7x7 oak post	3/1	1	3 2
		7-6 of 6x6 do.	2/3		16 10
		136-0 of 4x4 do. return 24 posts 12 mts	11 ²	6	4 8
		4-0 of 6x4 " sleeper	1/6		6 0
		3 lbs. galv. staples	11		2 9
		28 lbs. " wire	8		18 8
		3 gals. tar			2 0
		12 lbs. of iron for stand retaining eyes			4 0
		2-2½ x 3/8 bolts			5
		1 lb. nails			6
		4-0 of 2x1 battens for steps	9-19-6		6
	7	19 hrs. rehang iron gates			
	8	19 hrs. do.			
	9	3 hrs. do. 4 hrs.		2	1 0
		14 lbs. iron for 2 bands & 2 stays			4 8
		making & fixing new catch to gate			7 6
		repair work of wicket gate			1 3
		2 oak blocks	2-15-5		1 0
		forward	22-8-5	22	8 5

1919	forward	22-8-5	22	8	5
Dec. 11	1 hr. measure netting gates				
13	4½ hrs. make hang of paint				
14	9½ hrs. "				
15	8½ hrs. "				
16	9½ hrs. " 33 hrs. at 10°		1	7	6
	2 holdfasts			1	0
	9-0 of 11x1 deal		10½	7	9½
	6-0 of 3½x5/8 "		4	2	0
	6-9 of 3x2 plank		4	2	3
	46, 1" screws			1	0
	2 pairs 10" Tee hinges			1	9
	wire netting 4/3 nails 3°			4	6
	paint	2-9-0		1	3
17	sharp saw			1	0
	repair fire screen	3-6		2	6
27	6 hrs. make gate				
28	8½ hrs. "				
Nov. 7	9 hrs. hang "				
8	5 hrs. " 28½ hrs.			1	8
	4-0 of 4x3 deal		11½	3	10
	8-0 of 4x2 "		6¼	4	2
2	4-0 of 3x2 "			1	8
	14-0 of 7x1 " pale		6½	7	7
	2. 3½x5/8, 1. 1½x¼ bolts			7	
	6. 1½" screw			1	5
	14-0 of 4x4 oak plank (2)		11	12	10
	2 lints, 1 latch, catch & guide 7 lb.			7	0
	2 lbs. paint, 2/6 ½ lb. nails	£ 3-9-0		2	9
	mason repairing wall and steps				
	+ lime stone quoins at Lawn Gates			1	13
20	Pay map to station 2/6 to Exmouth 4/6			7	0
27	do 3/6 Dec. 6. station 2/6			5	6
		£ 30-15-8	£	30	15
				8	

1919 Rev. Glynne Inylds. The Vicarage, Sheldon £ s d

Nov. To clearing out the old frame, floor beams, and putting in new oak frame beams & re-hanging the 2nd bell in Sheldon Church Tower as per estimate of May 9. 1919 65 0 0

Credit by Old bell

gross weight 7c. 2q. 12 lb.

less old iron staple 4 lb.

Nett. 7. 2. 8

7c. 2q. 8 lb. at £6-5-0 = 47-6-6

less Rail carriage to London

19-6

breaking up & lowering bell

from Tower 1-0-0 1-19-6

45 7 0

£ 19 13 0

Received Dec. 17. 1919 £10-10-0 on a/c.

B. Godfrey Esq. Willamhead, Woodbury, Salterton

1919

			£	s	d
Nov. 10	150-0	of 2x1 battens	1	0	3
	120-0	of 2x3 paper	2	0	0
		$\frac{1}{2}$ gal. essence			9
		delivery		3	0
Dec. 6	58-6	of 7x3/4 match		19	6
	20-0	of 2x3 paper		6	8
		delivery		3	0
			<u>7</u>	4	13 2

Mr. C. Sumnerfield

1919

£ s d

Nov.	17	10 hrs.							10	10
Dec.	1	1 1/4 hrs.	2 1/4 hrs.	make glass prime 2					15	2
				lights for Hogsbrook						
				5-0 of 9x1 1/2 dead						50
				12 panes glass 7x9 ea.						46
				3 lbs putty priming						16
				1 pair 2" bolts screws						6
				1 hook rope						1
				1. 10" stay			1-18-2			7
	30	9 hrs.		firing racking out frame piping 91-						90
Dec.	8	2 men 9 hrs. ea.		putting in new floor						
	9	2 men 9 hrs. ea.		joists at Bee View						
	10	2 men 9 hrs. ea.		skirting 54 hrs.					2	14 0
				3 lbs. priming						2 6
				6 lbs. floor brads.						3 0
				5 lbs. nails						2 6
				36 8-0 of 7x1 floor			4 1/4		5	12 7 1/2
				135 .. 0 of 4x2 joist.			4 3/4		2	13 5
				44-0 of 4x3 plates		11-1-1 1/2	7		1	5 8
				9-0 of 2x3			3 3/4			1 10
				47-0 of 7x1 O.C. skirting			4 3/4			18 7
Dec.	8	27-0 of 7x1 floor					4			9 0
				3 bales. paint laths						16 6
Nov.	18	2 hrs.		put up shed at Mr. Hicks						
"	19	1 1/2 hrs.								
"	20	18 hrs.								
	21	16 hrs.	13 hrs.	17 1/2.						
"	22	12 hrs.								
	24	9 1/2 hrs.								
Dec.	3	13 hrs.	8 3 hrs	4-3-0					4	3 0
				17 lbs. nails						8 6
				6 wall plate ins., 12 nails 14 lbs.			16-6			8 0
				found						
									22	7 3 1/2

1919			£	s	d
		forward	22	7	3½
Oct	2	carting 1 load gravel from Exmouth to Yard	9	0	
"	7	Three Waggon to Exeter Exmouth	16	0	
	10	1 load sea gravel, " to Heathfield	16	0	
	18	do.	16	0	
	23	carting lime sand to Woodmanton	16	0	
	24	do. bricks do.	16	0	
	27	" cement & gravel Exm. to Heathfield	16	0	
	29	Carting bricks to Yard 1 day	16	0	
Nov.	8	" 1 load gravel Exmouth to Yard	9	0	
	18	" do to Woodmanton	9	0	
	19	" 1 load gravel 1 load bricks 1 day	16	0	

£ 30 2 3½

Paid Feb. 13/20

Mr. C. Summerfield
Combe Park

1919			£	s	d
Dec.	23	1 load sea gravel	16	0	
	29	do.	16	0	
	30	do.	16	0	
Jan.	5	1 load cement r.	16	0	
	28	1 load sea gravel	16	0	

£ 4 0 0

1919 C. Dairy. Exp.

£ s d

	To acc. rendered			17 0
Oct. 1	Carting manure 1 day			16 0
20	do.			16 0
Nov. 28	Carting 3 loads gravel			9 0
Dec. 3	" 1 load turf, 1 load gravel			6 0
Oct. 6	55-0 of $6\frac{1}{2} \times 3\frac{1}{4}$ planed 2 sides	4 $\frac{1}{2}$	1 0	7 $\frac{1}{2}$
22	1. 18rd. ladder			
	1. 14rd. ladder 32rds. at $2\frac{1}{4}$		3	14 8
Nov. 10	18 hrs. remove problem, repair shed	}		
11	18 hrs. hang ladders 3			
12	18 hrs.			
13	18 hrs.			
14	18 hrs. 90 hrs.			4
	25-0 of 2x3 for post.	4		8 4
	2 lbs. nails ^{1 lb.} wire ^{10^s} cuts ^{1 lb. 6^s}			1 4
	7-0 of 7x3 oak cart-block	1/3		8 9
	4-0 of 4x4 oak "	"		3 8
	4 spikes			1 0
	4 shut bolts, 8. 1 $\frac{1}{2}$ screws			5
	2. 5 $\frac{1}{2}$ x $\frac{3}{8}$ bolts.			7
	7 brackets for ladders			7 0
18	3 hrs. abrad bells strap reeve _{dim} 3-9	}		
21	2 hrs. do. 2-6			
	1 $\frac{1}{4}$ lbs. Salomoniac 1-6			
	3 Zincs 1-9			9 6
	29 hrs. make garden boxes 1-9-0			
	180-0 of 7x3/4 4- 3-0-0			
	3 lbs. nails 1-6			
	24-0 of 2x1 battens 2-6		4	13 0
	1. 20x38 Interior Gate with brass canopy 5 13 6			
	12. Inured green tiles 12 0			
	Summerfields hill piping 2 13 6 $\frac{1}{2}$			
	forward	£	29	1 11

	forward	28	1	11
	2 iron bars for chimney. 4 eyes & 2 stays			
	for posts			90
Oct 15	Summerfield repairing slates			69
		<u>7</u>	28	178

Mr. W. Sage, Vermont.

1919

Oct.	6	9 1/2 hrs. repairs			
	7	9 1/2 hrs.			
	8	9 1/2			
	9	9 1/2			
	10	9 1/2			
	11	6 hrs. 53 1/2 hrs.		2	9 0 1/2
	12	6 1/2 lbs. put. nails			3 3
		6 lbs. cut nails			2 6
		1. 10" Taper bolt.			1 0
		6. 3/4 screws			1 1/2
		1 smaller catch			2 1/2
	13	9 1/2 hrs.			
	14	9 1/2 hrs.			
	15	9 1/2			
	16	9 1/2			
	17	9 1/2			
	18	6 53 1/2 hrs.		2	9 0 1/2
		5 lbs. cut nails			2 6
		3 doz. screws. 4. 2 screws			.. 11
		6 lbs. paint	1/2		7 0
		1 ring + eye. 2 plate dowel			3 6
Nov	4	9 1/2 hrs.			
	5	9 1/2			
	6	9 1/2			
	7	9 1/2			
	8	6 44 hrs.		2	0 4
		12 lbs. nails			5 0
		5. 2 1/2 x 3/8. 10 1/2 4. 3 1/2 x 3/8 bolts 12			2 2 1/2
		1 catch + 1 guide (small)			5
		2 pairs glass 7 x 6 1/2 ea.			1 0
		12. 1 1/2" screws			3

forward

7/2

8 8 3 1/2

1919

		forward		8	8	3 1/2
Nov.	10	9 1/2 hrs.				
	11	9 1/2 hrs.				
	12	9 1/2				
	14	9 1/2				
	15	5 1/2	43 1/2 hrs.	1	19	10 1/2
	17	9 1/2				
	18	9 1/2	19 hrs.		17	5
		2 lbs. nails				10
		6 shank screws				4 1/2
		1 lb. putty				4
				<hr/>		
				11	7	1 1/2
				<hr/>		

Mr. W. H. Stamp

1919

7 0 d

May	14	man's time pulling up bridge + 6 spikes			12 0
Oct	20	17 hrs. take down shed, pulling up shed			
	21	19 hrs. repairing rail fence 13			
	22	19			
	23	19 74 hrs		3	14 0
		17-0 of 2x1 battens			25
	27	19 hrs.			
	28	19 hrs.			
	29	19 hrs.			
	30	19 hrs.			
	31	19 hrs.			
Nov -	1	12 hrs. 10 7 hrs.		5	7 0
		11-0 of 4x2 rafter	5		4 7
		40-0 of 3x2	4		13 4
		25 galv'd nails			6
		15 lbs. mixed nails	5		6 3
		12. 3 + 3/8 bolt washers			2 6
		2. 3" staples			3
		14. 2" screws			5
	3	19 hrs			
	4	9 1/2 hrs. 28 1/2 hrs.		1	8 6
		2. 5 1/2 x 3/8 bolts			7
		1. 7" Tower bolt			1 0
	17	9 hrs. fencing			
	18	9 hrs. 18 hrs.			18 0
	25	4 1/2 hrs. pit planting on shed			4 6
		3. 6 pr. 6 1/2 x 18 / 10 1/2 r 1. 2 pr. 2 3/4 4" planting		1	1 2
		5 white screws. 1/2 lb. pulley			6 1/2
		12 lip end			8
		4 cramps			2 8

15 3 10

Mr. R. Pyne, Greendale

1919

£ p d

July 14	1 new nose band for wheel 3/7				
	cutting 1 nose band 9° 2 hrs			3 9	
16	cutting & phosting 4 2 1/2" tyres			1 8 0	
	do. 1. 4" tyre			9 0	
	repairing side of waggon, & lade eyes			. .	
	5 hrs. 1 plate of iron 4 lbs.			7 0	
	2. 4 x 3/8 bolts			. 6	
	new lynch pin			1 0	
Aug 18	17 1/2 hrs. ring broad wheel			17 6	
	1 new 4 1/2" tyre 78 lbs.	7°		2 5 6	
	6. 4 1/2" elm felloes			7 0	
Aug 25 in Sep 1	4 hrs. putting new pole & draff			}	
	+ seat to roller				2 1 0
	1 oak pole				10 0
	1 oak cross bar				1 0
	4-0 of 3 1/2 x 2 ash draff				2 0
	6-6 of 3 x 1 1/2 do.				2 0
	4. 5 x 1/2, 2. 4 1/2 x 7/16 bolts 7				2 0
	44. 1" screws				1 0
	1 seat				3 6
	paint	4-18-0			2 6
	22 hrs. making & altering ironwork				1 2 0
	30 lbs. new iron				10 0
	cutting 4 bolts			1 0	
Sep 10	29 hrs. put pole to drill			1 9 0	
to 25	pole, draff, bolts 15			17 0	
	2 hrs. making ironwork			1 1 0	
	18 hrs. cleaning drill			19 0	
	25 lbs. new iron			8 4	
	13 coulters, 13 bolts	3/6	2-5-6	2 5 6	
	fixing coulters 3 hrs			3 0	
Dec. 11	new cop. pin & plate, 2 staples & clips for draff			11 6	
	forward			18 11 7	

Mr. Edgar Ware

1919

£ o d

Sep. 29	9 hrs. repair lades			
30	6 hrs. do.			15 0
	5.0 of 2x7 ash lade side	11 ^o		4 7
	3.0 of 2x3/4			3
	1. 6", 1. 4", 1. 3x3/8 bolts	£ 1-0-8		10
Dec. 11	3 hrs. take off car shaft			
22	1 hr. put in shaft			
23	9 1/2 hrs. do.			
29	4 1/2 hrs. do		18 hrs.	18 0
	1 ash shaft			17 0
	repair shaft, immortals			2 6
	paint			- 6
31	7-6 of 10x1 dry oak 6-3 at 10 ^o			5 3
		7		3 3 11

Mr. J. C. Miller.

Oct. 8	re-leather pump sucker			3 0
9	sharpen 2 saws			1 6
Dec. 1	2 hrs. repair pump			2 6
15	put in 2 hatchet handles			2 0
				9 0

Woodbury School

£ s d

Aug	7 hrs repair, paint + enamel cupboard	8 9
	6. 1/4 screws 1 1/2, 1 lb. paint 1/3, enamel 6 ^o	1 10 7
	rope + putty	5
		11 0
Oct. 25	13 1/2 hrs. put in glass	14 0
	3 lbs. putty	1 0
	5 panes pattern glass	11 9
	£ 1.6-9	
	£	1 17 9

	Mr. C. Stamp. Woodbury House	
Oct. 11	repairing trap seat	3 6
	stopping leaks in gutter	2 0
Dec. 2	putting in glass + keeping up plumbing	2 0
	£	7 6

	Mr. Samuel Skinner	
Dec. 21	4 hrs. fit up trough	4 0
	1 1/2 lbs. pat. nails	9
	£	4 9

1919 Mr. J. F. Gilman, Rydon Farm

		£	s	d
Oct. 25	To clearing and painting cart	3	0	0
	New hole for top boards, & plug in wheel		1	6
		£	3	1 6

Mr. Bert Stamp

Oct. 13	new flat iron		2	6
21	sharp saw		·	9
Nov. 8	1 plough piece		1	9
10	4 lengths in chain		1	0
Dec 4	putting new rail to tailboard & 2 chains & rings		6	6
	repair paint ladder 2 coats		10	0
8	sharp saw		·	9
16	do		·	9
31	do.		·	9
		£	1	4 9
6	repair chair		·	9
		£	1	5 6

Rev. Dr. Telford

1919

Nov. 17	36 1/2 hrs. make new window &				
to 29	light,			1	16 6
	13-6 of 4x3	11-			13 6
	4-6 of 9x2	1/5			6 4
	3-2 of 9x3	1/11			6 3
	6 panes glass 11x11 ea.				4 0
	1 lb. putty				4
	2 pairs 2" lute screws				1 0
	2. 10" window stays				1 2
	2 cranked bolts				1 6
	1 fastener				8
	priming	1/6			1 6
	3-0 of 5 1/2 x 1 pole board	3-14-1			1 4
Nov. 18	repair stove & clean				2 9
Dec. 11	9 1/2 hrs. take out old & fix new window				9 6
12	8 hrs. put in glass, lacing window &				8 0
	1 pane glass 9x11 & putty				9
22	3 1/2 hrs. paint window				3 6
	2 lbs. paint				2 6
Oct. 29	2 hrs. take off & put on carriage wheel	2/6	}		
	lengthen & repair 6 wheel bolts	3/3			
	oil for wheels	3			6 0
				£	5 7 1

Mr. A. Fitzwarren Smith. Tarrants.

1919

Oct. 24	9 $\frac{1}{2}$ hrs. repair cart wheel	9 6
	6 hrs. put point on shafts.	6 0
25	3 hrs. wheel	3 0
	3. 4 $\frac{1}{2}$ elm felloes	1 2
	1-6 of 3 x 3 ash shafts	9
	4. 4 x 3/8 bolt.	1 0
	paint 6 $^{\circ}$	7
	1 plate iron 2 $\frac{1}{2}$ lbs.	2 6
	tyring 1. 4" wheel	9 0
	2 shaft crooks & piping	2 6
27	2 hrs. put in name & put on wheels 1-18-6	2 6
Dec 3	1 $\frac{1}{2}$ hrs. take off shafts	1 6
9	8 hrs. put in shafts	8 0
10	6 $\frac{1}{2}$ hrs. do.	6 6
	1. 4" bent ash shafts	12 6
	3-9 of 2 x 3 ash	1 3
	13. C-S nails. 1. 4 x 3/8 bolt	6
	paint 9 $^{\circ}$. nails 2	11
	Repair cart iron work 6 hrs. 6/6 } 2-0-0	6 6
	new plate of iron 5 lbs. 11 lbs } 1-19-8	2 6
	To acc. rendered	12 5 3
		<u>16 3 9</u>

Mr. H. J. Pyle: Parkhayes

Dec. 8, 9 & 10.	28½ hrs. repair mangers & 9 lbs. pat. nails		1 8 6 4 6
		1	1 13 0
	^{The close} Mrs. Anderson, - Wineford		
Oct 29 + 30	time 4 hrs. overhauling bell at - Wineford Church		3 9 0
	Railway fare		15 4
	Smiths bill for bolts & oil		11 6
	Candles, Nails & Oil		1 5
	Lodgings	1 5-1 3	4 0
	1. 6 Sp. bellevoye		1 11 9
			6-13 0
	Rev. G. R. F. Molinert, Colyton.		
Aug 21	man 12½ hrs. unhang tenor bell	1/6	18 9
	Rail fare		8 1
Oct. 22	men 24 hrs. rehang tenor bell		1 16 0
8	2½ hrs. fit up gudgeon		3 9
	Rail fare		16 2
	Smith at Colyton		1 6
	Oil 1/-, 1-bolt. 6 ^d . 2.C.S. nails		1 7
	1 new steel gudgeon		1 10 0
	Carriage of chain blocks		9 6
		1	6 5 4

Mr. W. Mantzoy, New Street, South Molton

To new clapper 25 lbs.	1/9	2	3	9
Shooting clapper			4	6
Carrriage			2	9
		<u>£</u>	2	11 0

Mr. Daniels The School House,
 Nov. 14 repairing chairs
 Paid

				5	6
--	--	--	--	---	---

Mr. A. Stamp Butcher

Dec. 11	To new leathering 4 waggon wheel			12	0
23	To oiling & collaring 1 wip wheel			4	0
				<u>16</u>	0

Mr. Abraham Harell

Nov. 13	1 hr. put in glass		10
	1 pane 13x13 putty		10
Dec. 2	3 1/2 hrs. 3 hrs 9/2, 9/2, 5, 1 1/2, 1 1/2, 8.		
10	16 5, 4 1/2 hrs make frame tight		2 6 6
	7-6 q 9x1 1/2	4-	7 6
	17-0 q 3x3	9 1/2	13 5 1/2
	8-0 q 3x2		4 0
	1 pair, 2 bolts screws		6
	1 hook eye, 1 stay		8
	2 lbs putty		8
	9 panes glass		6 0
	4-8 q 9x3 sill	1 1/2	9 0
	12. 1" screws.		3
	1 lb. priming		1 3
17	3 1/2 hrs. fix window		3 6
	3-0 q 2x4 deal blocks		1 3
22	4 1/2 hrs paint		4 6
23	5 hrs "		5 0
	2 lbs paint, 2/6 1/2 lbs putty 2"		2 8
	7 hrs. paint 2 window		7 0
	mason till fix window		2 6
			<hr/>
			6 18 2 1/2

Mr. John Pyne. Postlake. Woodbury

		£	s	d
Dec. 18	To making Coffin carrying at funeral	7	0	0
	Hearse & 2 Carriage	4	12	0
	Vicar, Clerk & Sextons Fees		10	6
	Gloves		6	0
	Ties		4	0
	Telegram		2	3
	<u>Paid</u>	<u>£</u>	12	14 9

Mr. John Pyne, Postlake, Woodbury

Dec. 2	repairing clothes horse		4	9
Nov 20	repairing manure drill		10	0
24	repairing plough, tying embers		1	0 0
	<u>Paid</u>	<u>£</u>	1	14 9

Jamaica Bros.

Oct.	3	man & 2 Horses working field	1	2	6
	8	do.	1	2	6
	9	do.	1	2	6
	11	man & 1 Horse (Sat.)		8	0
	13	To Remouth for timber		8	0
	14	man & 2 Horses working field	1	2	6
	15	do.	1	2	6
	16	do.	1	2	6
	17	man & 1 Horse 1 day sawing		14	0
Nov.	11	Cart 1 load gravel from Remouth		9	0
Dec.	16	1/2 load from Remouth		4	0
			<u>1</u>	8	18 0

Mr. Gibbons, Aylmer

Jan. To putting in 2 fellos in cart wheel
& new tyrePaid.

1 12 6

Mr. Gibbons, Aylmer

Feb. 5 To putting 3 fellos & 2 spokes in trap wheel
Cutting shooting tyre

1 1 0

6 0

1 7 0

Mr. Rowe.

Bengaluru.

Oct. 21	man horse 1 day		16	0
22	do.		16	0
Nov. 1	do 1/2 day		8	0
		£	2	0
May 24	curr. load of ash			26
		£	2	26

Mrs. Tom Lock

1920		£	0	0
Jan. 24	To making an elm coffin for the late			
Feb. 4	Mrs. Hawkins carrying out the funeral			
	arrangement		6	0
	Vicar's fee		2	6
	Clerk's fee		1	0
	Septon's fee		8	0
	Grave Bell			
	Removing & re-fixing headstone		2	6
	Payment to pit bearers		1	4
	Paid	£	7	18

May 21	To repainting 126 letters at 1 ^o		10	6
	To cutting & painting 150 letters at 3 ^o		1	17
	To cleaning headstone		5	0
		£	2	13

Mrs. Stokes, Senr. (Washington)

1919

Apr-	3	3 hrs.			
	4	6 $\frac{1}{2}$			
	5	5			
	7	9			
	8	9 $\frac{1}{2}$			
	9	9 $\frac{1}{2}$			
	10	9 $\frac{1}{2}$			
	12	5	57 hrs.	2	17 0
		12-0	of 8x12 window frame	41	13 0
		8-0	of 7x1	6 $\frac{1}{2}$	4 4
		12-0	of 2x1		1 6
	14	9 hrs.			
	15	9 $\frac{1}{2}$			
	17	9 $\frac{1}{2}$			
	19	5	33 hrs.	1	13 0
		2 lbs.	putty		8
		6	panes glass		53
		1	pair 2" bolts, 12 screws		6
		1	hook & eye		1
		35-0	of 7x1 floor	5	14 7
		1	pair 12" Tee hinge screws		13
		1	Nyork latch complete		8
		6	gutter bolts		3
		4	do. galv'd. screws washers		3 0
		4	shute cramps		1 8
		8	8 pr sheets galv'd. iron 8/9	3	10 0
		1	3 $\frac{1}{2}$ " outlet 2 stop ends		3 4
		2	6 pr. 3 $\frac{1}{2}$ " 2nd. gutter		10 2
		1	5 pr. do.		3 6
		123-0	of 4x2	2	9 0
		39-0	of 7x $\frac{3}{4}$ match		11 5
		102-0	of 7x $\frac{3}{4}$ floor	1	6 10
			forward	15	11 0

	forward		15	11	0
	34.0 of 2x3			11	4
	7 lbs. nails			3	6
	4 holdfasts			1	6
	9 lbs. paint			9	0
	1 window stay				7
Apr 12	9 hrs.				
23	9 $\frac{1}{2}$				
May 12	4 12 $\frac{1}{2}$ hrs.		1	2	6
	4 lbs. paint			4	0
Dec 4	4 hrs.			4	0
	6.0 of 4' $\frac{1}{2}$ rd pulley			6	3
	1 tripod				8
	2 holdfasts			1	4
	3 shut screws				1 $\frac{1}{2}$
	$\frac{1}{2}$ lb. putty				2
	8x8x1 elm				2
May 31	1 load sea gravel carting			9	0
June 13	do.			9	0
17	do.			9	0
	C. Summerfields bill for wall floor ^{2.00}		5	10	0
	3 bags cement		1	13	0
			27	6	1 $\frac{1}{2}$

Trustees (late 1880s)

		2 fire blocks	J. Lark had		46	
		15 lb. fire clay	for pipes		39	
Oct.		C. Summerfield, repair roof at Wildes James		100		
May		do. rebuild furnace & repair floor at Mrs. Davys		1126		
Apr	5	new furnace cover	Leach		66	
	19	5-6 of 3x3 1/2 oak	} garden gate		30	
		1 staple				6
		2 stop iron, 4 screws				6
		1. 2" butt screws				3
May	7	repair locks	James		40	
	15	whiten bedroom ceiling			50	
	29	repair door posts	table		40	
		2.0 of 5x5 oak			26	
		2. 4x3/8 bolt			6	
		whiten sitting room ceiling			100	
July	14	repair pit cupboard			39	
	25	2 1/2 hrs. repair roof	James		26	
		14.0 of 2x1			19	
		8.0 of 2x3			28	
		1/2 lb. nails			3	
		30 paint			76	
Aug.	1	2 pks. cement			50	
Sep.	24	1 2 pint pail			106	
		re-leather sucker	Globe tile		30	
Oct.	10	3 1/2 hrs. repair door	Smeath		30	
		1 set handle			29	
		2.6" spikes			6	
Nov.	16	new false bottom			76	
Dec.	9	solder can			13	
					795	

Rev. Henry Edwards. The Vicarage. Delabole

1920

Feb. 19	To one bell rope 60 pr.	1	8	0
	Postage			9
				<hr/>
				1 8 9

Paid. 19. 2. 20

Woodbury Public Hall Co. Ltd

Jan 29	repair shuting 4 ¹ / ₂ in	4	6	
	screws			3
Feb. 16	repairing piano	4	0	

				<hr/>
				8 9

Paid. 13. 3. 20

Mr. F. J. Hobbs, Peeds Farm, Kingsnympton

Mar 13	To one treble rope 60 pr. long	1	8	0
	Postage			9

Paid same date

				<hr/>
				1 8 9

Col. Marden Oakhays.

1920

Feb.	13	18 hrs.		
	14	11 hrs.		
	16	18		
	17	18		
	18	18		
	19	18		
Mar	2	18		
	3	18		
	4	3 140 hrs.		7 0 0
		26 posts, 5-6 long ea. 4x4 4/6 8 ea.		5 17 0
		41 0 of 4x3 posts	7 1/2	1 5 7 1/2
		3 lbs. nails		16
		1 1/2 gal. tar		10
		1 cw. galv. wire		4 9 0
		6 lbs. staples	11	56
		To erecting wire netting (3/4) fence		- . -
		stakes on Lawn Hedge		10 10 0
	31	To repairing pruners		3 9
				<hr/>
			7	29 134 1/2

Mr. Pineford, Exeter Rd. Exmouth

1920

Jan 9	To 1 bellrope 60 ft. long	1 8 0
-------	---------------------------	-------

Jan 9	Rev. Canon Bales, Newton & Gyre 3 Hand pieces for Pipes	1 9 6
-------	--	-------

Feb 4	Rev. P. A. Neuman, Hawkridge Rectory To 2 bellropes 60 ft. long ea. Postage	2 16 0 1 0 <u>2 17 0</u>
-------	---	--------------------------------

Feb 19	Rev. A. R. Hudson, Huntsham Rectory To 3 bellropes 60 ft. long ea. Postage	4 4 0 2 0 <u>4 6 0</u>
--------	--	------------------------------

Feb 27	Rev. D. C. Duncan, Citticham Rectory To 3 bellropes 60 ft. long ea. 7-8-6	4 5 6
--------	--	-------

Mar 22	Rev. H. Hugh Borton, Sheepstor Vicarage To 14 ^{1/2} 1/2 lb. chime cord 3/6 lb.	2 10 9
"	To 6 hand rubbers 1/3 ea.	7 6
		<u>2 18 3</u>

1920 The Churchwardens of Clyst & George £ s d

Feb. 9 To supplying and fitting 3 pairs
of springs, new felts & leathers, and
box wood pegs to the whole set, six
new straps, and tuning & cleaning
the set of 12 handbells 3 15 0

Paid

1920
May Rev. G. O. Apthorp, Rector
To recharging the tenor bell as per
estimate of Jan. 27. 1920 25 0 0

1919
~~July 15~~ ^{Aug 2} Mr. Henry Miller, Marsh Farm, Poughill
To examining & reporting on
Poughill Church Bells 1 1 0
Travelling expenses 7 6

1919
July 3 Mr. W. H. Bridgman, Marden, Paignton
To examining & reporting on Marden
Church Bells 1 1 0
Rail fare & trap hire 16 6

1920 St. Thomas Rural District Council

Jan.	15	Horse Waggon deliver timber to W. Salters		4 0
	20	man qhrs. fix bridge at Honey Lane		9 0
	21	man qhrs. do Cannon Walls		9 0
		16-0 of 6x4 oak beams	1/3	1 0 0
		32-0 super of 2" oak planks 8 pr.	8	1 1 4
		20-0 of 9x3 oak	1/8	1 13 4
		6-0 of 6x3 oak	1 1/4	5 7 1/2
		20-0 of 4x2 oak rails	5 1/4	8 9
		6-0 of 4x4 oak posts	10	5 0
		4 lbs. flat nails		2 0
		4. 6x3/8 bolts.		2 0
		2 bolts plates 4 1/2 lbs.	6-5-10 1/2	4 6
		4 spikes		1 4
	22	27 hrs. fix bridge at Creamery, Shles	}	
	23	18 bridge in Park fields at Pertain		
	27	11 Village, & post rails at		
Feb.	2	18. Cranford pond		
	3	18		
	4	18		
	5	1 1/2		
	9	18		
	10	18 147 1/2		7 7 6
		23. 6x3/8 bolts		7 8
		4 lbs. nails	2 0	
		3 bolts washers, & 4 spikes q lbs.	9 0	
		4 square staples	2 0	
		6. 1/2" bolts, 2 1/2" 6 coach screws 2 1/2	4 6	
		Straightening bar	1 0	
		Deliver timber	8 0	
	✓	12-0 of 5x5 posts	1/4	16 0
	✓	18-0 of 4x2 rails	5 1/4	7 10 1/2
	✓	15-0 of 4x4 stump	10	12 6
		forward	£	17 3 11

	forward			17	3	11
✓	6-0	of 9x1½	treads			40
✓	11-0	of 3x2	rail	3¾	3	5½
✓	5-0	of 3½x3½	posts	7½	3	1½
✓	5-6	of 4x2	rail	5¾	2	5
✓	5-6	of 3x2	.	3¾		18½
✓	36-0	of 12x4	bridge	2/10	5	20
✓	20-0	of 4x4	posts	10	16	8
✓	12-0	of 4x2	rails	5¾	5	3
✓	6-0	of 6x4	beams	1/3	7	6
	24-0	of 4x2	rails	5¾	10	6
✓	6-6	of 4x2	.	5¾	2	10
✓	4-0	of 4x3	posts	7½	2	6
✓	20-0	of 5x5	posts	1/4	1	68
Jan 24	11 hrs.	making changing				
26	5 hrs.	miked gate. posts &				
Feb. 11	9 hrs	rails at Farmington				
12	18 hrs					
13	2 hrs	45 hrs.			2	50
	3 lbs	nails				16
	2 hooks	twists	12 lbs.			120
	4.	5-6 of 4x4	22 p. posts	10	18	4
	1.	6-0 of 4x4	posts	10	5	0
		3-6 of 4x3		7½	2	2
		21-0 of 3x2		3¾	6	7
		7-0 of 4x2		5¾	3	1
	25.	3-6 of 2x1			9	4
		6-0 of 2x4	rail	5¾	2	7½
		deliver timber				80
			5-13.7½			
		forward		£	32620	

		forward		32	6	2
Jan	17	Oak stakes for Ford water			10	0
	30	6 oak stakes for Village			7	6
Feb.	19	8.			"	"
	20	1 1/2 Halpway + Aphaes Lane			"	"
	21	4			"	"
	25	3 1/2			"	"
	26	<u>9 + 5</u> ³¹ / ₂₆ hrs. repair paint sign post		1	11	0
		Fetching post 4/6			4	6
		Deliver do. 4/6			4	6
		7-9 of 6x6 oak	2/3		17	5
		2-0 of 5+1 deal				10
		4. 6x1/2 bolts				18
		3 lbs. paint	1/6		4	6
		nails. 1 1/2 lbs. putty 3-11-11				6
		letter post 7 doz. letters.			7	0
Mar.	5	7 1/2 hrs. make new doors. repair w/f.				
	8	8 hrs. new cover. put on corner				
	9	9 hrs. squares. + paint 2 crabs to				
	10	9 hrs. Sleeping Van				
	11	9 hrs.				
	12	9 hrs.				
	13	5 1/2 hrs.				
	16	9 hrs.				
	17	9 hrs.				
	18	9				
	19	9				
	20	5 1/2				
	22	9				
	23	9				
	24	<u>1 1/2</u>				
		118.	10-4-6		6	7
			forward	7	43	35
					10	5

forward		43	3	5
4-0 of 2x1 1/2 deal	9		7	3
16-0 of 2x3/4 match	4		5	7
4-0 of 2x1 ledge	6 1/2		2	2
12. 1 1/4. 8. 3/4 screws				5
1 key for lock			1	0
2. 2 1/2. 2. 3 1/2. 9. 4 1/2. 8. 5 1/2 x 3/8 bolts			5	5
4-0 of 2x1 deal	6 1/2		2	2
2-0 of 2x3				8
12-0 of 2x1			2	0
60 wire nails. 2 doz. clouts			1	0
15 lbs. paint	1/6	1	2	6
3 lbs. putty			1	0
4 corner squares for van 34 lbs.	9 0	1	5	6
		47	0	1
		47	0	1

Mr. W. Jaman

March May, plough garden. plough in
potatoes. & drag garden

June 14 laying matook

9 0

2 6

11 6

Rev. J. P. Harrison, The Rectory, Brendon

May 5	To 4 bell ropes	£ 1-8-0	5	12	0
	Postage			1	9
	Paid		£	5	13 9

Mr. J. R. Burgess, Chiltonhampton, N. Devon

May 12	To 4 bell ropes	£ 1-8-0	5	12	0
	Carriage			3	6
			£	5	15 6

Rev. E. C. Payne, Bickington Vicarage
Newton Abbott.

May 18	To fifty feet of bell rope		1	2	6
	Carriage				9
	Paid		£	1	3 3

Mr. W. M. Moulton, New Rd. South Molton

To repairing handbells as per estimate of Apr. 7. 20	net.	£	6	11	0
Paid					

1920 January. Bros.

£ . d

	forward		8	18	0
Jan.	6	1 horse Cart 1 day Castle Cottage		14	0
	7	do. do.		14	0
	12	do. 10 Bull Tame with poles		7	0
	23	1/2 load from Exceter		7	0
	29	1 load sea gravel Public Hall		9	0
	30	do. do.		9	0
Feb.	3	1/2 load from Exceter		8	0
	5	2 journeys to Topchan		16	0
	6	1 do.		8	0
	21	Wagon 2 horses with bricks to Italway		11	3
	21	1 horse Cart sand do.		7	0
	28	Wagon 2 horses bricks do.		11	3
Mar	10	1 horse Cart sand to Mr. Loran		8	0
	11	do. do.		8	0
	12	1 load from Exceter		16	0
	16	1 horse Cart 2 loads sand to Mr. Loran		16	0
	18	1 load sea gravel to Mr. Loran		16	0
	31	Chain harrow grass field to 1-30. x 2			
Apr.	7	Rolling grass field do. x 2			
	9	13 cov. cement r. from Exceter		10	6
	10	Rolling grass field x 3	1	10	0
	20	1 load sundries from Exceter		9	0
May	18	1 load sea gravel 10 Yard		9	0
June	11	1 load sea gravel 10 Yard		9	0
	22	2 horse load sundries from Exceter		16	6
Feb.	4	1 window square		5	3
Mar	15	2 bolts & 4 plates for Public Hall		6	0
				<hr/>	
				22	18 9

Mr. W. B. Stubbs, Coombe Park

1914

Dec.	16	cutting off & drilling bed posts & jitting flange	7 0
	17	5 hrs. taking up pump	.
	18	8 hrs. repair pump	16 3
		new end to handle & rod, new bolts, } new pin & key } new pulley, & leather } 1 leather collar } 5-6 of 4x3 oak leaves } 2. 12 x 1/2 bolts, 2. 4" coach screws 1/2" 2 inch pins } 2 phub screws } 21 6 hrs. fix pump, repair planking } 29 3 1/2 hrs. repair floor } 3-6 of 6 1/2 x 1 floor } 1920 Jan. 3 6 hrs. fix trunk } man horse 4 hrs. } 28.0 of 2" elm } 4 lbs. nails } Feb. 10 6 hrs. make 2 plough drags 6' } elm. 1 3/4 staples 6" & pairs 3" } 23 6 hrs. repair pump & better cart } making iron bar } Mar. 4 laying plough ends } 9 repair plough clip } Apr. 7 16 hrs. repair roller 1 1/2 } new gudgeon wedges 9 lbs. 3/4 } lead 1 1/2 lb. 9" 1 bolt. 6" } June 10 new pick handle jitting 1 hr. } £ 7 9 0	

1920 Mr. S. G. Miller,

I o a

Feb. 2	9 hrs. fix motor house				
4	5 hrs. do.				
5	9 hrs. do.				
6	9 hrs. do.				
7	5 1/2 hrs. do. 38 hrs. 11.			2	12
	24-0 of 6x6 2 oak posts 6 cube			2	10 0
	nails #10/6				1 6
	14-0 of 4x2		5 1/2		6 5
	4 hooks 8 lbs.				8 9
Mar 26	repair pump.				1 6
30	putting in glass				2 6
Mar 29	2 panes glass				.. 8
8	5 1/2, 10 th 9 hrs. 11 th 8 hrs. 22 1/2 hrs. ring wheel				.. .
	12 th 4 hrs. total 26 1/2 hrs.			1	13 2
	14, 2 1/2 + 2 1/2 each piece				18 8
	14 drive		1/2 2-14-2		2 4
	2 new tires 94 lbs.		9 ^o .	3	10 6
7 th	7 hrs. 17 th 9 hrs. 18 th 18 hrs. 19 th 18 hrs.				.. .
25 th	3 1/2 hrs. 27 th 7 hrs. 62 1/2 hrs. repair			3	18 2
	56-0 of 7x5/8		3 1/2		16 4
	4 sets of couplings 5/1- 12 bolts 4/1-				9 0
	2 brake plates 7 lbs. 7/1- 14 screws 1/2				7 4
	1 split key 3 ^o . 1.9' hinge 6 ^o				9
	2 fasteners 1/6 1 drawer handle 11-				2 6
	1-6 of 9x3/4 9 ^o 2. 3 1/2 x 3/8 bolt.				1 5
	2 large leather collar.				2 0
	4. 1x1/4 bolts.				5
	1 dash board.		1/2 6-8-0		2 3/4
	nails				9
	repairing top inner, 3/6, 1 nut w bolt-6 ^o .				4 0
	altering 2 steps 2/1- sharpening stay 1/1-				3 0

forward

18 4 5

Mr. W. Glanville . Ford

1920

May 27, 28.	June 3, 4, 7 & 8	28 ¹ / ₂ lbs. ring trap wheels	1	15	8
14.	2 ¹ / ₄ x 2 ¹ / ₄ felloes	at 1/3		17	6
	tying 2 trap wheels			14	0
	put piece in one wheel type	$\frac{1}{2}$ 3-9-3		2	0
	To cleaning, painting, striping and varnishing trap		4	10	0
	To repairing trap 6 lbs.	9-0			
	trap for billboard	6			
	repairing front corner of trap	4-3		13	9
			<u>7</u>	8	13 0

Miss Rose Edith Martin

1920

Apr. 17	To 100 poles & carting		4	15	0
June 21	To 8 lbs. nails			4	0
			<u>7</u>	4	19 0

Mr. John Pyne

1920

£ s d

Mar.	To cleaning, skinning, painting and varnishing trap		5	0	0
	To ringing one wheel		1	15	9
	new type 30 lbs at 9 ^d		1	2	6
	28 rivets at 14 ^d			9	4
	22 hrs. putting new spring blocks, new collar, new pieces to rise seat	7	1	2	0
	2 leather collars large			2	0
	2 blocks				6
	2 sheep leather 3/6 r fixing 2/9			6	3
	5.0 of 1 1/4 x 1 1/4 ash				10
	12. 1 1/2" screws				3
	4 new clips couplings			3	4
	1 pair brass tail fastener			4	6
	repairing steps & wheelbolt	£ 2.3.5		3	9
Mar 24	lying collar			4	0
Apr. 28	hat coat suit			2	3
May 5	repair chair			1	0
	make cheese press	6/3			
	wood	3/2			
	ironwork	4.0			13 6
17	lying collar				4 0
	1 new band		7.0		
	2 bolts. 8 ^d + 1 Key 4 ^d 2 hrs. fixing 2/6		3.6		10 6
June 1	repair horse rake			10	0
17. 18 & 19	33 1/2 hrs. painting dairy		2	1	11
	18 lbs. paint		1	4	0
	3 glasspaper & putty				6
	1 garden fork handle			1	3
28	put name in waffer			1	6
Sep.	fixing steel hub 5 hrs.		3	10	0
	4 1/2 lbs. paint		2	16	8
	2 sheep tongs		2	0	0
	forward				
		£	24	12	1

1920 Rev. Dr. Telford

Jan 7	3 hrs. put new brake blocks to front wheel + blocks			4 0
Feb. 20	9 hrs.			
21	5 1/2 hrs.			
23	17 hrs.			
24	9 hrs.			
25	4 1/2 hrs.			
27	3 hrs. 4 1/2 hrs.			3 0 0
	5 pints Linseed Oil + Turbine	1/10		9 2
	5 sheets glass paper			5
	paint			9
	1-0 of 2x2 oak	1/3 - 10 - 10		6
24	repair stove			2 0
26	9 hrs. repair carriage			11 3
	3-3 of 2x1 1/2 oak			1 3
	1- 3x5/16 bolt 3". 9. 1 1/4 screw 3			6
	2 nuts on wheel piping			9
	removing stove			10
				<hr/>
				4 11 7

Mr. Edgar Ware

1920

£ p d

	forward	305		3	3	11
Feb. 5	1 beetle handle				1	9
Mar 5	repairing & lettering lamp				5	0
June 25	17 hrs. ring wheel	1-1-3				
	6. 3x3 oak filler	10-0				
	tying wheels	8-0				
	paint & dusters	9		2	0	0
				<hr/>		
				£	5	10 8

	Miss Hooper					
Feb. 18	1 pane of glass piping				3	9

	Woodbury School					
Mar 27	To one pane glass piping				4	6
July 5	To new bell rope				7	6

	ap. rendered				12	0
Nov. 1	8 hrs. repair desks				10	8
	12. 1/2 + 1/4 bolts					16
	3 plates iron 9" + 1" + 1/4 in.					9
	12. 1/4 screws					4
				<hr/>		
					15	3

1920 Mr. W. Sage. Vermont.

£ . s . d

Jan.	14	9 hrs. repair horse wheel 4 bolts	9	9	2	3
	26	making traps & 1 staple	2	0		
Mar.		To cleaning painting staining & varnishing trap	5	0	0	
		11 hrs. repair wheel	13	9		
		1-2 ¹ / ₂ felloe	1	3		
		4 hrs. repair trap	5	8		
		9 screws ³ 2. 3 ¹ / ₂ + 3 ¹ / ₅ ⁶ 2 2. 1 ¹ / ₂ + 1 ¹ / ₄ bolt.	1	0		
		repair front board iron, 3/-, repair seat iron 5/- 1 yr 2 wheels 14/-	1	2	0	
	31	9 hrs. repair gate	11	3		
Apr.	1	9 hrs. do.	11	3		
		2 lbs. nail	1	2		
		2 staples		4		
		1. 7" spike 6 ³ 12. c.s. nails		10		

 7
 2
 9 2 6

C. Davy, Esq

1920

£ p d

Jan	3	1 load turf from Black Hill			60
	17	1 load gravel			40
Apr.	7	pea sticks from Pydm			50
	8	2 loads of manure			50
	22	clearing drain			76
May	27	1 hr. about post			
	29	2 hrs. do			
	31	8 hrs. fit			
June	1	9 hrs. "			
	2	9 hrs. " 29 ¹ / ₂ hrs.			1 16 11
		6. 9 hr.			
		4. 8 hr. - 86-0 of 2x3 deal	4 ¹ / ₄	1	10 5 ¹ / ₂
		48-0 of 2x1 deal	6 ¹ / ₂	1	6 0
		60-0 of 2x1	13 ³ / ₄		8 9
		1 gal. creosote.			2 3
		1 lb. nails	7		7
		8 iron squares, 8 wedges 27 lbs. 1/1		1	9 3
	3	9 hrs. repair bank pipes 12			
		7 hrs. do			
	5	11 hrs. do			
	7	5 ¹ / ₂ hrs. do. 32 ¹ / ₂ hrs.		2	0 8
		1 stay. 2 pieces iron screw. 12 staples			2 4
		1 lb. paint			1 3
		3-6 of 4x3 oak	7 ¹ / ₂		2 2
		1 galv'd. tin 2/9			
		3 sockets 3/.			
		2 bends 4/6			
		6 pr. pipe 8/.		1	3 0
		filling do.			4 0
June	10	clean out bank & carting rubbish		1	4 6
	11	carting 2 load of rubbish			5 0
	30	8 turned oak blocks			16 0
					14 0 7 ¹ / ₂

1920 Mr. H. J. Tyle, Parkhays, Woodburn, Salterton £ o d

Feb.	To making a new body of cart with bent ash shafts & painting wheels		21	10	0
	also repairing wheels.	9.0			
	1. 4" elm felloe	1.2			
	2 axels	4			
	tyring wheel	9.0			
	cut & shov 2 wze bands	<u>2.0</u>			
			1	1	6
			<u>£</u>	<u>22</u>	<u>11 6</u>
July 15	tyring 1 front waggon wheel				7 0
			<u>£</u>	<u>22</u>	<u>18 6</u>

Col. Mardon, Oakhays

1920

£ s d

	To fixing fence in Orchard as per contract of May 25 th /20			24	0	0
Apr. 12	To new body of barrow, with 10 ¹ / ₂ boards, & eyes & painting wheel			3	3	0
13	10 hrs. put new handles on garden roller & pitch rake back roller	12/6				
	2 handles	2/6				15 0
14	repairing field gate 5 hrs.	6-3	}			
	2 eyes 2 lbs.	2-6				
	2 staples	6				9 3
26	1 axe handle	3/-	}			
	1 hammer stem	6				
	2 hrs. fixing	2-6				6 0
May 30	4 wedges for wood splitting		}			
	6 lbs. 16 lbs.					16 0
June 18	1 manure fork handle & fix					2 9
	3 scythe wedges	2/3				2 3
26	2 hrs. make little	2/6				
	wood for do.	1/-				
	3 rings & studs	6 lbs.	}			
	2 hrs.					9 6
July 19	new trap & fix in orchard door	7/-				7 0
				<u>£</u>	<u>30</u>	<u>10 9</u>

1920 J. H. F. Foster - Esq.

Aug.

To coloring, painting, repairs ¹² at
 Mr. Turner's Cottage, Broadway
 Woodbury as per contract of May 31/20
 Credit by not painting partition

57 5 0

1 2 6

56 2 6

Extra.

To 4 new oak rails

34.00 of 3 1/2 x 3 at 7.00 19-10

To line piping 1-2-6

2 2 4

58 4 10

Mr. S. S. Withercombe.

Hilltop

Fremington

sep 22 To one bell rope 60 ft. long
 Postage

1 8 0

1 0

£19 0

Capt. Kaufman, Stallenber

£ s d

To oak field gates at £ 1-9-0

13 10

To 3 oak posts 8-0 long 7x7 in. at 2/7

3 20

To 4 do. 8-0 long 6x6 in. 1/10 1/2

3 00

To new pair of double entrance gates

4 180

To 4 piggy doors

6 18

July 16	Time 15 hrs.	(20) 18.	(21) 18.
22	18	(23) 18	(24) 11
27	18	(Aug 4) 19	(5) 18
Aug 6	24 1/2	(9) 18	(10) 18
11	18	(12) 9	(13) 9
30	18	(31) 18 1/2	
	<u>111 1/2</u>	<u>100 1/2</u>	<u>74</u>
	100 1/2		
	<u>74</u>		

286 lbs. pig gates, doors 15

17 17 6

4-1 of 4x3 oak sill

28

11-5-6 of 4x3 dead jambos

11 1/2

10 6 1/2

6-0 of 7x3/4 stop

4

2 0

17-6 of 7x1 latch

5 1/4

7 8

5-0 of 7x1 1/4 ledge

7 1/2

3 1 1/2

8-0 of 6x1 1/4 "

7

4 8

8-0 of 4x2

5

3 4

3-0 of 2x4 oak

1 0

1-0 of 4x3 oak

8

1. 4 1/2 x 3/8, 30 1. 3 1/2 x 3/8, 30 21. 3 x 3/8, 4 1/2 31. 4 x 3/8

8 10 1/2

4. 1 1/2 x 1/4 bolts

4

6 washers

3

24. 1 3/4 clouts

6

1 lb. lead

5

8 1/2 lbs. pat. nails

4 8

12 doz. screws

3 0

3. 8" Tower bolts

2 6

found

£ 50 15 4 1/2

	found		50	15	4 $\frac{1}{2}$
	2 pairs 16" Tee hinges			5	0
	2 staples				4 $\frac{1}{2}$
	9 $\frac{1}{2}$ lbs. paint		14	3	
	2 lbs putty				8
	5# sets of gate hangings, 8 hinges & 16 staples	}		3	6
	3 sets of door hangings				
	7 latches, 7 catches, 7 guides for doors				
	2 iron squares				
	4 bolts plate		63 lbs. 1/6	4	14
	new fastener for double gates			3	0
	repairing ironwork			8	3
July	17 2 Horse Waggons deliver gates &c.			17	0
Aug	4 " " do. do.			7	6
	10 Deliver door &c.			7	6
	31 " " do. do.			7	6

7 59 4 5 $\frac{1}{2}$

57 $\frac{1}{2}$ for interest

15 0

Mr. W. H. Stamp, Kenniford, Clyst S. Mary

1920

Feb.	26	9 hrs. fix railing				99
	27	6 hrs. do.				66
		4 1/2 lbs. nails				27 1/2
Mar.	22	9 hrs. take down pool house				99
		Carting pool house				30
	23	1 1/2 hrs. fetch pool house				18
	26	3 1/2 hrs. take down safe shelves				40
	31	18 hrs. take down fence				
Apr.	1	18 hrs. " "	36	1/1		190
	12	Banking fencing	2 hrs.	man		50
	14	4 hrs. repair iron stands				
	15	7 hrs. do.				
	16	2 hrs. do.	13 hrs.	1/2		163
		1 new strainer 1 hr.	2/6			26
	15	1 hr. take off bulllock chains				13
	21	10 hrs. fix mill rails				
	22	8 hrs. do.	18 hrs.			196
		4 posts 5' 9" long 4x4 in. 23/4				
		1 do. 6' 0" long 4x4 6/4		29/4	9 1/2	130
		96' 0" of 2x4 elm rails 3 1/2				180
		5 lbs. nails				211
		6' 0" of 8x1 1/4 elm				20
	23	18 hrs. fix iron fence				
	24	11 hrs. do.				
	26	18 hrs. do.				
	27	18 hrs. do.				
	28	18 hrs. do.				
	29	18 hrs. do.				
	30	11 hrs. do.	11 2	at 1/1		614
		60 emmer keys				18
		18 staples				9
		forward				1505 1/2

		forward		15	0	5½	
May	5	2 hrs. repair front house	} 16 at 1/3	-1			
	6	9 hrs. do.					
	7	5 hrs. do.					
		12-0 of 2x3				4 0	
		9-6 of 2x1				1 5	
		8. 1" screws.				3	
		2. 5½x5½ squares				2 0	
June	7	3 hrs. repair front house	} 40½ at 1/3				
	8	9 hrs.					
	9	5 hrs.					
	10	12 hrs.					
	11	9 hrs.					
	12	2½ hrs.					2 10 8
		6-0 of 2x1 match				2 7½	
		8-0 of 2x1				1 2	
		36-0 of 2x3				12 0	
		1 lb. nails, 7 3/8 screws, 9 2 staples, 1"				1 5	
		15 lbs. paint				1 2 6	
		12. 4½x3/8 bolts, washer 3/3 12, 2" screws				3 7	
	15	5 hrs. paint				" .	
	16	3 hrs. " }	8 hrs.			10 8	
		2 squares, 2 plates, 2 staples 3/3					
July	10	7 hrs. piping				8 9	
		Horse wagon deliver home				10 0	
	27	take off trap wheels & wrap 5 hrs	6-3			5 0	
	29	To re-rubbering 1 pair 4-2 trap wheels				5 5 6	
		carriage of wheels				9 0	
		put on wheels + oil 2½ hrs.	6-2-6			3 0	
Aug.	4	8 hrs. repair trap seat, patch springs					
		roller wheels				10 0	
		oil 2 small rollers, 1" screw nuts, lengthen seat iron P. 4-				5 0	
		forward				10 0	
				£	29	90	

	forward		29 9 0
Exp. 2	7 hrs. repair trap springs		10 0
	8 new cut & repair bolts, 6 ^o 2 each blocks, 7 ^o		19
	8 hrs. take off & pack wheels		
22	2 hrs. put on wheels		
	To re-mulberrying 1 pair of trap wheels		
	4 hrs. put seat rail in trap		5 0
	4 screws		2
	3.0 of 4x1 ash		7
	To re-mulberrying 1 pair of 3-6 wheels with		
	1 1/4 iron on byes	4-0-0	}
	Carrage 7/8 milk 1/2. Station 46	10-8	
	8 hrs. take off pack put on	10-0	
	Card	1-4	
			5 2 0
			<u>35 8 6</u>

Mr. Harold Ware.

1920

June	14	To me window frame & lights		2	12	0
	16	6 hrs. fit beam in garage			7	6
		13-0 of 4x3 deal	21-	1	6	0
		1 lb. nails				7
July	9	4 1/2 hrs. work garage			5	7 1/2
		16-0 of 4x3 deal jamb	11 1/2		15	4
		2 plate dowels			1	0
		1/2 lb. paint				9
		2 bolts plates 2 1/2 lb.			3	2
	14	3 hrs. glass lights			3	9
		6 panes glass 11 x 13 3/4			6	8
		1 1/2 lbs. putty				6
	21	9 hrs. fit up garage				
	22	9 hrs. do.				
	23	9 hrs. do.				
	24	5 1/2 hrs. do.	32 1/2		2	0 7 1/2
		12-0 of 4x3	11 1/2		11	6
		12-0 of 4x2	5		5	0
		79-0 of 2x3	4 1/4	1	8	0
		7-0 of 9x1	8 1/2		4	11 1/2
		24-0 of 2x1	1 1/4		3	6
		31-0 of 7x3/4	4		10	4
		4 lbs. nails, 2/4 6. 1 1/2" screw 2			2	6
		1 window stay, 1 hook eye			1	4
		1 pair 2 1/2" brass screw				11
		6-1/4 2. 2 1/2 x 1/4, 4. 3 x 1/4, 6. 3 x 3/8 bolts				1 10
	31	50 1/2 hrs.			3	3 2
		1 lb. nails, 7 1/2 1 lb. 3/4" clouts 1/3				1 10
		8-0 of 4x2, 3/4 84-0 of 7x7/8 nail ch 1-6-3			1	9 7
		12 lbs. stone color				17 0
		12-0 of 2x5/8				1 0
		3 rolls of roofing felt			1	16 4
		forward				
					19	1 11 1/2

forward

19 1 11 1/2

Aug 3	9 hrs.		11 3
June 18	taking down water pipe		5 0
	altering hooks & units		3 0
	1 door plug, 2 staples & screws		2 6
	12-0 of 9 x 3/4	1 1/2	6 6
			<hr/> 20 10 2 1/2
			<hr/> 20 10 2 1/2

Mr. Harold Ward (Pigeon box)

Aug 23	22 hrs. make pigeon box		1 7 6
	15-0 of 11 x 3/4	7 1/2	9 4 1/2
	18-0 of 7 x 5/8	3 3/4	5 7 1/2
	12-0 of 7 x 3/4	4	4 0
	9-0 of 2 x 1	1 3/4	1 4
	1 1/2 doz. screws		4 1/2
	1 lb. nails		7
	3 lbs. paint	7 2-13-0 ✓	4 3

July 14	laying masonry		3 6
Aug 5	2 plates of iron for W.C. seat		1 6
Sep 20	3 hrs. rehang garden door	3/4	3 9
	1 pulley		1 2
	4- 2 x 1/4 bolts		4
	12- 1 1/2" screws		3
			<hr/> 3 3 6

Mr. Harold Ware

(Office)

1920

Aug 7	32½ hrs. make office front		2	0	8
8	15-0 of 4x3	11½		14	4½
	7-0 of 7x2½	1/3		8	9
	14-0 of 4x2	6/4		7	5½
14	38 hrs.		2	7	6
	7-0 of 7x7/8	3¾		2	2½
	8-6 of 11x1¾	1/9		14	10½
	6-6 of 9x1	8½		4	7½
21	18 hrs.		1	2	6
28	38 hrs.		2	7	6
	7-9 of 8x1	8		5	2
	32-6 of 7x1 match	5¼		14	3
	2 lbs. nails 3½ 3 lbs. ½ priming 1/3			5	6½
	7-6 of 7x1	5¼		3	3½
	2-9 of 9x1	8½		2	1
	2 pair 2½" bolts 1/4 42-1" screws 10½			2	2½
	1 pair 14" Tee Hinges			1	11
	10-0 of 9x1 featheredge	8		6	8
Sep. 4	50½ hrs.		3	3	2
	8-6 of 9x1	8½		6	0
	16 panes 11x8			10	6
	8 do. muntins 11x8			5	6
	4 lbs. putty			1	4
	41-0 of 2x3	4¼		14	6
	80-0 of 7x¾ match	4	1	6	8
	8-0 of 7x¾ ledges	4		2	8
	2-6 of 7x½	3¾			9½
	1 pair 14" Tee Hinges 1/11 3½ do. screws			2	10
	1 steel case lock screws			8	0
	2 window stays 2/4 2 fasteners 1/-			3	4
	1 ventilator			3	9
	1 lavatory basin fitting			1	0
	joining do. 1/6			0	0
	forward			21	0 5½

	forward			21	0	5½
	6.0 of 4" stove pipe				19	3
	2. bands				18	0
	1 top				3	6
	4 coat paper .1/8 24 3/4 screw				1	11
Sep. 11	4 1/2 hrs.			2	11	11
	6.0 of 2x1		5 1/4		2	7 1/2
	6.0 of 2x3/4					
	64.0 of 2x3/4		4		1	1 4
	18.0 of 2x1		1 3/4		2	7 1/2
	1 lb. nails 7. 9. 3/4 screw 3					10
	13 1/2 lbs. paint		1 1/5		19	1 1/2
18	4 5/2 hrs.			2	16	11
	1 steel case latch				2	6
	1 level roller 1/6				1	6
	2 blind rollers fitting 3/6				3	6
	2 lbs. paint		1 1/5		1	9 9
25	9 1/2 hrs.				11	11
	green blind material making				14	0

34 18

Mr. R. Pyne

Greendale

1920

Jan 28	2 new draft clips		3 0
March	To cleaning, staining & varnishing trap		5 0 0
	To re-rubbing one pair of wheels		4 0 0
	To repairing trap, new corner plates & qtrs. 1 1/3 plates 2 1/2 screws 6 ³ , 1 bolt for chaps 9 ³		13 6
	2 new brass sharp stops .41- shackles tube 41-		8 0
	repairing lamp		10 0
Apr. 3	repair chair, 2 legs & 1 bar		4 6
7	making whippers & r staples		16 8
14	new handle in basket		2 0
May 20	4 fork handles 4-4 } 4 rings & fixing 4-0 }		8 4
June 28	2 wheels for lute-runner		2 6
July 7	make drafts work for do.		4 6 15 0
Aug 13	new binder board		5 0
Sep 23	1 pane glass		3 6

 13

 16 6

Mr. S. Cornick

Feb.	24	4 hrs. put in cart shaft	4-4		
	25	9 hrs. do. r ring wheel	9-9		
	26	9 hrs. do.	9-9		
	27	8 1/2 hrs. do. repair cart	9-3	1	13 1
		1 cart shaft			13 0
		6. 3-10, 3+3 felloes			10 0
		4-6 of 3 1/4 + 3 oak hick piece	7		27 1/2
		7-0 of 7+3/4 fir bottom			19
		1 staple			2
Mar	1	2 1/2 hrs.			
	2	9 hrs.			
	3	1 1/2 hrs.			
	5	1 1/2 hrs. 14 1/2			15 8
		tyring 1 wheel	4-4-3		8 0
Apr.	10	15 1/2 hrs. put in roller judges	17-6		
		3 lbs. lead	1-6		
		2 lbs. wedges	1-0		1 0 0
	8	2 1/2 hrs. make roller frame			
	9	9 hrs.			
	10	5 1/2 hrs.			
	12	8 hrs.			
	14	9 hrs.			
	15	9 hrs.			
	16	5 1/2 hrs. 48 1/2 1/2			2 16 7
		11-6 of 10 x 3 1/4 oak plank			1 6 0
		5 lbs. paint			6 8
		8. C. S. nails, 4 staples			10
		1 1/2 hrs. repair roller in work 13 1/2 hrs			13 6
		4 links 114 2 crooks 2-			3 4
		2. 8 x 1/2 bolts	5-9-0		2 1
June	19	2 1/2 hrs. put new stock in wheel			1 5 1
		2 spokes			1 4
		forward			11-19 8

	forward	11	19	8
June 23	8 hrs. box wheel		8	8
	put on stock bands 1 hr.		1	2
	2 new stock bands		3	0
	tying 2 wheels 1 1/2 hrs.		12	0
	6 - 3 x 2 1/2 bolts		1	3
	2 large leather collars		2	6
	To cleaning, painting & varnishing traps	3	10	0
		<u>1</u>	16	18 3

Mr. S. Ware

1920

Aug 3	1 1/2 hrs put in haytuner shafts		1 29
	2 shafts 15.0 of 3x3 ash	7 1/2	96
	paint 9.		-9
	repair ironwork		10
			<hr/>
			7 1/2 1140

Ware Pumps, Mills

May 3	2 wood brake blocks		39
June 14	2 iron brake plates rifting		60
			<hr/>
			75 99

Mr. H. Glanville

May 18	repairing fire dogs	7	89
--------	---------------------	---	----

Mr. Arthur T. Pyle, Malster Arms

May 20	2 Horses Cart drawing manure part day		126
25	do. do.		160
June 2	man & 2 Horses working field		150
3	do		150
4	do.		150
			<hr/>
			7 536

1920 Mr. A. Fitzwarren Smith. Farrants

Aug.	156 hrs. make new body to spanning waggon. fit up sideboards & repair lades & paint waggon 1/2	9	2	7
	put in name			16
	new part to screw in			50
	fitting do.			13
	fitting bolts to sweep			10
	repair bolts. 2 couplings			50
	materials, paint 13	4	6	10
		<hr/>		
		$\frac{1}{2}$	14	32

Dr. Darbyshire

June 22	To grinding hooks & shears			26
	To bolt in shears			10
Oct. 25	To grinding scythe			13
		<hr/>		
				49

Mr. W. Aldon

Apr. 26	board for shelves			96
May 15	side table			80
		<hr/>		
				176
		<hr/> <hr/>		

Mr. B. Stamp

1920

Feb.	23	1 link in chain	4
Mar.	4	3 links in chain	10
	10	1. K 3 shear	10
	12	repairing plough clip	20
		tying coulters	40
	19	1 link	4
May	18	repair ironwork of draft	60
Aug	3	2 links in tip chain & alter 3 eyes	26
July	24	2 shoes on cole	50
Aug	12	do	50
Feb.	25	repair trap, ¹ / ₆ bolts, ² / ₂ screws	110
Mar	29	repair chair & stool	30
Apr.	26	1 pint Oil	16
June	11	6 lbs. paint washstand 1 lb. paint	76
Aug	3	3 lbs. fix tip chain to cart	39
		put in name	16
Sep.	13	sharp saw	9
			<hr/> 2710

Mr. B. Stamp

1919

June	18	man horse 1 day hay making	120
		2 men 5 hrs. ea. do.	84
Aug	6	man horse 1 day	140
		Boy 2 hrs. 1/2 man horse 1 hr. vestime	30
	11	man 1 day	70
		horse 1/2 day	36
	23	man 1 day	70
		horse 2 hrs.	20
Sep.	22	man 1 day	70
Nov.	15	man 1 day	70
¹⁹²⁰ Apr.	28	man & 2 horses 1 day	140
July	14	do.	140
"	"	do - 4 hrs.	316
	19	man & 2 horses 1 day	140
		do. 5 hrs.	176
		Boy 1 day & 5 hrs. vestime 6 hrs.	60
	20	man & 2 horses 1 day	140
		do. 4 hrs.	140
		Boy 1 day 4 hrs.	56
	21	man & 2 horses 1 day	140
		do. 3 hrs.	106
Aug.	3	man & 2 horses 4 hrs.	140
		Self 2/2 Boy 2/2 4 hrs.	70
	7	man & 2 horses 7 hrs.	146
		Boy 7 hrs.	36
	10	man & 2 horses 1 day	140
		do. 3 1/2 hrs.	123
	14	man & 2 horses 7 1/2 hrs.	163
	16	man & 2 horses 1 day	140
		man & 1 horse 4 hrs.	94
	21	man & 2 horses 6 hrs.	110
	23	do. 1 day	146
		forward	22108

		forward		22	10	8
Aug.	28	man & 2 horses 7 hrs.		1	4	6
	30	horse to Mr. Conicker			2	6
Sep.	4	2 horses 4 hrs.			9	4
		man 1 day 4 hrs.			12	0
		Boys 6 hrs.			3	0
		Sally 5 hrs.	25-7-3		6	3
July	16	2 men 7 1/2 hrs. ea. haymaking			18	9
	19	do. 12 1/2 hrs. ea. "		1	11	3
		1 man 6 1/2 hrs.			8	2
	20	1 man 8 hrs.			10	0
	30	1 man 8 hrs.			3	9
¹⁹¹⁴ June	18	man 9 1/2 hrs.			7	2
		man 5 hrs.		28	13	9
Sep.	23	man 5 hrs.			5	9
				<u>7</u>	<u>29</u>	<u>14</u>
¹⁹¹⁴ Aug.	13	man 1 day haymaking			7	0
Sep.	8	man & horse 6 hrs. harrowing barley			11	0

1920 Mr. Fred Stamp

Jan. 28	2 seams straw			16 0
Mar. 6	¹ / ₂ do. 5 lbs. mangal seed			8 0 16 0 12 6
Feb. 7	1 new drag casting 9/16 piping 2 hrs. 3/9			13 6
Mar 15	9 hrs. repair cart wheel	9/9	}	- -
	2 spokes, 2/1- 1. 3+3 ash fellow 1/1	3 8		- -
29	7 1/2 hrs. repair wheel	9 9		1 5 2
	type 2 wheels (25")			18 0
Apr. 13	2 hrs. put plate of iron on shaft	2 2	}	- -
	4. 3 1/2 + 3/8 bolt. 1- 4 + 7/16 bolt	1-6		3 8
	making plate of iron for cart shaft		}	- -
	2 new ends for tip iron. 1. 12 7/12 bolt			6 0
20	7 hrs. repair cart wheel		}	- -
22	5 hrs. "			- -
30	8 hrs. " 20 hrs.			1 1 8
	2 new tyres 117 lbs. (25")	9 1/2		4 12 1/2
	spoke			3 4
May 25	1 1/2 hrs wheel 1/2 hrs.		}	- 9
	repair tip roller gudgeon. 3 lbs. iron			- -
	2 lbs. lead 8 1/2 hrs.			12 9
28	4 1/2 hrs. ring wheel		}	- -
29	5 1/2 hrs. "			- -
31	9 hrs. "			- -
June 1	7 1/2 hrs. "			- -
2	10 1/2 hrs. " 37 1/2			2 0 8
	1 spoke 1/1. 12. 3 1/4 + 3 1/4 ash fellow 7/1. 12 drush 1/4			1 2 4
	2 new tyres 140 lbs.	9 1/2		5 10 10
8	lying horse hoe post			3 0
14	do.			3 0
16	repair drag. 2 new bolts. 4 new washers			4 0
21	2 new tyres 132 lbs.	9 1/2		5 4 6
	2 hrs. chop around wheels			2 6
	forward			26 18 9 1/2

		forward		26	15	9½	
July	10	new drag skid		3	0	0	
	23	set stone pump, 2 rivets & drilling			1	6	
Aug	18	new plate on skid ^{exp. 9½} 10/9 piping 3½ hrs. 3/9			14	6	
Sep	6	rivet on drag skid etc.			1	0	
	13	9 hrs. put in new chaps	}				
	14	5 hrs. " " 14 hrs.				17	6
		1 ash chaps				13	0
		repair in work				1	6
						1-12-0	
				<hr/>		£ 32 7 9½	

1919 Mr. R. Pile, Bagwood,

Aug. 20	To 1 milking stool	43
Dec. 1	To making new beetle	60
Jan. 12	5 hrs. repair tailboard of cart	43
	repair tailboard iron, 3 rivets	20
13	5 hrs. put new felloe in wheel	" "
	1. 4 1/2" elm felloe	60
	tyring 1 wheel	120
Apr. 16	7 hrs. 19" & 8 hrs. 20" 1 hr. = 16 hrs	
	putting in cart shaft	188
	1 new cart shaft	144
	1 long staple & repair shaft iron	26

7
1

3 10 0

Mr. A. R. Stamps

1920

Apr.	3	2 peat bags for trap & piping		3 0
"	17	repair trap, peat & str.		2 0
June	10	2 1/2	ring 1 cart wheel & chop	
	11	1 1/2	around 1 cart wheel	
	12	3 1/2		
	14	8 1/2		
	15	5 1/2	1 hr. 23 1/2 1-9-2	
		2 spokes	2 10	
		6 3x3 elm poles	6 0	
		6 dowels	9	1 18 0
		tyring 2 cart wheels		18 0
Sept.	28	2 brake blocks piping		3 9
Feb.	26	man horse 1 day		16 0
	27	do.		16 0
				£ 4 16 9

Mr. J. Ramsey

Mar.	22	4 1/2 hrs. repair glass		4 6
		2 lbs. putty		8
				£ 5 2

1920 Mr. J. F. Glanville Rydon

Feb 20	9 hrs	repair milk cart wheels			
23	9 "				
24	5 "				
27	2 1/2 - 25 1/2 hrs			1	7 3
	4 spokes				4 0
	2 new tyres 100 lbs. 9?			3	15 0
Mar 16		riveting spoke of wheel			3 6
June 11		cut short waggon tyre forward from 306			7 0
				3	1 6
				£	8 15 3

Rev. R. T. Gardner, Brent Knoll

July 22	To time 22 hrs.	screwing up jollies			
23		framework of Brent Knoll Church Bell		2	4 0
		Lodgings			6 0
		Rail fares			16 9
				£	3 6 9

Mr. F. W. Lynham, Builder, Brent Knoll

Aug 16		2 lined patrics			9 0
		2 square do. with galv. ring			9 0
		Postage			1 3
				£	19 3

Rev. E. J. Barlow, Holcomb Bogus

1920

June 12	To inspecting bells Rail fares	1 1 0 66
Sept 28-29-30	To main's time overhauling & screwing up bell fittings, part renewing clapper types, leathers & staples, and travelling expenses	4 12 6
		<hr/> 6 0 0 <hr/> <hr/>

July 31	Mr. S. C. Miller 5 1/2 hrs. put in glass & repair ladder 6/5 1 pane glass 1/6 pulley 2 5 ladder rungs 2/6 1 iron rod 6	} 11 2
Aug 5	1 gate hook	
Aug 14	1 lb. nails	7
Sept 18	43 lbs. strand wire	9 1/2 1 14 0 1/2
Oct. 2	2 1/2 hrs. repair chest of drawers 3-4 9. 1 1/2" screws, 3 1-lb of 7x1 floor 8" paint 3	} 4 6
Oct 4	4 hrs. put on brake blocks 5/6 2 brake blocks 1/- 4. 2 1/2 x 3/8 bolts 1/-	
Oct. 11	1 1/2 hrs. repair clock case & drawers 17/4 3-0 of 12x 1/2 elm 1-0 12 screws, brads & stain 6 piece of deal 2° 2	} 19 0

forward to 341

37 11 1/2

Mr. J. Handford

1920

Feb	13	sharpen mattock			8
Apr	6	do - pick			8
	30	do			8
May	6	do			8
	14	lying do		36	
	17	sharpen do			8
		repair do	1-	10	
	25	sharpen do			8
June	4	new pick	12/6	126	
	10	sharp do			8
	17	do			8
	26	do			8
July	3	do			8
	6	do			8
	13	lying do		36	
	27	sharp do			8
	29	do			8
Aug	4	do			8
	11	do			8
		repair pick		10	
	16	sharp pick			8
	19	do			8

 7

 1 12 10

1920 Rev. M. D. Buckingham, Buntingford £ s d

June 14	To main line, taking off head of 2 nd			
15-16	bell, losing bell & rehanging bell new hanging ironwork, repairing wheel & travelling expenses		5	5 9

Rev. Claude D. Kingston, S. Teath Vicarage
for the Churchwarden

Nov. 16	To 5 bellropes ea. 60 ft. long at £1.8.0 Carriage		7	0 0
				4 11
			7	4 11

S. Thomas R. D. Council

1920

£ o d

Apr. 27	8 hrs. - make iron steps		10-0	
	3-0 of 11x1	10 ^{1/2}	2-8	
	3-9 of 2x1 ^{1/2}	11-	3-9	
	4- 2" screws, 2" nails 2 ^o	paint 1/6	<u>1-10</u>	18 3
June 23	5 hrs. fit up motor sign		6-3	
	10-0 of 4x4 oak	10 ^o	8-4	
	2-3 of 4 ^{1/2} x1 ^{1/2} deal		8	
	1 lb. paint		<u>1-6</u>	16 9
Aug. 20	5 hrs. fit up motor sign		6-3	
	10-0 of 4x4 oak	10 ^o	8-4	
	2-3 of 4 ^{1/2} x1 ^{1/2} deal		8	
	1 lb. paint		1-6	
	3- 5x5/16 bolts, 2- 2x1/4 bolts		<u>1-0</u>	17 9
20	3 hrs.			
21	4 1/2 hrs.			
23	7 hrs.			
24	2 hrs. 16 1/2 hrs.		1-0-8	
	11-0 of 2x3 oak parts	3 ^{3/4}	3-5	
	10-0 of 3x1 deal		2-6	
	5-0 of 2 ^{1/2} x3/4 "		7	
	7-0 of 11x1 "	10 ^{1/2}	6-1 1/2	
	2 lbs. paint		3-0	
	1/2 lb. nails		4	
Sep 18	5 hrs. 3 1/2 hrs.		6-3	
	16-6 of 2x3 oak parts	3 ^{3/4}	5-2	
	2-9 of 11x1 deal	10 ^{1/2}	2-4 1/2	
	4-0 of 3x1 "		1-0 1/2	
	2-0 of 2 ^{1/2} x3/4 "		3	
	1/2 lb. nails		4	
	1 lb. paint	2-13-6	<u>1-6</u>	
	7 notice boards at 8/-			2 16 0

forward

£

5 8 9

1920

		forward		5	89
Aug	25	3 hrs. prepare post rails for Halfway			39
	28	5 1/2 hrs. fix post rails			68
		4 hrs. paint post rails 2 coats			50
		2 lbs. paint			30
		2 oak posts 5-6 of 5x5 ea. - 11/2	14		148
		1 rail 10-0 of 4x2 oak	5		42
		2 - 4x1/2 coach screws			6
		deliver	2-5-9		80

Sep.	28	17 hrs. fix post rails Indwater			
	29	18 hrs. do.			
	30	18 hrs. do.			

Oct.	1	15 hrs. do.			
	2	11 hrs. do.			
	4	7 1/2 hrs.			
	5	9			
	6	3 1/2 hrs.			
	7	9 hrs.			
	8	9 hrs.			
	9	5 1/2 hrs.			
	11	6 1/2 hrs.			
	23	5 1/2 hrs.			
	29	9 hrs.			
	30	5 1/2 hrs. 14 9 hrs. 1/3	9-6-3		

14.	6 lbs. of 6x6 oak posts	84 ft.	1/10 1/2	7-17-6
	9-0 of 4x3 oak rail		8 1/2	6-4 1/2
	2 lbs. nails			1-2
	6 lbs. paint			9-0
	4 lbs. putty			1-4
	1 gal. turpentine			1-6
	iron saw			4 1/2

forward

18	36
<u>25</u>	<u>180</u>

25 18 0

forward

Oct.	12	18 hrs. repair fence Cillbrook
	13	18 hrs. do.
	14	18
	15	18
	16	5
	18	18
	19	18
	20	18
	21	13
	22	18

Nov.	8	9
	9	9
	10	9
	11	9
	12	9
	13	5 $\frac{1}{2}$

23	8 $\frac{1}{2}$	22 hrs.	13-16-3
	24-0	of 4x4 oak 10 $\frac{1}{2}$	1-0-0
	7 posts	5-6 long 6x6 ea. 38-6 1/10 $\frac{1}{2}$	3-12-3
	4 do.	5-6 - 5x5 .. 22-0 1/4	1-9-4
	17 "	7-0 - 6x6 - 1/10 $\frac{1}{2}$	13-1 $\frac{1}{2}$
	3 "	5-0 - 5x5 " 1/4	1-0-0
	3 rails	8-0 long ea. 4x3 7 $\frac{1}{2}$	15-0
	3 do.	8-0 long " 4 $\frac{1}{2}$ x3 8 $\frac{1}{2}$	17-0
	32 spikes	9"	1-6
	5 lbs.	nails	2-11
	11 lbs.	paint	16-6
	6 $\frac{1}{2}$ lbs.	putty	2-2
	1 $\frac{1}{2}$ gal.	bar creosote	2-3

24 8 3

50 6 3

1920 Jarman Bros.

July	2	1 load sea gravel	9 0
	9	Horse Wagon to Messrs. Loran for poles	8 0
Sept.	17	1 load sea gravel Escomb to Messrs. Loran	16 0
*Oct.	1	1 load sea gravel to do.	16 0
Nov.	12	Carting earth to Miss Martin	16 0
	15	do.	14 0
	25	Carting 500 bricks	14 0
	26	Horse Wagon to Baker (empty)	12 0
	27	Carting 500 bricks	14 0
	29	do.	14 0
Dec.	7	Carting concrete to day	16 0
	8	part load timber cement (11 cwt)	6 0
	20	Carting ^{5 loads} 4 loads lime to from Station	1 6 8
	21	Carting gravel from Ryden Lane 2 horses	12 0
	8	6 sets latches, catches & guides at 1/9	10 6
	13	1 turning bar old iron 15 lbs.	7 6
		1 new latch to oven door & fitting	6 0
		repair post cap	2 0

1 10 19 8

Mr. Edgar Ware

1920

Dec.	7	18 hrs.			
	8	18 hrs.			
	9	18 hrs.			
	10	16 hrs. 70 hrs. at 1/3		4	7 6
		10 lbs. put. nails			6 2
		3 lbs. cut. nails			1 9
		20-0 g 3x4 oak	7 1/2		12 6
		5. 3 1/2 + 3/8 bolts 1/3 2. 1 3/4 x 1/4 bolts 2			1 5
		6. 1 1/2" screws 2" 2 doz. screws washers 1/6			2 2
		2 doz. zinc nails 6			- -
		2 pairs hooks & twists 15 1/2 lbs.			19 4 1/2
		2 latches, 2 catches, 2 guides, 2 hooks			" "
		1 # staples 4 lbs.			6 0
		1 plate iron & repair bolt for barrow			1 3
					<hr/>
					6 18 7 1/2
					<hr/>

Ware, Sams, Millers, Woodbury

Dec. 20 To one 12 run ladder

1 10 0

Mr. Harold Ware

1920

Nov. 2	9 hrs.	matchboarding office floor			
3	7 1/2 hrs.	paint board, stain varnish deck			
4	9 hrs.				
5	3 hrs.	28 1/2 hrs.			1 15 8
		48-0 q 7 x 3/4 match	4		16 0
		20-0 q 2 x 1 balustr	13/4		2 11
		4-0 q 3 1/2 x 9/8	2		8
		41-0 q 7 x 1 floor	5 1/4		17 11
		24-0 q 4 x 2 rafter	5 1/4		10 6
		4-0 q 3 1/2 x 1/4	1 1/2		6
		stain varnish 2/-			2 0
		3-9 q 18 x 1 elm stairs 5-9	5 1/2		1 9
		2 lbs. paint			3 0
Dec. 10	2 hrs.	fix leather shelves			
11	11 hrs.	do.			
13	18 hrs.	31 hrs.			1 18 9
		9. 16 pr. q 3 x 2, 1. 14 pr. 3 x 2	158 pr.	4 1/4	2 16 0
		1. 13 pr. q 2 x 1		1 3/4	1 11
		5 lbs. nails		7	2 4
		2 panes glass 11 x 7 ea.			1 0
		1 lb. putty			4
		2. 8" spikes, 1 dowel			7
					9 11 10

Mr. John Ryne

1920

Sep 22 q hrs. hang gates 15

23 q

24 q

25 5 1/2

27 q

28 q

29 q

30 q

Oct 5 q

6 q

7 q

9 5 1/2 hrs.

6 gate hooks - 6 eyes

2/3 per pair

9 hawses + 18 staples

6

~~39~~ staples 22

13 lbs. post. nails 8

5 19 5

13 6

4 6

2 9

8 8

7 8 10

1 15 10

Credit by blm tree 17-3+1-7 = 43 pr. at 10°.

±

5 13 0

1920 Woodbury Women's Institute

£ s d

Nov-9 To 4 folding tables

2 0 0

Woodbury Public Hall Co. Ltd

May 6 To repairing floor

2 3

Oct. 12 to 21. 6 hrs. put roof over gangway

4 9 4

44-0 of 2x4

54

19 3

41-0 of 2x3

44

14 6

2 lbs. nails

1 2

9-0 of 4x4 oak

10

7 6

8 lbs. sheet lead

4 0

2 iron squares

1 6

24 screws, 12 clouts

8

14 lbs. paint

19 3

2. 3x3/8 bolts

6

8-0 r-6 galv. iron

2 0

1 pair hooks & nuts 5 1/2 lbs

6 11

2 holdfasts

1 0

iron stay 4 lbs

8-16-7

4 0

Nov-20 6 folding tables

3 0 0

£

11 83 30

1920 Mr. T. Harris, Little Greendale, W. Salterton £ o d

Dec.	To cleaning, painting, striping and varnishing market trap		5	0	0
	4½ hrs. repair bottom. & put new dash board			5	8
	2 dash boards 6'0" of 7x¾"			2	0
	3'6" of 7x¾" bottom.			4	5
	nails				2
	repair dash board inner 6' new inner 1/9			2	3
	4 shackle plates, 6 bolts			4	6
	fit on wing boards	£ 1-0-0		1	0
			£	6	0

1920 C. Dary Esq. Knoll Cottage

Sep. 25	Cart 1 load manure from R. Harris		29
Nov. 22	do.		29
"	4½ hrs. make brackets shelving		
23	5 hrs. fit do.		128
	18.0 of 7x3/4	4	60
	5.0 of 2x3		19
	2 dowels		3
	1 pane glass 7½x8¼ pulley		9
24	13 hrs. fit barbed wire		
25	3½ hrs. do.		120
	15 lbs. wire	17.	126
	1 lb. staples. 2. C.S. nails		10
	1 iron tie bar 3/4		39
Dec. 3	repair electric bells 2/-		20
6	3½ hrs. repair flush cistern		48
	solder ball tap 1/3		13
17	Carting stakes from Rydon		50
			<hr/>
			3 19 1
Mar. 10	2 hrs. fetch pea sticks from Rydon.		50
			<hr/>
			4 4 1
			<hr/> <hr/>

Mr. S. Miller

	corr. from page 335		3 13 11½
Dec. 11	2 hrs. repair drawers	2/8	- .
	3-0 of 2 x ½ deal	1-	3 8
23	2. 6 x 3/8 bolts		8
Nov* 22	2 hrs. repair car hood		2 8
Nov 30	½ hr. fix car hood 16 screws		1 6
	38-9 of 7 x 1 floor		5¼ 17 0
Nov- 26	1½ hrs. repair ends	12-6	} 18 9
	inside 5-0 of 3½ x 2¼ ash 7½	3-1	
	10-6 of 3½ 3½ x 1 ash 2 hrs 3"	2-7	
	paint	7	
" 23	1 shaft crook ring		1 3
24	chopin & straighten crow bar		9
27	9 staples		1 6
30	2 gate links, 2 gate eyes 2/3 per pair		4 6
Dec. 6	alter door fastening of car, 4 screws		1 6
17	lengthen bolts		6
21	link in drag chain & end to lift pack		2 6
		∑	5 0 8
			6 14 8½

Mr. W. Sage.

£ p d

Aug.	12	repair spreader					
Sept	23	6 hrs. take out old casements make new ones				14	
Sept	24	7 1/2 hrs. make casements	}				
	25	4 1/2 do					
	30	9					
Oct.	1	1 1/2					
	5	5					
	8	2	29 1/2 35 1/2				
		7-6 of 2 x 1 1/2 deal	10 ³			27	
		2 lbs. putty				19	
		1 lb. paint				4	
		2 panes glass 16 x 8				6	
		18-1" screws				8	
				2-18-0.		16	
Dec.	16	roughing horse				4 1/2	
						20	

				3-1-4	£	3	13	4
June	5	repairing manure distributor			£	11	10	
					£	4	3	2
						3	13	2

Mr. C. Summerfield

Jan.	12	3 loads sand					6	9
	13	1/2 load cement from Exmouth					4	6
May	8	2 loads sand					4	6
	20	1 load lime from Torquham					8	0
							1	3
June	17	helping plumber 1 1/2 hrs.					2	9
					£	1	5	9

Miss Taylor. The Warren

1920

Oct. 6	13 hrs. repair motor car		
7	6 hrs. do. 19 hrs.		186
	12-0 of 2x1 malle		53
	3-0 of 1 1/2 x 1		3
	2 1/2 doz. 1" screws		8
	6. 1 1/2 x 1/4 bolts		6
	1 pair 1 1/2" back flap		7
	paint, nails & varnish		10

off

1169

Miss Mellen. The Warren

Oct. 26	6 hrs. make pigs trough	8-8	}	
	7-0 of 10 x 1 1/2 elm 6 ft.	4-0		
	3-3 of 12 x 1 1/2 " 3 ft.	2-2		
	1 lb. nails	7		
				160

Mr. H. ~~Stotes~~ ^{Knott}, Woodbury,

Aug 3	8 hrs repair trap, also set steps r.		8 0
	smith	dr.	5 0
	1. 3 1/2, 1. 2 1/2 + 3/8	1. 2 + 1/4 bolt	- 7
19	3 hrs.		3 0
25	10 1/2 hrs. repair wheel		11 10
	2 spokes	1.14 - 5	1 0
Oct. 2	tyring 2 wheels		12 0
	To cleaning, painting, striping & varnishing marker box		5 0 0
			<hr/>
			7 11 5
			<hr/> <hr/>

Dr. Darylshin

Nov 29	1 stool		4 6
	making 4 tubs	119 ea.	7 0
			<hr/>
			11 6
			<hr/> <hr/>

Mr. W. Glanville

Aug - 7	2 milking stools		9 0
			<hr/> <hr/>

Rev. Dr. Milford

1920

£ s d

Aug	6	releathering pump sucker			4 0
		1 plate of iron for do.			9
	10	5 1/2 hrs make of pit tunnel post			7 0
		3-6 of 4x4 oak 3/2 turning 1/6 carriage 1/2			5 8
		1. 3 x 1/4 bolt.			2
	28	figures in frame			6
Oct.	1	8 hrs. pit stove	12 1-	}	
		6 lbs. iron	3 0		
		4 bricks	9		
	21	repairing tray			4 0
Nov.	12	4 hrs. pit 2 fork handle	6 6		
		2 fork handle	6 6		11 0
		To cleaning Portland Cross bases and 2 Permanent Cross Kerbs. Small			
		made Cross re. repairing 327 letters			4 10 0
1921	Jan. 18	2 hrs. repair veranda			2 9
	Feb. 21	39 hrs. clean ceiling, whiten			
	24	ceiling strips rise walls, pit			
		lock box, pictures, ease window, doors re.			
		re paper Hall			2 18 6
		7 pieces wallpaper 17 1/2 1 pch paste 1/2			18 0
		1 pch. rise, distemper			3 0
		1. 2' luth. hinge rollers			4
		3-6 of 7 x 5/8 1/2	3-6 of 2 x 1 5/8		1 7
		1 brass knob	nails 1/4 - 2 - 5		1 0
					<hr/>
					11 4 0

Rev. J. G. Clum. Romandigh Rectory

1920

Dec.	2	1 new clapper	17 lbs at 21-	1	14	0
		4 ¹ / ₂ lbs. boxing shooting clapper			6	9
		1 clapper box			2	6
		1. 3 ¹ / ₂ + 3/8 boll.				3
		carriage w/ trailer			1	0

2 4 6

Mrs. Rowe. The Bungalow.

Sep	21	new furnace cover			8	8
Nov.	24	carting gravel			16	0

\$ 1 4 8

1920 Miss Gigg, Trenarri, W. Salterton

Oct.	1	9 lbs.	put in cart shops	
	2	3 1/2 lbs.	12 1/2 lbs	16 8
		1.	2 1/2 ash shops.	6 6
		1.	4 x 3/4 boll.	4
			paint	6
				<hr/>
				1 4 0
				<hr/>

Mr. A. Stamp, Butcher

Dec.	1.	ap.	out field gate	1 9 0
------	----	-----	----------------	-------

Mr. Hollett, The Firs,

Nov.	1	making double drap.	5 staples	
		1 iron plate		7 6