

## Blyford Manor

1908

£ s d

brok. forward

6 4 11

9 lbs. sheet iron

16

12 rivets, 13 screws

4

1" 6" of 11x1/2 deal, black paint

6

trap delivering do.

10

Dec. 22 to putting up of chain to telltale of  
~~system~~

10

£ 6 9 3

W.C. Warren Esq. Marshfield, Grand Avenue, West Worthing, Sussex

1908		£	s	d
Aug.	21	examining roofs at Elford Manor	2	0
	28	stopping in leaks, time & lead	5	4
Sep.	14	To repairing pump, 1 new valve, solder leaks in pipe, time & solder	11	0
Nov.	30	To soldering leaks in pump pipe, time & solder	8	9
Dec.	21	To fixing new 1 1/2" suction pipe, 2 lead collars, bolts & nuts, repair & shoot handle of pump & putting in new oak bearers, time & material	5	10
			£	6 8 1
Credit by old lead pipe			£	1 0 0
			£	5 8 1

Warren

Aug.	21	3 hrs. examine roofs	2/-
	24	3 hrs. stop in leaks	2/-
	28	3 hrs. do	2/-
		4 lb. red lead	1/4
Sep.	14	3 hrs. with plumber about pump	17/6
		Plumber repair pump, 1 new valve, solder leaks in pipe, time & solder	
Nov.	30	3 hrs. help plumber about pump	4/6
		soldering leaks, time & solder	
		trap fetch plumber	1/-
Dec.	21	To fixing new 1 1/2" suction pipe, 2 lead collars bolts nuts & repair & shoot handle of pump as per contract of Sep. 16. 1908	4-12-6
		6 hrs. help plumber	3-3
		8-0 of 4x2 oak bearers	3-0
		1-0 of 12x1 oak	3
		trap	2-0
			5-0-0

## Bleford Manor

1908

£ s d

brok. forward

6 4 11

9 lbs. sheet iron

16

12 rivets, 13 screws

4

1" 6" of 11x1/2 deal, black paint

6

trap delivering do.

10

Dec. 22 to putting up of chain to telltale of  
~~system~~

10

£ 6 9 3

W. C. Warren Esq. Maresfield, Grand Avenue, West Worthing, Sussex

1908			£	s	d
Aug.	21	examining roofs at Elford Manor		2	0
	28	stopping in leaks, time & lead		5	4
Sep.	14	To repairing pump, 1 new valve, solder leaks in pipe, time & solder		11	0
Nov.	30	To soldering leaks in pump pipe, time & solder		8	9
Dec.	21	To fixing new 1 1/2" suction pipe, 2 lead collars, bolts & nuts, repair & shoot handle of pump & putting in new oak bearers, time & material		5	10
			£	6	8 1
		Credit by old lead pipe	£	1	0 0
			£	5	8 1

Paid February 1909

Dec. 13. 1908

Rev. G. F. Powys. The Vicarage. Montacute

1908			£	s	d
July	23	1 man 11 hrs. overhauling Bells			
..	24	1 man 9½ hrs. do.	8		
		railway fares		10	4
		lodge		1	0
		trap to station		2	6
			£	1	76

Settled Oct<sup>r</sup> 19<sup>th</sup> 1908

Mr A Gigg

October 19<sup>th</sup> 1908

Received from Mr A Gigg the sum of  
 five work done in building new cow-house  
 & stable at Wilkin Farm Nylorburn  
 as per contract -

£ 0 1

5 5 0

Ropes  $\frac{1}{2}$  feet long  
175 feet

Nov-7<sup>th</sup>/08 P.R. Henry Stanley Esq  
Langworthy  
Lea Down  
N. Devon

The Churchwardens of Bratton Clovelly.

1908

October

For providing and fixing a new set of 6 Bell  
Ropes to the 6 Bells in Bratton Clovelly Church  
Tower  
extra for overhauling and screwing up  
frame & bells

£ 0 0  
" " "  
5 1 0  
" "  
10 0

---

£ 5 11 0

---

Paid Nov-14<sup>th</sup> 1908

Rev. H. A. Hill

1908

Oct-30	For supplying and fixing the Elacombe chroming apparatus to the 6 Bells in West Washington Tower according to estimate of August 26 <sup>th</sup> 1908 man screwing up bells & frame	£ 0 d
		8 120
		50
		<hr/> 8 170

Settled Nov-20<sup>th</sup> 1908



Nov<sup>r</sup> 24<sup>th</sup> 1908W<sup>r</sup> H Holland

Dr to H Stokes

1908

Nov <sup>r</sup>	18	For making a Polished Elm Coffin with	£	0	d
	19	electn brass fittings for the late W <sup>r</sup>	"	"	"
	21	Bessie Holland, telegrams to Exminota	"	"	"
		and taking coffin to Exminota and	"	"	"
		bringing back W <sup>r</sup> Holland and carrying	"	"	"
		out the Funeral.	2	18	6
		Vicar & Clerks fees	"	3	6
		sextons fees	"	8	0
			<hr/>		
			£	3	10
				0	

Paid Nov<sup>r</sup> 26<sup>th</sup> 1908

Nov 27<sup>th</sup> 1908

# The Vicar & Churchwarden of Churchtown

1908

Sept  
Nov

<sup>frame & fittings of</sup>  
 For repairs to the ~~6 bells~~ The 6 bells  
 in Churchtown Church Tower according  
 to estimate of July 2<sup>nd</sup> 1908  
 Providing and fitting and fixing 5  
 new stocks  
 Putting new carriages to bearings, and  
 new plates to gudgeons  
 Man helping about floor -

£ 0 0  
 35 18 0  
 5 5 0  
 3 15 0  
 6 0

£ 45 4 0

Decr 1<sup>st</sup> 1908 Received on acc<sup>t</sup> = £ 30.0.0  
 Decr 31<sup>st</sup> 1908 Received the balance - £ 15 4 0

Dec-4<sup>th</sup> 1908

1908. J. Jones Esqr

Nov =	24 <sup>th</sup>	Had putting up a Platform in Woodbury	0	d
"	25 <sup>th</sup>	School for W.B. Lake Esqr Meeting and taking it down again	"	"
			6	0

Paid Dec-4<sup>th</sup> 1908

The Executors of the late W<sup>m</sup> Joseph Skinner

1908

Dec		£	s	d
9 <sup>th</sup>	For making a Polished Elm Coffin		0	0
12	12 <sup>th</sup> with brass furniture and fillings lined			
	with white oiled down and fillings for			
	the late W <sup>m</sup> Joseph Skinner and carrying			
	out the funeral	4	10	0
	8 bearers	2	0	0
	Organ & clerk and sextons fees		8	0
		<u>£</u>	6	18 0

Paid Dec-16<sup>th</sup> 1908

Dec 14<sup>th</sup> / 05

Mr A Stokes

1908

Mr	25 <sup>th</sup>	For a Portland Headstone for his late Wife and 2 children	£	0	d.
		Engraving & Polishing 227 letters		2	20
		etching & fixing stone in Woodbury Churchyard		19	0
		vicar's fee		4	6
		Sexton's fee		1	10
		Sexton making up 2 graves		1	0
				<hr/>	
				4	120

Paid December 17. 1908

W- A Stokes

1905

Sept= 22 <sup>nd</sup>	For cleaning and repairing marble	£	0	d
to 26 <sup>th</sup>	Headstone, Portland Kerbing, and railing, late W-Grays, in Woodbury Churchyard and repainting 403 letters Section fee and reurfing grave.		2	15 0
				2 6
		£	2	17 6

Paid June 3<sup>rd</sup> 1909

12/27  
19

Jan 11-10

Mr. Henry Glawille

1908			£	s	d
		trap. brot. over from page 105	22	4	9½
Nov.	24	repair bottom of cart		1	10
Dec.	4	to repairing bottom of waggon +			
	5	making a new tailboard		6	10
	11	to re-leathering pump sucker		1	0
			<hr/>		
			22	14	5½
Dec.	1	Credit by oak posts + planks	1	13	0
Dec.	23 <sup>rd</sup>	1908 by Contra acc.	9	4	6
			<hr/>		
		left due	£	11	16 11½

December 28<sup>th</sup> 1908 Received by payment of  
 Insurance 3.0.11  
 and by Cash 16 0  
 3.16.11

		left due	£	8	0	0
1911	Sep. 26	1 man 3½ hrs. hanging gate sharp gate hook + repair clip		1	5	6
			<hr/>			
			£	8	1	11

April 27<sup>th</sup> 1912 Received on acct- 1.1.11  
 July 1<sup>st</sup> 1912 Received on acct- 1.0.0  
 Received on acct 3.0.0  
 July 4<sup>th</sup> 1913 Received the balance of 3.0.0

---

£ 8.1.11

S. Thomas Rural District Council

1908

£ s d

Nov. 5.	1 man 6 hrs. prepare posts for Bridgepit			2	9
10	1 man 7 1/2 hrs. fix do do			3	5 1/2
	1 labourer 7 1/2 hrs. help do do			2	10
	1 oak post 5-6 long 6 x 5 1/2	} 10-9	11		
	1 " 5-3 long 6 x 5 1/2				
	1 " 5-3 long 5 x 5	} 9-0	8 3/4		
	1 " 3-9 long 5 x 5				
	1 " 4-0 long 4 x 3 1/2		8 1/4	2	9
	2 iron bars			5	8
Dec. 1	1 man 6 hrs prepare posts			2	9
3	1 man 9 1/2 hrs. fixing posts rails			4	4 1/2
..	1 labourer 9 1/2 hrs. do do			3	7
5	1 man 4 hrs. paint rails			1	10
12	1 man 2 1/2 hrs. do			1	2
	2 oak posts 6-3 long ea. 5 1/2 x 5	- 12-6	9 1/2	9	11
	1 " 6-0 long 5 x 5				
	1 " 4-0 long 5 x 5	} 10-0	8 3/4	7	3 1/2
	1 " sill <del>3-5</del> long 7 x 3 1/2		8 1/4	2	9
	3 lbs. priming paint			1	6
	4 lbs. white paint 2 coats			2	0
	1 new iron bar & lengthening bars			6	0

£ 3 17 1

Invoice bill sent on Dec. 17. 1908

Paid January 20<sup>th</sup> 1909



Rev. W. G. Carew, Bickleigh Rectory £ s d

1908  
 Oct.  
 Nov.  
 Dec.

To lowering down Bells taking out old fittings, frame, floor and beams from Bickleigh Church Tower and providing new beams, floor & frame for 6 Bells and hanging 5 Bells as per estimate of May 6. 1908	105	15	0
To providing changing a new Tenor Bell	70	11	6
To recasting the 3 <sup>rd</sup> Bell	16	13	6
To inscription of 40 letters		13	4
	£	193	13 4
Estimated weight of tenor 8c. 19. 14 lbs.			
Actual weight do. 8. 1. 0			
			14
By credit 14 lbs. of metal at	1/3		17 6
	£	192	15 10

Paid January 1<sup>st</sup> 1909

5  
 2  
 5  
 0

Mr. John Dew

1908

£ s d

July	1	1 man 2 hrs. make machine drap			9 <sup>1</sup> / <sub>2</sub>
	16	2.9 of 3x1 1/2 ash. 4 screw lying coulters			16
		2 new axles + 1 new wheel stem			24
	23	2 men 5 1/2 hrs. ea. ring cart wheels			45
	24	2 men 1 day ea. do.			74
	25	1 man 2 hrs. paint do.			9 <sup>1</sup> / <sub>2</sub>
	27	1 man 5 1/2 hrs. <del>do</del> do.			22 <sup>1</sup> / <sub>2</sub>
	29	1 man 2 hrs. do.			9 <sup>1</sup> / <sub>2</sub>
		1 spoke			4
		12. 3" ash felloes			60
		4 lbs. paint			20
		2 new tyres 12 lbs. 2-7-6	2 1/2	1	37 <sup>1</sup> / <sub>2</sub>
Aug	28	4 shoes			24
Sep.	12	1 man 5 hrs make cart shaps			20
	14	1 man 1 day do.			38
	15	1 man 7 1/2 hrs. do.			30
	16	1 man 8 1/2 hrs. do.			34 <sup>1</sup> / <sub>2</sub>
		10.6" of 10 1/2 x 3 1/2 ash shaps	11		97 <sup>1</sup> / <sub>2</sub>
		4.0 of 3 x 3 1/2 do. bar	3 1/2		11
		4.0 of 3 x 2 do. "	1 1/2		7
		2. 4 1/2 x 3/8 bolts			2 1/2
		10. C. & P. nails			2 1/2
		2 lbs. paint			10
		repair shap ironwork, cut 4 bolts,			
		sharp wang, new crook, 2 staples + 1 pin			
		+ key shap.			16
		2 mudguards			6
Oct.	9	4.0 of 15" x 3 1/2 elm	10		34
	27	1 shoe			7
Nov.	5	3 shoes			19
	6	1 shoe			7
Dec.	7	2 old ropes			20
	17	link in chain			2

Paid by contra acc<sup>t</sup> and  
by cash  
Feb 30<sup>th</sup> 1909

£ 4 10 1

Mr. Ferris-Kerr Esq

1908

£ p d

July	4	1 man 6 1/2 hrs. alter RWR Pipe + make block for watercart			28 1/2	
		4'0 of 2 1/2" pipe			19	
		1- 12x2 1/2" swan			11	
		2 pipe nails, 4 screws, + 6 nails			3	
		1 band for pipe			6	
		3'3 of 9x1 1/2" deal			10	
		1'3 of 3x3 "			3	
		1 lb. paint			6	
		soldering watercart			6	
	6	do. do. 2 hrs.			13	
	7	1 grease trap			26	
	24	repair 2 pair of shears			9	
Aug.	7	1- 9x1 1/2" galv'd. pipe for pump 1 collar carriage 1 hr. fixing	} 1/10		13	
					2	
					5	
					6	
	18	repair stilt			6	
	27	1 hr. put in hammer-stick			7 1/2	
Sep.	29	1 man 1 hr. re-pipe R.W. Pipe			10 1/2	
	29	1 man 4 1/2 hrs. repair kitchen table	} 1/4-		18	
	30	1 man 4 hrs. do. do.				2 1/2
		1'6 of 5 1/2 x 1" deal 18. 2" + 4. 1 1/2" screws				3
	30	1 man 3 hrs. put glass in garden lights			13	
		5 panes glass 4 sq. ft. } 1 1/2 lbs. putty }			12 1/2	
					2 1/2	
Oct.	12	1 man 9 hrs. make + fix shelves in apple room			39	
	13	1 man 6 hrs. do. + put in glass			26	
		38'6 of 7x1 floor prep.	1 1/4		40	
		17'0 of 9x3/4 prep.	2 1/4		32 1/2	
		6'3 of 11x3/4 edging	2 1/2		14	
		23'6 of 2x1 brackets			8	
		forward	£		194	
					194	

£ o d

	forward	1	19	4
	1 1/2 lbs. nails			3
	1 pane glass 15 x 7" & putty			3 1/2
Nov. 12	put handle in spade } rivet in handle 4"			1 0
13	1 man 5 hrs. take out cistern of boiler			2 1
17	1 man 5 1/2 hrs. fix new cistern			2 3 1/2
	1 man 5 hrs. do. & solder pipe			2 1
18	1 man 1 hr. do.			5
	1 cistern,			8 6
	1 nut (back)			5
	4 bricks, 1 bkt. mortar			10
	4 1/2 pk. cement			3 1/2
	new damper iron & ring			3 3
	solder			3
16	1 man 5 hrs. repair shuting } 3 shute holdfast 6. 1 1/2" screws			2 1
				1 0
				2
17	1 man 3 1/2 hrs. fix lamp bracket } deal, nails & screws			1 5 1/2
				3
18	1 man 4 1/2 hrs. make book stool, ease drawer & stop in shuting			1 10 1/2
	2" q of 12 x 3/4 deal for stool			7 1/2
	2" o of 3 x 1 1/2 "			2
	putty			1 1/2
23	1 hr. fix lamp shade. } 1 glass bell + crook			5
				1 5
25	1 hr. fix stable lamp			5
0 + 24	1 man 4 hrs. make flower staging			1 8
25	1 man 9 hrs. do.			3 9
26	1 man 8 hrs. do.			3 4
27	1 man 9 1/2 hrs. do.			3 11 1/2
	forward	£	4	4 1
			4	4 1

1908

£ s d

forward.

4 4 1

Nov. 25 1 man 4 hrs. flower staging

1 8

30 1 man 3 hrs. do.

1 3

Dec. 1 1 man 2 hrs. do.

10

4 1 man 5 hrs. do.

2 1

11 1 man 1 hr. do.

5

76.0 of 7x1 floor

17

7 11

8.6 of 7x1 "

15

10 1/2

68.0 of 2x3 rafter

5 8 1/2

1 1/2 lbs. nails

1/2 2-0-0

3 1/2

12 1/2 lbs. paint 3 coats

6 3

Nov. 30 1 man 9 hrs. repair greenhouse lights

..

put in glass & repair shuting

3 9

" 1 man 5 1/2 hrs. do.

2 3 1/2

Dec. 2 1 man 3 hrs. fix shuting

1 3

3 panes glass 1 1/2 eq. pr.

9

2 pair 3" bolts

10

26 screws

4 1/2

4. 2" & 4. 1" screws

2

4 gutter bolts

2

1 lb. putty, 1/2 lb. paint

4 1/2

1. 6.0 length of 4" O.C. shuting

1 10

Dec. 1 polter watercan

6

" 1 man 3 1/2 hrs. make harness room stool

1 5 1/2

5.0 of 9x1 deal

2/6

1 2 1/2

7 sharpen & cut saw

9

£

6 7 1

Paid by cash January 9<sup>th</sup> 1909

6 7 1

Mr. Charles Copp.

1908

			£	s	d
Aug. 19	1 man 1 day 2 hrs. put in posts for				
	Yard Gates				
					4 5 1/2
20	1 man 1 day 2 hrs. making gates				4 5 1/2
21	1 man 1 day 1 1/2 hrs. do. changing				4 3
24	1 man 5 1/2 hrs. do. do.				2 2 1/2
19	1 man 4 hrs. repair pump sucker at Cottages	17			
	new leather	7			
	spindle rubber	3			
	gclouts & 2 split keys	1			2 6
					<hr/>
					17 10 1/2

Sep. 24	7c. 2 q. 5 lbs	} apples			
Oct. 19	17c. 2 q. 22 lbs.				
26	27c. 1c. 2 q. 13 lbs				
28	11c. 1 q. 0 lbs.				
	4. 18. 1. 12	at 1.10.0 per ton			7 7 6
					<hr/>
					£ 8 5 4 1/2

Paid Decr 30<sup>th</sup> 1908

## Mrs. Langdon Telford. The Priory £ . d

1908

July 3	fixing castor on bed	..	8
Aug. 17	1 man 1 1/2 hrs. repair bedroom floor	..	7 1/2
	4.6 of 7x1 floor	..	6
	4.6 of 2x1	..	2
	nails 1/-	..	1 1/2
Nov. 25	1 man 1 1/2 hrs. put lock on letter box	}	.. 7 1/2
	1 lock, 4 screws		.. 16 1/2
Dec. 10	1 man 1 1/2 hrs. repair handle of door	}	.. 7 1/2
	1 screw, 1 china escutcheon & 2 screws		.. 4 1/2
		£	.. 53

## Miss Fulford The Priory

1908

£ s d

Dec. 7	To exchanging 2 handbells. repairing fittings of clapper & putting on new handles reaps carriage of do.	} } }			
					1 14 6

Paid January 23<sup>d</sup> 1909

## Mr. Charles Stamp.

1908

£ s d

Dec. 11	repair & fix lock				9

Paid March 1909

## Mr. Wallace,

## Oakhayes

1908

£ s d

Dec. 11	lifting Fire Bracket Table for Herald Range				5 6 4 6
---------	--	--	--	--	------------

Paid. January 6. 1909



Mr. John Pyne, Greendale,

£ s d

1908

July	8	1 man 6 hrs. ring cart wheels			2 4 <sup>1</sup> / <sub>2</sub>
		man & boy 3 <sup>1</sup> / <sub>2</sub> hrs. washing cart			2 0
	9	1 man 8 hrs. ring cart wheels			3 2
	10	1 man 1 day do.			3 8
	11	1 man 1 day do.			3 8
	13	1 man 1 day put bottom in cart ring wheels			3 8
	15	1 man 1 day do. & repair cart			3 8
	16	1 man 8 <sup>1</sup> / <sub>2</sub> hrs. do.			3 4 <sup>1</sup> / <sub>2</sub>
	17	1 man 1 day 1 hr. paint cart			4 1
	18	1 man 1 day do.			3 8
	20	1 man 1 <sup>1</sup> / <sub>2</sub> hrs. do.			7
		2 new tyres 183 lbs.	2	1 10 6	
		repair 2 tailboard irons, rivets			1 2
		15-6 of 12 x 1 elm			3 3 <sup>1</sup> / <sub>2</sub>
		12-0 of 11 x 1 "			1 9 <sup>1</sup> / <sub>2</sub>
		3-6 of 3 <sup>1</sup> / <sub>2</sub> x 1 "			2 <sup>1</sup> / <sub>2</sub>
		3 lbs. nails			6
		12 4 <sup>1</sup> / <sub>2</sub> elm felloes			6 0
		12 lbs. paint			6 0
		1 lb. putty			1 <sup>1</sup> / <sub>2</sub>
				£	<u>4 3 6</u>

Aug.	21	2 men 1 day ea. repair & clean trap			8 0
	22	1 man 7 hrs. do.			2 11
		1 man 4 hrs. do.			1 8
	24	1 man 1 day 1 <sup>1</sup> / <sub>2</sub> hrs. do.			4 7 <sup>1</sup> / <sub>2</sub>
		1 man 8 hrs. do.			3 4
	25	1 man 1 day 1/2 hrs. do.			4 7 <sup>1</sup> / <sub>2</sub>
		1 man 9 hrs. do.			3 9
	26	1 man 2 hrs. do.			10
	27	1 man 3 hrs. do.			1 3
	31	1 man 1 day 1 hr. do.			4 5
		forward	£	1 15 5	

1908

£ s d

		forward	1	15	5
Sep.	1	1 man 5 hrs. trap		2	1
	2	1 man 7 hrs. do.		2	11
	3	1 man 8 hrs. do.		3	4
		re-typing 2 wheels		5	0
		iron plate & new clip for tail iron		..	8
		2 shaft irons		3	4
		leather for shafts		5	3
		putting on leather		2	9
		canvas for bottom		5	0
		2 harness staples		..	7
		2. 3 x 3/8 bolts, 1. 1 1/2 x 1/4 bolt		..	3
		2 1/2 lbs. paint		1	3
		1 1/2 pints of varnish		3	0
		3/4 pint of Goldsize		1	0
		man striping		4	6
		3-0 of 6 x 1/2 walnut dash board		..	..
		3-6 of 1 1/2 x 3/4 do. do.		1	0 1/2
	7	1 man 1 1/2 hrs. put trap together		..	7 1/2
				<b>£</b>	<b>3 18 0</b>
Nov.	25	1 man 6 hrs. repair trap shaft & dash board		..	..
		3-0 of 6 x 1/2 walnut dash board		2	7
		varnish paint		..	9
		sewing on leather		..	3
		repair dash board irons, step, & put 2 clips on shaft		..	6
				3	6
				7	7
				3	18 0
				4	3 6
Dec.	8	3 hogheads		..	15 0
				<b>£</b>	<b>9 4 1</b>

trap cart

Print February 5<sup>th</sup> - 1909

1908 Mr. Henry Pile, Bagmoor Farm

				£	s	d
July	16	1 hr. repair sheep dip				5
		12. 1 1/2" screws				2
		repairing hinges				16
Sep.	10	1 man 1 day make cider trough				38
		12. 6' of 14 1/2" x 1 1/2" elm	<del>3 3/4</del>			42
		4. 6' of 17 1/2" x 1 1/2" elm	5 1/2 <del>1 1/2</del>			20
		4 lbs. nails				8
	12	put handle in pick				5

£ 13 0

Paid June 9<sup>th</sup> 1909

Mr. C. Nickells, Exton Mills

				£	s	d
1908						
Oct.	20	1 man 1 day repair pond				3 10
	21	1 man 1 day do.				3 10
		put nut & plate on bolt				4

£ 8 0

Paid April 27<sup>th</sup> 1909

Feb 4<sup>th</sup> / 09

H. W. Furnivall, Esq.

1908

£ s d

Aug 6	1 man 2 hrs. put in sash cords		10
	4 sash cords + clouts		15
Sep 12	1 man 6 hrs. prepare fire stop block + posts for yard door		26
	2-0 of 6x4 oak stop block	8	14
	2-0 of 4½x3 post	4½	9
	1-6 of 4½x4 "	6¼	9½
	2 hooks + eyes + <del>2</del> screws		7½
	3. C.S. nails, 4. 1½ screws		2½
	iron plate + staple		10½
14	1 man 3 hrs. make table		13
15	1 man 9½ hrs. do.		3 11½
16	1 man 5½ hrs. do.		2 3½
19	1 man 1 hr. do.		5
	13-6 of 12x1 deal top	3½	3 11
	6-6 of 11x1 "	3	17½
	2-3 of 3x1 "		2½
	4 castors + 12. ¾ brass screws		3 9
	stain + varnish		6
	turning 4 legs	19-8.	19

£ 190

Print February 5<sup>th</sup> 1909

## Mr. Walter Stamp

1908

£ s d

July	11	2 shoes	pony	1	0
	18	2 shoes	do.	1	0
Aug.	14	2 shoes	do.	1	0
	22	2 shoes	do.	1	0
Sep.	21	2 gate hooks		..	8
	23	1 hasp + 2 staples		..	6
	-	1 shoe steeled		..	9
	26	3 shoes	pony	1	6
Oct.	8	2 removes	horse	..	7
	17	2 shoes	do.	1	2
	19	1 shoe	pony	..	6
	24	2 shoes steeled		1	4
Nov.	7	2 shoes	pony	1	0
	12	1 shoe	"	..	6
	20	2 shoes steeled		1	4
Dec.	5	2 shoes	horse	1	2
	11	1 shoe	pony	..	6
	18	3 shoes	"	1	6
	24	2 shoes fasten shoes		..	2

24

17 2

Paid May 4<sup>th</sup> 1909

Jan. 20. 10

## Rev. Godfrey Bird

1908

£ s d

Aug. 15	1 man 3 hrs. make loft door		1	3
	12' 0" of 6 x 3/4 match	1	1	3
	8' 0" of 9 x 3/4 deal		1	6
	6' 0" of 7 x 1 ledges		..	7 1/2
	1/2 lb. nails, 1/2 lb. paint		..	4
17	1 man 4 hrs. hang loft door & fasten jambs		1	8
	1 lb. paint, 1/2 lb. nails	7/3	..	7 1/2
Sep. 14	24' 0" of 2 x 3 rafter		2	0

£ - 9 3

1909  
June 7 1-6 of 12 x 1 deal planed

6

£ 9 9

## Rev. R. W. Fawkes

1908

£ s d

Aug. 25	1 man 3 1/2 hrs. repair wheel bolts & oil wheels		1	9
	new nuts 10 bolts & screw bolts		1	0
	6. 1" screws		..	1

£ - 2 10

1909  
June 8 1 man 1/2 hrs. oil trap wheels  
.. solder Kettle

1 0

5

Paid August 6<sup>th</sup> 1909

£ - 4 3

Mr. T. Stocker, Raleigh Cottage, Withycombe  
Raleigh

1906			£	s	d
Aug.	18	1 man 1 day 2 hrs. repair rails + make gate for Cottages		4	5½
	19	1 man 1 day 2 hrs. make + hang gate		4	5½
	20	1 man 2½ hrs. paint gate + put square on door jamb			10
		14-3 of 4½ x 3 oak for 3 posts	4½		55
		3-6 of 11 x 3 deal for gate	8		24
		3-6 of 9 x 1 " "	2½		9
		2. 3½ x 3/8 bolts			2
		7. 1½ screws, 2 C. S. <del>screws</del> nails			2
		4. 1¼ screws			1
		2-3 of 2½ x ½ deal			2
		1 square + holdfast			6
		2 lbs. paint			10
			£	10	6

Paid January 14<sup>th</sup> 1909

1908 Mr. W. Chapman. Carrier

		£	s	d
Aug. 27	1 man 1 day make pump trough		3	8
28	1 man 1 hr. paint do			
31	1 man 2 hr. pic do			7½
	4 lbs. paint		2	0
	2 lbs. nails			4
	6-6 of 4x3 oak legs	3½	1	11½
	13-0 of 11x1½ deal	4½	5	8½
	1-6 of 7x1½ "			4½
		£	14	0

Paid February 3, 1909.

Mr. W. Troake. Southhill

		£	s	d
1908				
Sep. 28	1 man 5 hrs. repair trap, collar wheels &			
	leather collars		2	0
	screws			5
	new shaft iron			1
	cut & shoot tyre			9
			2	6
		£	5	9

Paid May 24<sup>th</sup> 1909



Mr. John Skinner

1908

				£	s	d
Sep.	21	1 man 4 hrs. repair <sup>gate at</sup> cottages			1	7
	22	1 man 3 hrs. do. do.			1	2½
	24	1 man 3 hrs. hang & paint gate & post posts right				2½
		11-3 of 2x3 deal				11½
		1 lb. nails				2
		2 lbs. paint			1	0
		7 1½ screws				1½
		3-3 of 4½ x 1 deal				5
		1 holdfast				3
Nov.	4	1 man 6½ hrs. make stairs for 2 stamps			2	7
	5	1 man 1 day do. do.			3	8
	6	1 man 1 day do. do.			3	8
	7	1 man 1 day do. do.			3	8
		22-0 of 9x¾ deal	2		3	8
		46-0 of 11x1 "	3		11	6
		3-0 of 9x1 "				9
		11-0 of 3x3 "	2½		2	3½
	9	1 man 1 day fix stairs			3	8
		1 man 2½ hrs. helps do.			1	0
	10	1 man 7½ hrs. fixing do.			3	0
		1 man 3 hrs. repair lynchay roof			1	2½
	11	1 man 8½ hrs. fix stairs linings			3	4½
	12	1 man 1 day do. & doors			3	8
	13	1 man 1 day do. do.			3	8
	14	1 man 1 day do. do. make barge scappings for J. Godfrey's lynchay				38
		13-9 of 5½ x 1½ jambs in stairs	2½		2	10½
		11-3 of 5½ x 1 "	1½		1	5½
		12-9 of 7x1 ledges	1½		1	7
80-6		80-6 of 7x¾ match	1¼		8	4½
		15-9 of 9x½ deal	1¼		2	3½
		forward			3	186½

1908

£ s d

	forward			3	18	6½
x	4.6 of 2x1 deal			..	2	
F	7.0 of 4x2 .. prop			..	8½	
	2 bow latches complete & screws			1	0	
	1 pair of Tee hinges & screws			..	6	
	1 pair 12" do. do.			..	7	
	4 lbs. nails			..	8	
L	30.0 of 2x1 batten roof			..	11	
L	6.0 of 2x4 rafters ..			..	7½	
+	1.0 of 4x3 ..			..	3½	
+	1 holdfast & guide ..			..	5	
+	1 lb. nails ..			..	2	
L	25.0 of 7x1 barge	1¼		2	7½	
L	12.6 of 9x¾ capping	2		2	1	
L	½ lb. nails			..	1	
Nov. 25	1 man 8 hrs. fix barge & capping			2	0	
L	1 lb. nails			..	2	
L	1 lb. of paint			..	6	
Dec. 4	1 man 4 hrs. paint stairs			1	7	
5	1 man 3 hrs. do.			1	2½	
..	1 man 2 hrs. put perforated zinc			..		
+	in window at W Channon's			..	9½	
L	4.0 of 2x1 batten			..	2	
+	2.3 x 1.10 of perf. zinc	4p.	3	1	0	
L	40. ½" clouts			..	3	
L	4½ lbs. paint for stairs			2	3	

£ 4 19 3

stairs 3-14-6½  
 January 11<sup>th</sup> 1909 Received on acc<sup>t</sup> £ 2.10.0  
 Settled, July 19. 1909.

30.12.08

## The Vicar &amp; Churchwardens of Kingsbridge

1908

Decr

For repairs to the peal of 8 bells in Kingsbridge Church Tower according to estimate of July 10 <sup>th</sup> 1908	£ 0 0
For putting in extra struts and bolts to the frame as per estimate of Oct 5 <sup>th</sup> 1908	31 14 0
	" " "
	4 10 0
	<hr/>
	£ 36. 4 0

Paid January 5<sup>th</sup> 1909

Rev<sup>d</sup> G. H. Molineux. Colyton

1908

Dec<sup>r</sup>

For repairs to the bells in Colyton Church	£	0	d
Towse according to estimate of Oct <sup>r</sup> 19 <sup>th</sup> 1908	25	0	0
For grants turning the 2 <sup>nd</sup> Bell	1	2	0
	<u>£</u>	26	20

February 4<sup>th</sup> 1909 Received on acc<sup>t</sup> £20=

April 24<sup>th</sup> 1909 Received the balance

## Rev. H Fuller Maitland, Awliscombe

1908

			£	s	d
October	7 <sup>th</sup>	2 mens time and rail fares going			
&	8 <sup>th</sup>	to Awliscombe, setting Tenor Bell right			
		and overhauling the other bells & frame.			
		Trap to W. R. & back, twice to W. R.		2	6
		2 mens rail fares		7	10
		Wedges & oil		1	4
		Time 41 hours at 8 <sup>h</sup>		1	7 4
			£	1	19 0

Paid. Jan. 8. 1909.

1908

Mar. 25. 1909

Oct.	9	To one quart of Castor oil rean			
		omitted from Christmas acc.			
				2	0

Paid April 28<sup>th</sup> 1909

Rec<sup>d</sup> A. V. Cox. Stockland

1908

Nov-30

2 mens time and rail fares, going to Stockland, setting Tenn Bells right- and overhauling the other bells

Trap to W.R. twice with <sup>and after</sup> chain blocks  
rail fares

2 6

3 11

Trap at Honiton to Stockland & back

10 3

time 22 hrs at 8<sup>d</sup>

14 8

---

£ 1 11 4

Paid January 15<sup>th</sup> 1909

## The Rector &amp; Churchwardens of Lympstone

1908

Decr 21 For one Ball Rope 40 feet long

11 6

Paid April \* 1909

Wm J Brown. Carpenters Herndon

1908	Nov 24	For 6 Bell Ropes for Herndon Church Bells at 14- per Rope	3	6	0
------	--------	--	---	---	---

Paid June 3<sup>rd</sup> 1909



Jan. 8. 09  
Jan. 11. 10

Rev. G. J. Powell. The Vicarage. Holbeton

1908

£ s d

Nov. 3	To repairing & tuning a set of 12 handbells carriage	1 16 0
--------	---	--------

Paid. Jan. 17. 1910

Decr 31<sup>st</sup> 08  
June 30 09  
Aug 24 09

Rev<sup>d</sup> G. H. May. Rotorough Rectory. Beaford

1908

Oct<sup>r</sup> 22<sup>nd</sup>

For 4 Bell Ropes each 20 feet long at 11/6

£ 0 8  
2 6 0

August 26<sup>th</sup> 1909 Received on acct £ 0 8  
1 10 6

Sept 4<sup>th</sup> 1909 Received the balance 15 6

Sent to Mr. Fumaine  
Aug. 7. '09

Feb. 3. 1909.

## The Vicar &amp; churchwardens of Berry Pomeroy

1908

Decr

For overhauling & screwing up the Bells  
& frame in Berry Pomeroy to church Tower  
according to my letter of Decr 4<sup>th</sup> /08

1 10 0

Repairs to Tower Wheel

2 0

New Sledge to 6<sup>th</sup> and carriage of  
same to Totnes

3 6

£ 1 15 6

Paid August 21<sup>st</sup> 1909

The Vicar & Churchwardens of Wedmore

1908

Decr	19 <sup>th</sup>	For 6 Bell Ropes at 11/6 per rope
"	"	2 do - do with strap ropes at 13/-

£	s	d
3	9	0
1	6	0
<hr/>		
4	15	0

Settled April 6<sup>th</sup> 1909

Rev. W. B. Mason

1- Make. Vicarage, Puryear

1908

Decr	19	For 3 Bell Ropes each 70 ft long and carriage by Parcel Post	£ 0 1	1 14 6
------	----	---	-------	--------

---

Paid April 1<sup>st</sup> 1909

Paid W. D. Pitman, Weton Giffard

1908

June

14<sup>th</sup> Mens line & train fares going to Weton  
Giffard, screwing up bells & frame

Chapter 11/1

18 0

Paid March 31<sup>st</sup> - 1909

Rev<sup>d</sup> R.W.G. Pomb. Coombe in Lignhead

1908

Dec <sup>r</sup>	21 <sup>st</sup> Man's time & rail fares going to Coombe-	£	0	d
"	in - Lign-head screwing up bolts & frame	"	"	"
"	rail fares 3/6 time 10 <sup>1</sup> / <sub>2</sub> hrs 4 <sup>d</sup> - 9 <sup>d</sup> 10 <sup>d</sup>	"	11	4
		<hr/>		

Paid April 4<sup>th</sup> 1909

Rev. H. Gordon Lowe

1908

Dec- 15<sup>th</sup> For overhauling the frame, and screwing  
up frame & Wells in Coleridge Church

Toda

Train fares -

~~Time ~~20.00~~ ~~at~~~~~~Wet gas & oil~~

4 11

~~5 4~~

3

---

10 6

---

Paid June 5<sup>th</sup> 1909 - 10/6



June 30 '09  
Oct - 2nd / 09

W. C. Bere. Chunchwaiden. Silverton

1408

Dec- 23

2 mens rail fares to Silverton &amp; back

44

2 mens lunch 23<sup>rs</sup> at 8<sup>th</sup>

154

2 pulleys - one to 1<sup>st</sup> rope & one to 2<sup>nd</sup> rope

60

2 Bell Ropes 60 feet long 2<sup>nd</sup> & 4<sup>th</sup>

130

= 288

Paid Oct. 18. 1909

Rev. J. E. Waldie  
 The Vicarage Broadkempston

1908  
 Dec<sup>r</sup> 10<sup>th</sup>

balance due for fixing chiming apparatus  
 mans rail fare from Tolnes to Haslemere  
 and back, and time screwing up frame & bells

£ 0 0

4 0 0

" "  
 8 6

---

4 8 6

February 2<sup>nd</sup> 1909 Received Postal order for  
 from Mr. C. Newkham Hon. Sec. to Church Council

8 6

left due

4 0 0

Nov. 22. 1910 Received on a/c.

2 0 0

left due

2 0 0

Jan. 8 - 09  
 Aug - 28 / 11  
 Jan. 10

Mr. James Hall, Baker

1908

£ p d

Sep.	30	1 man 1 day make trap cover			38
Oct.	1	1 man 1 day thr. do.			40
	3	1 man 4 1/2 hrs. do.			19 1/2
	5	1 man 1 hr. paint do.			5
	6	1 man 1 1/2 hrs. do.			7 1/2
		5-6" of 7x1 deal	1 1/4		7 1/4
		5-6" of 11x3/8	2		11 1/2
		3-9" of 12x3/8	2		7 1/2
		12-0" of 9x3/4	2		20
		3-6 x 3-0 of Zinc = 10-6	3		27 1/2
		52 clout, 6 screws			3 1/2
		1 1/2 lbs. paint, 1/2 lb. nails			10
		2 trap plates + rail for cover			20

12 0 = 4 1/2

£ 106

1909

Feb.	17	cut & shoot type			20
Apr.	28	do.			20
		2, 2 1/2 x 3/8 bolts			2
May	22	1 man 7 hrs. alter tables			29 1/2
	24	1 man 7 1/2 hrs. do.			30
		5-0" of 2x4 legs	2 1/4		12
		5-0" of 1x7 frame	7/9		7 1/2
		12, 1 1/2" screws.			2

£ 112 5

Sept 2nd 1909 Received on acct 12-5

Jan. 8. 09

Mrs. Jane Glanville

1908

			£	s	d
Oct.	14	1 man 1 day make bullock boxes		3	8
	15	1 man 1 day do.		3	8
Nov.	2	1 1/2 hrs. put in pane glass			
		1 pane 14x10 sputty		1	3
			£	8	7

Paid March 3<sup>rd</sup> 1909

Jan. 8. 09

Mr. M. Hearn

1908

			£	s	d
Oct.	15	1 man 8 1/2 hrs. ring carriage wheel		3	4 1/2
	16	1 man 5 1/2 hrs. do. do.		2	2 1/2
		5 ash felloes (small)		1	3
		4 spokes		1	4
		1/2 lb. paint			3 1/2
		new tyre		4	10 1/2
			£	13	4.

Paid January 23. 1909

Jan 8. 09

Messrs. Carter, Wynards, &amp; Buddleigh

1908			£	s	d
Oct.	26	1 man 4 hrs. alter steps, & clean. paint + varnish trap	1-8		18
	27	1 man 6 1/2 hrs. do.	2-8 1/2		28 1/2
	28	2 men 1 day ea. do.	8-0		80
	29	1 man 7 1/2 hrs. do.	3-1 1/2		31 1/2
		1 man 5 1/2 hrs. do.	2-3 1/2		23 1/2
	30	1 man 1 hr. do.	5		5
	31	1 man 4 hrs. do.	1-8		18
Nov.	2	1 man 5 1/2 hrs. do.	2-3 1/2		23 1/2
	3	1 man 5 1/2 hrs. do.	2-3 1/2		23 1/2
	4	1 man 8 hrs. do.	3-4		34
	5	1 man 1 hr. do.	5		5
	9	1 man 5 1/2 hrs. do.	2-3 1/2		23 1/2
		striping trap	7-0		70
		patent leather	5-0		46
		saw on do.			26
		canvas	3-3		33
		1 1/2 pints. Varnish	3-0		30
		1 lb. black japan	2-0		16
		1 lb. green paint	9		9
		1 lb. drop black	9		9
		4 new spring clips	1-8		20
		2 ash blocks	3		3
		smith altering steps	1-0		16
			2-17-0	£	2176

Paid by Contra etc.

August 2. 1909

1908 Mr. M. Stokes Glasgow

£ s d

Nov.	5	1 lab. 3½ hrs. take off roof at Miss Lakes		1	3½
	6	1 lab. 1 day clean tile r.		3	4
		1 man 1 day put on roof		3	8
		1 man 7½ hrs. do.		3	0
		1 man 6 hrs. do.		2	4½
	7	1 man 1 day do.		3	8
		1 man 4½ hrs. do.		1	9½
		1 lab. 1 day do.		3	4
	9	1 lab. 1 day do.		3	4
		1 man 6½ hrs. do.		2	7
		143-0 of 2x1 batten		4	4
		40-0 of 1½x1 do.		..	9
		130-0 of 2x3 rafter		9	6
		22-0 of 2x4 poll plate		1	10
		25-6 of 3x4½ plate & bearers	2	4	3
		8 lbs. nails		1	4
		1 piece sheet iron 12x9 & clouts		..	2
		76 bricks		2	8
		2 barrows mortar		1	2
		100 tiles		5	0
		18 yds. brown felting	29¼	4	1½
		13-3 of 2x3 W.C. jambs		1	0
		2-6 of 3x3½ oak sill do.		..	8
		4 dos. clouts, 3 shutt screws		..	4
		putty ? 9' of 9x2 deal		..	2
		1 piece hoop iron, 2 screws		..	2
		4 holdfasts		..	8
		3 shutt holdfasts		..	10½
		1 plate & 2 bolts		..	10½
	14	1 man 5 hrs. fix shuting		2	0
	20	repair damper chain		..	4

carried forward to page 254

7

3 10 7

Jan. 8. 09  
 July 23. 09  
 Jan. 20. 10  
 Exton

Mr. Ashton Hill, Rusholme,

1908			£	s	d
Nov.	23	To making and painting a dog's kennel + delivering same	1	12	0
	26	1 man 3½ hrs. make shelf brackets		1	7½
	27	1 man 8½ hrs. make + fix do. + shelves		3	11
		60-9 of 7x1 floor	14	6	4
		24-0 of 2x1 batten		10	½
		1½ lbs. nails		3	
		deliver do.		10	
			£	2	6
				0	

Paid. Mar. 12. 1910

Mr. Beau Miller

1908			£	s	d
June	1	1 man 2½ hrs. make pig trough 9-6 of 10½ x 1½ elm 1½ lbs. nails		1	0
				3	0

Paid January 12<sup>th</sup> 1909

Mr. Alfred Stokes

1908

£ s d

Dec. 17	1 man 1 hr. make casements (4)	..	5
18	1 man 5 1/2 hrs. do.	2	2 1/2
19	1 man 1 day do.	3	8
21	1 man 1 day do.	3	8
22	1 man 1 day hang + glaze do.	3	8
23	1 man 1 day do. + repair stairs	3	8
	2 panes 12 1/2 x 7 1/2 ea.	..	4
	4 do. 9 x 7 1/2 ea.	..	5
	8 do. 11 1/4 x 8 1/2 ea.	1	4
	2 pair 2" butts. + screws	..	7
	1 button, 1 knob, 1 hook + eye	..	3
	6" 0 of 2 x 3 deal for stanchions	..	6
	1" 9 of 5 x 3/4 "	..	2
	2 lbs paint	1	0
	nails 1"	..	1
	2 1/2 lbs putty	..	4
	7" 0 of 11 x 1 1/2 deal for casements	4 3/4	2 9
	1 window stay	..	4

1909

Jan. 4	1 man 7 1/2 hrs. making casements (3)	3	0
5	1 man 1 day do.	3	8
6	1 man 1 day do.	3	8
7	1 man 1 day make, fix. + glaze do.	3	8
8	1 man 1 day do.	3	8
9	1 man 5 1/2 hrs. do.	2	2 1/2
11	1 man 7 1/2 hrs. make casements	3	0
12	1 man 7 1/2 hrs. do.	3	0
13	1 man 7 1/2 hrs. repair gate put in posts	3	0
14	1 man 7 1/2 hrs. repair floor + fix down pipe	3	0
15	1 man 7 1/2 hrs. make 3 casements	3	0
16	1 man 3/4 day do.	2	9
	20" 0 of 7 x 1 1/2 deal for casements	5	0
	16 panes glass 11 1/4 x 8 1/4 each.	2	8

forward to page 265

£ 3 10 8

3 10 8



## Miss Moulton Barrett

1908

			£	s	d
Nov.	2	39-0 of 2x1 batten		1	3
Dec.	5	1hr. put glass in garden light		..	5½
		glass 2-3 x 5½		..	5½
		putty			2
	17	5hr. repair & glaze garden light		2	3½
		3-3 of 4x¾ deal		..	3½
		2lbs. putty		..	3
		nails		..	2
	17	7hr. prepare old oak		..	..
		4-6 of 12x½ oak (old.)		3	6
	24	solder gas lamp		..	3
		new rod & thumb screw to gas lamp		10	
Dec.	31	do. do. do.		10	

---

£ 11 1

---

Paid. February 9. 1909.

Mr. Albert Gigg. Within Farm

1908

£ s d

July	Extra on pulpit 5½ x 3 instead of 4½ x 3			10	0
..	To making, fixing + glazing window in end of building as per estimate			15	6
Aug.	To providing, fixing + painting shuting as per estimate			4	0 0
15	1 man 3½ hrs. put post in stable			1	5½
26	1 man 2 hrs. prepare stall rail			..	10
..	1 man 1 day fix stall + shippen rails			3	10
27	2 men 1 day ea. do.			7	8
Sep. 24	1 man 4 hrs. do.			1	8
28	2 men 5½ hrs. ea. fit up stable			4	7
29	2 1 man 5 hrs. do.			2	1
	10 oak posts 7-0 long ea. 5 x 4½	73/4	2	5	2½
	2 do. 10-0 long ea. 5 x 5	14-7		14	3
	6 lbs. nails	8 3/4		7	0
	5. 7½ x 3/8 bolts			..	10
	7 bolts for shippen			3	0
	56-0 of 7 x 1 deal stall	4 1/4		5	10
	15-0 of 9 x 1 " "	2 1/2		3	1½
	1 lb. nails for stall			..	2
	48-0 of 4½ x 3 curb rail	3 1/2		14	0
	10-6 of 2 1/2 x 7 deal harness pegs			2	7½
	4-0 of 12 x 1½ elm do.			1	2
	16 bolts for racks + mangers +			..	..
	4 spikes			3	10
	4 catches			..	10
	2 mangers, + 2 racks		2	5	0
	8-0 of 4½ x 3 oak sill	4 1/2		3	0
	8-0 of 4½ x 3 deal top	3 3/4		2	6
		4		13	14 4

Paid February 8<sup>th</sup> 1909

Jan. 11. 09

Mr. Wm. Summerfield

1908

£ o d

Jan.	1	2 shoes		10	
	21	2 shoes		10	
Feb.	5	put pulley in block wood & screw		6	
	20	4 shoes		20	
Mar.	9	releather pump sucker		16	
	25	1 hr. repair cart	5 <sup>00</sup>	}	
		1-3 x 3/8 bolt	1 <sup>00</sup>		
		2 plates iron	1-0		
Apr.	9	cutting 2 down pipes		9	
	16	2 shoes		10	
		draw 2 loads sand		14	
	25	do.	do.	14	
	27	do.	do.	14	
May	28	2 shoes		10	
	19	sharp 3 chisels		3	
May	20	1 man 2 1/2 hrs. make paint shute	}	10	
		16' 0" of 1 x 9 deal		29/4	38
		1 lb. paint 6 nails 1 <sup>00</sup>			7
	27	1 man 3 1/2 hrs. repair & paint & varnish trap		15	
	28	1 man 1 day	do.	38	
	29	1 man 1 day	do.	38	
	30	1 man 3 hrs.	do.	12 1/2	
June	1	1 man 1 day	do.	38	
	2	1 man 6 hrs.	do.	24 1/2	
	3	1 man 2 1/2 hrs.	do.	10	
		screw bolts on step of trap		3	
		2 new tyres 54 lbs.	23/4	124 1/2	
		6' 0" of 1 1/2 x 3/4 ash		3 1/2	
		2' 9" of 5 x 3/4 deal		3 1/2	
		4, 1 1/2 x 1/4 bolts, 6-1 1/2 screws		3 1/2	
		2 leather collar	1-12-5	6	
		3 lbs. paint, 3/4 pint varnish		16	
		forward	£	2 12 3	
				2 12 3	

1908

£ s d

forward

2 12 3

May 29 1 man 4½ hrs. make a coping box

1 9 ½

2·0 of 12x1½ elm

· 7 ½

10·0 of 7x1 floor

1 0 ½

10·0 of 2x1 batten

· 4

8. 2 screws, ½ lb. nails

· 3

May 28 Horse + cart 1 day Lympstone

6 0

29 do. 1 day do.

6 0

June 1 do. 1 day do.

6 0

4 do. 1 day do.

6 0

12 4 shoes

2 0

July 6 2 shoes

1 0

.. draw 2 loads to Within

5 0

24 3 shoes

1 6

Aug 8 2 shoes

1 0

26 draw 1 load from Within

2 0

Sep 17 1 staple

· 2

Oct. 9 3 shoes

1 6

sharp pick

· 2

20 1 remove

· 3

29 2 shoes

1 0

Nov. 2 1 shoe

· 6

13 3 shoes

1 6

28 1 man 5 hrs. make centres

2 0

34·0 of 14½x1½ elm

12 10

45·0 of 2x1 batten

1 5

Dec. 2 2 shoes

1 0

7 draw 500 brick for boxton

6 0

8 draw 250 brick do.

3 0

10 draw 250 brick do.

3 0

15 sharpen pick

· 2

16 draw 250 brick do.

3 0

forward

£

6 10 3 ½

6 10 3 ½

1908

£ s d

		brok. forward		b	10	3½
Dec.	18	new flue			10	
	24	2 shoes			10	
	22	1 man 8 hrs. repair doors boarding at Mr. P. Smiths			3	2
	24	1 man 8 hrs. do. making doors			3	2
	28	1 man 7½ hrs. hanging doors			3	0
	29	1 man 7½ hrs. do. repair boarding			3	0
	30	1 man 4 hrs. painting stanning doors			1	7
		21-0 of 1x7 floor	1¼		2	2½
		1 lb. nails			.	2
		48-3 of 1x7 deal imp. 2 doors	1¾		7	0½
		16-9 of 1x9 "	2¾		3	10
		23-0 of 7x1¼ " ledges	2		3	10
		3 lbs. nails			.	6
		24-9 of 1x7 hatch h.e. door	1½		3	1
		7-6 of 1x7 ledges			1	1
		1 lb. paint			.	6
		8. 3x¾ bolts			.	8
		12. 1½" screws			.	2
		1 Norfolk handle complete screws			.	7
		9-0 of 12x1 elm			1	10½
		7-0 of 12x¾ "			1	2
		1 lb. nails, 10. 1" screws			.	3½
		tar			.	3
		3 pair of hooks & thist			6	6
		1 drop hasp + 2 staples			.	4
				£	9	0 3½
		to 1907 account		£	12	14 4½
		to 1906 account		£	18	17 3½
				£	40	11 11½

1909 Mr. W. Summerfield

	£	s	d
Feb. To repairs done to Aylesbeare Chapel as per contract of Jan. 11. 1909	17	15	0
Extra to above contract for putting in new lead shutters instead of repair old ones			15 0
To painting 4 windows & 1 door inside 2 coats of paint			8 6
To putting on drip board on door & put piece of board on inside of door			2 10
To putting on 28-0 of skirting in main room extra to the 40-0 in contract			4 8
To putting on 9-0 on back of pulpit			1 6

19 4 6  
 less 3 0  


---

 £ 19 4 6

Paid May 4<sup>th</sup> 1909

Mr. H. Taylor

1908

Dec	24	- 8 bolts	6 <sup>cts</sup>	20
"	30	12" o. of 12x1/2-	3 <sup>cts</sup>	30
"	"	4" o. of 12x1	2 <sup>cts</sup>	15
1909	Jan	6	alter & repair ironwork	20
	"	7	new cast ironwork	6 <sup>cts</sup>
	"	12	2- staples and web	6
				<hr/>
				10 11

Paid February 13<sup>th</sup> 1909

H. L. Brown Esq =  
The Mann House  
Edginswell  
near Tugway

Feb 13 - 1909

# The Churchwardens of Coffinswell

1909						
Jan <sup>no</sup>	4 <sup>th</sup>	4	4	Bell Ropes each 20 ft long	£	0 d
"	"	"	"	at 11/6 per Rope	2	6 0

Paid February 1909



R. D. Puckman Esq<sup>r</sup>  
Dow

1909

February 23<sup>d</sup> For 5 Muffles at 3/617 6<sup>d</sup>Paid February 26<sup>th</sup> 1909

W<sup>m</sup>-W Pyle, Churchwarden. Talatou

1909

Feb 26

For 6 Bell Ropes each 40 feet long  
at 11/6 per Rope

£	0	d
3	9	0

Paid by Money Order.  
March 4<sup>th</sup> 1909

Rev<sup>d</sup> C. G. Barton  
 Roudon Rectory.  
 Lyme Regis

1909		£	s	d
January 15	For providing and fixing chiming apparatus to the 3 bells in Combepyne Tower, according to estimate of Decr 24 <sup>th</sup> 1908	5	6	0
		<hr/>		

Paid April 10<sup>th</sup> 1909

Rev<sup>d</sup> W. F. Connor  
The Rectory  
Kingsnympton

1909

Feb <sup>ry</sup> 3 <sup>rd</sup>	For providing and fixing the Ellacombe chiming apparatus to the 6 bells in Kingsnympton Church Tower according to estimate of Dec <sup>r</sup> 21 <sup>st</sup> 1908	£	0	d
		"	"	"
		"	"	"
		8	3	0

Paid April 19<sup>th</sup> 1909

Rev<sup>d</sup> T. G. Fox  
The Vicarage  
Shebbear

1909						
Feb <sup>ry</sup>	18 <sup>th</sup>	For providing and fixing the Ellacombe chiming apparatus to the 6 bells in Shebbear Church Tower according to estimate of January 23 <sup>rd</sup> 1909	£	0	d	
		extra for putting a door with lock & 2 keys		8	18	0
					7	0
			£	9	5	0

Paid April 1<sup>st</sup> 1909

## The Vicar &amp; Churchwardens of Broadclyst

1909				
Jan <sup>ry</sup>	27	examine bells -		7 6
Feb <sup>ry</sup>	24	2 men 10 $\frac{1}{2}$ w <sup>rs</sup> each 21 w <sup>rs</sup>		12 3
		Horse & Waggon to Broadclyst with things		4 0
		trap to Broadclyst & to return with 5 bearings		4 0
	25	2 men 10 $\frac{1}{2}$ w <sup>rs</sup> each 21 w <sup>rs</sup>		12 3
	26	2 men 10 $\frac{1}{2}$ w <sup>rs</sup> each 21 w <sup>rs</sup>		12 3
		man's cart fuel to 6 <sup>th</sup> & back with gudgeons &c		9 9
	27	2 men 8 w <sup>rs</sup> each 16 w <sup>rs</sup>		9 4
March	1 <sup>st</sup>	2 men 10 $\frac{1}{2}$ w <sup>rs</sup> each 21 w <sup>rs</sup>		12 3
		Horse & Waggon fetch things		4 0
		2 mens fares from Woodbury R <sup>d</sup> to Broadclyst		1 11
		Gaston & King putting new gudgeons & bearings		" .
		to 3 <sup>rd</sup> , 5 <sup>th</sup> & 6 <sup>th</sup>		2 4 0
		Repairs to Ironwork at Broadclyst		2 0
		6 coach screws 4 x $\frac{1}{2}$		9
		1 Pulley		2 6
		Lodgings		3 0
				£ 6 15 3

1909  
 Jan<sup>ry</sup> 27 In examining the peal of 8 bells in  
 and Broadclyst Church Tower, and for  
 Feb<sup>ry</sup> 24 overhauling the frame and fittings of  
 to all the bells, and putting new gudgeons  
 March 1<sup>st</sup> and bearings to 3 of the bells and  
 one new pulley £6-13-3-

Paid April 8<sup>th</sup> 1909

Mess<sup>rs</sup> Greenleaf & Tripsam  
Hyle Street  
Hereford

£ s d

1909

February	12	1 -	5.10	Bell Wheel	1	7	6
		1 -	5.11	" out-1/2	1	8	0
		1 -	6.1	" Newcut-6 inch	1	9	0
		1 -	6.4	" Gloucestershire	1	10	6
		1 -	6.7	"	1	12	6
		1 -	7.0	"	1	15	0
				carriage to G. W. Rail & extra			26
					£	<u>950</u>	

1909	March	22 <sup>d</sup>	1 -	5.1	Bell Wheel	1	3	6
			1 -	5.2	" out-to works	1	3	9
			1 -	5.4	" Hereford	1	4	3
			1 -	5.6	"	1	5	6
			1 -	5.10	"	1	7	6
			1 -	6.2	"	1	9	6
					carriage to G. W. Rail & extra			26
					£	<u>4166</u>		

Paid May 5<sup>th</sup> 1909

The Vicar & Churchwardens of Thorrington

1908

August 27<sup>th</sup> For 2 bell Ropes at 11/- each

£ 0 4

1 2 0

Paid April 1<sup>st</sup> 1909



## The Vicar of Hloington: Heron

1909	March 6 <sup>th</sup>	For 4 Bell Muffles at 3 <sup>o</sup> 9 <sup>d</sup> include telegram	15 0
------	-----------------------	--	------

Paid April 17<sup>th</sup> 1909

The Vicar & Churchwardens of Pillon

1909

Jan 5 <sup>th</sup>	For 3 Bell Ropes for 6 <sup>th</sup> 4 <sup>th</sup> & 2 <sup>nd</sup> belf-	£ 9 d
	Tenn Bells. Tenn Rope with loop in it - 14. 14.	1 14 0

Paid June 10<sup>th</sup> 1909

## The Church Treasurers of Littlehampton

1909			£ 0 1
Febrs	15	For 5 Bell Ropes at 11/- each	2 15 0
			<hr/>

Paid April 15<sup>th</sup> 1909

The Vicar & Churchwardens of Winstock

1909

January 25	For 1 Bell Rope	11 0
	carriage by Parcel Post	6
		<hr/>
		11 6

Paid May 11<sup>th</sup> 1909

March 30  
June 30, 1909

Rev. J. Newman  
The Rectory West Buckland, Southminster

1904

March 22<sup>nd</sup> For 4 Bell Ropes at 11/- each

£ 0 4  
2 4 0

Charge 12/-

May 26 To 4 Bell Ropes 7ft. long ea. at 12/-

£ 2 8 0

Paid July 6, 1909

# Drake Egg  
Warden of Governors

March 30  
June 30, 09  
Oct- 11/16 09

248

The Crediton Church Governors

1909

March 22<sup>nd</sup> For 2 Bell Ropes at 11<sup>..</sup>9 each  
carrage paid

£ 0 d  
1 3 6

---

Paid Jan. 15. 1910

R. Butland, Esq; Decombe, Mardon, Paignton

1908		£ s d
Nov. 9	2 quarts of Castor oil + can	3 0 0

Paid April 8<sup>th</sup> - 1909

## Woodbury Churchwardens

1909

£ s d

Jan. 30	1 hr. put-pane glass in Vestry room.	} 9 <sup>00</sup>	..5
	1 pane 9 <sup>7</sup> / <sub>8</sub> x 12 <sup>1</sup> / <sub>8</sub>		..3
	putty		..1
Mar. 13	1 man 3 <sup>1</sup> / <sub>2</sub> hrs. fixing photograph in Porch & repairing notice board	}	.. :
15	1 man 1 <sup>1</sup> / <sub>2</sub> hrs. do. do.		20
	mason stop in wall		4
	4. 1/2 screws. 2 nails		2
Apr. 6	1 man 3 <sup>1</sup> / <sub>2</sub> hrs. prepare slabs for Cottages	}	
10	1 man 2 <sup>1</sup> / <sub>2</sub> hrs. fix slabs. do.		24 <sup>1</sup> / <sub>2</sub>
	26" 6" of 13" slabs		34
	9 bricks		..6
	1 bucket mortar		..4
5	1 man 1/2 day make fence for Churchyard		110
6	1 man 1 day do. do.		300
	2 men 2 hrs. ea. painting do.		17.
7	1 man 1 day make fence do.		310
	1 man 1 day painting do.		35
	1 man 6 hrs. do. do. }	} 8	.. :
	1 man 2 hrs. do. do. }		32
8	1 man 1/2 day making fence do.		111
	1 man 1 day fixing " do.		38
	1 man 6 <sup>1</sup> / <sub>2</sub> hrs. do. do.		27
	1 man 2 hrs. painting do.		..9 <sup>1</sup> / <sub>2</sub>
10	1 man 1 day 1 hr. " do.		<del>4</del> 4
	1 man 3/4 day 1 <sup>1</sup> / <sub>2</sub> hrs. do.		<del>3</del> 4
	5 <sup>1</sup> / <sub>2</sub> lbs. paint		29
	To putting rivet in handle of turf cutter		..3

£ 272.

Paid April 10<sup>th</sup> 1909



May 27<sup>th</sup> 1909

Rev<sup>d</sup> G. Bramwell  
The Vicarage Burescombe

1909

Mach	31 <sup>st</sup>	2 mens time overhauling the frame			
April	1 <sup>st</sup>	and 5 bells 244 lbs at 7 <sup>½</sup>		1	7 6
		For supplying and hanging a new Tuble Bell in the Church Tower, according to estimate of January 1 <sup>st</sup> 1909		51	17 0
		5 new bell Ropes at 11.0 each		2	18 9
		6. Clappa stays at 4/-		1	4 0
		Inscription of 40 letters at 4 <sup>d</sup>			13 4
				£	58 0 7

Paid May 25<sup>th</sup> 1909

June 30<sup>th</sup> 09  
Oct 11<sup>th</sup> 09

250

W<sup>m</sup> Charles Covey  
The Welches Lodge  
Kewley, near Harlow, Essex

1909  
April

8<sup>th</sup>

For 2 Bell Ropes each 60 ft long for 5<sup>th</sup>  
and 6<sup>th</sup> bells at 11/6 per Rope  
Carriage by Parcel Post

1 3 0

9

---

1 3 9

Paid October 25<sup>th</sup> 1909

X

June 30.09  
Oct-9/09

Wm Swain  
Wilmington

£ o d

1909

April

8<sup>th</sup>

For 2 Bell Ropes for 5<sup>th</sup> & 6<sup>th</sup> bells

1 3 0

Paid Nov. 4. 1909

June 30: 09  
Oct 9<sup>th</sup> 09

Recd. J. D. H. Patch  
Springton. Newton Abbott -

1909

April 19

For 5-13 lb Ropes each 60 feet long  
at 11/- per Rope

2 15 0

Paid Oct. 15. 1909

X June 30. '09  
 Get 9 04

Rwd R. W. Sealy

The Vicarage

Abbots Ham. 1.0

1909				
April 8	For 1 Bell Rope 50 ft long and carriage			
"	by Parcel Post for 4 <sup>th</sup> 13d			130
May 4 <sup>th</sup>	For 2 Bell Ropes each 50 ft long for 2 <sup>nd</sup> & 3 <sup>rd</sup>			160
				<hr/>
				190
				<hr/>

Paid October 29<sup>th</sup> 1909

May 25<sup>th</sup> 1909

June 28<sup>th</sup> 1909

# The Organ & Churchwardens of West Abington

1909

May 15

To lowering down the 6 Bells and taking out the old fittings, frame floor & beams from the Church Tower, providing and fixing 5 Oak beams and oak panning bed and a deal floor, and providing and fixing an Iron frame for the 6 Bells and hanging the Bells complete with new fittings, according to estimate of October 27<sup>th</sup> 1908

£ 0 d

£ 155 18 0

May 25<sup>th</sup> 1909 received on account £ 100 =  
 July 16<sup>th</sup> 1909 received the balance of £ 55 18/-

# The St. Thomas Rural District Council

1909.			£	s	d
		To repairs at Truckhayes & Winkleigh foot bridges at Colaton Raleigh			
Mar	22	1 man 4½ hrs prepare posts r.	5½		2 1
	23	2 men 5½ hrs. ea. fixing bridges			5 0½
	24	2 men 9½ hrs. ea. do.			8 9
	25	1 man 3½ hrs. do.			1 7½
	26	1 man 4 hrs. painting do.			1 10
	23	Horse & Cart deliver do.			1 6
	25	<del>do. clear away old bridge</del>			1 6
		12 spikes + 3 bolts 10 lbs.			3 4
		2. 21' 0" of 11x4 deals - 42 ft.			..
		2. 16' 0" of 11x4 .. - 32 ft. = 74' 0"	11	3	7 10
		14' 0" of 5x5 oak for 2 posts	8¾		10 2½
		6' 0" of 4½x2 oak post	4		2 0
		13' 0" of 8x5 oak bearers (rough)	8		8 8
		3' 6" of 8x1 deal	2¾		9
		10' 0" of 3x2 .. rails			.. 10
		2 lbs. nails			.. 4
		3 lbs. paint			1 6
		1 lb. putty			.. 1½
		To putting 4 new 11x4 deals and 3 oak post & bearers and painting railings at Winkleigh & Truckhayes foot bridges at Colaton Raleigh.			
			£	5	16 5.
Apr.	13	1 man 2 hrs. prepare post r. for Pydon Bridge			.. 11
	14	1 man 9½ hrs. fixing bridge			4 4½
		18' 0" of 11x4 deal	"		16 6
		6' 0" of 3x2½ .. rail			.. 9½
		4' 9" of 3x4½ oak post	4		1 7
		paint + nails			.. 4
		Horse & Cart deliver do.			1 0
			£	1	5 6.

Invoice sent  
May 21. 1909  
Bill sent  
June 16. 1909

1909

£ s d

Apr. 13	1 man 7½ hrs. prepare post rails for Greendale Bridge			3 5½
14	1 man 5½ hrs. do.			2 6½
15	2 men 9½ hrs. ea. fixing do. 1 man 3½ hrs. prepare rails do.			8 9 1 7½
16	2 men <del>4</del> 9½ hrs. ea. fixing do.			8 9
17	2 men 8 hrs. ea. do. do.			7 4
19	2 men 9½ hrs. ea. do. do.			8 9
20	2 men 2 hrs. ea. do. do.			1 10
	3 oak posts 19-0 of 6x5	10		15 10
10	do. 64-6 of 6x5½	11		2 19 1½
	94-6 of 4x3 deal rails	3		6 3 7½
	tar			.. 9½
	2 lbs. paint			1 0
	Horse cart deliver do.			1 6
	do. fetch stools &c.			1 0
	2 lbs. spikes			.. 8
	2 lbs. nails			.. 4
	Totals			7 6 11
	Masons work			1 17 0
				£ 9 3 11
Apr. 20	2 men 7½ hrs. <sup>ea</sup> repair fencing at Stocklake Pit			6 11
21	1 man 1 hr. paint do.			.. 5½
	28-0 of 4x3 deal 2 rails			..
	16-0 of 4x3 deal 2 rails 44-0	3		11 0
	2 lbs. nails			.. 4
	tar			.. 6½
	1 lb. paint			.. 3
	2½ lbs. spikes			.. 10
				£ 10 4.

Paid June 30. 1909.



Mrs. M. Stokes. Glasgow. (book page 236).

1909		£	s	d
	brok. forward	3	10	7
Jan.	4 1 man 7 hrs. put up W.C. door panels (17 in slates)		3	0
	5 1 man 1 day do. + repair + case up stairs do.			3 8
	6 1 man 1 day do. + paint do.		3	8
	7 1 man 1 day do. " do.		3	8
	8 1 man 6 1/2 hrs do.		2	7
	21-0 of 3/4" match board for door	1/4		2 2
	2-2 of 11 x 1 deal ledges			6 1/2
	2-2 of 4 1/2 x 1 do.			3
	5-3 of 2 x 3/4 do. stop do.			2 1/2
	1 pair 9" Tee hinges + screws			7
	1 bow latch			6
	31-0 of 3/4 x 9 board for stairs	2		5 2
	10-0 of 3 x 1 deal nosing			9
	2 lbs. nails			4
	3 1/2 lbs. paint			1 9
	1 pair 2" butts + screws			3 1/2
	1 window sash			4
May 29	re-leather pump sucker			9
		£	5	0 9 1/2

Paid

1909



Miss Martin. (Painting)

1909

£ s d

Apr	21	2 men 1 day ea.			7 6
	22	2 men 1 day ea.			7 6
	23	2 men 1 day ea.			7 6
	24	1 man 5 hrs.			2 1
		1 man 7 hrs.			2 11
	26	1 man 8 hrs. 1 day	5		3 9
	27	2 men 1 day ea.			7 6
		1 man 4 hrs. 1 day	1-10 <sup>5</sup>		<del>3 9</del> <del>1-10<sup>5</sup></del>
	28	1 man 1 day 2 hrs.			4 7
		1 man 1 day			3 9
	29	2 men 1 day ea.			7 6
		1 man 7 1/2 hrs.			3 1 1/2
		1 man 6 hrs 1 day	1-3		8 9
	30	3 men 1 day 2 hrs. ea.			13 9
		1 man 6 1/2 hrs			2 8 1/2
May	1	1 man 6 hrs 3/4 day			2 10
		2 men 1 day ea			7 6
	3	2 men 1 day 2 hrs. ea.			9 2
		1 man 4 1/2 hrs. 1 day	1-10 <sup>5</sup>		<del>3 9</del> <del>1-10<sup>5</sup></del>
	4	2 men 1 day 2 hrs. ea			9 2
	5	2 men 1 day 2 hrs. ea.			9 2
	6	2 men 1 day 2 hrs. ea.			9 2
	7	2 men 1 day 2 hrs. ea.			9 2
		1 man 7 1/2 hrs.			3 1 1/2
	8	2 men 1 day ea.			7 6
	10	2 men 1 day 2 hrs. ea.			9 2
	11	1 man 1 day 2 hrs.			4 7
	12	1 man 1 day 2 hrs.			4 7
	13	2 men 1 day 2 hrs. ea.			9 2
	14	2 men 1 day 2 hrs. ea.			9 2
		1 man 4 1/2 hrs.			1 10 1/2
	15	2 men 1 day ea.			7 6

forward

£

9 18 3

9 18 3

1909

9 18 3  
~~7~~ 0 d

	bro. forward		9 18 3
May 15	1 man 1 hr.		. 5
17	graining front door windows	6	6 6
"	2 men to <del>the</del> ea. 1 day 1 hr. ea.		8 4
	1 man <del>to</del> <sup>1/2</sup> hr. 1 day	3-1/2 3 1/2	3 9 1/2
18	2 men 1 day, 2 hrs. ea.		9 2
"	1 man 4 hrs.		1 8
19	2 men 1 day, 2 hrs. ea.		9 2
20	2 men 1 day 2 hrs. ea.		9 2
	1 man 5 1/2 hrs.		2 3 1/2
21	2 men 1 day 2 hrs. ea.		9 2
22	2 men 1 day ea.		7 6
	22 sheets glass paper		" 11
	7 lbs. putty		" 10 1/2
	1 1/2 pints benzoline		" 7 1/2
	1 pane glass 8 1/2 x 10		" 3
	1 do. 2-6 x 7		" 6
	1 1/2 pints Linseed Oil		" 6
	30 1/2 lbs. paint		" "
	116 1/2 lbs. "		" "
	33 lbs. "		" "
	12 lbs. "		" "
	12 lbs. "	20 4 lbs.	5 1/2 4 13 6
	1 1/2 pints Varnish	17-12-8	3 9
24	2 men 1 day 2 hrs. ea.		9 2
25	1 man 4 hrs.		1 8
28	2 men 1 day 1/2 hr. ea.		7 11
29	1 man 1 day 1/2 hr.		3 11 1/2
June 1	1 man 1 day		3 9
2	1 man 1 day		3 9
5	1 man 1 day		3 9
7	1 man 4 hrs.		1 8
	forward	7	20 1 11
			20 1 11

1909

£ p d

brn. forward

20 1 11

37 lbs. paint

16 11 1/2

1 pint of Linseed Oil

.. 4

June 8 (man &amp; hrs.)


3 4

---

 £ 21 2 6 1/2
 

---

Settled Nov<sup>r</sup> 8<sup>th</sup> 1909



June 2, '09

W<sup>o</sup> Henry Glanville, Junior

1909

May 18	For supplying a Pennant <del>stone</del> Headstone and fixing same in Woodbury Churchyard to the memory of the late W <sup>o</sup> Joseph Skinner and W <sup>o</sup> Mitchell	£	0	<sup>24</sup> / <sub>1</sub>
	Headstone		3	10 0
	engraving and leading 124 letters		1	11 0
	Setting and fixing same			10 0
	Picar Fees		1	1 0
	Sextons fees for 2 Headstones			2 0
		£	6	14 0

Paid June 5<sup>th</sup> 1909

Miss Martin (General Repairs)

1909			£	s	d
Mar.	26	repair lock			2
Mar.	30	1 man 5 hrs. take off locks on yard doors			
		+ take off repair lock on bedroom door		2	1
Apr.	2	1 mason 1 day repair plates & clean shutters		4	6
		1 lad 5 hrs.		1	3
	3	1 mason 1 day		4	6
	"	1 man 5 hrs.		2	1
		50 plate nails	1		5
		3 1/2 lbs. lead strips			7
		12. 12 x 2 1/4 plate		3	9
		1/2 lb. red lead, 1/2 lb. priming	1		6
		1 new key		1	3
		1 piece sheet iron & 2 screws	1		3
	5	1 mason 1 day repair roof of <sup>potting shed</sup> greenhouse	1		4 6
	6	1 mason 1 day	1		4 6
	7	2 masons 1 day ea. coloring	2		8 6
	8	2 masons 1 day ea.	2		8 6
	10	2 masons 1 day ea.	2		8 6
		50 plate nails	1		5
		11 zinc poakers 13 x 6 ea.		1	4
		6-3 x 3-0 of zinc flashing		5	7
		18 laths			3
		1 1/2 lbs. lath nails			4 1/2
		2 lbs. umber	2		5
		49 lbs. ochre	4		6 6
		5 lbs. tallow		2	3 1/2
		1 barrow lime			9
		5 barrows mortar		3	4
		3 do. roughcast		2	0
	13	2 masons 1 day ea. coloring	2		8 6
		1 man 1 1/2 hrs.			7 1/2
	14	2 masons 1 day ea.	2		8 6
	15	2 do. 1 day ea.	2		8 6
		forward	£	5	5 2 1/2



Miss Martin

1909

£ s d

brt. forward

5 5 2 1/2

Apr. 15	2 men 1 hr. ea.	coloring			10
16	2 masons 1 day ea.	do.	2	8	6
17	2 masons 1 day ea	do.	2	8	6
	2 1/2 gallons tar				11
	1/4 pk. plaster				1 1/2
19	1 mason 1 day	coloring Retreat +:	1	4	6
20	1 mason 1 day	"	1	4	6
	1 man 1 1/2 hrs.	"			7 1/2
21	1 mason 1 day		1	4	6
22	1 mason 1 day	clean off drawing room	1	4	6
23	1 mason 1 day	put piers upright	1	4	6
	1 man 7 hrs.	"		2	11
24	1 mason 1 day	"	1	4	6
	1 man 2 hrs.	"			10
	2. 12 x 24 plate				8
	1 bag cement			5	2
	2 barrows lime stone		2		8
	4 do. concrete		3	2	3
	1" 6 of 10 x 4 1/2 oak block			1	9
26	1 mason 1 day	clean off drawing room	1	4	6
27	1 mason 1 day	color it & put in	1	4	6
28	1 mason 1 day	prate re.	1	4	6
29	1 mason 1 day	"	1	4	6
30	1 mason 1 day	"	1	4	6
May 1	1 mason 1 day	"	1	4	6
	2 barrows mortar			1	4
	1 barrow hair mortar			1	0
	1/2 bag of cement			2	7
	1 peck plaster			1	6
	100 bricks			3	6
	1 piece zinc				5

forward

1/9

£ 10 3 6 1/2

## Miss Martin

1909

£ s d

brok. forward

10 3 6 1/2

1 doz. chairs

1

1 tile Register Grate

2 15 6

extra on green ~~hearth~~ tiles panels

3 6

7 2/3 doz. green hearth tiles

13 5

1 delft tile Kerb

2 0 0

carriage of grate

2 0

May 3 1 man 7 1/2 hrs. repair drawing room floor

3 1 1/2

.. 1 mason 1 day color drawing room

4 6

4 1 mason 1 day

4 6

5 1 mason 1 day

4 6

6 1 mason 1 day

4 6

7 1 mason 1 day

4 6

8 1 mason 1 day

4 6

1 square + 4 screws

4

1/4 cwt. of whitening

1 4

1 lb. pipe

9

1/4 cwt. of Halls Distemper

4

12 0

12.6 of 7x1 deal for floor

17

2.0 of 3x2 ..

2

nails

1

2

new hook for gate

3

1 9

new flue for stove

3

2 6

19 1 man 3 1/2 hrs. put knocker on door

1 5 1/2

20 1 man 4 hrs. alter stop of gates

1 8

1 brass knocker

6 0

1 set of door handles

4 3

1 bell pull + screws

3 0

1 lb. of wire + 6. 1 1/4 screws

3

June 2 1 man 5 1/2 hrs. paint drawing room

10

23 1/2

3 1 man 1 day do. + repair floor

3 9

.. 1 man 7 1/2 hrs. paint do.

3 1 1/2

forward

£

19 14 6 1/2

1909		£	p	d
	boot. forward		19	14 6½
June 4	1 man 8½ hrs. paint drawing room &		..	..
"	repair lock		3	6½
5	1 man 6 hrs. do.	1.3	3	9
"	1 man <del>6 hrs.</del> <sup>3 ¼ day</sup> make mirror stand & repair frame		2	10
	9 lbs. paint for drawing room		<del>7</del>	1½
	3 lbs. putty, 3 sheets glass paper		..	6
	2'0" of 2x1 deal. 1 lock spring	1	..	6
7	1 man 7½ hrs. enamel drawing room		3	1½
"	1 man 1 day fix mirror stand &		..	..
"	repair carved work		3	9
8	1 man 8 hrs. repair table		3	4
"	1 man 1½ hrs. enamel drawing room		..	7½
9	1 man 4 hrs. repair table		1	8
"	1 man 4½ hrs. put up blind, & put on finger plates		..	1 10½
	3'0" of 4½ x 3 deal for mirror stand		..	10½
	5'0" of 2½ x 1½		..	5
	5'0" of 3 x ½		..	3½
	38 screws		..	6
	1 square & eye		..	8
	2'6" of 1 x 8½ oak for table	2	1	10
	4. 15" screw		..	1
	1 finger plate	1		9
	1 small escutcheon		..	2
	6 brass screws	1	..	2
	1 quart of enamel	21-5-8		50
	iron clip for gate		..	2
25	1 man 3 hrs. take off boiler tap		1	10
28	1 man 1½ hrs. fix do.		..	7½
	1 new boiler tap & lead collar		10	6
26	1 man 4½ hrs. fix overmantel hooks forward		1	10½
		£	28	8 7½

1909

£ s d

		book forward	22	8	7½
		3. 2" screws			1½
July	1	drawing 16 loads of gravel 1¼	1	2	0
Aug.	16	1 man 3 hrs. put in glass			13
		1 pane glass 1-6" x 1-2"			6
		putty			1
Mar.	30	repair mower take out broken cog			16
ap.	13	1 cog wheel & fixing same			46
x	19	repair 1 pair of fire tongs			19

£ 24 0 4

May 8. Received on ap. £ 10-0-0

May 20. do. £ 2-0-0

July 24. do. £ 5-0-0

17-0-0

17 0 0

left due

7 0 4

Settled Nov 8<sup>th</sup> 1909

24-0-4  
 21-2-½  
 ---  
 45-2-10½

10-0-0  
 2-0-0  
 5-0-0  
 28-2-10  
 ---  
 45-2-10

Mr. M. Hearn

1909			£	s	d
Jan.	14	1 man 6½ hrs. repair front carriage		2	7
		1 stay for carriage. 2 plates for shafts		2	4
	x	3. 1¼ x ¼ + 1. 3 x 5/16 bolts			3
	22	1 man 7½ hrs. ring wheel		3	0
	"	1 man 3 hrs. do.		1	2½
	23	1 man 4½ hrs. do.		1	9½
		5 ash felloes		1	3
		5 spokes		1	8
		new tyre 20 lbs.	3	5	0
		½ lb. paint			3
	25	1 man 1 hr.	14/7		5
	+ 15	2 lbs. paint			10
Apr.	17	new plate to shaft + 2 bolts			16
May	17	1 man 1 day 1 hr. ring 2 wheels		4	1
	18	1 man 1 day 2 hrs. do.		4	5½
	19	1 man 8 hrs. do.		3	2
		4 spokes		1	4
		12 ash felloes		4	0
		½ lb. paint			3
		2 new tyres 5 lbs.	1-9-8 2/4	12	4½
June		9 retyping 4 wheels			60
		12 rivets + rivetting 2 wheels			16
			<u>£</u>	<u>219 5</u>	

Paid August 19<sup>th</sup> 1909

## W. Fernier-Kerr. Reqs.

1909

£ s d

Jan	8	1 man 5 hrs. repair paint stable barrow	2	1	
	9	1 man 6 1/2 hrs. do.	2	8 1/2	
	11	1 man 2 1/2 hrs. do.	1	0 1/2	
		9-6 of 1 x 12 elm sides & bottom	2	0	
		4-0 of 1 x 9 " "		7 1/2	
		1 lb. nails		2	
		4. 3 x 1/4 bolts		2	
		1 1/2 lbs. paint		9	
		new spill, 2 eyes, 2 strap plates + 2 hooks & staples			20
	27	2 men 4 1/2 hrs. ea. put glass in greenhouse			39
		8-0 x 7 of glass		13	
		2 1/2 lbs. putty		4	
Feb.	10	1 man 1 1/2 hrs. put in pane of glass		7 1/2	
		1 pane 12 x 10 7/8		3 1/2	
		putty		1	
Mar.	2	1 man 1/4 day tar hurdles, cattle shed & poultry house			34
	4	1 man 1 day do.			34
	5	1 man 1 day do.			34
	12	1 man 4 hrs. do. put on felt			18
		6 1/4 gal. of tar			24 1/2
		100 clout nails			3
		6 yards of felting			20
		wood wedges			6
	15	1 man 1 1/2 hrs. put glass in chicken house			7 1/2
		1 pane 14 1/2 x 5 1/2			2 1/2
	30	sharpen saw			9
Apr.	2	1 man 9 1/2 hrs. fixing fencing			31 1/2
	"	1 man 10 hrs. do. repair 4/8			47
	"	1 lab. 4 hrs. do.			14
		forward			261

1909		£	s	d
	forward	2	6	1
Apr.	3 1 man 6 hrs. repair fencing		2	6
	14 lbs. of iron		2	4
	6 blocks			16
	.. new handle to grease trap		..	8
	24 new bolt to shears		..	6
May	1 1 man 3 hrs. put glass in bedroom window		1	3
	1 pane 15" x 11"		..	5
	putty		..	1
	4 2 new arms for mower		5	4
	5 fitting do		1	0
	.. repair bolt of tree & fix it		..	10
	.. 1 man 2 hrs. put in sash cords		..	10
	2 cords. 5 clouts		..	9
	11 repair pruning knife		..	6
	20 new ring on stable pick		..	3
June	2 solder & repair water cast		1	3
		£	3	6
				1

Settled August 6<sup>th</sup> 1909

Mrs. Langdon Fulford

1909

£ s d

	To a/c. rendered		53
Jan. 12	1 man 5 hrs. repair floor clock 8-0 of 1x7 floor nails & stain		21 10 -2
Feb. 9	1 man 7 1/2 hrs. repair bedroom floor 50-0 of 1x7 red 2 lbs. floor brads .. ease front lap of stove	14	3 1/2 5 2 1/2 .. 4 .. 6
May 11	1 man 11 1/2 hrs. papering Hall - 6 pieces paper at 1/3 paste		49 1/2 76 .. 6
13	To painting & papering dining room as per contract of April 26 <sup>th</sup> £2-5-0 less 2/3 on paper .. 1 hr. put pane of glass in picture } pane 13x20		.. .. .. .. 2 29 .. .. 10
17	1 handle for bell. 1 hr. put it on		16
26	1 man 1 1/2 hrs. cut out bedroom floor		.. 7 1/2
June 2	1 man 2 1/2 hrs. do.		10 1/2
1	To cleaning & lettering headstone (7 hrs)		36

£

40 10 1/2

Paid Sept 17<sup>th</sup> 1909



Mrs. Jane Hanvill

1909

£ s d

Jan	15	2 men 5½ hrs. ea. make waggon shafts		"	47
	16	2 men ¼ day ea.	do.	os	29
	18	2 men 7½ hrs. ea.	do.		63
	19	1 man 2 hrs.	do.		13
	20	1 man 1 hr.	do.		5
		9-9 of 2½ x 7 ash		6	410½
		3-9 of 2½ x 6½ ash		5½	19
		4-0 of 2½ x 5 ash		4½	15
		3. 3 x ¾ bolts			3
		3½ lbs. paint			19
		repair shop ironwork			10
		1 key & washer			3
Apr.	19	1 man 1½ hrs. put in rask pulley & cord			7½
		1 pulley			3
		1 cord.			4
		2 screws & 2 clouts			1
	19	1 man 1½ hrs. clean venetian blind			7½
	20	1 man 5½ hrs. paint do.			23½
	21	1 man 1½ hrs. do.			7½
	22	1 man 2 hrs. do.			10
	24	1 man 3½ hrs. re-web & fix blind			15½
		1½ lbs. paint			9
		2 squares			5
		6¼ yds. webbing			
		12 yds. cord			48
		4. 1" & 2. ¾ screws & tacks			1

Paid. Sep. 21. 1909

£ 1 19 6 ½

## Ware Sons

1909			£	s	d
Jan.	11	1 old bellows			16
	20	new handles to skin knife			13
			£		29
Paid August 5. 1909					

1909			£	s	d
Mrs. Henry Ware					
May	4	1 man 1 hr. at bedroom			5
	7	1 man 1 day strip velsan off walls			38
	8	2 men 6 hrs. ea. paint room			54 <sup>1</sup> / <sub>2</sub>
	12	1 man 1 day 2 hrs. papering room			45 <sup>1</sup> / <sub>2</sub>
	13	1 man 4 hrs. do.			17
		6 <sup>1</sup> / <sub>2</sub> lbs. paint			33
		1 <sup>1</sup> / <sub>2</sub> lb. size			4
		8 pieces paper at 1/1 <sup>1</sup> / <sub>2</sub>			90
		paste			6
	19	toputting in 1 pane glass, glass & putty			10
			£		197
Paid August 9 <sup>th</sup> 1909					

Woodbury School Managers

1908

£ p d

Nov.	20	1 man 1 hr. fixing platform		..	5
	24	3 men 2 hrs. ea. do.		2	6
	25	3 men 2 hrs. ea. take it down		2	6
	28	1 man 9/2 hrs. repair W.C. seats		3	11 1/2
		3.0 of 1x11 deal	3	..	9
		5.9 of 1x9 "	2 1/4	..	14
		2.9 of 1x7 "		..	3 1/2
		7.0 of 3x4 oak	4	..	24
		7.9 of 2 1/2 x 2 1/2 deal		..	13 1/2
	30	1 man 5 1/2 hrs. do.		2	3 1/2
		5.9 of 1x11 deal	3	..	15 1/2
		5.9 of 1x9 "	2 1/4	..	14
		12 lbs. nails		..	3
		6.0 of 1x3 deal		..	6
Jan.	4	1 man 1 hr. paint seats W.C.		..	5
	6	1 man 9/2 hrs. repair seats W.C.		3	11 1/2
	7	1 man 9/2 hrs. make & fix cover to pit		3	11 1/2
	8	1 man 9/2 hrs. repair seats W.C.		3	11 1/2
	9	1 man 8 hrs. do. paint in glass + blind cords for seats		3	4
		12.9 of 1x9 deal	2 1/4	..	11 1/2
		5.6 of 1x11 "	3	-	14 1/2
		3.0 of 1x4 "		..	4
		3.6 of 3x4 oak		..	12
		10.0 of 2x3 deal		..	10
		8.6 of 1x7 match		..	11
		2 lbs. nails		..	4
		1 1/2 lbs. paint		..	9
		29.0 of 1x7 deal for cover	1 1/2	..	37 1/2
		4.0 of 1 1/2 x 9 sh		..	10
		1 lbs. nails		..	2
		2.0 of 3x4 oak		..	8
		Tar		..	2
		1 pane glass 14 1/2 x 11 1/2 putty		..	6
		forward	£	2	6 2 1/2

1909

£ s d

Jan. 9	brok. forward		2	6	2 1/2
	1 man 1 1/2 hrs. make rod for Turkey Head				7 1/4
	1 Turkey head				5 8
	1 tin joint				4
	8' 0" of 1 1/4 x 1 1/4 deal handle				8
	3 tassels & 9 yds. of blind cord				1 6
20	1 man 7 1/2 hrs. make ventilator		3		1 1/2
21	1 man 7 1/2 hrs. do.		3		1 1/2
22	1 man 2 hrs. do.				10
30	1 man 9 1/2 hrs. fix do.		3		1 1/2
	1 mason & 1 lab. 7 hrs. ea. fix do.				5 3
	16 bricks, 2 1/2 pecks. cement				
	1/2 barrow of mortar				4 4
Feb. 6	1 man 9 hrs. fix ventilators		3		9
	1 man 2 1/2 hrs. do.				10 1/2
	1 mason 6 hrs. do.				2 6
	60' 0" of 1 x 9 deal	13/4			13 9
	7' 0" of 1/2 x 5 1/2 "	1			7
	2 pairs of 2" brass bolts & screws				1 2
	2 brass knobs				4
	2. 9 x 9 galvzd. ventilators				4 0
	1.6 x 9 of perforated zinc				2
	2 lbs. nails				4
	stan. 1/4 pt. varnish				6
11 13	1 man 5 hrs. fix R.V.P. & alter leaves of ventilator				2 1
	1 man 5 1/2 hrs. do. & varnishing				2 3 1/2
	1 pipe nail				
	1 shute screw				1
	5' 0" of 1 1/2 x 1 1/4 deal moulding				3
20	1 man 1 hr. varnishing ventilators				5
Mar. 27	1 man 9 hrs. repair glass desks & cupboards forward				3 9
		£	5	12	7

1909

£ s d

	brok. forward		5 12 7
Mar.	repair iron standards of desks		2 0
	6. 1" + 6. 1½" screws		.. 2
	1 pair 2" butts + screws		.. 3½
	4' 0" of 1½" x 1" deal		.. 2
x 29	1 man 2 hrs. make patterns of glass		.. 10
	1 man 1½ hrs. repair desk		.. 7½
x 30	1 man 2½ hrs. put in glass		1 0½
	4. 1½" screws		..
	2. 1½" x ¼" bolts		.. 2
	2 panes of glass for heads of windows		1 3
	ill. putty		.. 1½
Apr. 16	1 man 9½ hrs. repair floor		3 11½
17	1 man 9 hrs. do.		3 9
	148' 0" of 1" x 7" floor	1¼	15 5
	21' 0" of 2" x 4" joist		2 2½
	4 lbs. nails		.. 8
June 1	1 man 8½ hrs. repairing desks		3 6½
2	1 man 9 hrs. do.		3 9
3	1 man 9½ hrs. repairing floor		3 11½
4	1 man 9½ hrs. do.		3 11½
	47' 6" of 2" x 4" deal joist floor	¼	4 11
	153' 0" of 1" x 7" floor		15 11
	12 bricks		.. 6
	4 lbs. nails		.. 8
	7' 0" of 3" x 4½" deal plate	3½	2 0½
	12. 1½" x ¼" bolts desks		.. 6
	24. 1½" screws		.. 4
	repair iron legs		7 0
	1 cupboard lock screws		.. 10
Apr. 17	To making + fixing a platform + trestles as ordered by Mr. A. S. Phillips		..
			10 0 0
		£	19 13 2

Paid August 9<sup>th</sup> 1909



## Mr. Walter Stamp

1909

£ s d

Jan.	2	2 shoes steeled	1	4
	27	2 shoes	1	2
Feb.	12	2 shoes steeled	1	4
	17	1 link	2	6
	20	4 shoes pony	0	6
Apr.	8	new screw + fit to plough wheel	1	0
	13	2 shoes pony	1	0
	20	2 shoes pony	1	0
	30	2 shoes steeled	1	4
May	14	2 shoes pony	1	0
	25	2 shoes	1	2
June	1	2 shoes steeled	1	4
	7	2 shoes pony	1	0
	17	2 shoes pony	1	0
	21	2 shoes steeled	1	4

---

 £ 16 7
 

---

Paid 7/6 in the £ - - -

s d  
6/-0August 11<sup>th</sup> 1909

## Mr. Alfred Stokes

1909

£ s d

	bror. forward from page 237	3	10	8
	4 panes glass $8\frac{1}{4} \times 7\frac{1}{2}$ ea.	..	5	
	4 do. $9\frac{1}{2} \times 7\frac{1}{2}$ ea.	..	6	
	4 lbs. putty	..	6	
	2½ lbs. paint	1	3	
	2 pairs 2" butts & screws	..	7½	
	2 iron knobs. 2 buttons	..	4	
	16. 1" screws	..	2	
	5-g of $5\frac{1}{2} \times 3\frac{1}{2}$ oak put	2	10	
	7" 0 of 2x3 deal rails for gate	..	7	
	1. 6" 0 of 2½" R.W. pipe	2	2	
	1. 2½" toe. 6 pipe nails	1	1	
	1 lb. paint	..	6	
Jan 18	1 man 6 hrs. make window frame & .. clean & paint casements	..	2	4½
19	1 man 7½ hrs. fix & glaze casements	3	0	
20	1 man 7½ hrs. do. & paint do.	3	0	
21	1 man 7½ hrs. make window frame	3	0	
22	1 man 4 hrs. repair & change old casements	1	7	
	8" 6 of 9x1½" deal for casements	2	8	
	1½ lbs. paint	..	9	
	18 panes glass 11x7 ea	2	0	
	2½ lbs. putty	..	4	
	1 pair 2" butts & screws	..	3½	
	1 hook & eye, 1 window stay	..	5	
	4" 0 of 2x7 deal sill own house	1	0	
	1 pair 2" butts & screws	..	3½	
	1 pane glass 11x7	..	1½	
	1 lb. priming	..	6	
25	1 man 7½ hrs. fix & paint frame & casements	3	0	
	1 mason & 1 lab. 1 day ea. fix window & repair roof	6	6	
	1 barrow mortar, 2 pks. cement, 2. 8x16 plate	3	8	
	forward	£	5	16 4



1909

£ s d

		brok. forward		5	16	4	
Jan.	28	2 men 8 hrs. ea. put up fence in field			6	4	
	29	2 men 1 day ea. do.			7	4	
	30	2 men 1 day ea. do.			7	4	
		1½ lb. paint for window				9	
		1 window stay "				4	
		½ lb. putty "				1	
		6 lb. nails for fence				10	
		½ lb. staples				3	
		4 lbs. wire				9	
		12. 18'-0" of 2x3 rails 216'-0"	1		18	0	
		6. 18'-0" of 2x4 .. 108'-0"	1½		11	3	
		7 sleepers 14 sleeper posts				16	4
		4 gallons tar.	5		1	0	
Feb.	1	1 man 3 hrs. tar rails				12½	
		1 man 1 day do. make gate				38	
	3	1 man ½ day hang & tar gate				110	
		2 gate eyes, 1 gate hook				10	
		4'-0" of 4½x3 deal tail	3½		1	2	
		4'-0" of 3x2 .. head				4	
		7'-9" of 4x2 .. top rail				10	
		21'-9" of 7x1 .. (imp) rails	1½		28	½	
		1 lb. nails				2	
		tar				3	
	25	1 man 5 hrs. repair floor & fix brass step				20	
		brass step, 6, 1 screw				81	
				£	10	10	4

Paid August 16<sup>th</sup> 1909

Aug 5  
Jan. 11. 10

Mrs. Matthews

Barnstable

1909

£ s d

Apr. 21	1 man 3½ hrs. make gate			1 5
22	1 man 6½ hrs. do.			2 7
26	1 man 6 hrs. hang do.			2 4½
	3-3 of 4x3 tail	3/4		10½
	9-9 of 2x3 head & rails	1/4		1 5
	6-6 of 9x1 pales			1 6
	3-3 of 3x1¼ brace			3
	1 lb. paint			6
	2. 3½ x 3/8 & 1. 1½ x 1/4 bolt			2½
	4. 2", 2. 1½" screws & 1/2 lb. nails			3
	latch, catch, guide, & 1 new hook			10
May 21	1 man 2 hrs. paint gate			9½
	1 lb. paint			6

£ 13 6

Paid January 12<sup>th</sup> 1910

W. C. Warren Esq. Matushka, Grand Avenue West Worthing

1909			£	s	d
Jan.	12	1 man + 1 lab. 9 1/2 hrs. repairing slates of roof at Bedford Manor	6	6	7 6 1/2
	13	1 man + 1 lab. 9 1/2 hrs. ea. do.	6	6	7 6 1/2
	14	1 man + 1 lab. 9 1/2 hrs. ea. do.	6	6	7 6 1/2
		70. 10 x 20 slates, 25. 8 x 16 slates)			..
		12. 11 x 22 .. + 12. 12 x 24 ..			..
		9 lbs. of lead strips			..
		3 lbs. plate nails			..
		3 peck cement			..
		1 bucket of mortar			..
		cartage of do.	2	9	1 19 3
	15	To plumber repairing leaks in lead gutters of roof. 8 lbs. solder. 1 quart of oil and time. 1 man 2 hrs	13	5	15 5
					<hr/>
					3 19 3 1/2

Paid July 28<sup>th</sup> 1909

Rev. W. S. Stayner. Elford Manor

1909

£ s d

To ac. rendered

6 9 3

Jan. 19 1 man 7 hrs. put in pane glass, put in sash cord, cheap plumber fix pipe in W.C.

3 2 1/2

20 1 man 1 1/2 hrs. put in glass

5

1 10

2 lbs. putty

.. 3

1 pane glass 12 x 15 1/2

.. 6

1 sash cord 5-0 long

.. 5

6 clouts

.. 1

paint for pipes in W.C.

.. 3

To plumber putting on new pipe &amp; ball tap to cistern in W.C. &amp; regulating Bells

7 9

8-6 of 1/2 lead pipe, 1. 1/2 stop cock

.. "

1. 1/2 ball tap, 3 steel clips &amp; solder

10 3 1/2

Feb. 23 To plumber clearing &amp; regulating ball tap in cistern

4 0

26 examining cistern

1 6

June 11 1 man 7 1/2 hrs. repairing bell wire &amp; tanks

3 5 1/2

6. 1 1/2" screws, 1-0 of bell wire, 1 doz. nails

.. 6

£ 8 3 3 1/2

Paid August 9<sup>th</sup> 1909

1909 Mr. Charles Copp.

f p d

Feb.	5	1 man 7 1/2 hrs. repairing bell-wires	30
	8	1 man 4 hrs. do.	17
		1 bell spring }	"
		2 cranks }	18
		7.0 lb wire }	"
		1 doz. nails }	9

f " 70

Paid Sept<sup>r</sup> 13<sup>th</sup> 1909

Mrs. Westlake

Aug 5

Feb.	6	1 hr. put lock on box } new lock	20
------	---	-------------------------------------	----

Paid August 14<sup>th</sup> 1909

## Rev. J. Hill Hosegood. Thelbridge

1909

		£	s	d
June 18	To rechanging the peal of six Bells in Thelbridge Church Tower as per estimate of June 2. 1908	52	16	0
	To providing and fixing a new iron rope guide in bottom of Tower as per estimate of May 7. 1909	2	10	0
		£	55	6 0

Paid by Cheque £55.0.0  
on June 22. 1909.

July 20<sup>th</sup> 1909The Vicar & Churchwardens of St-Philip & St-James Church  
Deposited

1909			
June & July	Work repairs done to the frame and fittings of the peal of 6 bells according to estimate of April 10 <sup>th</sup> 1909	£ 0 1	
	Work putting one new stock to 3 <sup>rd</sup> bell	38 11 0	
	Work putting new blocks and bows to the 5 wheels and repair Ropes	" 10 0	
		" " "	
		2 15 0	
		<hr/>	
		£ 41 16 0	
	6 muffles-	<hr/>	
		1 1 0	
		<hr/>	
		£ 42 17 0	

Paid August 11<sup>th</sup> 1909

## Miss Stogdon. Exton

1909

£ s d

Jan 12	1 man 4 hrs. put up post at D. Potters livery		..	..
	7.6 of 5x8 oak post		4	6
	1 lb. nails		..	2
Feb. 5	1 man 7 1/2 hrs. repair front door at Mrs. Burdens		3	0
6	1 man 1/2 day do. do.		1	10
	3.0 of 3x4 deal	3 1/4	..	10
	3.9 of 3x4 oak sill	4	1	3
	3.0 of 6x1/2 deal		..	3
	1 Norfolk handle catch screws		..	7
	1. 4" butt. hinge screws		..	3
	1 lb. nails		..	2
	paint			2
	forward	£	..	14 7



Sep. 7. '09

## Mr. W. Summerfield

				£	s	d
1909		To a/c. r		40	11	11½
Jan.	12	draw 2 loads of gravel to J. Potters			3	0
	13	" 1 do " "				16
	15	" 1 load of sea gravel			4	0
	16	" 2 loads of gravel "			3	0
	21	" 11 loads of gravel to Mr. Spencer			14	8
	"	" 1 load of gravel to J. Potters				16
Ap.	17	draw load of scaffolding to Witleycombe			2	6
May	17	draw 500 brick to Mr. J. Skinner			6	0
	22	do.	do.		6	0
June	11	do.	do.		6	0
	14	do.	250 brick do.		3	0
	15	do.	do. do.		3	0
Jan.	6	1 shoe				6
	12	1 man 4 hrs. repair cart shafts			1	7
		5. 4 x 3/8 bolts				4
		2 plates old iron for shafts			2	6
		lengthen strap plate				2
	14	1 shoe				6
	21	sharp pick				2
	22	screw bolt & alter plate				3
Feb	1	new turning bar			1	8
	2	new flue & damper			2	10
	"	to making W.C. seat for Dylesbeare			4	7
	6	2 shute cramps				8
	11	2 shoes			1	0
	13	1 man 3/4 day put in glass, hang casement				
		& put on letter plate			2	9
		1 pair 2 1/2 butts screws				4
		3 panes glass				6
		1 lb. putty				1 1/2
	16	2 shoes				10
forward				£	44	7 7

1909		£	s	d
	forward	44	7	7
Feb.	19 new flue		2	8
"	repair casement at Miss Stogdons		6	4
	23 sharp hatchet		..	2
	26 fixing W.C. seat at Aylesbeare		2	6
Mar.	* 8 1 man 1 hr. make frame jambs for Izel Villa		..	..
	12' 0" of 4x3 deal	3	3	0
	2 dowels		..	1 1/2
	8' 6" of 4x3 .. wallplate		2	1 1/2
	8' 6" of 3x2 .. head		..	8 1/2
	* 16 1 man 5 1/2 hrs. hang door & fit key to lock & paint door Izel Villa		..	..
			2	2 1/2
	* 15 1 man 7 1/2 hrs. make door & put on roof at Izel Villa		..	..
			3	0
	7' 9" of 7x1 ledge	1 3/4	1	1
	26' 0" of 7x1 floor door		2	8 1/2
	8' 6" of 3x2		..	8 1/2
	1 pair 16" Tee hinges & screws		..	9
	1 latch catch, guide & screws		..	7
	1 key to lock		..	6
	5 screws		..	1
	1 1/2 lbs paint, 1/2 lb. putty		..	10
	18 1 man 2 1/2 hrs. take off & put on new cog to chaff cutter		..	..
	new cog		1	0
	22 put pulley in block		..	4
Apr.	8 1 man 2 hrs. put block on cart springs		..	9 1/2
	3' 0" of 2x3 1/2 clms		..	4 1/2
	2. 3x3/8 coach screws		..	1 1/2
	20 to making centre as per contract		1	0
	22 1 shoe		..	8
	forward	£	48	4 2 1/2

1909		£	s	d
	forward	48	4	2½
Apr.	23 8.0 of 3x3 deal wedges 1hr.		18	
	28 2 shoes		10	
May	14 2 shoes.		10	
	17 shop 2 saws		10	
	" 23.0 of 2x4 deal		25	
	20 103.0 of 7x1 floor board (dirty)		76	
June	3 1 shoe & fasten 2		8	
	11 3 shoes		16	
	18 1 man 1 day repair door & jambs		38	
	2.6 of 6x1¼ deal		5	
	1 Norfolk latch complete		7	
	12. 1" x 6, ¾ screws		3	
	2 dowels		12½	
	paint		2	
	28 1 shoe		6	
Mar.	1 To making new body of cart, new shafts, new axles, repairing springs, and ringing one wheel			
			6	15
		£	56	18

Settled December 9<sup>th</sup> 1909.

## Mr. Summerfields Cart

1909		£	s	d
Jan.	29	1 man 1 day	3	6
	30	1 man 1 day	3	6
Feb.	1	1 man 1 day	3	6
	2	1 man 1 day	3	6
	3	1 man 1 day	3	6
	4	1 man 1 day	3	6
	5	1 man 2 hrs		9 <sup>1</sup> / <sub>2</sub>
	6	1 man 1/2 day	1	9
	8	1 man 1 day	3	6
	9	1 man 2 hrs		9 <sup>1</sup> / <sub>2</sub>
	10	1 man 8 hrs	3	2
	11	1 man 1 day	3	6
	12	1 man 1 day	3	6
	13	1 man 2 hrs		9 <sup>1</sup> / <sub>2</sub>
	15	1 man 6 hrs	2	4 <sup>1</sup> / <sub>2</sub>
	16	1 man 1 day	3	6
		1 man 3 hrs		12 <sup>1</sup> / <sub>2</sub>
	17	1 man 1 day	3	6
	18	1 man 1 day	3	6
	19	1 man 1 day	3	6
		1 man 2 hrs		9 <sup>1</sup> / <sub>2</sub>
	20	1 man 1 day	3	6
		1 man 2 1/2 hrs		10
	22	1 man 1 day	3	6
	23	1 man 2 1/2 hrs		10
	24	1 man 2 hrs		9 <sup>1</sup> / <sub>2</sub>
	27	1 man 1/2 hr		2 <sup>1</sup> / <sub>2</sub>
Mar.	1	1 man 1/2 hr		2 <sup>1</sup> / <sub>2</sub>
Feb.	2	cart iron work 8 lbs	2	8
	4	do. 7 lbs	3	6
	6	do. 15 lbs	5	7 <sup>1</sup> / <sub>2</sub>
	8	do. 8 lbs	2	8

forward

4 1 10

1909

£ s d

forward

4 1 10

Feb.	16	put 2 leaves in springs		47
	17	put on tyre		2 0
	18	2 new clips for axle & lengthen 2		1 6
	19	2 axle bolts		5 4
		6" 0 of 11x3 oak plank	11 <sup>1</sup> / <sub>2</sub>	5 6
		4" 6 of 7x2 "	4 <sup>3</sup> / <sub>4</sub>	1 9 <sup>1</sup> / <sub>2</sub>
		4" 0 of 3x2 <sup>1</sup> / <sub>2</sub> "	2 <sup>1</sup> / <sub>2</sub>	" 9
		4" 3 of 2x2 <sup>1</sup> / <sub>2</sub> ash	1 <sup>3</sup> / <sub>4</sub>	7 <sup>1</sup> / <sub>2</sub>
		3" 9 of 2x3 "		7
		9" 6 of 13x1 <sup>1</sup> / <sub>2</sub> elm	4	3 2
		10" 6 of 6 <sup>1</sup> / <sub>2</sub> x1 elm		1 1
		6" 9 of 12x1 "		1 4 <sup>1</sup> / <sub>2</sub>
		3" 9 of 4 <sup>1</sup> / <sub>2</sub> x4 <sup>1</sup> / <sub>2</sub> "	4 <sup>1</sup> / <sub>4</sub>	1 4
		8" 6 of 2 <sup>1</sup> / <sub>2</sub> x8 ash		4 9 <sup>1</sup> / <sub>2</sub>
		4" 0 of 2x2 <sup>1</sup> / <sub>2</sub> "		7
		4" 0 x 3" 0 of 1" elm		2 6
		30. 1 <sup>1</sup> / <sub>4</sub> " screws		5
		10. 2 <sup>1</sup> / <sub>2</sub> x3 <sup>1</sup> / <sub>8</sub> bolts		8
		8. 6x3 <sup>1</sup> / <sub>8</sub> "		8
		6. 3x3 <sup>1</sup> / <sub>8</sub> "		4 <sup>1</sup> / <sub>2</sub>
		1 pr. chain		2
		6 ash felloes		2 6
		1" 6 of 4 <sup>1</sup> / <sub>2</sub> x1 <sup>1</sup> / <sub>2</sub> elm		2
		1 <sup>1</sup> / <sub>2</sub> lb. nails		3
		1 pair 2" axle boxes		15 6
		6. 3 <sup>1</sup> / <sub>2</sub> x3 <sup>1</sup> / <sub>8</sub> shackle bolts		9
		2 <sup>1</sup> / <sub>2</sub> lb. priming		1 3
		* 5 <sup>3</sup> / <sub>4</sub> lb. paint		2 10 <sup>1</sup> / <sub>2</sub>

Paid

6 19 11

## Summer fields Cars

Jan. 29	1 day	_____	3-8
30	1 day	_____	3-8
Feb. 1	1 day	_____	3-8
2	1 day	_____	3-8
3	1 day	_____	3-8
4	1 day	_____	3-8
5	2 hrs.	_____	9 $\frac{1}{2}$
6	$\frac{1}{2}$ day	_____	1-10
8	1 day	_____	3-8
9	2 hrs.	_____	9 $\frac{1}{2}$
10	8 hrs.	_____	3-2
11	1 day	_____	3-8
12	1 day	_____	3-8
13	2 hrs.	_____	9 $\frac{1}{2}$
15	6 hrs.	_____	2-4 $\frac{1}{2}$
16	1 day	_____	3-8
	3 hrs.	_____	1-2 $\frac{1}{2}$
17	1 day	_____	3-8
18	1 day	_____	3-8
19	1 day	_____	3-8
	2 hrs.	_____	9 $\frac{1}{2}$
20	1 day	_____	3-8
	2 $\frac{1}{2}$ hrs.	_____	1-0
22	1 day	_____	3-8
23	2 $\frac{1}{2}$ hrs.	_____	1-0
24	2 hrs.	_____	1-0
	$\frac{1}{2}$ hr.	_____	2 $\frac{1}{2}$
			3-9-11 $\frac{1}{2}$

1909

£ s d

forward

			4	1	10
Feb.	16	put 2 leaves in springs			47
	17	put on tyre			20
	18	2 new clips for axle & lengthen 2			16
	19	2 axle bolts			" 4
		6" 0 of 11x3 oak plank	10 <sup>1</sup> / <sub>2</sub>		56
		4" 6 of 7x2 "	4 <sup>3</sup> / <sub>4</sub>		19 <sup>1</sup> / <sub>2</sub>
		4" 0 of 3x2 <sup>1</sup> / <sub>2</sub> "	2 <sup>1</sup> / <sub>2</sub>		" 9
		4" 3 of 2x2 <sup>1</sup> / <sub>2</sub> ash	19 <sup>1</sup> / <sub>4</sub>		7 <sup>1</sup> / <sub>2</sub>
		3" 9 of 2x3 "			" 7
		9" 6 of 13x1 <sup>1</sup> / <sub>2</sub> elm	4		32
		10" 6 of 6 <sup>1</sup> / <sub>2</sub> x1 elm			11
		6" 9 of 12x1 "			14 <sup>1</sup> / <sub>2</sub>
		3" 9 of 4 <sup>1</sup> / <sub>2</sub> x4 <sup>1</sup> / <sub>2</sub> "	4 <sup>1</sup> / <sub>4</sub>		14
		8" 6 of 2 <sup>1</sup> / <sub>2</sub> x8 ash			49 <sup>1</sup> / <sub>2</sub>
		4" 0 of 2x2 <sup>1</sup> / <sub>2</sub> "			7
		4" 0 x 3" 0 of 1" elm			26
		30. 1 <sup>1</sup> / <sub>4</sub> " screws			" 5
		10. 2 <sup>1</sup> / <sub>2</sub> x3 <sup>1</sup> / <sub>8</sub> bolts			" 8
		8. 6x3 <sup>1</sup> / <sub>8</sub> "			" 8
		6. 3x3 <sup>1</sup> / <sub>8</sub> "			" 4 <sup>1</sup> / <sub>2</sub>
		1 pr. chain			" 2
		6 ash felloes			26
		1" 6 of 4 <sup>1</sup> / <sub>2</sub> x1 <sup>1</sup> / <sub>2</sub> elm			2
		1 <sup>1</sup> / <sub>2</sub> lb. nails			3
		1 pair 2" axle boxes			15 6
		6. 3 <sup>1</sup> / <sub>2</sub> x3 <sup>1</sup> / <sub>8</sub> shackle bolts			9
		2 <sup>1</sup> / <sub>2</sub> lb. priming			13
		* 5 <sup>3</sup> / <sub>4</sub> lb. paint			210 <sup>1</sup> / <sub>2</sub>

Paid

6 19 11

Mar. 1.  $\frac{1}{2}$  hr.\* 3.9 -  $11\frac{1}{2}$ 

25

~~7 x 3 oak plank  
 4-6 of 7 x 2 oak  
 4-0 of 3 x  $2\frac{1}{2}$  oak  
 4-3 of 2 x  $2\frac{1}{2}$  oak  
 3-9 of 2 x 3~~

4-10 $\frac{1}{2}$ 

2-5-6.

Feb. 2 cart ironwork fls. 2-8  
 4 do. 7 lbs. 3-6  
 6 do. 15 lbs. 5-7 $\frac{1}{2}$   
 8 ~~add~~ 8 lbs. 2-8  
 16 put 2 leaves on }  
     sponges } 4/7  
 17 put on type 21-  
 18 2 new clips for axle &  
     lengthen 2 1/6  
 19 2 axle bolts 4

7-3-5.



Mr. J. Dew

1909

£ s d

Jan.	11	2 old ropes	26
	29	1 shoe	" 7
Feb.	9	repair plough, 1 piece of plate, 5 new bolts, straighten beam & handles + sharp coulter	33
	18	3 shoes	19
Mar.	2	6 new bolts	16
	"	lengthen 6 bolts + screwing + new nuts	16
	5	repairing plough	36
		1 new clip for wheel, 2 keys + washers nails	13 .. 6
	6	4 eyes + 4 hooks for lades 17 lbs. repair foot of wheel drag	58 .. 6
June <sup>x</sup>	28	4 shoes	24
Apr.	9	1 K. 4 shear	" 7

forward

£ 1 5 5

R. D. Prickman Esq  
Winn House  
Ind

1909

May 12

For 1 Bell Rope

0 1

11 0

"

Postage by Parcel Post

" 6

---

11 6

---

Paid July 24<sup>th</sup> - 1909

Oct 9<sup>14</sup>/09

Rev. G. H. Wynne Vicar of Cadbury  
Dunsall. Thowton

April 22	1 man 9 hrs screw up bells & frame in Cadbury Tower	d 4-	53
	rail fares to Thowton & back		23
			<hr/> 76

Paid. Oct. 14. 1909

Rev<sup>d</sup> E. M. Russell  
The Rectory  
Stoodley

1909

May 21

For 1 bale rope (to the order of Mr W. H. Gault)  
carriage

11 0

6

---

11 6

---

Paid October 12<sup>th</sup> 1909

Aug 5  
Oct. 19.

Miss Moulton-Barrett,

1909

£ o d

Feb.	20	sharpen saw	..	5
		6 panes glass 8x8 ea.	..	10
		2 do. 15½x15½ ea.	..	9
Mar.	4	soldering water can	..	6
	16	2 panes glass 13x13 ea	..	6
Apr.	13	2 hrs. repair table )	..	..
		2, 1½ screws, 1 5/8" do. }	..	..
		oak + glue 2"	..	16
		solder can	..	4
	30	solder lamp	..	6
	23	2 iron stays	..	18

£ 72

July 23 solder kettle .. 4

£ 76

Paid Nov. 9. 1909

Aug 5 1909  
Jan 11 10  
June 30<sup>th</sup> 1910  
Jan 5 1912

Mr. Henry Pile

1909

£ s d

Feb.	25	1 man 5 hrs. put in cart shaft		20
	26	1 man 1 day do.		38
	27	1 man 1 1/2 hrs. repair tailboard		7
		10' 6" of 5 x 3 1/2 ash shaft	6	53
		12 C.S. nails		2
		1' 3" of 1 x 3 elm		1
		1 lb. paint		6
		1 staple & repair shaft ironwork	13/-	9
Mar.	3	1 man 6 1/2 hrs. put front board to trap		27
		2' 3" of 3/4 x 9 deal	2	4 1/2
		2 plates + 6 small staples		10
		8. 1" screws		1 1/2
		paint + oil for wheels		4
	16	1 man 1 1/2 hrs. make drafts		8
		2 staples for do.		4
Apr.	7	re-leather pump sucker		13
	8	1 man 1 day repair 2 roller frames		38
		1 new bolt for roller + screw one		6
June	10	1 1/2 hrs. take off opert-on dashboard		9
		repair 2 wing irons		6
	24	1 1/2 hrs. repair sheep dipper		7
		3 screws. 1 doz. nails		6
		2' 0" of 1 x 1 deal		2

£ 162

Dec. 21. 04

Mr. John Skinner

1909

£ s d

Mar.	2	1 man 1 1/2 hrs. prepare jamb for door Mr. J. Godfrey		7
	9	1 man 7 1/2 hrs. repair jambs do.		30
	10	1 man 3 hrs. repair door r. do.		12 1/2
		6.0 of 4x3 deal jamb	3 1/4	17 1/2
		3.4 of 4x3 oak pill	3 1/2	10
		1 pair 15" Tee hinges & screws		9
		12 screws for squares		2
		2 iron squares		8
		8. 3/4" screws for latch		1 1/2
		5.6 of 1x3 deal for door		5 1/2
June	5	1 man 1 hr. prop wall of linchay		5
	9	1 man 5 hrs. take off linchay roofs		20
		1 man 5 1/2 hrs. do.		22 1/2
	16	2 men 7 1/2 hrs. ea. put on do.		60
	17	2 men 1 day ea. do.		74
	18	2 men 1 day ea. do.		74
	19	2 men 1 day ea. do.		74
		22 1/2 lbs. nails		39
		1 doz. 1" clouls		1
		194.0 of 6 1/2 x 7/8 floor	10/9	116
		740.0 of 2 x 3/4 batten	2/6	186
		46.0 of 3 x 4 1/2 red	2 1/4 2/-	87 1/2
		90.0 of 3 x 4 do.	2 2/-	150
		384.0 of 2 x 3 rafter	7/8	180
		5246.0 of springing	13/4	77
		1/2 gal. tar		6
		1 wall plate iron		8
	22	1 man 1 day make & fix barge rapping		38
	"	1 man 8 hrs. do. do.		32
	23	1 man 1 day fix fillets & tar boarding r.		38
		42.0 of 3/4 x 9 deal	2	70
		42.0 of 3/4 x 7 "	1	36
		forward	2	7175
				7175

1909

£ s d

forward

7 17 5

16.0 of 3/4 x 7 floor

1 4

17.9 of 3/4 x 2

8

2lbs. nails

4

June 22 Drove away 5 loads colr

2 6

23 do. 1 load colr

6

30 do. 1 load stone

6

Oct. 19 1 man 3 hrs. repair garden door

1 2 1/2

3.0 of 7 x 1 1/4 deal ledge

6

3.0 of 3 x 1 capping

3

1.6 of 4 x 1 "

2

4. 2" screws, 1/2 lb. nails

2 1/2

26 1 galvanized furnace pan 4/4

-

1 set of door + bottom fittings 2/6

8 0

Nov. 25 1 man 7 1/2 hrs. repair casement at C. stamps

3 0

2.0 of 3 x 1 1/2 deal

-

2.0 of 2 x 1 1/2 "

4

1 pane glass 10 x 11.

3

1 lb. putty

1

£ 8 17 3

Received on ac. Ap. 11. 1910

4 0 0

" " Oct. 21. 1910

2 0 0

8 17 3



Mr. G. Pyne. Postlake

£ s d

1909

Mar. 6	1 1/2 hrs. put in 2 panes glass	}	..	7 1/2
	2 panes glass 13 1/4 x 10 ea.		..	6
	1 lb. putty		..	12
11	1 man 1 day put up rails			38
12	1 man 1 day do.			38
13	1 man 1 day do.			38
15	1 man 1 day do.			38
	14 1/2 lbs. nails			21

£ 180

Paid August 18. 1909

1909

Mr. James Glanville

£ s d

forward		6	9	5
6. 2" C.P. nails	}	..	..	..
8. 1" clout nails		..	2	..
1 1/2 lbs. paint		..	9	..
2 long staples & 2 hooks			10	..
repair cast ironwork		..	9	..
1 tail pin & chain, 2 mudguards, 2 plug		..	..	..
hasps, 1 bolt, 3 staples			20	..
1 new back chain			16	..

£ 6 15 7

June 12 <sup>1911</sup>	Settled by contra acct.	£ s d	4	17	9	and
	by Cheque	..	1	15	0	
	and Cash	..	2	10	..	
		£	6	15	9	

Jan. 20. 1910

Mr. James Glawille

1909

£ s d

To acc. rendered

2 8 4

Mar. 12	1 man 3 1/2 hrs. ring trap wheels	1	15
13	1 man 1 day do	1	3 8
15	1 man 1 day do	1	3 8
16	1 man 3 1/2 hrs. do	1	15
18	1 man 7 hrs. do	1	2 9 1/2
	3 spokes	1	10
	14. 2 1/2" ash fellows	1	70
24	1 man 1/2 hr.	1	2 1/2
30	1 man 3 hrs. paint do	1	12 1/2
31	1 man 1 1/2 hrs do	1	7
Apr. 2	1 man 1 1/2 hrs. do	1	7
	3 lbs. paint	1	16
	2 new tyres 7 lbs. at 2 1/2 <sup>0</sup> $\frac{1}{2}$ 2-1-3	1	16 3
Mar. 13	1 man 1 day make trunk & gate		3 8
	4 lbs nails		8
May 17	1 man 2 hrs leather trap wheels } 1/4 lb. leather }		16
June 9	tyring 2 wheels		50
Apr. 22	1 man 8 hrs. repair drags		3 2
	5' 0" of 3 x 3 1/2 elm	2 1/2	1 2 1/2
	2' 3" of 3 x 3 "	2 1/4	5 1/2
Dec. 14 <sup>th</sup>	1 man 3 1/2 hrs. put in 2 cart shafts		15
15	1 man 1 day put in do		3 8
16	1 man 5 hrs. do. do		20
17	1 man 4 1/2 hrs. repair bottom & sides of cart		1 9 1/2
17	1 man 7 hrs. do. do		2 9 1/2
18	1 man 1 1/2 hrs. paint shafts		7
	6' 0" of 1 x 1 1/2 elm bottom		1 4 1/2
	1' 8" of 1 3/4 x 1 3/4 ash		1 1/2
	10' 4" of 9/2 x 3/2 ash shafts	1 1/2	10 0
	1. 5 x 3/8, + 2. 4 1/2 x 3/8 bolts		3
	1 lb. nails		2

forward

£ 6 9 5

Rev. M. H. Hayman, Myrtle Cottage £ s d

1909

Mar. 22	1 man 2 1/2 hrs. make flower boxes (3)			1 0 1/2
23	1 man 7 hrs. do.			2 11
27	1 man 2 hrs. paint do. 3 coats			.. 10
	19-0 of 7 x 3/4 floor			1 7 1/2
	5-0 of 1 x 11			1 3 1/2
	2-6 of 1 x 7			.. 4 1/2
	1 lb. nails			.. 2
	2 1/2 lbs. paint		9/6	1 3
25	1 man 2 1/2 hrs. repair coal box	}	1/3	.. ..
	8. 1" brass screws			1 3
	3 bits walnut			.. ..
May 10	grinding 2 pairs of shears			1 6
17	1 man 4 1/2 hrs. make & paint flower sticks		1 10 1/2	1 10 1/2
20	6-0 of 1 x 11 deal	} 12 flower sticks		.. ..
	6-0 of 1 x 2 ..		19 1/2	1 7 1/2
	1 lb. paint	4/-	6	.. 6

I .. 16 3.

Paid August 11<sup>th</sup> 1909

# Major Kaye

1909

£ s d

Apr. 5	1 man 1 hr making & fixing shelves, bracket for lamp, letter box & plate & per contract			18 6
6	1 man 1 1/2 hrs. repair coal box & ease windows	}		
	8. 3/4 screws			9
May 6	1 man 3 1/2 hrs. alter & fix curtain poles			15 1/2
17	1 man 2 hrs. do.			10
18	1 man 2 1/2 hrs. do. & repair leg of table			10 1/2
	4. 1" brass pole brackets			18
	2. 2 1/2" do.			12
	4 brass ends			24
	18. 3/4 + 3. 1 1/2" brass screws			4
	2. 0 of 1 x 1 ash for joints			1
17	1 man 7 hrs. make table			211
18	1 man 6 hrs. do.			26
	7. 4 of 12 x 1 deal	}	3 1/2	22
	4. 6 of 11 x 1 "		3	11
	9. 6 of 2 1/2 x 2 1/2 "		1 1/2	12
	1. 6 of 2 x 1 "			1
	6. 1 1/2" screws			1
June 21	1 man 2 1/2 hrs. make & fix shelf & bracket			10 1/2
	2. 6 of 1 x 9 deal			7
	2. 6 of 1 x 2 "			1 1/2
	4. 1" screws			1
	12 nails			1
	1 lamp hook & rose			9

£ 2 0 10

Paid August 10<sup>th</sup> 1909

Mr. Charles Stamp

£ s d

1909

Apr.	5	1 man 1 day repair floor	3	8
	6	1 man 1 day do.	3	8
	7	1 man 2 hrs. do.	..	10
		236..0 of 1x7 floor	1	47
		61..0 of 2x4 joint	6	4½
		3-3 of ¾x7 floor	..	3½
		5½ lbs. nails	..	11
May	4	mend & screw iron slay	..	8

£ 2 10

Paid August 11<sup>th</sup> 1909

Aug 4

Mr. W. C. Abbott

£ s d

1909				
May	10	2 plates of iron to shaft, 3 bolts & fitting	3	0
June	15	laying twobill	1	0
July	10	2-10 of 10x1 elm for manger & fitting	..	9

£ .. 49

July 1 bag potatoes

40

Paid August 17<sup>th</sup> 1909

89

## Mr. Medland. Lower Mallocks

1909			£	s	d
Apr	7	1 man 7½ hrs. make body of barrow	3	0	
	8	1 man 3 hrs. do.	1	2½	
	10	1 man 1 day do.	3	8	
	13	1 man 9 hrs. do.	3	7	
		repair barrow iron work & rivets		10	
		put tyre on wheel		6	
		timber		2	2½
			£	15	0

Paid Sep. 25. 1909

Sep. 7. '09

## Mr. William Daley

1909			£	s	d
Mar.	8	4 shoes		2	0
May	11	4 shoes		2	0
			£	4	0

Paid Sept-15<sup>th</sup> 1909

## Dr. Turnwall

£ s d

1909

Apr.	15	1 man 7½ hrs. burn off yard doors	3	4
	16	1 man 6 hrs. repair 1 prime do.	2	6
		2 lbs. priming	1	0
		6" of 4¼ x 1¼ deal	-	1½
		1 pint benzoline	-	2½
		2 sheets of glass paper	-	1
	19	1 man 4½ hrs. paint yard doors	1	10½
May	4	1 man 5½ hrs. do.	2	3½
	5	1 man 3½ hrs. put in sash cords, & fix cornice	1	5½
	8	1 man 2 hrs. paint yard doors	1	10
		7½ lbs. paint	3	11
		4 sash cords. 4 clouts	1	5½
		4 screws	-	1
		glue up chair	-	3
			740	18
				7

Paid August 17<sup>th</sup> 1909

Aug 5

Mr. John Pyne, Kerslakes, Yellington

1909

£ s d

May 10	1 man 1 day, whiten ceilings	4	3
	<del>1 man 2 hrs.</del>		
11	1 man 1 day, whiten ceilings	4	3
"	2 men 1 day ea. painting 2 rooms	8	0
12	1 man 1 day 1 hr do	4	5
	1 man 9 hrs. do	3	9
"	1 man 1 day color & repair staircase	4	3
13	1 man 1 day do do	4	3
"	1 man 1 day painting	4	0
"	1 man 5 hrs. papering	2	1
14	1 man 1 day do	4	0
15	1 man 1 day do	4	0
"	1 man 4 1/2 hrs. 2-9-1 1/2	1	10 1/2
	12 1/2 lbs. paint	5	2 1/2
	14 lbs. distemper	5	0
	28 lbs. whitening	1	3
	1 lb. size 8 1/4 pk. plaster 4	1	0
	1/2 lb. putty paste		6
	1 pint petrifying liquid		3
	1 pair pole brackets & screws		7
	8 pieces paper at 1/6	12	0
	20 yds. frieze at 3 3/4	6	3
	7 pieces paper at 1/-	7	0
	18 yds. frieze at 4 1/2	6	9
	1 piece pitch paper		9
	Horse cart deliver do. 4-17-8	2	0
	2 lbs. paint 9		10

£ 4 18 6

Paid August 17<sup>th</sup> - 1909



## The Vicar &amp; Churchwardens of Malborough

1909		£ s d
June	For repairs to the frame and fittings of the Malborough Church bells according to estimate of May 28 <sup>th</sup> 1909	£ s d
&		" " "
July		25 0 0

Paid August 30<sup>th</sup> 1909

Rev. R. Jenkins  
The Rectory, Talaton.

1909

July

For repairs to the Talaton Church  
Bells according to estimate of March 11<sup>th</sup> 1909

19 14 0

Paid. September 1. 1909.

Sept 30

Messrs Greenleaf & Tristram  
Fyfe Street. Hereford

1909					
August	9	1 Bell Wheel	W <sup>i</sup> 5 <sup>0</sup> 1		1 3 6
		do	5 <sup>0</sup> 1	sent to	1 3 6
		do	5 <sup>0</sup> 2 $\frac{1}{2}$	St. Paul's Church	1 4 0
		do	5 <sup>0</sup> 4	<u>Shrewsbury</u>	1 4 3
		do	5 <sup>0</sup> 2		1 6 0
		do	5 <sup>0</sup> 10 $\frac{1}{2}$		1 8 0
		do	6 <sup>0</sup> 1		1 9 0
		do	6 <sup>0</sup> 5		1 11 0
		carrriage to G. W. Rail Exeter			3 6
					<hr/>
					£ 10 12 9

Paid October 12<sup>th</sup> - 1909

Rev. J. G. Clavin  
Northampton

1909

Aug-

12

He going to Twitchen inspecting  
Frame & Bells, Rail fares & Time

£ 0 d

1 1 0