

H. B. Ormsby Trench Esqr

£ s d

1901

		to balance due from account rendered	14	18	2½
Jan.	9	6 sacks of saw dust		6	6
	16	1 man 5½ hrs. putting in glass in verandah & piping a piece of skirting in smoke room			
		5 panes of glass		2	5½
		2 lbs. of putty			2 6
		3' 6" of 7x1 for skirting			3
		paint & screws			5½
	19	putting in glass in twenty picture frames & putting eyes in some of the frames &			3
Feb.	11	making, painting & varnishing a pair of steps for carriage & putting hinges to same			
		making hanging, glazing & painting a pair of sash doors for smoke room		1	13 6
		mortise lock, brass handles & bolts for doors			
		coloured glass for doors		1	15 0
		burning off linings & jambs of doors			
		putting in a piece of oak on sill & unhangings & leasing doors			12 0
	21	sharpen hand saw			6 0
	23	repairing capping on barn roof for piping & painting turned railing in front of house as per contract			
Mar.	13	putting a pane of glass in bedroom window		21	0 0
	16	for piping & painting paling in kitchen garden as per contract			1 0
	19	painting vases		8	0 0
					7 6
			£	50	6 10

公
文

ap. 11 16/7/01

Mr. John Dew

1901

£ s d

Jan.	10	turning iron for crook	..	3
	8	2 new bolts		
	12	1 body of wheelbarrow + paint wheel	14	0
	16	2 shoes	1	2
Feb.	15	2 shoes	1	2
	19	lengthening iron bars	..	9
Mar.	5	1 shoe	..	7
	19	1 shoe	..	7
		laying coulter	1	6
		1 share	..	7 $\frac{1}{2}$
		2 large S for draft	..	8
	21	lengthen axle	1	0
	30	turning iron for cart	..	3
April	9	1 new shoe + fasten 2	..	9
	11	lengthen 2 rods	..	4
	17	1 man 2 hrs put shaps in trap	..	9 $\frac{1}{2}$
	18	1 man 6 hrs. do.	2	4 $\frac{1}{2}$
	19	1 man 7 hrs. do.	2	11 $\frac{1}{2}$
	20	1 man 4 hrs. do.	1	9 $\frac{1}{2}$
		1 pair of new shaps	10/3	11 0
		2 breeching staples	..	6
		2 plates for shaps repair ironwork	1	6
		2 plates of iron + alter trace hooks	..	6
		3' 0" of 2 x 1 $\frac{3}{4}$ ash	..	4 $\frac{1}{2}$
		6. 2 $\frac{1}{2}$ x 3/8 bolts	..	6
		4. 2 $\frac{1}{2}$ x 1/4 "	..	6
		16 screws	..	1 $\frac{1}{2}$
		1 lb. paint	..	6
		leather for collars gross.	£	10
		varnish	..	4
			..	11
	22	1 man 1/4 day trap	..	4
	25	1 shoe	..	4
May	3	1 plough share	..	4 $\frac{1}{2}$
		forward	£	29 10

1901

£ s d

bro. forward

2 9 10

May 9 2 shoes & fasten 1

1 3

15 2 shoes

1 2

June 7 1 link in timber chain

.. 6

11 sharp two-bill

.. 2

21 2 shoes

1 2

22 put handle in pick, rivet

.. 4

April 20 horse 1 day & man $\frac{1}{2}$ day put in oats

4 9

May 2 6 lbs. mangel seed 6/- carriage 5⁰

6 5

£ 3 5 7

Settled, by Contra ap.

£ 2 14 6 & Cash 11/-

September 14, 1901

12/7/01.

Mr. John Bastin

1901.

£ s d

Jan.	1	3 shoes			1	6
Mar.	1	2 new hooks for oven door and catch for flue piping			1	9
May	10	2 iron squares, bolts & screws for waggons + putting them on			1	9
	14	1 shoe				6

Paid

£ 5 6

W- John Bastin

1901

		Account- rendered	56
July	8	1 shoe	6
Aug	17	1 shoe	6
Nov ^r	1	4 shoes	20
Dec ^r	16	new part- to Dampier	10
			<hr/>
			96
			<hr/>

Paid March 4th 1902

Mr. Henry Stanvill

1907

£ s d

		ap. rendered		5	11	2
Jan.	1	lying coultter				16
	4	1 man 7 hrs. making shutters for Miss Hitchcock				29 1/2
	7	1 man 7 hrs. fixing do. do. 4 3/4				30
		alter shutter catches & put 2 new bars to them				10
		1 pair 12 Tee Hinges & 14 screws				4
		14. 1 1/4 screw				2
		2 bow fastenings & 6 screws				8
		3 lbs. paint				16
		1 1/2 lbs. nails				3
		9.9 of 1 1/4 x 1				3
		6.0 of 1 x 11 ledge	3 1/4			17 1/2
		66.6 of 6 x 3/4 match } shutters	1			56 1/2
		1.6 of 3 1/2 x 1 rill }				2
	17	repair plough wrench				4
	31	new part to coultter eye, new part to stem & sharp coultter				16
Feb.	1	1 man 7 1/2 hrs. repair top of cowshed	4 3/4			30
		2 lbs. nails				4
	5	lying coultter				16
	6	2 new shoes				12
	27	turning pick for dung drag new ring & fit same				6
		4 lengths in chain, & 2 new staples & 1 new cross for harness				19
Mar.	30	# 6 shoes & 2 removes				41
Apr.	2	new axle for plough wheel				9
	..	new large plough wheel				26
May	2	lying coultter				16
	2	1 man 2 1/2 hrs. repair roller frame				10
	18	2 shoes & 2 removes				19
	24	sharpen 3 scuffle knives				13
		forward				
			£	10	13	1 1/2

1901.

£ s d

		boot. forward	10	13	15
June	8	4 shoes			24
	17	1 man 5½ hrs. ringing waggon wheel			22½
	18	1 man 1 day do.			38
		1.9 of 22 x 3½ elm			119½
		1 lb. paint			6
	19	tyring 1 waggon wheel			26
		new tyre on small waggon wheel 41 lbs.			94½
	27	4 removes			12
July	15	flap crook for hamses			9
	17	new bolt for machine			2
		1 remove			3½
	25	1. 5/8 nut			1
	30	4 shoes			24
Aug.	6	2 shoes			12
	19	2 shoes			12
	30	1 man 1½ hrs. make draft			7
		1 large staple for do.			2
Sep.	9	1 man 4 hrs. repair waggon shaft.			17
		1 long staple for shaft.			9
		2.6 of 3 x 3 ash for shaft.			8
	27	2 shoes + 3 crooks for hamses			18
Oct.	1	1 flap crook for hamses			9
	2	1 man 1 day repair pound			38
		1 rivet + 12 nails			4
	3	new foot to coulter			10
	4	2 shoes			12
	5	2 shoes			12
	7	lying coulter			16
	18	1 man 3½ hrs. make 3 whippletrees			15
		3 staples for do.			6
	23	lying coulter			16
		forward	£	13	11½

change 8/3

change 3/-

1901

£ s d

		brok. forward	13	1	15
Nov.	4	1 man 2 hrs. repair pound			9 ¹ / ₂
	14	light lie on two ble			14
	"	1 man 4 ¹ / ₂ hrs. about screw of pound			19 ¹ / ₂
		1 lb. white lead			4
	22	sharpen coulter			3
Dec.	6	2 shoes			12

£ 13 6 9¹/₂

Mr. Henry Glanville

1902

£ s d

ap. rendered

13 6 9⁵

Jan. 14

2 shoes

1 2

28

man 2¹/₂ hrs. repair horse wheel

1 0

2 3¹/₂ x 3¹/₂ bolts 2 countersunk nails

.. 3

2 stay irons for do.

2 1

.. put in grate back

.. 6

Mar. 15

2 shoes

1 2

20

4 shoes

2 4

Apr. 10

lying coultter

1 6

May 26

4 shoes

2 4

June 6

2 shoes & 2 removes

1 9

£ 14 0 10⁵

Settled by cash & contra account
October 11th 1902

Mr. Wm. Summerfield

1902.

£ s d

Jan.	7	2 shoes			1 0
Feb.	5	1 man 5 hrs. put in front side in barrow			2 9
		5' 0 of 13 x 1 elm			
		6 rivets repair strap plates			6
	23	drawing 2 loads of gravel from Exmouth			6 0
	27	4 shoes			2 0
		1 iron grating			2 0
Mar.	6	sharpen brick hammer			2
	7	1 man 5 hrs. make barge trapping			2 0
	8	1 man 2 hrs. do.			4 1/2
	12	1 man 1 hr. paint do			5
		36' 0 of 7 x 3/4	1		3 0
		36' 0 of 7 x 1	1 1/4		3 9
		5' 0 of 9 x 3/4	13/4		1 2
		12' 0 of 9 x 1	2 1/2		2 6
		1 lb. nails			2
		1 1/2 lbs. paint			9
	12	1 new brick hammer stem			1 10
	22	sharpen 3 bits			3
	23	do.			3
		25' 0 of 7 x 3/4 match	1 1/4		2 4
	22	drawing 250 brick from Otterton to Woodbury Cottages			4 0
	23	drawing 250 brick			4 0
	25	do.			4 0
	26	do.			4 0
	27	do.			4 0
	29	do.			4 0
	30	do.			4 0
April	2	new flue 10 lbs.			3 9
	3	drawing 250 brick from Otterton			4 0
	4	drawing 250 brick to Woodbury Cottages			3 6
		forward	7		3 14 3 1/2

1901

£ s d

		brk. forwd.	3	14	3½
April	6	draw 250 brick to Salterton		3	6
	10	draw 250 brick from Exmouth to Cottages		3	0
	15	" 250 " " " "		3	0
	18	4 shoes		2	0
	27	draw 200 brick from Exmouth		2	5
	29	draw 250 brick from Otterton		4	0
	30	1 man 2½ hrs. put new leather to sucker & spindle of pump leather & clouts		"	"
				1	10
May	4	draw 1 load tile from Otterton		4	0
	6	" 1 load tile "		4	0
	7	" 500 brick from Exmouth		6	0
	8	" 250 brick "		3	0
	11	" 250 brick " Otterton		4	0
	14	" 250 brick " "		4	0
	16	" 250 brick " "		4	0
	17	" 250 brick " Exmouth		3	0
		" new bar handle for grindstone		4	2
		" 1 hr. make wood handle for do.		6	
	18	draw 250 brick from Exmouth Otterton		3	0
	22	draw 250 brick from Exmouth		3	0
		" 250 brick from Exmouth to Ebford		3	0
	29	" 250 brick from Exmouth		3	0
	30	" 250 brick from Otterton		4	0
	31	" 250 brick do.		4	0
June	3	" 250 brick " Exmouth		3	0
	4	sharp brick hammer		"	2
	5	sharp pick		"	2
	6	draw 250 brick from Otterton		4	0
	7	" 250 brick do.		4	0
	10	4 shoes		2	0
		forward	£	8	5 0½

1901		£	s	d
	brought forward	8	5	0½
June	11 sharp pick		..	2
	13 sharp pick		..	2
	18 draw 250 brick from Otterton			40
• 8	21 " 250 " do.			40
	25 " 250 " from Exmouth			30
	27 " 250 " from Otterton			40
	28 " 250 " do.			40
	29 " 250 " do.			40
June	For work done at Cothulls Farm as per estimate of April 13. 1901	2	2	0
July	4 strap plate for sieve		..	6
	6 1 shoe		..	6
	12 2 plates of old iron <u>15lbs</u>	1½		10½
	13 For painting &c done at Cothulls (late Crook's cottage) as per estimate of May 28. 1901		..	5 90
	15 1 load floor tile from Otterton			40
	16 sharp pick		..	2
	17 sharp pick & brick hammer		..	3
	18 1 load floor tile from Otterton			40
	.. drawing 250 brick from Exmouth topped			30
	.. 2 new eyes & axle for barrow			13
	19 ^{1 day} drawing away clay from cottages			60
	20 1 load tile from Otterton			40
	22 1 day draw away earth from cottages			60
	23 sharp 2 chisels		..	2
	25 2 shoes			10
	26 draw 2 Hds. lime from Topsham topped			30
	draw 2 load sand do.			16
	.. new twist & drop catch & shaper for own garden gates		..	10
	forward	£	18	18 5

£ s d

	brok. powder.		18	18	5
July 27	1 man 6 hrs. put twist on gate & hang grindstone	4 3/4	2	4	1/2
	2. 4 x 3/8 bolts.				3
	6. countersunk nails, 6, 2" screws				3
27	new flue 10 lb. plain		21		21
	2 staples & make plate				5
	sharp pick & hammer				3
29	sharp brick hammer				1
31	sharp pick				2
Aug 8	2 men 2 day ea. drill headstone in churchyard				38
9	2 men 2 day ea. do. do.				38
	1. 5/8" pin 14" long				4
12	1 shoe				6
13	For work done at Mr. Sages. Withycombe as per estimate of March 6. 1901.		2	15	0
	delivering gates				30
	1 man 8 hrs. put up barge boards & repair boarding & studs at Mr. Sages				34 1/2
	40.0 of 7 x 3/4	1 1/4			34 1/2
	6.0 of 9 x 3/4	1 3/4			10 1/2
	17.0 of 3 x 2 studs	1			15
	2 lbs. nails				4
Sep. 4	sharpen pick				2
10	3 new shoes				16
17	draw 250 brick to T. Perrys				30
	4 load sand				30
18	500 brick to				60
20	250 brick to				30
	1 new pin & key for Hooper's pump forward				9
			23	18	1

1901

£ s d

			£	s	d
		brok. forward	23	18	1
Sep.	23	drawing 1 ton blue lias from Greter		6	0
	24	" 200 brick to T. Perry's		2	5
	25	" 500 brick do		6	0
	25	making 2 new gate hooks for Woodbury Salterton	
	26	new twist to iron gate & new, latch & guide & cutting off bottom of gate	
	27	new catch for wall		3	4
Oct.	4	drawing 500 brick to T. Perry's		6	0
	7	" 250 do. do.		3	0
	8	" 250 do. do.		3	0
	.	" 4 load sand do.		3	0
	12	" 500 brick do.		6	0
	16	4 shoes		2	0
x	17	drawing 250 brick to W. Salterton		3	6
	21	" 250 do. do.		3	6
	22	" 250 do. do.		3	6
	26	" 3 load tile from Station to T. Perry's		6	0
	28	" 1 load tile do.		2	0
	31	sharp 2 pin hammers		..	2
Nov.	6	drawing 250 brick to T. Perry's		3	0
	.	" 1 load sand do.		..	4
	9	drawing 250 brick do.		3	0
	11	" 250 " do.		3	0
	"	15'-0" of 2x1 batten		4	6
	13	drawing 250 brick do.		3	0
	14	" 500 brick do.		6	0
	18	man 2 hrs. lad 1 1/2 hrs. make grating frame 5'-0" of 4x3 oak for frame		1	2
	23	solder zinc gutter		..	3
Dec.	4	making wood block		..	3
		forward	£	28	8 5

1901.

F o d

	brof. forward			28	85
Dec. 9	4 shoes				20
18	2 men 1 day ea. lay floor at ^{upair joint} Mr. Antons				74
19	2 men 1 day ea. do. do.				74
20	2 men 1 day ea. puttidge in glass. + repairing casements & casing windows				74
	10 1/2 lbs. nails				19
	365.0 of 7x1 floor	1 1/4	1	180	
	26.0 of 4 1/2 x 3 joint	2 7/8		6	83
	1.6 of 4 1/2 x 1 1/2 for casement				3
	4 panes glass 10x6				8
	3 do. 10 3/4 x 6				6
	2 do. 7 1/2 x 6				3
	1 do. 7 3/4 x 6				8 1/2
	1 do. 7 x 9				2
	2 1/2 lbs. putty				4 1/2
	18, 1" screws, 1 butter-screw				3
	1 square for casement				2
23	4 shoes				20

carried to page 228

£ 32 3 1/2

32 3 1/2

July 11. 1907
wrote him on Sept 12th 1907

Rev. Godfrey Bird

1907.

£ s d

		account rendered	7	5	0
Jan.	8	2 shoes + 2 removes fittings caulks to shoes			20
	12	sharpen 2 chisels			4
Feb.	5	2 shoes + 2 removes			17
Mar.	20	2 shoes leather + 2 removes			26
April	25	4 removes on pony			12
		.. repair hoe + fork			8
June	3	1 man hrs. fit sideboard re			21
	4	1 man hrs. repair chair, steps + door + hanging door			26
		2-6 of 9 x 3/4 deal } 2-6 of 7 x 3/4 " } repair 7-6 of 3 x 1/2 " } door			5 2 1/2 4
		3-0 of 7 x 3/4 for steps			3
		screws + nails			2 1/2
	20	4 shoes			20

£ 8 13

September 23rd 1907 Received Cheque for £ 4 5 0

left due £ . 16 3

Rev. Godfrey Bird.

1901.

£ s d

balance due on a/c rendered

16 3

July 25 4 removes

1 2

shooting + rivetting 20 bars

10 0

sep. 10 4 removes

1 2

Oct. 3 4 shoes

2 4

15 altering wire arches

1 0

Nov. 5 4 removes

1 2

30 4 shoes + 2 leathers

3 4

Dec. 31 4 removes

1 2

£ 1 17 7

Sir Charles Pearson

1907.

£ p d

				£	p	d
Jan.	1	1 man 9½ hrs. piping shelves		3	11½	
	10	1 man 9½ hrs. do. brackets &c		3	11½	
	11	1 man 9½ hrs. fit towel rollers, put lock		
	..	on gardeners door &c		3	11½	
	..	1 man 3 hrs. make shelves & towel rollers		1	3	
	..	new crook for harness room		..	9	
	..	6½ lbs. nails		1	1	
	..	4 gutter bolts, 4, 2" screws			3½	
	..	½ lb. white lead & putty		..	1	
	..	13' 0" of 11 x 1 deal shelves	3	3	3	
	..	3' 6" of 2 x 2 towel rollers	- 40	..	2½	
	18	1 man 9½ hrs. fitting up shelves		3	11½	
	21	1 man 1½ hrs. make shield		..	7½	
	22	1 man 2½ hrs. do.		1	0½	
	23	1 man 9½ hrs. piping shelves & shutting		3	11½	
	24	1 man 9½ hrs. do.		3	11½	
	..	4' 0" of 9 x ½ board	13½	..	7	
	..	stain, size, varnish		..	4	
	..	1 pair 2½ brass bits, screws		..	11	
Feb	26	1 man 3½ hrs. make sword trophy		1	5½	
	27	1 man 9½ hrs. piping shutting, brackets &c		3	11½	
	28	1 man 6 hrs. make sword trophy		2	6	
	..	4' 0" of 9 x ¾ one trophy	2	..	8	
	..	6' 0" of 9 x ¾ } one trophy	2	1	0	
	..	2' 0" of 5 x 1½ } one trophy	2¼	..	4½	
	..	3' 0" of 2 x ½ } one trophy	½	..	1½	
	..	stain & varnish		..	6	
Mar.	4	½ hr. varnish trophy		..	6	
	5	1 man 7½ hrs. piping sundry articles		3	1½	
	6	1 man 7½ hrs. do.		3	1½	
	..	4 washers for gate		1	2	
	..	½ lb. putty		..	2½	
	13	2 new eyes & axle for barrow wheel		1	6	
	..	forward =	£	2	13	10½

1901.

£ s d

		amount brok found.	2	13	10½
Mar.	25	2 lbs. grey paint		1	0
		1½ lbs. pink "		"	9
		1 lb. white "		"	6
Apr.	25	1 lb. paint		"	6
May	15	1 man 9½ hrs. fixing boarding		3	11½
	16	1 man 9½ hrs. do.		3	11½
		22.0 of 1" match	1½	2	9
		1 lb. putty			1½
		8 ^{lb} nails		1	4
		repair greenhouse iron		1	6
	21	1 man ^{9½ hrs} 1 day fix netting & shelves		3	11½
	22	1 man 9½ hrs. do.		3	11½
		2 doz. 1½" screws			3#
		1 screw for door knob			1
June	11	½ lb. green paint		"	3
	19	sharp 3 mattocks, 2 ends each		1	0
		put new bolt to garden shears		"	3

£ 4 0 0

Paid July 12. 1901

July 11. 1901

1901 Sir Charles ^{Pearson} Pearson

£ s d

April
+
May

Paid to Mr. Bennet Colley for
putting a piece of glass in the
memorial window in Thorne Church
and opening and replacing the
cover of the Family Vault in
Thorne Churchyard
Trap hire and time for self going
to Thorne from Montacute

15 6

10 6

 £ 1 6 0
Paid. July 12. 1901.

Mr. Brent-Spencer.

1907.

£ p a

Jan	11	2 men + 1 lad 2 hrs. ea. prop ceiling at Oakhayes	"	13
	14	1 man + 1 lad 7 1/2 hrs. repair roof		4 8 1/2
	15	1 man 7 hrs. do.		2 11
		1 lad 5 hrs. do.		10 1/2
	17	1 man + 1 lad 4 hrs. ea. do.		2 6
	18	1 man 6 hrs. paint skylight & bedding down lead on do. & put in pane of glass		2 6
		8 lbs. nails		1 4
		97.6 of 3x2 rafter		8 1 1/2
		518.0 of 2x1 batten		15 6
		2.3 of 4x1 1/2		" 4
		3 lbs. red lead, 1 lb. putty		" 5 1/2
		2 lbs. paint		10
		3 doz. of 1" clouts		2
		1 pane glass 6x5 1/2		1 1/2
		5 cwts. oqr. 6 lbs. of 5 lb. lead for gutters	5	13 2
	11.4	Plumber fixing new lead gutters	"	"
	14.4	& repairing old gutters, time	"	"
	17.5	& solder	1	15 4
	14	1 man 5 hrs. prop roof at Crooks		2 1
		17.0 of 3x2		15
		slabs for hanging up ceiling joist		6
		14.0 of 4x3	2 3/4	3 2 1/2
		22.0 of 2x1		" 8
		2 lbs. nails		" 4
	21	1 man 7 1/2 hrs. repairing Crooks cottage		3 1 1/2
	22	1 man 8 hrs. do. do.		3 6 1/2
	23	1 man 1 day " casements		3 8
	24	1 man 1 day putting in glass, & putting on fastenings to forward		3 8
			£	10 12 8

1917.

£ s d

		brought forward		10	12	8
Jan.	25	1 man 1 day painting				3 8
		1 man 7 1/2 hrs.				3 1 1/2
	26	2 men 1 day ea.				7 4
		4' 0" of 5 1/2 x 3/4 for repairs to floor	1 1/4			5
		4' 0" of 9 x 3/4 window balusters	2			8
		3' 3" of 6 x 3/4	1			3 1/2
		3' 3" of 7 x 1 mantel board	1 1/2			5
		2 blocks				2
		4' 0" of 7 x 1 floor	1 1/2			5
		1 bow latch & screws				6
		1 Norfolk latch & screws				7
		1 doz. 1" screws				1
		2 1/2 of 3 x 1 1/2 bottom rail of window				3
		5 panes of glass 12 x 9 ea. = 540				
		3 " " 11 x 8 1/2 " = 280 1/2				
		2 " " 8 3/4 x 13 1/4 " = 234				
		3 " " 9 1/4 x 13 1/4 " = 370 1/2				
		2 " " 7 3/4 x 11 1/4 " = 176				
		1 " " 7 3/4 x 13 1/4 " = 104 = 170 5/8				3 6
		4 1/2 lbs. putty				4
	28	2 men 1 day ea. painting				7 4
	29	2 men 1 day ea.				7 4
	30	2 men 1 day ea.				7 4
	31	2 men 1 day ea.				7 4
Feb.	1	2 men 1 day ea.				7 4
	2	1 man 1/2 day				1 10
		1 1/2 lbs. putty				10 1/2
		17' 6" of 1 x 7 mantel piece	1 1/4			1 10
		1' 0" of 2 x 4 blocks				1 1/2
		2' 9" of 3 x 1 1/2 for casement				1 1/2
	4	1 man 1 day painting forward				3 8
				£	13	19 9 1/2

1901

£ s d

		brought forward		13	19	9 $\frac{1}{2}$
Feb.	4	1 man $\frac{3}{4}$ day papering				2
	5	2 men 1 day ea. do. painting				7
	6	2 men 1 day ea. do. do.				7
	7	2 men 1 day ea. do. do.				7
	8	1 man 1 day do.				3
	9	1 man 1 day do.				3
		1 black iron knob				1
		33 $\frac{1}{2}$ lbs. paint inside & outside	6			16
		paste				1
	12	1 man 1 day repair Miller's cottage				3
	13	1 man $\frac{1}{2}$ hrs. put on knocker on door				7 $\frac{1}{2}$
		1 knocker				1
		varnish for door				3
		graining door				0
		1 turnbuckle, 1 wash fastener				10
		8, $\frac{1}{2}$ " screws, 1 screw in door handle				2 $\frac{1}{2}$
		1 pane of glass 3'-0" x 11 $\frac{1}{2}$ "				10 $\frac{1}{2}$
Jan.	31	1 man & lad $7\frac{1}{2}$ hrs. ea. repair roof of Drill Hall				"
		51'-0" of 5x2 deal props	$\frac{1}{2}$			6
		2'-6" of 7x1 "				3
		4'-0" of 3x2 "				4
		2 $\frac{1}{2}$ lbs. of nails				5
Feb.	4	1 man $5\frac{1}{2}$ hrs. put up rails in Oakhays barn				2
		14'-0" of 3x2 deal rail				1
		2 stakes, 1 lb. nails				5
		tar & piece of rope				3
	8	1 man $5\frac{1}{2}$ hrs. make skirting for pantry & housekeeper's room at Oakhays				"
		47'-3" of 9x $\frac{3}{4}$ skirting	2			8
		22'-0" of 1 $\frac{1}{4}$ x $\frac{1}{2}$				5 $\frac{1}{2}$
		6'-6" of 7x1 floor	$\frac{1}{4}$			8
		forward	£	18	8	11 $\frac{1}{2}$

1907

£ s d

		frought forward		18	8	11½
		3 lbs. nails				6
		½ lb. putty				1
Feb.	11	1 man 1 day fix skirting		3	8	
	12	1 man 6 hrs. do.		2	6	
		1½ lbs. paint				9
	28	2 hrs. examining roof & cistern				10
Mar.	1	1 man 2 hrs. making skirting for Dakhays		1	0	½
	2	1 man 1 day fix & paint do.		3	8	
		1 man 2 hrs. putting a piece of zinc in gutter				10
		13.6 of 7x¾ skirting (scullery)	1	1	1	½
		5.3 of 11x¾ " "	2½	1	0	½
		2.0 of 3x½ " "				1
		1 lb. nails				2
		½ lbs. paint				9
		4.0 long 5 wide of zinc				7
	4	1 man 6 hrs. fixing cistern		2	6	
		1, 100 gallon galv. cistern		1	13	6
		4.6 of 3x1 beaver	3½	1	2	½
	4	Plumber fixing new cistern and repair leaks of gutter				11 9
	15	1 man 4 hrs. make paint cover of ^{cistern} tank		1	8	
	18	1 man & 1 lad 2 hrs. ea. fix cover		1	3	
		16.6 of 6x1 match	1½	1	8	½
		6.0 of 7x1 ledges	1½			7½
		½ lb. paint, ½ lb. nails				4
	18	2 men 8 hrs. ea. put up linbays at Islobe Hill cottages				6 8
	19	2 men 6 hrs. ea. do.		5	0	
	20	1 man 3 hrs. make earth box for W.C.		1	3	
		60.0 of 4x3 deal	23¼ 23¼	13	9	
		forward		23	7	9½

1907

£ a d

	brought forward		23	7	9½
	83.0 of 4x2 studs	1¼		8	8
Mar. 25	2 men 5½ hrs. ea. linchays			4	7
26	2 men 1 day ea. do.			7	4
27	2 men 1 day ea. do.			7	4
	1 lad 2 hrs. do.			..	5
28	2 men 1 day ea. do.			7	4
29	2 men 1 day ea. do.			7	4
	6.0 of 9x1 elm earth top } 4.6		
	2.0 of 12x1 .. } 20.6.6	½		1	4
	½ lb. nails			..	1
	6 oak posts 9.6 long 4x3½ = 57.0	3¼		16	7½
	1 do. 9.6 long 4x5	5		3	11½
	135.0 of 3x2 rafter	1		11	3
	195.0 of 2x1 batten	3½		5	10
	326.0 of 9" feather edge board	1¾	2	7	6½
	13.6 of 1½x7 rough oak	2		2	3
	6.0 of 7x1 floor board	1¼		..	7½
	13½ lb. nails	2		2	3
	41.0 of 7x1 barge rapping	1¼		4	3½
	50.0 of 7x1	1¼		5	2½
	5.0 of 4x1 } 2 doors	1		..	5
	18.0 of 7x1 oak }	2		3	0
	2 lbs. nails }			..	4
	84.6 of 7x1 partitions	1¼		8	9½
	10.6 of 6x1 "	1		..	10½
	10.6 of 4x3 pill	2¾		2	5
	21.6 of 4x2 studs	1¼		2	3
	4 3½x3½ bolts			..	2
	1½ doz. counter sunk nails			..	3
	3.6 of 7x1	1¼		..	4½

forward.

£ 31 10 11

BRENT

1901

£ s d

	forward		31	10	11
ap. 9	1 man 2½ hrs. take down partition in linkway Globe Hill			1	0½
11	1 man 1 day do. do.			3	8
12	1 man 1 day do. do.			3	8
	1 plate of iron for catch of door				2
	9 screws & 2 lbs. nails				5
	14' 0" of 3x2 deal				12
	5' 9" of 1x7	1¼			7
	8' 0" of 3x¾ stops				6
	½ lb. of paint				3
	1 bucket tar, 1 pt. paraffin				10
May 25	1 man 2 hrs. repair floor of Drill Hall				10
	7' 6" of 7x1 floor	1¼			9½
	4' 0" of 2x3 joist				4
	nails				1
23	1 man 1 hr. repair shuting at Oakhays				5
25	1 man 6 hrs. 1 lad 4 hrs. do. do.				34
	2 shute holdfasts (^{old} pattern) 2 plain do.				30
	cutting & boring shuting				6
29	1 man + 1 lad 1 day ea. shuting				58
June 1	1 man 9 hrs. 1 day do.				38
	8 holdfasts special pattern				70
	cut & bore shuting				6
	2 4" angles 4/6 cost price				50
	5; 6' 0" lengths of 4" 2nd. shuting	1.96			89
	1 doz. white bolts 1/6 at length				3½
	2½ doz. 1¼" screws				4
15	1 man ½ day repair verandah roof				110
	150 clouts				6
	1 lb. nails				2
17	1 man ¼ day making shutes				11
18	1 man 1 day repair yard doors				38
	forward	£	34	10	11½

Brent

1901.

£ s d

	forward		34	10	11½
June	19	1 man 1 day 2 hrs. repair doors, shutters			4 6
July	"	1 man 1 day do do			3 8
	20	1 man ¾ day do cellar cover			2 9
	21	1 man 1 day repair doors, shutters			3 8
	22	1 man ¾ day put new rafter in potting shed			2 9
		5' 0" of 2¼" x 11" yard doors	5¾		2 5
		1' 0" of 2¼" x 6" "	3		.. 5
		23' 0" of 7 x ¾ phutes	1		1 11
		blbs. pitch	3d		1 6
		piece of line, 6' 0" x 4" = 2 sq ft.			3
		3' 0" of 4" x 3" sill to greenhouse			.. 19
		2 iron squares, & 12, 1¼" screws			10
		24, ¾" screws & 30, 1" clouts			4
		4' 9" of 7 x 1¼ cover of cellar	2		.. 9½
		13' 6" of 7 x 1 "	12¼		1 11½
		4' 6" of 9 x 1 "	2¾		1 0½
		7' 6" of 9 x ¾ coach house doors	2		1 3
		2' 9" of 9 x 1 pump	2¾		.. 7½
		8' 0" of 3 x 2 rafter potting shed			8
		8' 3" of 9 x ¾ barge rapping do. 2			1 4½
		4 blbs. nails			.. 9
			£	36	5 6
		Credit by old lead			£ 200 0

Mrs. Brent-Spencer.

1901.

£ s d

	to ac. rendered July 26.		34	5	6
June 29	1 man $\frac{1}{4}$ day, fix barge capping tease doors etc at Oakhayes		"	"	"
July 4	1 man 7 hrs. repair garden frame do		2	11	
5	1 man 1 day do.		3	8	
6	1 man 4 hrs. do.		1	8	
	13" 0 of 6 x $\frac{3}{4}$ capping	1		11	
	6" 6 of 2 x 9 pill for frame	$4\frac{1}{2}$		2	5 $\frac{1}{2}$
	3" 6 of 7 x $1\frac{1}{4}$ deal "	2		"	7
	1" 6 of 2 x $1\frac{3}{4}$ " "	1		"	1 $\frac{1}{2}$
	4. 1 $\frac{1}{2}$ " screws			"	1
9	1 man 2 $\frac{1}{2}$ hrs. re-leather sucker & repair pump at Globe Hill cottages new leather belonts			"	"
	2 new bolts, 2 keys, stopping up & re-boring holes in pump handle			"	"
13	For painting etc done at Oakhayes House as per estimate of May 11. 1901		38	12	6
17	1 man $1\frac{1}{2}$ hrs. repair porch Sunnyside			"	7 $\frac{1}{2}$
26	1 man 9 hrs. put up beams in stable at Oakhayes			"	"
	1 man 7 hrs. do. do.		2	11	
29	2 men 1 day ea. do.		7	4	
30	2 men 1 day ea. do.		7	4	
31	2 men 1 day ea. do.		7	4	
Aug. 1	2 men 1 day ea. do.		7	4	
	5. 9/16 bolts				16
	51" 0 of 11 x 4 for 2 beams & lintels	10 $\frac{1}{2}$	2	4	7 $\frac{1}{2}$
	2" 0 of 9 x 3 deal bond	6 $\frac{1}{2}$		1	1
	66" 0 of 7 x 2 deal joist	3$\frac{3}{4}$		15	6
	5" 6 of 7 x $1\frac{1}{2}$ " "	2 $\frac{1}{2}$		"	12
	10" 0 of 6 x 2 " "	2 $\frac{1}{2}$		"	21
	forward		£	78	19 8

Brent

1901

£ s d

	boot. forward.		78	19	3
	11 lbs. nails			1	10
	32.0 of 2x1			1	0
	5.6 of 4x2 1/2	2 3/4		1	3
129.	139.0 of 7x1 floor	1 1/4		14	6
	2.0 of 6x3	4 1/2		"	9
	4.6 of 9x3/4	2		"	9
	3.9 of 7x3/4	1		"	4
Aug 12	1 man 4 hrs. fix chute + down pipe on Porth at sunnyside				18
	14.0 of 1" gas pipe				65
	2 tin chutes				56
	6, 1 1/4 + 6, 1" screws				" 1 1/2
	4 pipe hooks				" 8
16	25.0 of 2x1 batten for Globe Hill Cottages + nails				" 10
25	1 man 4 hrs. repair gate, front door pump at C. Stamps				18
	altering twist of gate				" 6
	new rubber to pump spindle				" 4 1/2
	new box + 2 screws to door lock				" 3 1/2
Sep. 18	Plumber solder pump, time + solder at C. Stamps				20
19	1 man 1 day make fix pump case at C. Stamps				38
20	1 man 1 hr. paint do.				" 5
	1 holdfast + new pins for pump handle				10
	5.3 of 9x1 deal pump case	2 3/4			1 2 1/2
	12.3 of 11x1 " "	3			31
	5.3 of 8x2 oak staff plank	5 1/2			25
	3.0 of 3x1 1/2 ash handle				" 4 1/2
	8, 2", 2, 1" + 1 1/4" screw				" 1 1/2
	forward		£	81	12 11

Sept. 30th 1901

Brent.

1907

Lead

brok. forward.	81	12	11
½ lb. nails	1
1 lb. paint	6
to account for closets rendered Sep. 20. 1901.
	2	5	0
	<u>£</u>	83	17 6

Settled October 16th 1901

allowed Mr T Leam - £2.2.6 for discounts

July 25/1901

Mrs. Langdon Fulford

£ s d

1901.

to account rendered

8 9 0

Jan.	28	1 man 8 hrs. make yard door jambs		3 4
		1 lad 5 hrs. do.		1 0 1/2
	29	1 lad 2 hrs. do.		6 1/2
		1 man 1 day repair door		3 8
	30	1 man 1 day do.		3 8
	31	1 man 2 hrs. paint door jambs		10
		19.0 of 4 1/2 x 3 deal jambs	3 1/2	5 6 1/2
		4.0 of 4 1/2 x 3 oak sill	4	1 4
		17.6 of 2 1/2 x 1/2 stop	1/2	9
		3.6 of 1 1/4 x 11 for doors	3 3/4	1 1
		4.6 of 4 1/2 x 2 "	2 1/2	10
		7.0 of 1 x 9 "	2 1/2	17 1/2
		3 lbs. paint		1 6
		1 lb. nails		2
		2. 3" screws		1
Feb.	4	1 man 1 day fit jambs & hang doors		3 8
		1 lad 5 hrs. do.		1 0 1/2
		4.0 of 3 x 1/2 ^{2 1/2} + 1.9 of 3 x 1 1/4 ^{2 1/2}		4 1/2
		1. 10" bolt. 6 screws. 1 staple		1 0
		1 Norfolk handle & screws		8
		1 pair 18" Tee hinges, 18. 1 1/2" screws ^{3d}		1 4
		1 lb. nails		2
		1 staple & catch for door		4
	6	sharpen saw		6
	12	1 man 2 hrs. paint door		10
		1 1/2 lbs. paint		9
		1 1/2 lbs. putty		2 1/2
	13	1 man 2 hrs 2 men 1 1/2 hrs. ea. clear eistem		1 3
	20	3 1/2 hrs. making oak boards		1 5 1/2
		2 pieces of oak 8 1/2 x 11 x 1/2		1 0
		1 do. 13 1/2 x 13 1/2 x 7/8		1 0
		putting new spring in lock forward		6
			£	10 10 6

1901

£ s d

forward

10 10 6

Mar. 4 1 man 1 hr. help plumber about cistern
 Plumber putting a new ball tap to W.C. cistern
 piece of pipe, time & solder 9/11

. 5
 " "
 11 0

15 1 man 2 hrs. repair casement &
 handle of door

. 10

1 pair 2" butts.

4

4. 1" screws

" 1

2 screws for door handle

3

April 26 1 man 5 1/2 hrs. make fire screen charge for

2 3 1/2 x

27 1 man 2 hrs. make flower stand screen
 stain & varnish 4/6

.. 10 x

.. 3 x

3-9 of 1 x 9

2/6

.. 10 1/2 x

4 turned knobs

8 x

1 pair 3" brass butts & screws

1 3 x

4 turned legs

Charge for
 flower stand

1 0 x

29 1 man 2 hrs. flower stand

3/9

.. 10 x

May 29 put castor on table & repair castor

1 0

.. solder cistern

2 0

June 6 repairing garden shears

.. 6

26 1 man 4 hrs. repair pump & put in
 baluster

1 8

1 crank casement fastener

.. 4

2" 6 of 1 x 3/4 baluster

.. 2

£ 11 17 4

Paid by cheque December 28th 1901

~~Aug 13. 1900~~

Mrs. Langdon Fulford.

1901.

£ s d

		Wagon rendered						17 7	
July	2	lying twobill						10	
	2	1 man 1 hr. ^{take down pump} make pump case						" "	
	4	1 man 2 1/2 hrs. fix do.						1 5 1/2	
		400 of 1x6 oak						.6	
		1/2 lb. nails						.1	
	18	4 peg irons						10	
	"	2 men 7 1/2 hrs. ea. fix wire netting						63	
	19	2 men 7 1/2 hrs. ea. do.						63	
		3 rolls of wire netting			7/6	1		26	
		2 gross of staples						1 10	
		1 coil of fine wire						.7	
		160.00 of 3x2 posts			1			134	
Sep.	12	repair 2 locks						10	
	"	1 man 2 1/2 hrs. take off & put on lock outdoors ^{drawing room}						10 1/2	
	13	1 man 2 hrs. repair hall lock						10	
Oct.	18	put in twobill stem						10	
Nov.	9	1 man 2 hrs. repair casements						10	
		1 pane of glass 16x11						5 1/2	
		1 lb. putty						.1 1/2	
	"	repair handbell						10	
1902	June	23	clean off lettering cross					30	
Dec.	20	putting in fire block in stove, 1 new fire block + time + screws						50	
									£
July	22	pumping out well						20	
July	24	pumping out well						20	
Aug.	5	1 man 1 1/2 hrs. put in pane of glass						.7 1/2	
		1 pane glass 18x16 & putty						7 1/2	
	26	1 man 1 day repair front gates						38	
	27	1 man 1 day do. & doors						38	
	28	1 man 3 hrs. painting do.						13	
		forward			£	4	1	11	

1902

£ s d

	brob. forward		4	1	11
Aug. 30	1 man 5 1/2 hrs. painting			2	3 1/2
	1 plate + 2 square staples for gates			..	6
	1 bolt for old doors			..	6
	H staples + hooks for front gates			..	6
	16 1/2 lbs. paint			8	3
	1 1/2 lbs. putty			..	2 1/2
	10, 1 1/2 screws, 2 lbs. nails			..	6
	9..0 of 4 x 2 deal	1 1/2		..	4
	9..0 of 1 x 7 "	1 1/2		1	1 1/2
	9..0 of 3/4 x 9 "	2		1	6
	1..0 of 3 x 11 "			1	3 1/2
Dec. 15	2 small rope pulleys		
	1 man 2 hrs. take off + repair lock of bedroom door			..	10
	repair lock			..	6
15	pumping out well			2	0

£ 5 3 5

Paid March 5th 1903

The Churchwardens of Cotleigh

1901			
May	4 th	For 3 Bell Ropes for Cotleigh Parish Church Bells each 60 ft long	£ 0 1 1 15 0

Received by P.C.C.
May 10th 1901

allowed back Mr G. Shepherd. Seaton 2/-

July 12, 1901

x

W^{ch} # Stamp

1901.

£ s d

May 13

By account rendered Midsummer 1898
making a polished Elm Coffin for
his infant daughter

4 1 11
" "
18 0

£ 4 19 11

Paid 1902

Mr W Carter

August 24th 1901

1901

o d

May 6th For making a coffin for his ~~child~~
son Bertie Frank Carter

14 0

Paid in ~~eight~~ ^{seven} instalments
of 2/- ea. from Aug. 24. to
Oct. 5. 1901.

June 1st 1901

W^{rs} Hill

£ s d

1901

May 26

For making a Polished Eben Coffin
with Brass Furniture & Fittings for
the late W^c Noah Hill

3 10 0

Paid June 1st 1901

June 3rd 190

W-J Carter

1901

May 28

For making a coffin for his late
Son Thomas Carter aged 3 years 7 months

15 0

Paid June 3rd 1901

July 5, 1901

Mr Joseph Skinner

1901.

£ s d

Mar.	4	1 man 1 1/2 hrs. about pump		1	7
		plumber soldering pump. time solder		2	6
	5	1 man 3 1/2 hrs. repairing pump		1	14 1/2
		2-6 of 9x3 oak	6 3/4	1	5
		2-6 of 6x3 oak	4 1/2		11 1/2
		1/2 lb. nails			1
	11	1 man 1 day make door jambs for W.C.		3	8
	12	1 man 1 day do. gate		3	8
	13	1 man 4 hrs. make gate		1	7
		56-0 of 6x1 match	1 1/4	5	10
		6-9 of 11x1 ledges	3	1	8 1/2
		32-6 of 3x3 jambs	2 1/4	6	1
		1 1/2 lbs. nails			3
		4 dowel pins			4
April	18	1 man 1 hr. fix W.C. jambs			5
	20	1 man 1 hr. do.			5
	22	1 man 3/4 day about W.C.s		2	9
	23	1 man 1 day do.		3	8
	24	1 man 8 1/2 hrs. do. gates & posts		3	4 1/2
		1 spike & 4 dowels			5
		repair hooks & twist, 6 nails & 2 staples			8
		2 Norfolk latches. complete		1	2
		2 pair 14" Tee Hinges & screws		1	6
		2 " 10" do. do.		1	0
		12, 2, & 2, 1 1/2" screws			2
		14-0 of 1x18 elm	3 3/4	4	4 1/2
		6-6 of 3x2 beavers			6 1/2
		20 galvanised screws & washers			8
		1 oak post 6-0 long 4 1/2 x 4 1/2	6 1/2	3	3
		3 1/2 lbs. paint			19
		5-9 of 3 x 1/2 stops for W.C doors			3

forward

£ 217 6

1901

	£	s	d
brok. forward	2	17	6
15.0 of 1x7 pales for gate	15	0	0
8.0 of 3x2 rails	8	0	0
4.0 of 3x1 1/4 brace	4	0	0
nails			1
2. 3 1/2 x 3/8 bolts			2
June 8 new leather to pump spindle			11 1/2
	3	1	2 1/2

Paid. July 5th 1901.

Mr James Barwell

July 4th 1901

£ s d

1901		40 Great Hampton Street Birmingham				
June	27 th	1 -	3.6	Bell Wheel	1	2 0
June	18	1 -	5.1	"	1	3 3
		1 -	5.2		1	3 6
		1 -	5.4		1	4 0
		1 -	5.6		1	4 6
		1 -	5.8		1	5 0
		1 -	5.10		1	6 0

 8 8 3

 August 20th 1901 Received cheque for £8.8.3

July	4	2 -	2.6	Bell Wheels	1	17 0
July	15	1 -	5.2	Bell Wheel	1	3 6
		1 -	5.4		1	4 0
		1 -	5.6		1	4 6
		1 -	5.8		1	5 0
		1 -	5.10		1	6 0
		1 -	6.2		1	8 0

 4 11 0

July	30 th	1 -	4.10	Bell Wheel	1	2 6
		1 -	4.11	"	1	2 9
		1 -	5.0	"	1	3 0

August	5 th	1 -	2.9	Bell Wheel	1	0 0
--------	-----------------	-----	-----	------------	---	-----

 £ 13 16 3

 November 1st 1901 Received cheque for £13.16.3

JW - James Barwell

1907

Oct ^r	11 th	1-	2.6	Belt Wheel	186
Oct ^r	23 rd	3-	2.6	Belt Wheels	2 15 6
Nov ^r	27th	1-	5.0	Belt Wheel	1 3 0
		1-	5.1	"	1 3 3
		1-	5.2	"	1 3 6
		1-	5.3	"	1 3 9
		1-	5.4	"	1 4 0
		1-	5.5	"	1 4 3
		1-	5.7	"	1 4 9
		1-	5.9	"	1 5 6
					<hr/> £ 13 6 0

Paid, by Cheque
February 13th 1902

W Edmonds Esq
 Wiscombe Park. Golyon

1901

			s	d
June	10	1 Bell Rope	7	6
		1 Pulley in Oak Case	3	0
		1 Thimble		6
		Carriage		6
			<hr/>	
			11	6

Paid June 15th 1901

The Vicar & Churchwardens and Bell Committee of
St Mary Magdalene Church. Lancaster

1901	June 26 th	For providing 2 new Bells a 1 st and 2 nd to complete the octave, according to estimate of January 9 th 1901 -	£	0	4
		For taking out the old fittings and frame of the old 6 Bells, from the Tower, and providing and fixing a new English oak frame for 8 Bells, and hanging the 8 Bells with all new fittings complete according to estimate of January 9 th 1901		44	14 0
					153 18 0
			£	231	12 0

(Bell Ropes deducted — £ 4 16 0 and
 take out separate to the Churchwardens.
 Received the £ 4 16 0 for Ropes on July 12 1901)

Received on account — £ 160 0 0
 by Cheque on July 10th 1901

Received on account September 26th
 1901 — by Cheque the sum of £ 50 0 0

Received the balance February 3rd
 1902 — of — £ 16 16 0

H. B. Arnoldy Trench Coys

£ s d

1901				
April	10	account rendered		50 6 10
April	12	489 ft. of 7 x 3/4 board	1 1/2 per ft.	2 5 10
				<hr/>
				52 12 8
				<hr/>
October 7 th 1901 Received on account by cheque			£	26 12 0
December 27 th 1901 Received the balance by cheque			£	26 0 0

Mrs. Ash

~~July~~
1907

July

+ For making a Coffin for the
late Mr. W. Ash

£ c d

2 0 0

Paid. July 9. 1907.

July 3. 1907

1907. Rev. Canon Townend, Lasant, Launceston £ s d

June	20	1 man 2 hrs. at Lasant			1	3
	26	3 men 1 hr. each			1	0 8
		4 bolts for hanging Treble			4	0
		4 leathers for clappers 1. 3. 4. 5.			2	0
		6 galv. rings in blocks for ropes			6	0
		Rony & trap			4	3
		elm for stock				4
		For rechanging the treble bell, screwing up frame fittings, new leathering 4 of the clappers, six galvanised rings for ropes and trap hive				
					£	1 15 6

Paid, July 12th 1907.
by Cheque.

July 11. 1901
Jan. 7. 1902

1907 Mr. W. Stooke, Bridge Farm, Woodbury Satterton.

			£	s	d
Mar.	12	1 man 1 day		3	8
	13	1 man 1 day		3	8

Paid, January 8th 1902.

74

13/7/01

Mr. H. Ware Tanager

p a

1901.

Feb.	11	1 man $\frac{3}{4}$ day	fit machine		29
	12	1 man 1 day	"		38
	13	1 man 1 day	"		38
	14	1 man 1 day	"		38
	15	1 man 1 day	"		38
	16	1 man 1 day	"		38
		4" x 8" x 3" deal		6	23
		10" x 2" x 3"			10
		13" x 6" x 4" x 3"		3 $\frac{1}{2}$	38
		16" x 6" x 4 $\frac{1}{2}$ x 3"		3 $\frac{1}{2}$	410
		6" x 0" x 9 x 1"		2 $\frac{3}{4}$	14 $\frac{1}{2}$
		21" x 0" x 7 x 1"		1 $\frac{1}{2}$	27 $\frac{1}{2}$
		6" x 6" x 1 x 5 $\frac{1}{2}$ oak		1 $\frac{3}{4}$	11 $\frac{1}{2}$
		3 iron dowels + 4 spikes			12
		repair plate for guide			4
		4, 2 x $\frac{3}{8}$ coach screws			3
April	4	1 man $\frac{3}{4}$ day	casing belt		29
		1 man 8 hrs.	make skylight		34
	6	1 man 4 hrs.	do.		18
	9	1 man 1 $\frac{1}{2}$ hrs.	paint do.		7 $\frac{1}{2}$
		12" x 6" x 7 x 1"		1 $\frac{1}{4}$	13 $\frac{1}{2}$
		4" x 6" x 4 $\frac{1}{2}$ x 1 $\frac{3}{4}$		3	11 $\frac{1}{2}$
		2" x 6" x 4 $\frac{1}{2}$ x 1"		1 $\frac{1}{4}$	3
		5" x 9" x 1 $\frac{1}{2}$ x 1 $\frac{1}{2}$			2
		1 $\frac{1}{2}$ lb. putty			2 $\frac{1}{2}$
		1 lb. priming			6
		2 panes H.R. glass	3" x 4" x 12 $\frac{1}{2}$ "		210
	9	1 man 1 day	two house		38
	10	1 man 1 day	"		38
	11	1 man 1 day	"		38
	12	1 man 1 day 2 hrs.	"		46
	13	1 man 1 day 3 hrs.	"		411
		forward		1	3 14 6 $\frac{1}{2}$

1901.			£	s	d
		brok. wood.	3	14	6½
		2 pieces oak 9' 0" long 8" girth sawing		19	6
		10 9' 0" of 2x2 deal		9	1
ap.	17	1 man 1 day fix skylight		3	8
		4 pieces of 4lb. lead		6	9
		1lb. nails, 1lb. paint		..	8
		4 iron dowels		..	6
May	2	1 man 1 day fix machine, making		3	8
	3	1 man 1 day gate etc		3	8
	4	1 man 1 day ..		3	8
	6	1 man 1 day ..		3	8
	7	1 man 1 day ..		3	8
	8	1 man 1 day ..		3	8
	9	1 man 1 day ..		3	8
	10	1 man 1 day ..		3	8
	11	1 man 1 day ..		3	8
		75.6 of 6x3 deal	14	5	10
		11.6 of 4x2 .. X X	17	1	2½
		4.0 of 4x3 gate	3	1	1
		4.0 of 3x2¼ ..	1	..	6
		8.0 of 3x2 ..	1	..	8
		4.0 of 2½x1¼	4
		4.0 of 11x1 ..	3	1	0
		4.0 of 9x1 ..	2	..	11
		1lb. nails, 1lb. paint, 7 screws (2")	10
		10.6 of 9x3 deal	6	5	8½
	15	1 man ½ day		1	10
	16	1 man 1 day		3	8
	17	1 man 1 day		3	8
		12.0 of 4x2	1	1	8
		40.0 of 3x3	2	6	8
		1 doz. 2" screws	2
		Paid by Cheque	£	9	3 0½
		July 13. 1901.			

July 11, 1901

Mrs. Jane Glanville, Brewery

£ s d

1901

Mar.	20	1 man 4 hrs. repair bottom of mesh tub		1	8
	21	1 man 3 hrs. do. put in glass		1	3
		5.0 of 9x1 tub	2 3/4	1	2
		4.6 of 3x2 "	1		4 1/2
		nails ?			1
		1 pane glass 10x14 1/2 + putty			5
April	22	1 man 3/4 day repair roof at Sellicks		2	9
	23	1 man 1 day do.		3	8
	24	1 man 1 day do. jamb to windows		3	8
	25	1 man 1 day do. White Hart W.C.		3	8
	27	1 man 1 day repair W.C. White Hart		3	8
		1 twist, 8 nails, 1 staple			10
		86.0 of 3x2 rafters	1	7	2
		15.0 of 3x4 1/2 plate	3 1/2		41
		175.0 of 2x1 battens	2 1/4		53
		27.6 of 1x7 match } door	1 1/2		35
		8.0 of 1x9 ledges }	2 3/4		110
		7.6 of 4x2 frame	1 1/4		11
		5.6 of 2x3/4 stops			3 1/2
		2.0 of 7x1 1/2	1 1/4		3 1/2
		6.6 of 1/2 x 1 1/2 stop			2
		2 panes glass 11x9 } casement			6
		putty "			1
		5 lbs. nails			10
		22.0 of 4 1/2 x 3 White Hart W.C.	3 1/2		5 11 1/2
		20.0 of 7x1 floor "	1 1/4		21
		4.0 of 2 1/2 x 1 elm "	2 1/2		16 1/2
		4.0 of 1 9/16 x 1 "			14
		2 lbs. nails "			4
	29	1 man 1 day White Hart			38
	30	1 man 6 hrs. do.			26
		repair hooks twist, 1 square staple forward			6
			1 1/2	3	6 3

1901

£ p d

	brot. forward		3	6	3
	14.0 of 3 x 3 jambs	2 1/2		2	11
	3.3 of 3 x 2 1/2 oak	2 1/4		..	7 1/2
	4.0 of 7 x 1	1/4		..	5
	5.0 of 7 x 3/4	1		..	5
	2 1/2 lbs. paint			1	3
May 30	1 man 1 day paper bedroom			3	8
31	1 man 1 day paint bedroom			3	8
	3 lbs. paint			1	6
	1/2 lb. pine			..	4
	6. 1 1/2 screws			..	1 1/2
	4.6 of 2 x 1/2 deal			..	3
	2.6 of 3 x 1	2
			£	4	1 07

Paid August 30th 1901

97

12/7/01

Mr. Robert Channon.

Butcher

£ s d

1907.

Feb.	14	1 pin & key for cope of draft.	..	3
Mar.	9	2 shoes	1	2
	26	new ring to pry the	..	6
	28	2 shoes	1	2
April	15	2 shoes	1	2
	19	2 hrs. make ^{two} drop whippletrees 6" q of 3 x 2 1/2"	..	11 1/2
		6 staples, 2 S for whippletrees	2 1/4	1 3 1/2
	26	1 staple for harness	..	2
May	2	1 plough share, 2 new shoes	1	9 1/2
	6	2 shoes	1	2
	15	sharp crescent paw	1	9
June	1	2 shoes	1	2
	15	2 shoes	1	2
	17	2 shoes	1	2
	20	2 shoes	1	2
	25	new leather sucker of pump, new leather to spindle & wire around sucker	..	20

carried to page 183.

£ . 18 6 1/2

Paid

22/7/01

Mr. John Hurrell, Butcher.

1901

£ p d

	ap. rendered			4	1
Feb. 25	1 plough share			7	½
April 19	1 K. 3 share			7	½
June 21	2 shoes			1	2
				<hr/>	
				6	6

Settled by Contra account
July 22 1901.

July 11, 1901

H. W. Fournival, Esqr. South Croft.

1901

£ s d

Jan.	15	1 man 3 1/2 hrs. make barge & capping		1	5 1/2
	17	1 man 3 1/2 hrs. repair roof & fit capping		1	5 1/2
		13.6 of 7x1 barge	1 1/2		15
		13.6 of 7x 3/4 cap.	1		11 1/2
		16.0 of 2x1 batten			6 1/2
		1 1/2 lbs. nails			3
		2 lbs. paint			10
May	22	1 man 3 1/2 hrs. painting windows & extra		1	6
	23	1 man 1 hr. easing doors			5
	"	2 men 4 hrs. ea. painting extra		3	6
		4 lbs. paint		2	0
		1/2 lb. putty			1
	25	1 man 6 1/2 hrs. painting extra		3	0
		For painting done at Stables as per contract-		1	80
				£	259

extra painting yard
for 2 windows & door
10/6

Paid July 18th 1901

1900 Mrs. West, Greenfield, Woodbury, £ 0 0

Dec. 24 1 man 1 1/2 hrs. repair floor Mrs. Glanville }
 16 of 7x1 } 10

1901
 Mar 25 1 man 3 hrs. making skirting 1 2 1/2
 26 1 man 7 1/2 hrs. fix skirting 2 11 1/2
 27 1 man 5 hrs. fix cupboard frame 2 0
 .. 2 men 3 hrs. ea. removing furniture 2 4 1/2
 .. making two flue scrapes .. 6
 28 1 man 7 1/2 hrs. papering 2 11 1/2
 29 1 man 1 day do. 3 8
 30 1 man 1 day do. 3 8
 36.0 of 6x3/4 skirting 1 2 11
 3.0 of 3/4x3 cupboard .. 2
 4.6 of 1x4 " 1 .. 4 1/2
 1.9 of 1x10 .. 2 1/4 .. 5
 1 pair of 8" Tee Hinges, 14. 3/4 screws .. 6
 1 button, 1 knob. stain .. 4
 2 lbs. nails .. 4
 1 1/2 lbs. paint .. 9
 putty " .. 1
 1 1/2 buckets paste .. 9
 14 pieces paper at 4 1/2 p.p 5 3

x
 May 3 1 man 6 1/2 hrs. painting Mrs. Glanville 2 7
 4 1 man 4 1/2 hrs. do. 1 9 1/2
 7 1 man 4 1/2 hrs. do. 1 9 1/2
 9 1 man 3 hrs. do. 1 2 1/2
 2 1/2 lbs. paint 1 3
 piece of sheet iron for stove 1 0

x
 Sep. 12 1 man 4 hrs. repair floor 1 7
 10.0 of 7x1 1 1/2 1 3
 3.0 of 3x2 1 .. 3
 1 1/2 lbs. nails .. 3

£ 2 5 0

Paid August 16th 1901

July 11 1901

Mr. Alfred Stokes, Woodbury.

£ s d

1900

Oct.	27	2' 0" of 2" lead pipe 7 ¹ / ₂ lbs.	1	2	
Nov.	23	2 quarts Linseed Oil	1	10	
Mar.	25	New frame reasement complete	17	0	
April	3	fitting 2 keys & washers to carriage wheels	1	3	
May	6	4 removes		10	
	16	1 shoe		6	
	22	1 shoe		6	
	28	2 shoes		10	
June	26	4 shoes		20	

 £ 163

 Paid August 19th 1901
 #8.

1901 Mr. C. Fulford, The Warren, Woodbury, Salterton

Mar 20 2 new shoes & fasten 2

1 4

Aug 12 2 removes

.. 8

Paid August 12th 1901

£ . 20

July 10. 1901

Mr. John Godfrey

1901.

£ s d

		£	s	d
July 3	Shifting springs, putting in a new spring, and altering scroll iron of trap		7	9

Paid July 10th 1901

Rev. A. V. Cop. Stockland, Honiton.

1901.

		£	s	d
Mar. 22	Main time, railway fares + trap	"	"	"
+ 23	hire going to Stockland repairing the 2 nd Bell	"	"	"
		1	2	6

Paid February 5th - 1902

July 1901
January 29th - 1902
October 10th - 1902

Rev. J. A. Kempe. St. Verryan.

1901

£ s d

April 2 nd	Time, railway fares and trap hire	"	"	"
4 th	going to St. Verryan screwing up the bells	"	"	"
		2	2	6

Paid November 24th 1902

July 11. 1901

1907. Rev. E. Plenderleath, Mamhead Rectory, Exeter.

April 29 1 piece of chime tubing + postage

1 0

Paid by P.O on
July 15. 1901

July 11, 1901

C. Pearson, bag. Whitestone Rectory.

1901

£ s d

April 2 nd	For putting a new stock to the			
& 3 rd	Treble Bell in Whitestone Tower			
	and a new stay to the tenor, men's			
	time & railway fares	£	1	5 3

Paid by Cheque, July 13, 1901.

Rev. G. T. Lewellin, Sandford.

1901

				£	s	d
Apr.	12	2 new bearing covers			5	0
..	16	1 chime ball			2	0
			£		7	0

£

70

Mr. Matthias Hearn. Woodbury.

1901

£ s d

Jan.	24	2 hrs. ring wheels (carriage)			9 $\frac{1}{2}$
	25	1 man 1 day do.			3 8
	26	1 man 3 $\frac{1}{2}$ hrs. do.			1 5
		5 new ash feloes in small wheel			2 6
		1 spoke + 2 feloes in large do.			1 4 $\frac{1}{2}$
		4 new tyres 60 lbs. @ 3 $\frac{1}{4}$	+	18	9
		1 lb. black paint			" 6
		1 lb. blue red.			" 6

 £ 19 6

Paid - August 2nd 1901

Mr. George Goss. Baker, Woodbury

1901

£ s d

To account rendered

17 1

Apr. 9 2 shoes

12

29 2 shoes

12

May 11 1 shoe

7

31 1 shoe

7

June 22 1 shoe

7

25 1 shoe

7

£ 1 19

Paid Jan. 23. 1902

12/7/01

1901 Mr. James George.

£ s d

May	16	4 shoes			20
June	3	steel brick hammer			.. 6
	4	sharpen twobill			.. 2

 £ 28
Paid July 30th 1901

1901 Mrs. Livermore

£ s d

Mar. 19	putting in pane of glass	..	6
30	2 men 2 $\frac{1}{2}$ hrs. ea. shifting furniture	2	0
Apr. 1	1 man 1 day papering	3	8
2	1 man 7 $\frac{1}{2}$ hrs. fixing handrail	2	11 $\frac{1}{2}$
	7'-0" of 1 $\frac{1}{2}$ " x 1 $\frac{1}{2}$ " deal	3	
	26 screws, 1 doz. nails	..	3 $\frac{1}{2}$
	1 pulley rack	..	6
	paste	..	6
	4 yards blind cord	..	4 $\frac{1}{2}$
	1 holdfast	..	3
May 18	1 man 1 hr. fix hat pegs	..	5
	3'-0" of 3 x 3/4 rail 8 screws & nails 2 ^d	..	4 $\frac{1}{2}$
18	1 man 6 $\frac{1}{2}$ hrs. painting	2	9
	6 lbs. paint	3	0
25	2 hr. repair table, 14, 3/4 screws	}	.. 6
	3'-0" of 2 x 2		
June 3	repair pump sucker	..	7
"	new gutta perch for spindle	..	5

£ 19 4

Paid July 24th 1901

177/51
28/62

Miss Kerlake, Woodbury Salterton

1901

£ s d

April 23

1 deal table, with turned varnished
legs

190

Paid ~~July~~ January 29th 1902

1901 Mr. Charles Summerfield.

£ s d

July 13 1 deal table, with drawers &
 turned varnished legs
 " 1 wash stand
 4 putting in glass

.. .
 1 0 0
 3 0
 1 0

£ 1 4 0

Paid July 26. 1901 ~~25~~

Lady Elliot Drake, Nutwell

£ s d

1901

Jan. 7 Repairing 1 handbell

30

Paid July 31st 1901

Rev. P. H. Owen
Crewys Marchant Rectory

1907	July 19	For providing and fixing the Ellacombe chiming apparatus to the 6 Bells in Crewys Marchant Church Tower according to estimate of June - May 30 th 1907	£ 0 0
			" " "
			" " "
			9 19 6

Paid September 3rd 1907

Mrs. Vowden

£ p d

1901

July 22

For making a Coffin for the
late Mr. Vowden

2 2 0

Paid. July 29. 1901

July 29th 1907

W. J. W. Power

Churchwarden, St. Stephens, Grandpound Rd.

1907

July 25 For 6 Bell Ropes each 40 feet long
at 11⁰/₄ per rope

3 10 6

Paid August 9th 1907

August 1st 1901

W. W. Brook

1901	July 24 th	For a new sign board and lettering	0 d
"	"	same	756
			<u>160</u>

Paid, August 12th 1901

Mr Henry H Adams
North Down, Merchant

1901

August 1st For a set of 6 Bell Ropes, each 60 ft long
for the 6 Bells in Romaneligh Church

£ 0 2

" " "
3 9 0

Received by Cheque
August 10th 1901

W^c Jenkins.
Woodbury

£ 0 d

1907

August-

For putting on a new roof covered with
corrugated iron, as per Contract

" " "
4 4 0

Paid August 30th - 1907

x

June 6th 1902
Jan^{ry} 5th 1903

Mr. J. C. Palmer
Church warden East Budleigh

1907

August 30th For 6 Bell Ropes each 40 feet long
at 11^s 6^d per rope

£ s d
3 9 0

Paid April 9th 1903

The Vicar & Churchwardens of Broadclyst

Jan. 6. 1902
June 6th 1902

1902

Dec- 13th Gen repairs &c to the Broadclyst - 6 old

& 14 Bills

Mens time. 31 $\frac{1}{2}$ hrs at $\frac{1}{4}$ ^d

19 8

Trap to station twice

2 0

Railway fares

5 3

10 - 4 x $\frac{1}{2}$ coach screws

1 8

6 - 3 x $\frac{1}{2}$ do

9

2 - 8 x $\frac{1}{2}$ spikes

4

Zinc & hoop iron

4

1 10 0

Paid June 13th 1902

The Churchwardens of Southmolton

1907

July	9 th	For taking out broken gudgeon from	£	0	d
	12 th	Turn Bell, and putting in new one			
		2 Mens time & railway fares, 2 journeys to Southmolton			
		New Gudgeon		4	6
		Trap to Station 3 times		3	0
		Railway fares 17/8 16/8	1	14	4
		Mens time 50 hrs at 4 ^d / ₂	1	11	3
			<hr/>		
			3	16	1

Paid June 16th 1902

Sept-20th 1907

Rev. Proctor T Pulman, South Petherton

1907		
August 30	For taking down the cracked Bell from	£ 0 2
"	Trewen Church, and recasting her, and	" " "
"	hanging her again, in the Church,	" " "
"	according to estimate of July 9 th 1907	19 15 0

Received by Cheque

September 30th 1907

The Churchwarden of Bickton

1901				0 1
August 30 th	-	For one Bebe Rope 70 ft long		11 6
		ordered by Mr J C Palmer		

Paid March 24th 1902

Ellis, Son & Bowden

Bedford Chambers, Exeter

1907

August 28th - 1 sheeps belt

26

Paid by Postal Order

Sept 12th 1907

~~Rev. W W Arthur~~
 Atherington Vicarage

1901
 account rendered -
~~Sept. 2~~ ~~For 3 Bell Ropes each 70 ft long~~
~~Oct. 15th~~ ~~For 3 Bell Ropes do do~~

Mr. John Godfrey

1901
 Dec. 2 For putting on two new tyres
 on Trap Wheels

£ 0 0

17 0

Paid by Cash Dec. 16. 1901

Mrs Brent Spencer

Sept-20th 1907

1907				
August	27	For altering and fitting up 2 closets at	£	0 1
"	"	Miss Martins, Sydney Cottage	"	"
"	"	1 man 1 day	3	8
		2-6 of 4 x 3		7
		3-0 of 4 x 3 Oak } repair jambs		10 ¹ / ₂
Sept	2 nd	1 man 1 day	3	8
	3	1 man 1 day	3	8
	4	1 man 1 day	3	8
	5	1 man 1 day	3	8
	7 th	1 man 2 ¹ / ₂ hours		1 0
		16-0 of 3 x 2	1	1 4
		17-0 of 11 x 1	3	4 3
		3-9 of 9 x 1	2 ¹ / ₂	10 ¹ / ₂
		2 pair 8" Things & 30 screws		1 1
		4 black knobs and 2 iron buttons & screws		4 ¹ / ₂
		16 - 2" 6-1 ¹ / ₂ - 10-3/4 screws		5
		2 ¹ / ₂ lbs nails		5
		2-7 x 1-6 - 1-9 x 1-4 ^{4" - 4" in 6" post.} perforated zinc 100- ¹ / ₂ clats		2 4
		4 dowel pins		2
		3 ¹ / ₂ lbs paint		1 9
		6-6 of 11 x 1	3	1 7 ¹ / ₂
		8-0 of 9 x 3/4	2	1 4
		2-0 of 1 ¹ / ₂ x 1 ¹ / ₂		1 ¹ / ₂
		nails		1 ¹ / ₂
		2 sanitary buckets		8 0
			£	25 0

This account carried back to page 124

Recd H J Harkness

Sept 21	For lowering down the 5 Bells in St-Michaels Church Tower, Houston, taking out the old fittings and frame, and providing ^{making} and fixing a new Oak frame for same and hanging the Bells with all new fittings complete according to estimate of March 19 th 1901	102 18 0
	For providing, making and fixing in the Tower, framework to take 2 extra Bells according to estimate of September March 26 th 1901	14 12 0
	For taking out the old floor and beams from the Tower, and providing and fixing in the Tower 5 Oak Beams 14x12 and 14x10 , and providing and laying a floor 2 $\frac{1}{2}$ thick on same	34 14 0
		<hr/> £ 153 2 0 <hr/>

Settled October 28th 1901

Oct-21st-1907Rec^d of a Brine

Beechgrove, Hamilton

1907
September

For providing and hanging a Tumble Bell
to make the peal b. in St. Michaels Church
Tower Hamilton, according to estimates
of March 8th and March 21st 1901
Inscription of 37 letters put on Bell at 3¹/₂ letters

£ 0 d

" " "

" " "

42 10 0

10 9

 £ 43 0 9

Received by Cheque and 9 Postage stamps
November 7th 1907

Red Guard of Fund

1907

£ 0 1

Sept- 14

For 2 Bell Ropes each 60 ft long
at 10⁰/₂ per rope
Carriage by Parcel Post

1 1 0
11

1 1 11

Paid October 12th 1907

Oct. 2. 1901

C. E. Pitman Esq. Pinhoe Exeter

1901			£	s	d
Sept.	23	For fixing the Illacombe			
July	24	chiming apparatus to the six			
		bells in Pinhoe Parish Church			
		as per estimate of July 11. 1901.	8	17	6

Settled October 3rd 1901

1901 Mrs. John Gooding Woodbury £ s d

Oct. 8	For making a Coffin for her husband the late Mr. John Gooding	2	20	
	Vicar, Sexton's and Clerks fees		80	
		£	2	10 0

Paid October 21st 1907

Feb 8th 1902

Mr. W. Summerfield for work done at Mr. Sam Lindsey
at Woodbury Salterton.

1901				
April	1	1 man 7 1/2 hrs. put in glass		2 11 1/2
	2	1 man 1 day do.		3 8
	3	1 man 1/2 day make pump trough		1 10
	4	1 man 8 hrs. " gate		3 4 1/2
	6	1 man 2 1/2 hrs. " through		1 0
		new pass to gate twists		" 4
		new latch & guide for gate		" 9
		12 1/2 sq. ft. of glass	4	4 2
		4 1/2 lbs. putty		" 7
		1 lb. paint		" 6
		14-3 of 1x7 floor gate post	1 1/2	1 6
		16-6 of 2x3 " "	1	1 1/2
		4-9 of 3x4 " "	3	1 1
		5-0 of 3x1 " "		" 3
		2 lbs. nails	2	" 4
		1 1/2 lbs. paint	6	" 9
		10-3 of 1 1/2 x 11 trough	3 3/4	3 2 1/2
		7-0 of 1 1/2 x 9 " "	3 1/4	1 10 1/2
		5-6 of 3 x 3 1/2 oak " "	5 1/4	1 6
		2 lbs. nails	2	" 4
		2 lbs. paint	6	1 0
	9	1 man 1 day hang gate		3 8
	"	1 lad 7 1/2 hrs. do.	2 1/2	1 7
		2 plates of iron for gate		1 9
		2, 1 1/2 x 1/4 bolts for gate & door		" 1 1/2
		15, 1/4 x 3/8 "		" 10
		1, 3 x 3/8 "		" 1
		5, 2 screws		" 1 1/2
		5-0 of 2x1 pale		" 2
		1 lb. nails		" 2
	23	1 man 3/4 day repair roof		2 9
		1 lad 3/4 day do.		1 6
		forward	£	24 4 1/2

		£	s	d
	brok. forward		2	4 4½
	9.1.0 of 3x2 rafter X	1		9 9
	8.6 of 4x2 "	1¼		" 10½
	197.0 of 2x1 "	3/-		5 11
	9lbs. nails	2		16
May 13	1 man 7½ hrs. repairing			2 11½
14	1 man 1 day make jambs & frame			3 8
15	1 man 6 hrs. "			2 4½
18	1 man 1 day repairing			3 8
	10.0 of 3x3 for frame	2½		2 1
	2.8 of 1½x9 casements	8½		9
	6 panes glass 8¼x8			1 1½
	4 lbs. nails			" 8
	2.9 of 9x¾ barge	2		" 5½
	2.9 of 7x¾ cap.	1		" 7½
	14.0 of 4x3 for roof	2½		2 11
20	1 man 1 day make door & casements			3 8
29	1 man 6½ hrs. make seat & riser			2 7
30	1 man 1 day repair W.C.			3 8
	1 lad 7½ hrs. painting	2½		17
31	1 man 1 day 2 hrs. repairing			4 5½
	1 lad 1 day 2 hrs. painting			2 5
June 1	1 man 1 day repairing			3 8
	6.6 of 1x7 floor for W.C.	1¼		" 8
	3.3 of 1x20 elm "	2½		12
	3.3 of 1x18½ "	2½		10½
	7.0 of 2x3 deal "	1		" 7
	4.0 of 1x7 mantelboard	1¼		" 5
	2 pairs of 2" butts & screws	1		" 7
	1 hook & eye			" 1
	1 stay			" 4
	2 lbs. putty			" 3
	forward	£	5	8 3

1901

£ s d

		broo. forward.		5	8	3
		27.0 of 3x2 deal	1		2	3
		2 lbs. nails	2		..	4
		11 lbs. paint	6		5	6
		18.0 of 7x1 deal	14		1	10 1/2
		18.0 of 2x1 ..	4		..	7
		4.0 of 2x4 ..	1 1/4		..	5
		2.6 of 4x 1/2	1 1/2
		11 panes glass 6 1/4 sq. ft.	4		2	1
		1 pair 12" Tee Hinges + 16 screws			..	6
		1 Norfolk latch, catch + 16 screws			..	7
		1 pair 2" butts + screw			..	3 1/2
		6.0 of 1 1/2 x 1/2 stop.			..	2
		16.6 of 3x3 jambs	2		2	9
		3.0 of 3x3 oak sill	2 1/2		..	7 1/2
		29.3 of 3/4 match door	1 1/4		3	0 1/2
		6.9 of 5 1/2 x 1 deal ledges	1 1/2		..	10
		1 lb. nails			..	2
June	3	1 man 1 day 2 hrs. repairing			4	5 1/2
	4	1 man. 1 day 2 hrs. .. painting			4	5 1/2
		1 lad 1 day 2 hrs. ..			2	5
	5	1 man 1 day 1 hr. ..			4	5 1/2
		fit new key to lock & repair lock			..	10
		7 lbs. paint			3	6
		1.0 of 1/2 x 7 mantelpiece, 1, 2 1/2" screw			..	1 1/2
Aug.	2	1 man 1 day painting outside			3	8
	3	1 man 1 day do.			3	8
		6 lbs. paint			3	0
		2 lbs. putty			..	3
	7	1 man 1 day 1 1/2 hrs. make & fix barge			4	3
		scapping, repair door & repair pump		
		4.3 of 7x1 door	1 1/4		..	7 1/2
		3.9 of 9x1 barge	2 3/4		..	11
		forward			£	8 7 0

1901

870
£ 0 0

brot. forward

870

14.9 of 7 X 3/4 barge

1

12 1/2

1 button + screw

.. 1 1/2

1 lb. paint

.. 6

nails

1

leather + cloub for sucker

.. 10

1902

Jan. 6 1 man 1 day repair shunting, put
stop block to gate + put on 2 drift-boards

38

3.0 of 1 x 9 deal

.. 7 1/2

oak stop block

.. 8

shute screws, nails, paint + putty

.. 4

10 new elm curb for well

66

27 cutting pipe + repair bolts for pump 3 hrs

16

.. 1 man 7 hrs. re leather pump sucker +

29 1/2

make clack sleepers +

28. 1 man 7 hrs. fix do. do.

29 1/2

3.0 of 9 x 4 1/2 oak

20

3.0 of 2 1/2 x 4 1/2 oak

.. 8

new leather clack. new leather to sucker

13

4. 2" countersunk nails.

.. 1

7.0 of 1 5/8 galv. pipe 2 collars

69

£ 9 19 4 1/2

Mr Thomas Pike

Lacock. Clippertonham

1901
Oct 25

For 2 Bell Ropes, each 60 ft long
at 11.6 each carriage paid

" " "
1 3 0

Paid by Cheque
December 12th 1901.

Recd W W Arthur
Abernington

1901					
Sept	12				
March	24 th	Account rendered for 6 Mufflers			19 6
Sept	12	3 Bell Ropes each 40 ft long	at 11/6	1	14 6
Oct	14	3 Bell Ropes each 40 ft long		1	14 6

£ 4 8 6

Paid November 23rd 1901

The Church Governors of Creditor

sent to W. Wofford
Creditor

1907

July

30

For 2 boll Ropes at 11.9 each
carriage paid

1 3 6

Paid February 7th 1903.

Jan. 6 1902

Mr. W. There, Churchwarden Shobrooke
Great Gutton Farm

1902

Sept	4	Self to Shobrooke examine the Church Bells	6	0
Oct	26	2 men overhauling and putting 3 rd and 4 th Bells right	1	0 0
		Trap hire to Shobrooke Church, from Newton St Cyres Station		4 0
			<hr/>	
			1	10 0

Paid January 29th 1902

Lieut Colonel Mackintosh

Churchwarden of Awtiscombe

1901

Sept 27th Overhauling and screwing up the frame
and bells in Awtiscombe Church Tower

s d

10 0

Paid February 8th 1902

Jun. 6. 1902

The Rector & Churchwardens of Hemm

1902

Sept ^r	For overhauling the peal of 6 Bells in	£ 0 0
and	Hemm Church Tower, according to estimate	" " "
October	of June 20 th 1900 & July 4 th 1900	4 0 0
		<hr/>

Paid January 20th 1902

Rev. E. V. Freeman

The Vicarage, Exmouth

190

Sept 26

For repairs to the 4th Bell, drilling

" 27

her through head, and putting new
bolts and stock to her, ^{and new stopper staple in her} and rehauling
her again

2 18 0

Paid March 11th 1902

Jan^y 10th 1902Rec^d of J Munday

The vicarage barnwood

£ s d

1901

1901		£	s	d
Nov ^r	5 th For 6 Bell Ropes each 60 ft long at 11/- each	3	6	0
		<hr/>		

Paid February 28th 1902

Jan. 6. 1902

Row 0 # 6 any

1901

£ s d

Nov. 12 For 2 Bell Ropes each 60 ft long postage 1 2 0

Dec. 12 Tuner tuning bells at Trusham
time expenses 1 11 6

£ 2 13 6

Paid January 24th 1902

Jan. 6. 1902

Rev. R. Lionel Locke

The Rectory Combe Raleigh

1901

October 25 For securing up the Bells and Bell Frame
in Combe Raleigh Church Tower

10 0

Paid March 22nd 1902

Mr J. C. Hamaford
Chulmleigh

1907

Nov:

For overhauling and repairs to the peal
of 6 Bells in Chulmleigh Church Tower
according to estimate of Oct^r 24th 1907
Self examining Bells

£	0	d
"	"	"
6	7	6
		15 0

£ 7 2 6

Paid April 5th 1902

Mrs. Davey, Broadway

£ 0 0

Nov.	11	For making a C coffin for her son Sidney John Davey	1	20
------	----	--	---	----

Paid Nov-18th 1907

12/12/01

1901 Mrs. Scruton, The Hollies, Sunbury on Thames
£ 0 0

Aug

Making flower stand, packing & delivering it to station

60

Paid. December 18th. 1901.

Woodbury School Committee

1901

£ p d

Aug	27	1 man 2½ hrs. repair floor		1	0½
	28	1 man 9½ hrs. "		3	11½
	29	1 man 9½ hrs. "		3	11½
		1 lad 7 hrs. "	2½	1	5½
	30	1 man 9½ hrs. "		3	11½
		1 lad 9½ hrs. "		2	0
	31	1 man 8 hrs. "		3	4
		1 lad 8 hrs. "		1	8
		251.6 of 7x1 floor	1¼	1	6 2½
		68.0 of 6x1 "	1		5 8
		15 lbs nails			2 6
		27.6 of 5½x2 joist	2		4 7
		23.6 of 4x2 "	1¼		2 5½
		16.6 of 3x2 "	1		1 4½
		52.0 of 2x1 on joist			1 7
Sep.	7	clean off varnish picture frame making, hanging & painting a new gate between garden & playground re-hanging the playground gate & putting in glass in the Infants School as per estimate of Aug: 22: 1901.		1	14 6
	9	1 man 1½ hrs. putting up pictures 13			8
	27	1 man 3 hrs. repairing desks		2	1
		1 lad 5 hrs. do.		1	0½
		4. 2 x ¼ bolts ²⁴ + 7. 1½ x ¼ ³² do.			6
		1½ doz. 1. 1¼ x 1½ screws			2½

£ 560

Paid January 25th - 1902

Mr. W. E. Abbott.

1901

£ s d

Nov.	19	1 man 5½ hrs.	make milk pan covers	2 2½
	20	1 man 3 hrs	do.	1 2½
		5" q of 7x1		.. 7½

£	40 ½
	43.

charge for the 6

Paid. January 18. 1902

Mr. Joseph Skinner

1901.

Aug. 8	1 man 2 1/2 hrs. new leather sucker 1 spindle of pump leather		" "	19
Nov. 22	1 man 5 hrs. ease & hang doors & fix mantelpiece	4 3/4	" "	20
23	1 man 1 1/2 hrs. do. do.		" "	7
	1 catch, 1 guide, 2 nails		" "	4
	1 pair 16" Tee Hinges		" "	10
	1 " 12" do.		" "	8
	3 doz. screws		" "	4
	1. 9" stock lock		" "	26

Paid February 14th 1902

90

Mr. Richards White Hart.

Aug 29	1½ hrs. paint-out name	9
"	1½ hrs. hold ladder	6
30	5 hrs. put in name	26
31	1½ hrs. paint-over old one	9
	Paint	6
		<hr/>
	charge	50

Paid February 1st - 1902

1901. Mr. B. Shell.

Globe Hotel.

£ s d

July 17	1 man 2½ hrs. put in glass	10½
	1 pane glass 14 x 11	4
	1 lb. putty	1½
		<hr/>
		16
		<hr/>

Paid February 19th 1902

1901

Mrs. Livermore

H p d

Sep. 16	1 man 5 hrs. repair shop roof	2	1
18	1 man 5½ hrs. put in gutter re plumber soldering gutters	2	3½
	25.6 of 3x2 rafter	2	1½
	100.0 of 2x1 batten	3	0
	11.6 of 1x1 "		2
	3 lbs. nails		6
	1 piece of 4 lb. lead for gutter	14	6
		<u>‡</u>	<u>148</u>

Paid February 6th 1902

ST. Thomas District Council. (Mr. Chand)

1901

Oct. 26 putting in pane of glass & repair-
ing lock of door in Steam
Roller Van

L p a

.. ..

.. ..

19

Paid March 24th 1902

Dec-20th 1907

Rev. J. L. Thorold

The Rectory, Warkleigh, Kent

1907

December 14 th	For providing and hanging 2 new bells in Warkleigh Church Tower, according to estimate of June 11 th 1901	£ 94 12 0
	Providing & fixing Rope Guide for the 5 bells	2 6 0
	Overhauling old bells	16 0
	Tuning old bells	5 0 0
		<hr/>
		102 14 0
		<hr/>
	Weight of the new bells	
	1 st wt or lbs	4 " 1 " 13
	2 nd	5 " 0 " 9
	Total weight	9 " 1 " 22
	allowance off of -	" 2 " 6 at 1/4 per cent
		<hr/>
		3 14 6
		<hr/>
		98 16 6
		<hr/>

Settled December 24th 1907

W^{rs} Hawkins. Exton

£ s d

1907

Decr 15 For making a coffin for her late
Husband, Mr W. J. Hawkins - - -

2 5 0

Paid December 21st - 1907

The Rector & Churchwardens of Montacute.
Somerset

1901

Decr 20 th	For providing and hanging a new Treble Bell in Montacute Church Tower to make the peal 6- according to estimate of August 6 th 1901.	£ 0 d
	Inscription of 31 letters cut on Bell at 4 ^d per letter	" " " " " " 48 4 0 10 4
		<hr/> £ 48 14 4 <hr/>

paid December 27th 1901

Mrs. Jane Stanvill Brewery.

£ s d

1901

June	23	2 men 1 day ea. repair stand under tub spout in sill		7	4
		16' 0" of 5" x 4 1/2" oak	7	9	2
	24	1 man 1 day painting spout in glass W. Hart		3	8
	26	1 man 1 day " " "		3	8
	27	1 man 1 day " " "		3	8
		8 panes glass 11 3/4" x 9 1/4"	2 1/2	1	8
		1 " " 2" 11" x 1.2	4 1/2	1	1
		10 lbs. paint		5	0
		5 lbs. putty		..	7 1/2
July	4	1 man 6 hrs. painting White Hart		2	6
	5	1 man 1 day " "		3	8
	6	1 man 1 day " "		3	8
	11	1 man 1 day " "		3	8
	12	1 man 1 day " "		3	8
	13	1 man 1 day " "		3	8
		24 lbs. paint		12	0
		1 pair 6" H. hinges		4	
		19 screws		..	2
		1 window stay		..	4
		1 pane glass 10 1/2" x 10 1/2"		3	
	15	1 man 1 day painting White Hart		3	8
	16	1 man 1 day repairing & hanging door W. Hart		3	8
	17	1 man 2 hrs. do.		..	10
		3 lbs. paint		1	6
		2 iron squares		..	8
		3-6 of 4 1/2" x 3 oak sill	4	1	2
		1 pair 16" Tee Hinges		1	0
		2 1/2 doz. 1" screws		..	3
		1 Norfolk latch complete & screws		8	
Aug.	29	1 man 5 hrs. boxing pony trap wheels forward	£	4	5 2 1/2
				4	5 2 1/2

1901

£ o d

	brot. forward		4 5 2 1/2
	For putting in 1 felloe + 1 spoke in wheel, cutting & putting on tyres		" " "
	new bottom in cart, collaring wheels and painting & lettering		" " "
	spring cart		2 6 0
Oct. 1	1 man 7 1/2 hrs. repair ventilator, & mesh tub, & put in glass		" "
	2' 6 of 7 x 3/4 deal		3 1 1/2
	1' 0 of 6 x 1 oak		" 2 1/2
	4' 4 x 1' 0 of glass	4	1 85
	1 1/2 lbs. putty		" 2 1/2
	6. 3" screws. 1/2 lb. nails		" 2
7	1 man 4 1/2 hrs. make & fit bottom board in mesh tub		" "
	5' 0 of 7 x 1 deal	1 1/2	1 10 1/2
	2' 0 of 3 x 2 1/2 "		" 3
	nails P		" 1
23	1 man 1 day, repairing at Brewery		3 8
24	1 man 1 day do.		3 8
25	1 man 1 day do.		3 8
26	1 man 1 day do. White Hart		3 8
	12 nails & 1 staple for twist G		" 6 0
	8 1/2 lbs. nails		1 5
	1 doz. galv'd. screws & washers		6
	1 lb. paint		" 6
	69' 0 of 9' feather edge	1 1/8 1 1/8	10 9 1/2
	8' 0 of 4 1/2 x 2 oak	2 1/2	1 10
	4' 6 of 11 x 1 deal	3	1 1 1/2
	£ o d		
	Paid by Cash £ 10' 0		£ 8 10 8.
	February 27 th 1902.		

Mr. Walter Knott, Churchville

1901

Dec. 3	1 man 2 hrs. put in glass	4½
	1 pane 16" x 10½"	4
	1 " 13¾" x 11½"	3
	1 lb. putty	1½
		<hr/>
		16

Paid —

Mr. Thorn, Baker Albion St. Exmouth

1901

£ s d

Dec. 10	1 man 3 hrs. repair manger & yard doors at Mr. Smiths		1	3
	2, 3 x 3/8 bolts, 6, 3/4 washers			5
	4 3 of 13 1/2 x 1/2 elm nails			9
			"	1
27	2 men 5 1/2 hrs. ea. shifting door posts at Mr. R. Smiths			4
				7
		<u>£</u>		7
				1

Paid February 11th 1902

Sir C. K. Pearson. Tedstone, £ p d

1901

Date	Description	£	p	d
July 23	2 hrs. make chopping board } 1.3 of 1 1/2 x 11 ash }			1 3
25	1 man 7 1/2 hrs. make cupboard	*		3 1 1/2
26	1 man 9 hrs. "			3 1 1/2
27	1 man 8 hrs. "			3 4
29	1 man 9 hrs. "			3 9
30	1 man 9 1/2 hrs. fix "			3 1 1/2
31	1 man 9 1/2 hrs. fix "			3 1 1/2
Aug. 1	1 man 9 1/2 hrs. fix "			3 1 1/2
	13.3 of 11 x 1 deal frame	3		3 4
	20.0 of 9 x 1 leaves trails	2 1/2		4 7
	21.0 of 11 x 1/2 panels	2		3 6
	21.3 of 1 x 7 match	1 1/2		2 8
	17.3 of 3/4 x 7 "	1 1/4		1 10
	6.9 of 1 x 7 floor	1 1/4		.8 1/2
	2 pair 2 1/2" butter & 2 doz. screws	4		8
	2 brass turnbuckles			6
	4. 1 1/2" screws, 1 iron button			2
	4 1/2 lbs. paint			2 3
	2 1/2 lbs. nails 5" putty 1"			" 6
	5.6 of 4 x 1/2 deal			4 6
15	1 man 9 1/2 hrs. put up boarding in scullery	*		3 1 1/2
16	1 man 9 1/2 hrs. paper cupboard & fix shelves			3 1 1/2
17	1 man 8 hrs. do do			3 4
	39.6 of 3/4 match for scullery	1 1/4		4 1 1/2
	10.0 of 2 x 1 "			" 4 1/2
	5.0 of 2 x 1/2 "			" 2
	1 lb. nails			" 2
	35.9 of 3 x 1/2 for shelves	3/4		2 3
	3.2 of 9 x 3/4	2		" 6 1/2
	2.0 of 4 x 3 1/2 deal for coved jambs	4		" 8
	5.0 of 4 1/2 x 3 1/2 oak pill do.	5		2 1
	forward			3 11 10 1/2

Charged 9.0

1901.

£ s d

brot. forward
 2 iron squares 1-0 + 3 iron plays 2-
 18. 1 1/2 screws, 2 small esutcheons
 2 pieces of paper
 4 sash cords

3 11 10 1/2
 2 0 4

Aug 19 1 man 7 hrs. make passage door & jambs

2 11

20 1 man 9 1/2 hrs. do.

3 11 1/2

21 1 man 6 hrs. do.

2 6

23 1 man 4 1/2 hrs. fix do

1 10

22 1 man 9 1/2 hrs. fix

3 11 1/2

17-9 of 9 x 1 1/2 - 2.3 mce

3 1/2

10-0 of 11 x 1 1/2

2

18-0 of 3" arch. mould.

5 9

1 pair 3" butts, 1 doz. 1 screws

1 8

1. 6" rim lock

1 6

2 1/2 lb. paint

5

23 1 man 5 1/2 hrs. repair jambs & put sill to cowed door

2 3 1/2

Oct. 23 sharpen saw

6

25 do. & 2 chopper

10

Nov. 13 sharpen pruning saw

3

15 1 man 11 1/2 hrs. make garden frame *

4 9 1/2

16 1 man 2 hrs. do

10

15-6 of 11 x 1 1/2

4 1/4

7-9 of 3 x 1 1/2

"

2-6 of 9 x 1 1/2 } 5-0

3 1/2

6-6 of 7 x 1

1 1/2

nails 1. 1 lb. priming

8 4

21 1 man 7 hrs. paint frame & light

2 11 1/2

22 3 1/2 lbs. white

1 2 1/2

18 1 man 9 hrs. put in sash & blind cords *

1 8

20-0 of sash cord, 2 clouts

3 9

1 lb. black paint

1 2

forward

£ 6 14 2

charge £ 11. 11. 1/2 for door & jambs
 Architecture mould & Lock