

Mr. Wm. Summerfield

1900

		£	s	d
	brok. forward	4	12	0
	To Balance due on acc. rendered	41	16	4
July	4 2 shoes		1	0
	9 1 man 6 hrs. making water troughs		2	4 1/2
	" 1 man 7 hrs. do		2	9 1/2
	6 lbs. of 4 pat. nails		1	0
	18 13.0 of 7/8 galv. hoop iron	1		1 1
	30 1 man 5 1/2 hrs. put in cart shaft		2	2 1/2
	sharp long staple & repair bolts			4
	cut & shoot tyre		2	6
	31 1 man 1 day 3 hrs. put in shaft & repair cart		4	5 1/2
Aug.	1 1 man 7 hrs. painting cart		2	9 1/2
	1 tail pin & staple			5
	2 1 man 7 hrs. painting cart		2	9 1/2
	3.0 of 5x1 elm			3
	2.0 of 2x1 "			"
	2.6 of 4x1 "			3
	lash shaft		2	6
	putting in name		1	0
	5 lbs. paint	Charge		
		£ 1.2.0		
			2	6
	7 2 shoes		1	0
	" 27.0 of 2x1 batten			10
	11 18.0 of 2x1 "			7
	14.0 of 3x3/4 deal			8
	12 2 turning bars		2	0
	18 making 2 turning bars		1	0
	30 2 shoes		1	0
Sept.	5 fit up 2 pulley blocks			8
	10 25.0 of 2x1 batten			9
	24 1, 3x3/8 bolt			1 1/2
Oct.	6 2 shoes		1	0
	17 laying floor at Colaton Raleigh			
	18 as per contract		9	0
	21 2 shoes		1	0
Nov.	4 1 man 5 hrs. fixing shuting at Mr. Northcotes		2	0
	forward	£	49	0 2 1/2

1902

£ o d

forward

49 0 2½

2, 6.0 lengths of 2½" R. W. P.

21

4 2

1, 4.0 " " 2½" "

1 8

1, 2½" swan neck

1 1

1, 4" outlet

" 11

1, 2½" shoe

" 10

8 pipe nails, 4 gutter bolts

" 5

1 holdfast

" 3

1 lb. putty

" 1½

9 lbs paint

1 0

20 9.0 of 3x1 stops for mantelpiece  
planed & painted

" 6

22 1 man 3 hrs. make barge and  
capping

1 2½

12.0 of 5x1 barge

1½

1 3

12.0 of 4½x1 capping

1 6

nails &amp; paint

" 4

17 2 shoes

1 0

Dec. 1 2 shoes

1 0

2 sharp hammer

" 2

To putting on new roof on stable,

as at Mr. Wheatons for Mr. Stocker

as per Contract of May 14. 1902

11 12 0

5 1 man 5 hrs. cutting off beams & floor  
joist

2 0

16 1 man 2 hrs. repair old roof

" 9½

18.9 of 4½x3 lintels over door &amp; window

4 11

To making new stable door &amp; jambs, coal

House door &amp; jambs, lpr. door &amp; jambs and

easement &amp; frame glazed fixed and all painted

3 evats paint

3 " "

A new ledged door &amp; jambs for stable

1 3 10

forward

£

63 1 2

62 7 2

1902

Mr. W. Summerfield

£ s d

brot. forward	63	1	2
A new ledged door jambs for Coal House	1	0	6
A new ledged door jambs for Loft-	16	10	
A new frame & easement for stable	15	4	
5 iron rods for stable window			10½

£ 65 14 8½

January 23<sup>rd</sup> 1903 Received on account - £ 15 ==



Jan. 9. 1903

X

1902	Mrs. Jane Glanville	Brewer	£	s	d
Nov.	5	1 man 1 day repair coolers			8 8
	7	1 man 1 day do.			3 8
		24.0 of 7x1 deal	15		3 0
		20. 1" x 1 1/2 screws			.. 2
		3.6 of 1 1/2 x 9 oak	4		1 2
		4.6 of 1 1/2 x 13 1/2 oak	6		2 3
		1.9 of 2 x 6 oak	3 1/2		.. 6 1/2
		3 lbs. nails			.. 6
	10	1 man 1 day repair shed			3 8
	11	1 man 3 hrs. repair shed			1 3
	13	1 man 1 day repair gates trailing			3 8
	14	1 man 2 hrs. do. do.			3 1/8
	15	1 man 1 day 7 1/2 hrs. repair at White Hart brook			3 8
		10 1/2 lbs nails			1 9
		2 1/2 doz. galv. screws + washers	4 1/2		.. 11 1/2
		9.0 of 7 x 1 1/2 deal	2 3/4		2 1
		2 lbs. nails			.. 4
		28.0 of elm stakes			1 2
		81.0 of elm slabs. 1.0 wide			6 9
		3 staples, sharpen 2 hooks			.. "
		8 nails for turf			.. 11
	17	1 man 1 day repairing stable Mr. Hart			3 8
	18	1 man 1 day .. lades re Brewery			3 8
		6.0 of 4 x 3 deal Mr. H.	3		1 6
		2.9 of 1 1/2 x 1 1/2 ..			.. 2 1/2
		3.9 of 7 x 1 match Brewery	1 1/2		.. 5 1/2
		15.0 of 2 x 1/2 ash ..			.. 7 1/2
		1 doz. 2" staples ..			.. 3
		1 lb. of nails ..			.. 2
Dec.	2	1 man 1 day repair windows of Malbroom			3 8
	3	1 man 1 day do.			3 8
		2.3 of 9 x 1 deal	2 3/4		.. 6 1/2
		forward	£	3	3 3

	£	s	d
forward	3	3	3
2.0 of 2x9 deal			3½
2.3 of 1x3 ..			2½
3.0 of 2x2 ..			2½
8½ lbs. putty			11
84 sq. ft. of glass	3½		25
	£	3	7 5½

Paid February 10<sup>th</sup> 1903

Jan. 9. 1903 X

Mr. Robert Channon. Butcher.

1902.

July	14	1 back chain + 2 long staples	1 2
	19	2 shoes	1 2
	28	4 shoes	2 4
		4 links for tog chain, 1 copse bolt for drag shoe fitting	.. .
			1 3
Aug.	8	4 shoes	2 4
	26	setting scythe 1 wedge	.. 5
	28	1 shoe	.. 7
Sep.	2	1 shoe	.. 7
"	16	4 shoes	2 4
Oct.	2	2 shoes	1 2
"	10	4 shoes	2 4
"	30	2 shoes	1 2
Nov.	1	2 shoes	1 2
"	17	2 shoes	1 2
	27	1 shoe	.. 7
Dec.	1	1 shoe	.. 7
	16	4 shoes	2 4
			<hr/>
			£ 140

water  
12"

1905 Mr. Alfred Stokes

£ s d

Mar. 27	1 man 8 hrs. make hang door J. Hollands		3	2
28	1 man 5 1/2 hrs. put on drip board + put in glass		..	..
			2	1/2
Apr. 11	1 man 2 1/2 hrs. fix lock & paint door		1	0
	36-0 of 7x1 match	1 1/2	4	6
	9-0 of 7x1 ledges	1 3/4	1	4
	1 lb. nails		..	2
	4 lbs. paint		2	0
	1 1/2 doz. (1/4" screws		..	3
	3-0 of 1x7 drip board		..	5
	1 Norfolk handle complete		..	7
	3 panes glass 7x12 ea.		..	6
	1 lb. putty		..	1 1/2
	1.6 rim lock staple		2	0
			<hr/>	
			£	18 2

Paid, Oct. 16. 1905



X

1952. Mr. Joseph Skinner

£ s d

July	3	1 man 2½ hrs. help plumber about pump	1	0
	9	1 man 2½ hrs. " " fire pump 1" 0 of 4x2 oak	1	0 3
	11	1 man 1 hr. about pump take ofetch pump from Exmouth	"	5 4 6
July 3rd & 4th		Plumber repairing pump, line, solder, new lead pipe and beam face	1	10 10
Oct.	1	1 man ½ hr. put spring in lock at Mr. Summerfields	"	" 6
		1 lock spring		6
Nov.	28	1 man 7 hrs. repair cottage	2	9 ½
	29	1 man 1 day do.	3	8
		22.6 of 7x¾ floor	1	10 ½
		16.0 of 3x2	1	4
		4.6 of 7x1	"	6 ½
		3 lbs. nails	"	6
		2 iron buttons + screws	"	"
		1 doz. 1" clouts, 8. 1¼" screws		5
		5.6 of 7x½ deal	<del>5</del>	
		3.6 of 5x½ " }	"	5
		2 small catches	"	3
Dec.	1	1 man 1 day repair cottage bladder	3	8
	2	1 man 7½ hrs. do.	2	11 ½
	3	1 man 1 day do.	3	8
	4	1 man 1 day do.	3	8
	6	1 man 4½ hrs. painting do, taking off top of stove & fitting lap top on stove	1	9 ½ 8
		1 new front lap + 1 stop	1	10
		1 blue scrape	"	8
		2 pair 2½" butts + screws	"	3 ½
		1 " 2" " "	"	6
		3.6 of 4½x1½ casement forward	"	6
			£	3 10 6

up to D. 16

1902

£ s d

brot. forward 3 10 6  
 2.3 of 6x2 casement " 5 1/2  
 4 panes glass 9 1/4 x 6 1/2 " 8  
 1 lb. putty " 1 1/2  
 12.0 of 5 1/2 x 3/4 match small door 1 0  
 1.6 of 9x1 ledges " 4 1/2  
 4.0 of 7x1 floor " 5  
 4.0 of 1 1/4 x 1/2 stop " 2  
 1 pair 8" Tee hinges, 14 screws 6 1/2  
 1 button, screw & Knob 2 1/2  
 1 lb. nails " 2  
 3 lbs. paint 1 6  
 12 rounds for ladder 1 6

Dec. 29 1 man 1 day lying floor repairing at Mrs. Harnells " 3 8

30 1 man 1 day do. do. " 3 8

31 1 man 1 day do. do. " 3 8

227.0 of 7x3/4 floor 1 18 11

12.0 of 3x2 deal 1 10

9.6 of 9x3/4 deal 1 7

6 1/2 lbs. of nails 1 1

2.9 of 11x1 deal stair X 4 1/2

9.6 of 7x1 deal floor 1 0

1.0 of 9x1/2 } " 11

6.6 of 6x1/2 } old lead pipe " 9 1/2

3.0 of 12x1 elm " 7 1/2

1 latch & screws, 1 driving catch? 4

1 piece of iron & 2 nails to stay stairs 4

2 iron buttons & screws } 5 1/2

2 iron knobs, 3. 2" screw } 3 8

Jan. 1 1903 1 man 1 day repairing at Mrs. Harnells 3 8

6th 1 man 1 1/2 hr - put on new lock, put in pane glass 4

1 pane glass & putty 3rd 1-8 stock lock 2/0 2 3

allow for old lead pipe 4 1/2 Paid January 21st 1903 £ 6 1 14

## Sir Charles Pearson.

1902

£ s d

July	17	1 man $1\frac{1}{2}$ hrs. measure roof				7 $\frac{1}{2}$
	29	1 man <del>1 hr.</del> <sup>9<math>\frac{1}{2}</math> hrs.</sup> put on roof on gardeners house				3 11 $\frac{1}{2}$
		1 lad 9 $\frac{1}{2}$ hrs. do. do.				2 4 $\frac{1}{2}$
	30	1 man 9 $\frac{1}{2}$ hrs. do. do.				3 11 $\frac{1}{2}$
		1 lad 9 $\frac{1}{2}$ hrs. do. do.				2 4 $\frac{1}{2}$
	31	1 man 9 $\frac{1}{2}$ hrs. do. + repairs in house				3 11 $\frac{1}{2}$
Aug.	1	1 man 9 $\frac{1}{2}$ hrs. erecting arches				3 11 $\frac{1}{2}$
	2	1 man 8 hrs. paint roof + put in glass + fixing blinds				3 4
		11'-0" of 4x3 deal for roof	3 $\frac{1}{4}$			3 0
		240'-0" of 6x $\frac{3}{4}$ match do.	1 $\frac{1}{4}$	1		5 0
		5 $\frac{1}{2}$ lbs. nails "				11
		8 $\frac{1}{2}$ lbs. paint "				4 3
		2 doz. galv'd: screws + washers "	4 $\frac{1}{2}$			10 $\frac{1}{2}$
		1, 8'-0" length of Corrug: Iron "				3 2
		1, 5'-0" length do. "				2 0
		14 yards of felt "	5 $\frac{1}{2}$			6 5
		clouts for felt "				6
		glass 4'-6" x 2'-3" ... 10'-1" "	3 $\frac{1}{2}$			3 0
		3 lbs. putty "				4 $\frac{1}{2}$
	30	1 man 3 hrs. put cord in lips				1 3
		1 sack cord				4
Sep.	15	1 man 9 hrs. making wood brackets				3 9
	16	1 man 9 $\frac{1}{2}$ hrs. fixing shelves				3 11 $\frac{1}{2}$
	18	1 man 5 $\frac{1}{2}$ hrs. do. put in sack cord				2 3 $\frac{1}{2}$
		24'-6" of 7x11 brackets	1 $\frac{1}{2}$			3 1
		168'-0" of 11x1 shelves	3	2		2 0
		34'-0" of 9x $\frac{3}{4}$ "	2			5 8
		12'-0" of 4x $\frac{3}{4}$ "	1			1 0
		2'-0" of 9x1	2 $\frac{3}{4}$			5 $\frac{1}{2}$
		4 $\frac{1}{2}$ lbs nails				9
		forward	£			6 18 6 $\frac{1}{2}$

Water D16

£ s d

		brok. forward	6	18	6½
		1 sack cord			4
	16	Horse cart taking down shelves		1	6
	18	do do.			16
July	30	Mason time, <del>and</del> stopping under roof at Gardeners House, time, + cement mortar			60
			£	7	7 10½

Paid January 12<sup>th</sup> 1903

X

Mr. C. Stamp. Butcher Woodbury

1902.

July	9	1 man 1 hr. put in pane glass } 1 pane glass 15 1/2" x 11			10
Aug.	12	1 man 1 hr. refix blinds 1 brass roller end 1 pulley rack 3. 1 1/2" screws 1 latch 3-0" long			5 3 7 1 3
	16	1 man 7 hrs. make field gate } 1 oak gate 5 bar straighten twist for gate, 2 gate hooks } 1 hapse + 2 staples			130 17 38
Sep.	12	1 man 2 hrs. paint cistern cover			10
	13	1 man 2 hrs. do. do. paint for cover			10 10
	24	1 man 6 hrs. make field gate } 1 Oak 5 bar gate 2 staples			130 2
	26	1 man 1 day hang gate repair roller frame			38
Dec.	30	1 man 4 hrs. putting in glass 1 pane glass 10 3/8 x 13 3/4 1 do. 14 3/4 x 14 1/2 1 do. 15 3/8 x 10 3/4 1 do. 14 1/4 x 8 1/2 1 do. 15 3/4 x 8 3/4 = 5 1/2 sq. 2 lbs. putty			18 10 110 3

\$ 239

Paid January 20<sup>th</sup> 1903

1902

Mr. John Dew

£ o d

	bro. over from 222	1	16	5 <sup>4</sup>
July	11 2 shoes		1	2
	24 2 shoes		1	2
	26 Horse 1 day		3	6
	29 Horse 1 day		3	6
	31 fitting copse + 1 key to drag shoe		..	4
Aug.	7 2 shoes		1	2
	22 1 shoe		..	7
	30 3 shoes		1	9
Sep.	9 Man + Horse haymaking		2	6
Oct.	8 2 shoes		1	2
	9 1 K4 share		..	7
	15 1 new copse, 2 large staples for draft.		..	19
	22 fit handle to fork		..	6
	25 2 shoes		1	2
	30 1 new staple for hames		..	5
	.. lying coulter		1	6
Nov.	20 2 shoes		1	2
Dec.	4 1 old shoe		..	<del>4</del>
Nov.	26 1 1/2 hrs. boxing wheels		..	7
Sept	3 2 squares			9
"	1 man 1 hr. put in oil			5
			£	3 2 3

Paid April 1<sup>st</sup> 1903

Jan 9. 1903 X

1902 Mr. John Bastin.

£ s d

July	9	1 man $\frac{1}{2}$ hr. ring wheel			25
	10	1 man 1 day do.			38
	11	1 man <sup>6 fellows</sup> 5 hrs. ring wheel			20
	12	1 man 1 hr. do.	16..3		24 $\frac{1}{2}$
		one new tyre on trap wheel			80
Aug.	11	1 shoe			6
	21	3 shoes			16
	30	repair lamp iron of waggon 1 bolt			3
	..	putting name in waggon			10
sep.	13	1 man 1 day repair ralter sides of waggon foil wheels			38
		3..6 of 7x1			5
		1..0 of 4x $\frac{3}{4}$			1
		1, $\frac{3}{8}$ x3 bolt Oil & paint			5
		1 doz. screws			1 $\frac{1}{2}$
		2 eyes, 2 hooks, 2 staples ralter steps of waggon			10 $\frac{1}{2}$
Oct.	13	1 man 1 day put up W.C.			38
	14	1 man 1 day do.			38
		2 lbs. nails			4
	31	1 shoe + 1 remove			9
	24	repairing & putting new front part to carriage of waggon, bolts, key & links in chain			40
Nov.	3	6 pair rockers			19
"	17	1 shoe, 1 remove			9

£ 2.00

Paid March 14<sup>th</sup> 1903

1905 Mr. William Daley, Tailor.

			£	s	d
Mar.	2	2 shoes		1	0
	13	2 new stay irons for trap		1	0
	29	2 shoes		1	0
May	25	2 shoes		1	0
June	6	2 shoes		1	0
			£	5	0

Paid July 28<sup>th</sup> 1905



1902. Miss Dagworthy. Woodbury Salterton

Nov.	3	1 man 1 day repair shed	3 8
	4	1 man 1 day " hang grindstone <sup>re</sup>	3 8
	6	1 man 1 day do.	3 8
	7	1 man 1 day make roller frame <sup>re</sup>	3 8
	8	1 man 1 day do.	3 8
		2 braces for grindstone 3 1/2 lbs	1 9
	10	1 man 1 day roller frame	3 8
	11	1 man 1 day do.	3 8
		3 lbs. paint nails 2 <sup>d</sup>	1 8
	20	1 man 3 1/2 hrs. put frame together	1 4 1/2
		1 long bolt, 2 new chain eyes,	" "
		sharp 3 long staples cutting bolts	6 0
		4 new bolts + 1 staple	" 10
Dec.	8	1 man 4 hrs. about pound	1 7
	15	1 man 1 day do.	3 8
	16	1 man 8 hrs. do.	3 2

£ 25 8 1/2

Paid March 24<sup>th</sup> 1903

x  
Mr. G. Kerlake

x  
Woodbury Satterton  
F o d

1902

Aug. 20	1 man 1 day papering	40
21	1 man 1 day 2 hrs. "	4 10

8

10

Paid January 19<sup>th</sup> 1903

Dec. 20<sup>th</sup>  
1902

## The Vicar &amp; Churchwardens, of Bradwellby

1902

Decr	11 <sup>th</sup>	For lowering down the Bells from the Church Tower, and taking out the old fittings, frame floor and beams, fixing new beams and floor, and providing making and fixing an oak frame for 6 bells, and hoisting and hanging the 5 bells, in their places in the new frame, with all new fittings according to estimate of April 14 <sup>th</sup> 1902	£	93	5	0
		For supplying and hanging a new 6 <sup>th</sup> bell according to estimate of April 14 <sup>th</sup> 1902 extra charge for 8 <sup>lbs</sup> of metal for weight of bell over estimate		45	15	0
		weight of new bell <small>est. of lbs</small> 5.1.8 } estimate weight 5.1.0 }				9 0
		Tuning old bells		1	1	0
		Inscription of 70 letters put on new bell at 4 <sup>d</sup> per letter		1	3	4
			£	141	13	4

December 25<sup>th</sup> 1902 Received on account - £100-settled March 13<sup>th</sup> 1903

Messrs. Waver & Sons.

Tanners

1902

£ s d

Oct.	1	1 man 5 $\frac{1}{2}$ hrs. make hatch		2	2
		6.0 of 3 $\frac{1}{2}$ x 3 oak	}	3 $\frac{1}{4}$	1 7 $\frac{1}{2}$
		2.9 of 11 x 1 oak		3 $\frac{1}{4}$	.. 9.
		nails 2 <sup>0</sup>			.. 2 $\frac{1}{2}$
	31	put handles on skin knife		1	3
Nov.	15	making 3 pit stoppers		4	6
	20	1 man 1 day put on roof		3	8
	21	1 man 1 day do.		3	8
		10.0 of 4 x 3 deal	2 $\frac{3}{4}$	2	3 $\frac{1}{2}$
		21.6 of 3 x 3 "	2 $\frac{1}{4}$	4	0 $\frac{1}{2}$
Dec.	17	1 man 1 day make troughs		3	8
	18	1 man 1 day do.		3	8
	19	1 man 1 day do. repairs		3	8
	20	1 man 1 day do. "		3	8
	22	1 man 1 day do. "		3	8
	23	1 man 1 day do. "		3	8
	24	1 man 1 day do. "		3	8
		18.0 of 3 x 2 deal for stand	1 <sup>0</sup>	1	6
		1. 3/4 iron pin do.		1	3
		7 lbs. paint		2	11
				£	2 15 6

Paid by contra account and  
by cash 1.13.4 January 27<sup>th</sup> 1903

Mr. James Glanville. Rydon Farm

1902

£ s d

to account rendered

9 15 8

June 30 repair 3 picks

1 0

sep. 8 1 man 1 day repair trap wheels

3 8

9 1 man 5 1/2 hrs. repair trap, collar wheels

2 2

10 1 man 8 hrs. do. do.

3 2

11 1 man 3 hrs. do. do.

1 2

binding strap wheels

5 0

2 spokes 8". 2 fellows 1/2

1 10

3" 6" of 7x1

5

2 collars, oil & paint

1 4

Oct. 4 new spring for pound

1 3

£ 10 16 8

February 7<sup>th</sup> 1903 Received by Conhaick £ 14 0 0  
 and by Cash 1 0 0  
£ 8 14 0

left due - £ 2 2 8

1902 Mr. Henry Pile, Bagmore Farm.

£ s d

Jan.	7	1 man $2\frac{1}{2}$ hrs. put new collar in trap wheels and altering spring of trap 1 spoke plate + rivets 2 small leather collers $2\frac{3}{4}$	(	1	0	$\frac{1}{2}$
			)	.	9	
				"	5	$\frac{1}{2}$
	9	releathering sucker of manure pump time $1\frac{1}{2}$ hrs. leather clouts		"	"	
				2	0	
Feb.	4	releathering sucker of pump time $1\frac{1}{2}$ hrs. leather $\frac{1}{2}$ lb. 1 doz. clouts		1	9	
Mar.	5	1 man $3\frac{1}{2}$ hrs. repair tail iron of pony trap mending cross stay of trap, 1 plate 6. $1\frac{1}{2}$ screws 1. $3\frac{1}{2} \times 3\frac{3}{8}$ bolt		1	3	
				1	6	
				"	"	
				4		
	14	1 man 1 hr. sorting timber for drafts			5	
	17	2 staples for draft. 1 key in clip 1 plate trails		"	"	
				"	9	
	18	1 man 1 day making drafts new part to draft iron sawing ash 6 ft		3	8	
				1	0	
				4	3	
	25	1 man 1 day put shaft in roller		3	8	
	26	1 man 1 day do.		3	8	
	27	1 man 1 day do. repair roller frames		"	"	
				3	8	
		2 wangs. 1 staple, sharp 2 long staples lengthen 1 bolt and cut 2 bolts for rollers		"	"	
				2	0	
		2 long $\frac{3}{4}$ bolts		6	3	
		1 strap plate, 1 new bolt		"	9	
		cutting bolts, sharp 2 long staples		"	"	
		1 crook		1	0	
		1 doz. countersunk nails				
		3. $4\frac{1}{2} \times 3\frac{3}{8}$ + 1. $5 \times 3\frac{3}{8}$ bolts				11
		2 lbs. lead paint		1	0	
		forward	£	2	2	10

Mr. Henry Pile, (continued)

1902

£ s d

		brok. forward	2	2	1
May	6	1 man 6 hrs. repair trap, leather wheels or repair seat	.	.	.
		2. 4½ x 3/8 bolts 4 <sup>d</sup> leather 1" 0 4"	}	2	6
		1. block for spring, 1 doz. tacks		1	4
		repair cross bar at back of trap			3
		4 lbs. new iron			30
		cut + shoot pony trap wheel tyre			20
	12	1 man 2 hrs. put on 3 spoke plates on large trap			10
		3 spoke plates + rivets			12
Nov.	13	1 man 1 day make windlass + handspike for pound			38
	14	1 man 8 hrs. make pic windlass			32
		2 rings on windlass			28
		1 new gudgeon + 1 bearing fitting same			26
		1 ring + staple			3
		4. 2½, 1, 2 screws 4 counter sunk nails			6
			£	3	5 11

Paid August 1<sup>st</sup> - 1903

X

Major Gordon. Oakhays

1902

		£	s	d
Nov. 12	(1 man 1 1/2 hr. put fire plate in <sup>bedroom</sup> grate) (1 piece cast iron 12 x 11 x 1/2")		2	9
			3	6

Paid June 18<sup>th</sup> 1903



July 27<sup>th</sup> 1903

Mr. George Ross. Baker

1902

July 4	1 man 8 hrs. boxing trap wheels	3 2
5	1 man 1 day do. put <del>up</del> blocks to springs	3 8
	2 rivets + screwing bolts	.. 6
	cutting and shooting two tyres	5 0
	4. 6 <sup>1</sup> / <sub>2</sub> + 3 <sup>3</sup> / <sub>8</sub> bolts for springs	.. 8
7	1 man 4 <sup>1</sup> / <sub>2</sub> hrs. paint trap wheels	.. .
8	1 man 2 hrs. do. } 4 lbs. paint } 2 ash spring blocks }	2 7 2 0 .. 4
26	1 old shoe	.. 4
		<u>£ 18 6</u>

1903

July 13	1 shoe	6
		<u>£ .. 19 0</u>

Paid August 8<sup>th</sup> 1903

Jan. 4. 04.

Sep. 25	1 remove	.. 3
Dec. 5	2 shoes	1 0

1904

Jan. 4. 0.

Sep. 30	1 man 1 day put in 3 spokes in wheel	3 8
Oct. 3	1 man 1 hr. putting on tyre	.. 5
	3 spokes	2 0
	put in pane glass	1 0
Nov. 30		.. 10
Jan. 9	2 shoes	1 0
		<u>£ 10 2</u>

Paid. April 15. 1905.

x

Mr. James George.

1902

£   s   d

Sep. 11	2 shoes				10
Oct. 20	2 shoes				10
Dec. 29	4 removes				10

£   s   d

---

30

Paid January 26<sup>th</sup> 1903.

1902 Mrs. West. Greenfield. Woodbury. £ p d

Nov. 18	Man 7½ hrs. put in gate post & hang gate & repair porch.			2 11½
	1 oak gate post 5'6" 4½x4	5½		2 6
	2 small gate hooks			8
	1 lb. paint			6
	2'9" of 2x9 deal			4½
	10, 1¼" screws.			2
				<hr/>
				£ 72
				<hr/>

Paid June 27<sup>th</sup> 1903.

+

Mr. Henry Glanville, Woodbury.

1902

£ s d

July	15	4 shoes	2	4
Aug.	20	2 shoes + 2 removes	1	9
	26	1 shoe	..	7
Sep.	15	2 shoes	1	2
	30	2 shoes	1	2
Oct.	16	new guide in barley pick	..	9
	18	sharp land coulter	..	4
	21	2 shoes	1	2
	23	new axle for plough wheel	1	3
Nov.	6	lying skim coulter	..	9
		sharp coulter	..	3
	12	3 links in bullock chain	..	3
	14	2 shoes	1	2
		make hayrod sharp one	..	3
		2 old bell ropes	3	0
	24	2 shoes	1	2
		lying coulter	1	6
Dec.	9	1 new coulter clip	..	9
	16	repair wheel stem of plough	..	4
	22	lying coulter	1	6
		new spanner	1	0
	17	1 man hrs. about chaff cutter	3	2
		1. $4\frac{1}{2} \times \frac{1}{2}$ coach screw, 6, 2" and	..	..
		3. 3" screws <sup>2</sup>	..	4
		1 pair 2" butts. screws	..	3
		1. $5\frac{1}{2} \times \frac{3}{8}$ bolt	..	2
		1 piece sheet iron 18" x 5"	..	5

£ 170

X

Mr. Alfred Stokes, Woodbury.

1902

£ s d

Mar. 22	new fork handle & putting in	10
July 11	5 pieces wall papers	20
Sep. 25	1 man 1 day roof of house	38
26	1 man 1 day do.	38
27	1 man 1 day do.	38
	14 lbs. nails	24
	10.0 of 4 1/2 x 3 deal	23 1/2
	72.0 of 3 x 2 "	60
	3 shute cramps	13
	altering fitting 3 cramps and cutting and drilling 4 holes	16
29	1 man 1 day roof of house	38
30	1 man 1 day make casement	38
Oct. 1	1 man 1 day do. fixing	38
	2.4 of 4 1/2 x 1 1/2 deal casement	42
	6 panes glass 11 x 9	10
	1 pair 2 1/2 butts screws	4
	4 1/2 lbs. putty	6
	8 shute bolts, 1 doz. 1" screws	4
	glass 2-2 x 1-1 1/2	10 1/2
	glass 9 1/2 x 7 1/2	1 1/2
29	man hew pig trough	20

£ 240.

Paid February 17<sup>th</sup> 1903

1902 Mrs. Livermore,

£ s d

~~May 9 putting in pane of glass~~

Sep. 4 1 man 5½ hrs. repair steps

3.6 of 3x7 deal

2.0 of 1½x9 rough oak

15.6 of 3x4 oak sealing

2 lbs. nails

Dec. 15 1 man 1½ hrs. fixing latch

1 Norfolk latch 10 screws

Jan 14 1 man 5 hrs repair Palmy

14.0 - 3x2

15.0 - 2x1

nails & Tar

~~.. 5~~

2 2

1 3

6

1 3

.. 4

.. 7

7

2 0

1 2

5

4

10 4

Paid January 23<sup>rd</sup> 1903

1902 Mr. M. Hearn, Broadway

£ s d

July 16 cutting + shooting 4 carriage wheel tyres

80

Paid January 16<sup>th</sup> 1903

Mr. George Miller, Woodbury.

1903

			£	s	d
Jan.	3	For making a Coffin for his daughter Florence Miller	..	..	..
			..	14	0

Paid by Cash. January 3<sup>rd</sup> 1902



Jaws 6<sup>th</sup> 1903

W. G. Munday  
34 Bampton Street  
Tiverton

£ s d

1902				
May 2 <sup>nd</sup>	2 <sup>nd</sup>	50 feet of Rope for splicing		8 0
Oct 15 <sup>th</sup>	15 <sup>th</sup>	2 Bell Ropes	1 2	0
		3 - 10 feet ends for splicing		5 0
			<hr/>	
			1 15	0
			<hr/>	

Paid April 21<sup>st</sup> 1903

The Woodbury School Managers

1902		£	s	d
October	For carrying out the remainder of the	"	"	"
&	repairs & painting at the School and	"	"	"
November	School House, according to the specifications	"	"	"
	supplied, <sup>me</sup> and my estimates of July 4 <sup>th</sup> - 8 <sup>th</sup>	26	14	0

Paid February 14<sup>th</sup> 1903

J. J. Harding Esq -  
Churchwarden, Pilton, Barnstaple

1902

			£	s	d
October	2 <sup>nd</sup>	Mans time and train fares to Pilton			
	4	3 <sup>rd</sup> & back screwing up and overhauling the peal of 8 Bells			
		19 lbs at $\frac{d}{4\frac{1}{2}}$ -	11	10	
		Train fares	4	8	
		alter 2 Clappers	2	0	
			£	1	16

Paid January 14<sup>th</sup> 1903

Jan 6<sup>th</sup> 1903

Wm J Ackland

Churchwarden, Pottimore

£ 0 d

1902

October 27

For 2 bell Ropes each 60 ft long  
for Pottimore Church Bells at 11/- per Rope

" " "  
1 2 0

Paid April 10<sup>th</sup> 1903

Jan<sup>ry</sup> 7<sup>th</sup> 1902

## The Rector of Halse, near Taunton

1902

Mon <sup>th</sup>	Y <sup>th</sup>	Description	£	s	d
Nov <sup>er</sup>	7 <sup>th</sup>	For 6 Muffles for the Halse Church Bells at 3.6 each	1	1	0

Paid June 4<sup>th</sup> 1903Jan<sup>ry</sup> 7<sup>th</sup> 1902

## The Rector &amp; Churchwardens of Halse

1902

Sept <sup>em</sup>	24	Description	£	s	d
"	"	Mews time and Trap hire going from West Buckland to Halse, screwing up and overhauling the Halse Church Bells	1	9	0

Paid April 9<sup>th</sup> 1903

Rev<sup>d</sup> J L Thorold  
Warkleigh Rectory

1902

Nov <sup>r</sup>	6 <sup>th</sup>	Self to Warkleigh & back securing up bells & frame & put in 3 new Ropes			15 0
		3 new Bell Ropes each 70 ft long at 12/- each	1	16 0	
	13	Self to Warkleigh & back putting in 4 <sup>th</sup> Clapper		" "	15 0
		New part to 4 <sup>th</sup> Clapper			16 0
					<hr/>
					4 2 0

Paid January 9<sup>th</sup> 1903

Jan 15<sup>th</sup> 1903

Paid T. C. Tanner.

Burlescombe

1902

May	12	Mans time and railway fares, going to Burlescombe and back, & crewing up Bells and Frame	9	9
Nov <sup>r</sup>	26	Mans time and railway fares - do. do. do.	9	9
			<hr/>	
			196	

Paid January 30<sup>th</sup> 1903

January 1st<sup>th</sup> 1903  
 May 19<sup>th</sup> 1903

Redd A. B. Wrey St. Mary Church

1902

August 2 <sup>nd</sup>	Self to Mary Church & back examine bells	13	<del>10</del> 4
Sept 29	Self to Mary Church & back, put men to work	13	4
	Trap to W. Rd with mens tools	1	3
	2 mens fares to Torr & back	10	8
	Tools from Torr to Mary Church & back	2	0
	Lodgings for men	6	6
	10 lbs Paint, 5/0 Linseed Oil & Pulley 2/9	7	9
	Smiths work, repair Iron, & chime hammers	9	6
	8 new leathers for clappers	5	8
	carriage of chain blocks & shear legs to Exeter & back	3	0
	do do to Mary Church & back from Exeter	6	8
	Castor Oil & Sweet Oil	1	6
	2 mens time 134 hours at 4 1/2	4	3 9
	Trap to Woodbury Rd after mens tools	1	3
Oct 4	Self to Mary Church & back	13	4
		<hr/>	
		8	19 6

1902  
 August 2<sup>nd</sup> <sup>beat of</sup> Self inspecting the 8 bells ~~in~~ in  
 St. Mary Church Torr, and Sept 29<sup>th</sup> to  
 Oct 4<sup>th</sup> Self and mens time & train fares  
 examining and overhauling & tapping out  
 the 8 bells from their bearings, leveling up  
 bearings, easing gudgeons, repairs to Ironwork  
 Pulleys & chime hammers, new leathers to  
 clappers, and repairs to same, cleaning  
 and painting, Ironwork & stocks, and  
 oiling wheels &c.

Paid May 21<sup>st</sup> 1903



Jan 15<sup>th</sup> 1903

Rev J H Kempe  
Meth

1902

Decr 23<sup>rd</sup> For screwing up bells & frame.

" 176

Paid January 21<sup>st</sup> 1903

The Churchwardens of Houlton

Nov 8 <sup>th</sup>	Time & Train fares, screwing up Bells & frame in St Michaels Tower		10 6
---------------------	---	--	------

Paid March 20<sup>th</sup> 1903

Recd T B. Panther  
 Honiton

Jan<sup>y</sup> 15<sup>th</sup> 1903  
 July 24<sup>th</sup> 1903

1902

Dec<sup>r</sup> 21

For 2 bell Ropes, for 5<sup>th</sup> & Ten Bells,  
 in St Michaels Tower, Honiton  
Nicolls make

1.40

Paid Sept<sup>r</sup> 5<sup>th</sup> 1903

## The Trustees of the Brent Estate

		£	s	d
1902				
Decr	For repairs at Oakhayes House Woodbury, according to estimate of Wor <sup>r</sup> <u>4<sup>th</sup></u> 1902	2	13	0
1903	Sept <sup>r</sup> <u>4<sup>th</sup></u> repairs to Gate at Mrs Adcocks -		1	0
		<u>£</u>	2	14
Paid September <u>29<sup>th</sup></u> 1903				

W. H. C. Watts

Jan 21<sup>st</sup> 1903

Littlehampton  
Sec. to the <sup>Church</sup> Vestry

1903

January 1<sup>st</sup> For 4 Bell Ropes for the 4 back Bells  
in Littlehampton Church Tower. at 12/-

2 8 0

---

Paid January 21<sup>st</sup> 1903

Lieut-Col, Mackintosh  
Churchwarden Awliscombe

1902

Sept <sup>r</sup>	24	Carriage of old Clapper from Honiton	"	8
		Train fare to Honiton & back self put in new 2 <sup>nd</sup> Clapper	"	"
		Trap to Awliscombe from Honiton & back		3 9
		Time of self		2 0
		New Clapper		5 6
				1 0 0
Oct <sup>r</sup>	28	2 mens fares		7 6
		2 men time 13 <sup>hrs</sup> each 26 <sup>hrs</sup> at 7		15 2
		Trap line take out chain blocks from Honiton & back		4 0
				<hr/>
				2 18 7
				<hr/>
Hetch Clapper from Woodbury R <sup>d</sup>				5
				<hr/>
				<u>2 19 0</u>

Paid January 20<sup>th</sup> 1903

July 27<sup>th</sup> 1903W. G. Pitfield Chapple Esq.  
Axminster

1902

October	8 <sup>th</sup>	2 mens time at Axminster lifting out and			
&	9 <sup>th</sup>	overhauling the pair of 8 bells 26 <sup>th</sup> W <sup>m</sup> each 4 <sup>th</sup>	1	11	0
		Railway fares		11	2
		Trap to Station twice with tools & fetch same		2	6
		Lodgings		1	7
		2 lubricating covers for Tension & wick		7	0
		oil & candles		2	0
		2 telegrams		1	0
				2	16 3

Paid August-31<sup>st</sup>-1903

Oct<sup>r</sup> 8<sup>th</sup> Mens time and railway fares, going to Axminster  
& 9<sup>th</sup> & back, lifting out the 6<sup>th</sup> & 7<sup>th</sup> & Tension bells  
and cleaning their bearings, screwing up and  
overhauling all the other bells, and putting  
new pair of lubricating covers to Tension.

Jan 21<sup>st</sup> 1903  
Jan. 11. 1904  
Mar. 31 1904

Rev. R. H. Neely

1902

£ s d

Oct-11

putting in Bell Rope & piece  
chain at Exton Church

2 0



Miss Maulin  
Sydney Cottage

1902

October 30

For making a box for dog

39

Paid January 26<sup>th</sup> - 1903

W. S. Miller

X

1902

Feb <sup>ry</sup>	8 <sup>th</sup>	roughing horse	"	8
June	23	1 old shoe	"	3 1/2
Nov <sup>er</sup>	27	new stop block to doors, nails, staple & time	1	4 1/2

1903.

ap.	9	1 ton mangold		2 4
				10 0

F .. 12 4

Paid,

W<sup>rs</sup> H Stokes, Glasgow

X

1902

July 16

Making and fixing new handle to W<sup>rs</sup>  
Godalls Pump

16

Paid February 17<sup>th</sup> 1903

W. R. Hall.

Plumber, Exmouth

1902

July	15	1 piece leather for Pump & Clout	8
Decr	24	2 old Bell Ropes	2 6

Paid Feby 4<sup>th</sup> 1903

Mr. G. Shell, Colobe Inn.

1902

£ s d

Sep.	26	5' 0" of 7x1 deal	7 $\frac{1}{2}$
Nov.	10	1 man 7 $\frac{1}{2}$ hrs. repair cowsheds	3 0
		2 $\frac{1}{2}$ lbs. nails	" 5
		1 long staple, repair one long staple	" "
		1 link ring	1 7
Dec.	31	1 man 6 $\frac{1}{2}$ hrs. make tables & trestles	" "
Jan.	1	1 man 3 $\frac{1}{2}$ hrs. do. do.	3 11 $\frac{1}{2}$
		38' 9" of 7x1	4 10
		15' 9" of 3x2	1 4
		2' 6" of 3/4x9	" 5
		1 lb. nails	" 2
		1 lb. 1" screws	" 2
	1	1 man 2 hrs. fix tables	" 10
		8 - iron buttons for slides for tables	1 4

---

£ 18 7

---

Paid January 28<sup>th</sup> 1903

W-W Troake - Southside

1902

Nov	22	1 man 1 day make lade for cart			3 8
		1 man 1/2 day do			1 10
		1 man 1 hour do			4 1/2
		Ash for lade 5.6 of 6 1/2 x 2			1 10 <del>10</del>
		4.6 of 8 x 1 (2 1/2) "			1 4
		3.3 - of 8 x 1/2	4		6 6
		Paint repair old lade -			6
		2 wheels alter lade iron			6
Dec	13	1 man 6 hours repair cart			2 4 1/2
	15	1 man 5 1/2 hours do			2 2 1/2
		26.6 of 7 x 1 bottom	1 1/4		2 8 1/2
		4.0 of 3 x 2 1/2 oak	2 1/4		1 4
		3.3 of 3 x 1/2			2 1/2
		4 - 4 x 3/8 bolts			6
		1 lb. Paint			6
		6 ft hoop iron			6
		1 lb. nails 2 doz clubs			4
		3 eyes 3 lengths 2 ft chain, 4 wheels			1 4
Dec	18	1 man 6 1/2 hrs papering			2 4
	20	1 man 3 1/2 hrs do			1 5
					<hr/>
					≠ 16.6

new lade 10/5

repair cart 12.0

Paid March 26<sup>th</sup> 1903



Miss Hodgdon. Eaton

1902

Dec- 1 <sup>st</sup>	repair handle of Pump & 1 new pin	1 4
	1 1/2 lbs leathering Sucker &c	4 1/2
	leather & cloths	9 1/2
		<hr/>
		2 9

Paid February 6<sup>th</sup> - 1903

Rev<sup>d</sup> Godfrey Bird

1902				
August	5	Account rendered		3 5 10
July	24	2 shoes 2 removes		1 4
	25	1 Oak slab 6" x 12" 1		6
Aug	20	2 shoes 2 removes		1 4
Sept	5	straighten Iron hurdle		. 6
	23	4 shoes on Pony		2 0
Oct	2	1 man 1 day make glass door		3 8
	3	1 man 1 day do		3 8
	4	1 man 5 hrs do		2 0
	6	1 man 1 hr do		5
		12.0 - of 4 x 1 1/2	3 3/4	3 9
	7	1 man 4 hours hang door		1 8
8 <sup>th</sup> 9 <sup>th</sup>		1 man 5 1/2 hours glass do		2 3 1/2
		1 pair 3" bolts & screws 6" 1 - 4 brass bolts 1/2"		1 1 1/2
		glass for door 21 <u>00</u>		4 1
		Putty		. 4
		charge £1.3.0 for door & hanging		
4 <sup>th</sup> 5 <sup>th</sup>	9 <sup>th</sup>	1 man 8 1/2 hrs prepare shelves for cupboard & stops		3 6 1/2
	10	1 man 6 hrs fix shelves & put in sash cord		2 6
	11	1 man 2 1/2 hrs put in glass		1 0 1/2
		12 - 1/4 screws		1 1/2
		22.3 of 4 x 3/4 shelves	2	3 8 1/2
		4.6 of 3 1/2 x 1/2 stops 1.6 - 3 x 1		6
		4.6 of glass	3 1/2	1 4
		1 sash cord & putty		4 1/2
Oct	15	4 removes		1 2
Nov	6	4 shoes		2 0
	21	1 man 8 1/2 hrs repair & alter table		3 6
		20.6 of 4 x 1	1/4	2 1 1/2
		8.0 of 11 x 3/4	2 1/2	1 8
		7 doz 1/4 screws		1
	24	6.0 of 4 x 2		7 1/2
		carried over	£	5 19 11 1/2



## Red Godfrey Bird

1902			£	s	d
Nov		Amount brought forward	5	19	11½
25	26	repairing & putting new oak cover to box	5	4	
	27	4 removes 2 bathes	2	2	
		10.0 of 7x1 for shelf.	1	0½	
	28	fit up pincers	"	6	
		1½ W= about stove	"	7½	
Dec	23	2 small hooks		8	
			£	6	10 3½

Paid March 12<sup>th</sup> 1903

1902. Mrs. Lindsey, Broadway, Woodbury £ s d

Sep. 23	fitting new key to lock, 3, 2" screws	..	9
Nov. 12	1 man 7½ hrs. putting in glass repair floor	..	30
	3 lbs. nails	..	6
	1 pane 9¾" x 8¾" }	..	..
	1 do. 8½" x 6" }	..	3
	1½ lbs. putty	..	2½
	1 casement stay, 1 hook & eye	..	5
	1, 2" butt screw	..	1½
	4" 6" of 5½" x 1"	..	6½
	4" 9" of 9" x ½"	..	7
	28" 0" of 7" x 1" floor	2	11
17	1 man 1 day repair cottage & make casement - 75	..	38
18	1 man 8 hrs. do.	..	32
19	1 man 8 hrs. do.	..	32
20	1 man 4 hrs. do.	..	17
	10" 0" of 7" x 1" floor	..	10½
	2" 6" of 6" x 1½" casement	..	6
	6 panes glass for do. }	..	7½
	putty	..	2
	1 window stay, 1 hook & eye	..	5
	1 pair 2" butts & screws	..	2½
	1 square, 6, 1½ screws	..	5
	4 panes glass	..	6

£ 149

Settled April 24<sup>th</sup> 1903

Feb 4<sup>th</sup> 1903W<sup>rs</sup> Adcock

1902				
Nov	11	1 man 4 hours repair cistern, put in new wried <sup>s</sup> Wire, & Putty		1 8 4
1903				
Jan	6 <sup>th</sup>	1 man 3 hours repair & put new leather to cistern valve, and new wood to do new leather, 2.6 of 4x1 2- 1 <sup>1</sup> / <sub>2</sub> & 2- 3 <sup>1</sup> / <sub>2</sub> screws		1 3 2 <sup>1</sup> / <sub>2</sub> 3 <sup>1</sup> / <sub>2</sub> 2
				<hr/> 3 11

Paid February 5<sup>th</sup> 1903

The Vicar & Churchwardens of Bradford  
near Tamworth, Somerset

1903

January  
& February

For lowering down the 6 Bells from Bradford  
Church Tower, taking out the old fittings, frame  
floor and beams, and providing and fixing  
in the Tower new beams and floor, and  
oak paving bed, and  
new Iron Frame for the 6 Bells, and  
hanging the 6 Bells with all new fittings  
complete according to estimate of  
August 29<sup>th</sup> 1902

168 14 0

Putting an iron band around 5<sup>th</sup> Bell  
and boring hole through head of her and  
putting iron canon to her.

1 6 0

---

£ 170 3 0

---

Received £170 = March 15<sup>th</sup> 1903

January 1<sup>st</sup> 1903

## Mrs Marianne Stokes

1902	For Plumbers work to altering W.C. and putting new Force Pump and Water Supply to Cistern of W.C. at Rosemary Cottage		
August-23	New Force Pump, Ironwork &c complete 1 new Pedestal Closet 1 Mahogany Seat 6 ft length 4" pipe 3/- 1- 4" Tee piece 2 cast-iron brackets for W.C seat	3	16 0
25	Labour for Man & Boy & train fare about Pump		9 0
26	do do do do about W.C		11 6
"	do man about Pump		6 4
	1 wire top 10 <sup>d</sup> 1- 4 ft length 4" pipe 2/- 1 lead bend for W.C		2 10
	1 cast <sup>gns</sup> 2" <sup>lbs</sup> 22 of 1 1/4 Pump pipe 6 1/2 lbs solder	1	10 8
	New 1 1/2 valve for cistern		5 5
	3 ft 1/2 compo pipe for air pipe for W.C copper wire & 12 ft 1 1/4 lead pipe for W.C		6 6
	1 chain pull, putty bandage & cord		3 1 1/2
27	2 men & boy & train fares		1 4
			14 4
			<hr/>
		9	16 0 1/2

## Mrs Marianne Stokes

1903	For Masons, work done at Rosemary cottage		
August 25	1 man 1 day repair plaster & rough casting walls 4 barrows mortar, 1 barrow rough cast, 2 buckets, putty lime, 1 peck plaster $\frac{1}{2}$ bundle laths, lath nails & hair		3 8 4 3 $\frac{1}{2}$
26	1 man 1 day coloring walls of House &c 1 barrow mortar, 4 buckets of color		3 8 2 8
27	1 man 1 day coloring, and about well 2 barrows, mortar 3 buckets color		3 8 2 10
28	1 man $\frac{1}{4}$ day repair paving		11
29	1 man 1 day do. do, plastering & coloring 3 barrows mortar & color		3 8 2 6
30	1 man 1 day wash off ceilings, repair plaster &c		3 8
Sept 1	1 man $\frac{1}{2}$ day white ceilings &c 2 buckets color 15 <sup>lbs</sup> whitening $\frac{1}{2}$ <sup>lb</sup> glue		1 10 2 6
2	1 man $\frac{3}{4}$ day, whitewash, Dairy, Kitchen ceiling &c		2 9
3	1 man 1 day repair paving, color Kitchen &c		3 8
4	1 man 1 day Tarring, also drain &c Tar. $\frac{1}{2}$ peck plaster & color		3 8 1 9
5	1 man 1 day repair door steps, cow's door well &c		3 8
6	1 man 1 day coloring, whitewashing, tarring &c 1 barrow gravel 2 buckets color, 1 bucket lime		3 8 2 1
10	1 man $\frac{1}{2}$ day repair furnace 1 bucket mortar, 1 bucket gravel 45 buck, 3 peck cement - 9 paulite		1 10 6 6 0
			3 8 5 $\frac{1}{2}$

Mrs Marianne Stokes

1902		For carpenters & Painters work done to Rosemary Cottage, Woodbury	£	0	d
July	7	1 man 1 day ease Windows put in glass &c		3	8
	8	1 man 1/2 day Painting &c outside		1	10
		2 lbs Paint 10 <sup>d</sup> of panes glass 10 <sup>d</sup> Putty 2 1/2 <sup>d</sup>		1	10 1/2
Aug	12	1 man 1/4 day get out Staff Plank for Pump 5-6 of 8x2 Gate		"	11
	22	1 man 1 day take down back stairs &c		3	8
	23	1 man 1 day alter & fix door to Kitchen &c		3	8
		12-0 - 4x1 1-3 - 22-6 of 3x2 1-6 1/2		2	9 1/2
		4-6 - 9x3/4		"	7
	27	1 man 1 day Painting &c		3	8
	28	1 man 1 day, repair & paint front rails &c		3	8
		12-0 - 4x1 - 1-3 - 4-0 - 4x2 4		1	7
		1 ash cord - 1 iron button		"	3
Sept	4	1 man 1 day papering &c		3	8
	5	1 man 1 day stannings &c		3	8
		6 pieces paper & binder		2	9
		Paste		"	4
		1 tow latch 4 1 box staple 2		"	9
		25 lbs Paint for inside & outside of House		10	5
		1 1/2 pint of Vermorel		1	6
	8	1 man 1/2 day Painting		1	10
	9	1 man 1/2 day do		1	10
		4 feet 2 1/2 down pipe to back of House		"	10
		1 shoe for do		"	8
		4 pipe nails shute screws & screws		"	3
		2 Panes Glass in Green House & Putty		"	8
		1 piece perforated Zinc		"	3
		Smith repairing front iron gate, and putting 6 new cast tops to front		"	"
		Painting.		3	5
		3 lbs Nails			6
			£	3	3 7

Mr M Stokes

(Totals)

£ s d

Carpenters &amp; Painters work

3 3 4

Masons work

3 8 5½

Plumbers work

9 16 0½

Total amounts = 16 8 1.

	£	s	d
Credit for <sup>lbs</sup> 181 of old lead	"15"	1	0
received for Mr T Stokes share of Rents for Leasehold Cottages to Christmas 1899 -	"	"	15 9
Received Rents from Mr T Stokes Houses in Broadway Woodbury	5	10	0
	14	17	4

7 "14 9½

left due

10 2 6½

Received Rents at March 25, 1903  
from houses in Broadway

5 10 0

left due

4 12 6½

Paid Jan<sup>rs</sup> 1<sup>st</sup> 1904 Insurance

5 0

" Jan<sup>rs</sup> 8<sup>th</sup> 1904 Insurance

15 9

Advertising House to Let

2 6

5 15 9

Received Rents due at Christmas 1904

£ s d

3 17 6

Received Money Order Jan<sup>rs</sup> 9<sup>th</sup> 1904 for 1<sup>st</sup> 18 3

£ 5 15 9



March 14<sup>th</sup> 1903

W. H. Hooker

1903

Penquite. St. Brewand

£ 0 2

March 5-

For 6 Bell Ropes each 60 ft long  
 with 3.6 cables for St. Brewand Stunch  
 Bells at 12/- per Rope

" " "

" " "

3 12 0

Paid March 14<sup>th</sup> 1903

October 1902 The Vicar & Churchwardens of St George's Church  
1903 Hordington, Dorchester.

	£	s	d
March 24 <sup>th</sup> For lowering down the 6 bells from the Church Tower, taking out the old fittings frame, floor & beams from the Tower, providing and fixing new Oak beams and floor, and providing <sup>making</sup> and fixing an Oak frame for 8 bells, and hanging the 6 old bells with all new fittings complete, according to <del>estimate</del> of my amended estimate of August 1 <sup>st</sup> 1902 And under the direction of W.D. Carol. Exp. included.			
	162	11	0

April 17<sup>th</sup> 1903 Received from Mr Frank Shergold  
6 Chestnut Villas  
Dorchester  
a cheque on account for £100=

Nov<sup>r</sup> 2<sup>nd</sup> 1903 Received from Mr Frank Shergold  
a cheque for £62<sup>..</sup>11<sup>..</sup>0 to close account.

April 3<sup>rd</sup> 1903

## The Vicar &amp; Churchwardens of Paignton

1903				
January 5 <sup>th</sup>	For taking down the 1 <sup>st</sup> 2 <sup>nd</sup> 3 <sup>rd</sup> 4 <sup>th</sup> and			
to	Ten bells from the Parish Church Tower			
April 2 <sup>nd</sup>	and carriage of them to and from London			
	and tuning them, according to estimate			
	of May 21 <sup>st</sup> 1902			33 14 0
	For taking down the 5 <sup>th</sup> bell from the			
	Tower, carriage of her to and from London			
	and recasting, <sup>and repairing</sup> her according to amended			
	estimate of May 3 <sup>rd</sup> 1902			50 18 0
	For providing 2 new Treble Bells, a 1 <sup>st</sup> and			
	2 <sup>nd</sup> to complete the octave, and hanging			
	them in the Tower in new oak frames, and			
	with new fittings complete, according to amended			
	estimate of May 3 <sup>rd</sup> 1902			124 13 0
	For re-hanging the 1 <sup>st</sup> 2 <sup>nd</sup> 3 <sup>rd</sup> 4 <sup>th</sup> & Ten bells			
	according to estimate of May 23 <sup>rd</sup> 1900			30 15 0
	For putting 2 chiming hammers to the 2 new			
	bells, and overhauling and putting the old 6			
	in proper order			6 0 0
to be	For putting pedestal bearings to Ten			9 0 0
do	For putting new staple in Ten bell			1 14 0
	Inscription of 132 letters put on <sup>re-cast</sup> the 5 <sup>th</sup> bell at 4			2 4 0
	Inscription of 217 letters put on the 2 new bells at 4			3 12 4
				<hr/>
				£ 254 5 4
				<hr/>

April 2<sup>nd</sup> 1903 Received on account £100=

Settled April 22<sup>nd</sup> 1903

## The Churchwardens of Thoresdon

1903

Jan <sup>ry</sup>	15	For repairs and altering staple & clapper	
and	21	in Tenor Bell, and screwing up frame & bells	13 0

Paid January 8<sup>th</sup> - 1904

April 7<sup>th</sup> 1903T. H. Crooke  
Worcester  
Transaction

## The Churchwardens of Brampton Speke

1903

~~January 15 For repairs and altering staple & clapper  
in Tenon Bell and screwing up frame  
& bells~~

~~130~~

1903

January 15 For inspection and advice about the  
Brampton Speke Bell Frame

0 d

106

Paid April 9<sup>th</sup> 1903

Rev. R. H. Peely

19102

Oct. 11

~~man to 3 hrs put in Rope at  
Boston Church  
1.99 chain + S.~~

Woodbury Churchwardens

1902

£ s d

June	6	1 new Bell Rope for 6 <sup>th</sup>		10	6	
	13	1 man 3 1/2 hrs. take out & put in 7 <sup>th</sup> clapper	}	1	9	
		shooting up 7 <sup>th</sup> clapper, new part of clapper 27 lbs				
	18	1 man 2 hrs. take out Tenor clapper	}	1	0	
		shooting & repairing Tenor clapper				
		4 lbs. new iron			5	0
	<sup>re</sup> 20 <sub>p</sub>	1 man <del>hrs.</del> put in do			6	
Sep.	11	1 man 3 hrs. take up pump at G. Hensons		1	2 1/2	
	12	repair handle of pump new pin & key		1	3	
	13	1 man 1/2 day fixing pump		1	10	
		new box leather for pump		1	8	
		leather for sucker			7	
		red lead relouts			9	
	27	1 man 2 hrs. put lock to Church box fixing			9 1/2	
		lock & screws, & 8. 1 1/2" screws		1	6	
Dec.	22	soldering gutter at W Chapman		2	9	
	24	1 man 6 1/2 hrs. put new sleepers & leather sucker at W Chapman's pump		2	7 1/2	
		4 bolts + 1 plate for pump			10	
		9" o of 11 x 3 1/2 oak	11 1/2	8	7 1/2	
		6" o of 6 x 1 1/2 "	2 3/4	1	4 1/2	
		4. 5 x 5/8 coach screws		1	0	
		1 lb. <del>red</del> nails, 1/2 lb. red lead			3	
		leather for sucker			7	
	29	1 man 1 1/2 hrs. put leather valve to pump			7	
		leather valve			6	
		1/2 lb. red lead			2	
1903	Mar. 21	Tenor Bell rope with loop (in shape)		12	0	

Paid April 11<sup>th</sup> 1903

less

2/0

£ 3 19 5

Recd. by E. F. Molinoux.  
Harpford

1902

April 18

For screwing up the frame & fittings  
of Kern Battery and Harpford Church  
Bells

66

Paid. October 21<sup>st</sup> 1903.



June 10<sup>th</sup> 1903

Rev. C. H. Walker

£ s d

1903

Walkhampton.

May For repairs to the peal of 6 Bells in Walkhampton  
 Parish Church Tower, according to estimate  
 of December 29<sup>th</sup> 1902  
 " Repairs to the chiming apparatus  
 " 6 new Bell Ropes. Nicolls make, <sup>s d</sup> 13.9 each

" " "

" " "

23 18 0

1 10 0

4 2 6

29 10 6

Credit for <sup>lbs</sup> 39 of old bearings at <sup>d</sup> 3<sup>1</sup>/<sub>4</sub> per lb.

10 6

29 0 0

less £2 = Taken out from Mr. Walker

Settled June 15<sup>th</sup> 1903

## The Vicar &amp; Churchwardens of Clawton

1903

May	22 <sup>nd</sup>	For lowering down the 3 Bells from Clawton Church Tower, taking out the old fittings, frame &c providing and fixing new beams & floor, and new frame for 5 bells, and hanging the 3 bells, with all new fittings complete according to estimate of December 4 <sup>th</sup> 1902			77 15 0
		For providing and hanging 2 new Bells a 1 <sup>st</sup> & 2 <sup>nd</sup> to make it a peal of 5 according to estimate of Decr 4 <sup>th</sup> 1902			81 10 0
		weight of 1 <sup>st</sup> Bell <sup>wt in lbs</sup> 4. 1. 26			
		do 2 <sup>nd</sup> Bell 5. 0. 25			
		<u>4. 2. 23</u>			
		extra charge of 23 <sup>lbs</sup> overweight on estimate 1. 2 p <sup>ts</sup>			1 6 10
		Inscriptions of 41 letters put on the 2 Bells at 4 <sup>d</sup>			13 8
					<hr/>
					£ 16 1 5 6
		deduct for 4 beams supplied			£ 5 15 0
					<hr/>
					£ 15 5 10 6

Settled June 19<sup>th</sup> 1903

June 10<sup>th</sup> 1903

Mr John blot-worthing  
Builder. Witheridge

1903

May	16 <sup>th</sup>	For 3 Bell Ropes, salties, 3.3 long for Witheridge Church Bells, 12/- per rope				1 16 0
-----	------------------	---	--	--	--	--------

allow off <sup>o d</sup> 1.6 to Mr blot-worthing.

settled June 12<sup>th</sup> 1903

~~The Ocean & Churchwardens of Houston City~~

1903

April

Red C Square, St. Dominic

~~For~~For Rope Guides for St. Dominic Bells  
as per estimate of February 18<sup>th</sup> 1903

= 0 d

" " "

2 13 6

Paid August 8<sup>th</sup> 1903

July 3<sup>rd</sup> 1903

Rev. G. C. Ramsay. Lochne

1903

£ s d

Date	Description	£	s	d
May 15	Mans time <sup>7.11</sup> and rail fares <sup>4.6</sup> going to Lochne	"	"	"
"	screwing up bells & frame 13 <sup>1/2</sup> w.	15	5	
"	4 muffles for the bells	14	0	

---

 195
 

---

Paid July 5<sup>th</sup> 1903

July 31<sup>st</sup> 1903

Rec<sup>d</sup> - A H Everett, North Tamerton

1903

£ 0 1

May 27<sup>th</sup> For 6 muffles for the 6 Church Bells 3/6

1 1 0

Paid. Nov. 7. 1903

## The Churchwardens of Stoke Gabriel

July 3<sup>rd</sup> 1903  
Oct 7 1903

Rd 6 Puckridge. Near Pihse

1903

April 23 <sup>rd</sup>	For one Bell Rope - 40 ft long		11 0
	barrage by Parcel Post		9
			<hr/> 11 9

Paid Oct 14<sup>th</sup> 1903



July 3<sup>rd</sup> 1903  
Oct 27<sup>th</sup> / 03  
Dec. 30. 03

Rev. G. A. Lester. Bishop's Lynton

1903

£ s d

May	5	For 6 Bell Ropes - 5 - 60 feet long	11.6	2	14	6
		1 - 65 feet long for turn	12.0		12	0
				<hr/>		
				3	9	6

Paid January 8<sup>th</sup> 1904

Mr. Gennis, Fairfield

£ s d

May 26	18.6 of 11x1 deal planed	3	4.7½
	11.6 of 4½x1 deal rail	1½	1 2½
		£	5 10°

Paid June 11. 1903.

June 16<sup>th</sup> 1903  
Oct 7 1903Recd of Lighter  
3 Birmingham Terrace  
Birmingham

## The Vicar &amp; Churchwardens, of Littleham

£ s d

1903

March  
to  
May

For taking down the cracked Bell from  
the Church Tower, and recasting her, and  
re-hanging her again, in the Tower, providing  
~~and having~~ a new Treble Bell to hang to make  
the peal into 6, and hanging her in the  
Tower, in a new frame, and with new fittings  
and chime hammer, and tuning the old  
Bells, according to estimates of October 5<sup>th</sup>  
1901- and February 4<sup>th</sup> 1903 -  
old inscription of 19 letters put on the recast-Bell at 4

42 15 0

6 4

---

43 1 4

---

Received July 10<sup>th</sup> 1903 £65 =Settled October 9<sup>th</sup> 1903

The Representatives of the late W<sup>o</sup> Ellen Bamsey £ s d

1903			£	s	d
June	15 <sup>th</sup>	For making a coffin for the late	"	"	"
		W <sup>o</sup> Ellen Bamsey -	2	2	0

Paid June 20<sup>th</sup> 1903

July 28<sup>th</sup> 1903

Mr. John Gooding

1903

May 23

For making a coffin for his Infant  
child

10 0

Pean &amp; Sexton Fees

4 6

---

14 6

---

Received April 26<sup>th</sup> 1904 <sup>o d</sup> 2.6 on account  
by Postal Order -

June 20. 1904. Received 5/6 by cash

July 18<sup>th</sup> 1904 Received 4.6 to settle acct

W<sup>r</sup> - William Holland

1903

~~£~~ 0 0

June 22 For making a Polished Elm Coffin  
for his Mother the late W<sup>rs</sup> Hannah Holland

" " "  
2 5 0

---

Paid June 27<sup>th</sup> 1903

July 5<sup>th</sup>

The Woodbury School Managers

1903

June	3	1 man 2 hrs. making Washup cupboard		10
	4	1 man 1 day		3 8
	5	1 man 7 1/2 hrs		3 1 1/2
	6	1 man 1 day		3 8
	8	1 man 1 day		3 8
	17	1 man 1 day		3 8
	18	1 man 2 hrs		10
	19	1 man 1 1/2 hrs		7 1/2
	20	1 man 1 hr		5
	22	1 man 2 hrs		10
		23.9 of 1x9	2 3/4	5 6
		3.6 of 1x11	3	10 1/2
		34.0 of 3/4 x 7 mat-ck	1 1/4	3 6 1/2
		18.6 of 3/4 x 7 floor	1	1 6
		3 pair 2" bolts & screws	3	9
		20 - 1 1/2" 3 doz 1" screws		6 1/2
		2 1/2 lbs Paint		1 3
		stain & var		2
		1/2 pt Varnish		9
		1 neck toll - 4 1/2" 1 button & turnbuckle		9 1/2
		1 enameled bucket		3 7
		1 enameled water jug		3 4
		1 pair handles		8
				2 4 7
Paid September 25 <sup>th</sup> 1903			£	2 5 0
Feb.	18	1 man 2 hrs. repair floor		10
		4' 6" of 7x1 floor		4 1/2
		nails P.		1
Apr.	22	putting in new Bell Rope 2'		2 0
July	11	2 hrs. repair pump		10
		new leather for sucker		4
		new spindle valve P.		5 6

## The Vicar &amp; Churchwardens of Hapton

1903

July

4

For taking down the bells from Hapton  
church Tower, taking out the old fittings  
frame, floor & beams, providing and  
fixing <sup>in the Tower</sup> new beams and floor, and a new  
frame for the 5 bells, and hoisting the  
bells into the Tower, and hanging them  
with all new fittings complete <sup>and refixing chimes apparatus</sup> according  
to estimates of Sept- 10<sup>th</sup> & 19<sup>th</sup> 1902

£ 0 d

" " "

88 16 0

Paid. July 28. 1903.



July 4<sup>th</sup> 1903wrote April 10<sup>th</sup> 1903

Mr W. B. Fulford

44 Victoria Rd Exmouth

1903

July 4 <sup>th</sup>	For making a coffin, with brass furniture fittings, for the late Mr W. B. Fulford and for carrying out all the Undertakers work including - Hearse & Carriage, Bearers seaton, and Vicar & Clerks fees	£ 0 d
		" " "
		" " "
		" " "
		" " "
		8 10 0

July 6 <sup>th</sup> 1903	Received on account.	£ 3 0 0
January 27 <sup>th</sup> 1904	Received on account	£ 3 10 0

W-Johnson. Priory, Woodbury

1903

May	9 <sup>th</sup>	2 boards for garden			6
June	3	small frame		1	2
		piece of lead			6
June	19	2 stands		3	0
July	2	put in pane of glass		1	0
					<hr/>
					6 2
					<hr/>

Paid July 21<sup>st</sup> 1903

## Sir Charles Pearson

1903

s d

Jan	2	cutting 2 corrug. iron sheets		6
"	1	5'0" of corrug. iron cp 1/5		10
	5	put handle in pairons hammer 1 hr.		4
	8	1 man 9 hrs. repair doors, chairs, + put in oak cords.		3 11 1/2
	9	1 man 9 1/2 hrs. preparing shelves		3 11 1/2
"		sharp mattock 2 ends		4
	10	1 man 8 hrs. fixing shelves		3 4
		<del>1 long handle bolt for doors + staple</del>		<del>2 8</del>
		10'6" of 1x9 deal shelf	2 3/4	2 5
		6'0" of 3/4x7 " "	1	6
		2'3" of 1/2x8 deal	1 3/4	4
		2'6" of 2 1/2" moulding		2 1/2
r.		2'0" of 3x1 deal	1	2
		1'6" of 7x3 1/2 Oak	8	10
		2'10" x 8" glass 1'9" of glass		7
		1. 10" Tower bolt screws		9
		3. iron brackets	4	1 9
		2. 6" rim locks complete	3/-	6 0
		1 window stay		4
		1 window fastener		4
		23. 1 1/2" screws		4
		1 lb. nails		2
		1 lb. putty		1 1/2
		oak cord		4
		1 handle in twobill		10
	12	1 man 9 hrs. fix window stay fastener + stop block to coach house doors		3 9
	13	1 man 7 1/2 hrs. edging slabs part-		3 1 1/2
	19	1 man 9 hrs. fixing iron fence		3 9
	20	1 man 9 1/2 hrs. do.		3 11 1/2
	21	1 man 9 1/2 hrs. do.		3 11 1/2
		carried forward:	£	2 9 2 1/2

1903

£ s d

amt. brok. forward:

			2	9	2½
22	1 man 9½ hrs. make door for fence		3	11½	
23	1 man 9½ hrs. hang do.		3	11½	
	2 oak posts 17' 0" of 4½ x 3½	5½	7	9½	
	7, 17' 0" of 3 x 2 deal = 119		"	"	
	1, 13' 0" of 3 x 2 " 13 = 132' 0" at 1		11	0	
	34 sheets of corrug. iron 6' 0" long ea.	2/3	3	16	6
	1, half sheet do.	1/12	1	1½	
	150 galv'd. screws	4/6 per	4	8½	
	4 lbs nails		"	8	
	1 bucket tar		1	3	
	<del>2 oak cords</del>	1½	6	0	
	48' 0" of 7 x 1 match for door				
	12' 0" of 9 x 1 ledges "	2½	2	9	
	6' 0" of 5 x 3/4 stops "	1¼	"	7½	
	1 Norfolk latch complete & driving catch			8	
	3½ lbs. paint		1	9	
	6, 2" + 6, 1½" screws			3	
	2, 2½ x 3/8 bolts		"	2	
	1 pair hook + twist catch		3	8	
	1 horse rest - take down door		1	0	
	2 oak cords		"	8	
	1 doz. oak window wedges		"	6	
	1 bolt for yard doors		2	8	
16	1 man 4 hrs. make barrow		1	7	
17	1 man 1 day, do.		3	8	
19	1 man 1 day, do.		3	8	
20	1 man 7½ hrs. do.		2	11½	
24	1 man 4½ hrs. do.	18/0	1	9½	
	4 staples + 2 hasps for barrow		"	6	
Feb. 14	1 man 4½ hrs. make slab door		1	10½	
	1½ lbs. nails		"	3	
	15' 0" of 8½" slab.	13	3	1	
	22' 0" of 7" do.	13	1	0	
	delivered total door	£	10	5	1
	carried over				

10.5  
£ 0 2

1903

		amt. brok. over	10 5 1
Feb.	28	1 hr. paint tubs	1 0
ap.	11	paint - new gate eye clip bolt	1 6
ap.	6	1 man 3 hrs. take out - nails from beams	1 3
		Sawyers cutting old beams	11 0
	9	1 man 5 1/2 hrs. make book shelf	2 3 1/2
	11	1 man 8 hrs. do.	3 4
	14	1 man 9 1/2 hrs. do.	3 11 1/2
	15	1 man 9 1/2 hrs. put in sash cords, repair blind cords + stable left door	3 11 1/2
		2 sash cords	8
		1 lb. nails	2
		18.00 of 3 1/2 x 3/4 deal	9
		188.00 of 2 x 1 batten	58
	17	1 man 2 hrs. make Canterbury	10
	18	1 man 8 hrs. do.	3 4
	20	1 man 5 hrs. do.	2 1
	21	1 man 9 1/2 hrs. do.	3 11 1/2
	22	1 man 4 hrs. do.	1 8
	25	1 man 1 hr. do.	5
	27	1 man 1 hr. do.	5
		4 castors, 12, 5/8 screws	1 9
	30	48.00 of 2 x 1 batten	16
		sharpen saw	6
May	7	3 panes glass 13 x 7 3/4 each 2 1/4 p.	8 1/2
June	24	1 man 7 hrs. put in sash cords + 3 sash cords	3 1 1/2
		glue in table leg 1 hr.	10
		grinding knife	10

£ 13 2 11

Settled August 1st - 1903

Mrs. Jane Glanville (to go in after June 27 page 296)

1 pane glass in tap room 14x10 rputty		4	
7.0 of 4x2½ bed for W.C. seat	2½	15½	
4.0 of 4x2 channel for masonry	1¼	5	
8.0 of 1x½		2	
1 lb. paint for plumber	6	6	
2 Oak posts 10.03 long ea. 7x5	11-4-	1 #0 30	
12.0 of 4½x3 tail for gates	3½	36	
12.0 of 3x3 head "	2½	26	
25.6 of 4½x2 rails "	2½	54	
6.0 of 7x1¼ brace "	2	10	
27.0 of 9x1 poles "	2¾	62	
2 lbs. nails	2	4	
10. 2½ screws		2	
3 lbs. priming	6	16	
2.9 of 23x1 elm seat - 5.3	2½	141	
1 pair 2" butts & screws	3	3½	
6.6 of 6x½ stops	1	6½	
2 pairs 18" Tee Hinges	11	180	
2 " 2" butts & screws	3	7	
1. 6" bolt for W.C. door		5	
22. ¾ screws		2	
1 Norfolk latch complete	87	8	
5 doz. 1" screws, 12. 2" screws		7	
2 lbs. nails	2	4	
4.6 of 7x1	1¼	5½	
5.9 of 4x2	1¼	7	
3.0 of 9x1	2¾	8½	
pat. galvzd. bolt & screws		10	
1 tail bolt & screws for doors		43	
8. 3x3/8 bolts		10	
6. 1½ screws		1	
carried forward.	7	2 19 3½	

Mrs. Jane Glanville Brewery

1903.

£ 19 8 2

		amt. brok. forward		£	s	d
				2	19	3 1/2
Jan.	1	4.6 of 3x9 deal	6 1/2		2	5 1/2
		3.0 of 3x 1/2 "				2
June	3	1 man 7 1/2 hrs. make stable jambs			3	1 1/2
	5	1 man 2 hrs. fix do.				10
		1 <del>man</del> <sup>man</sup> 7 1/2 hrs. make " door			3	1 1/2
		4 bolts + 2 dowels for jambs			2	4
		20.9 of 4 1/2 x 3 deal stable jambs	3 1/2		6	0 1/2
		11.3 of 1x9 ledges " door	2 3/4		2	7
		51.0 of 1" match " "	1 1/2		6	4 1/2
		1 lb. nails	2			2
		2 lbs. paint	6		1	0
	9	1 man 1 day hang door stake down partition			3	8
	10	2 men 1 day ea. fencing			7	4
		1 labourer 1 day do.			3	0
	11	2 men 1 day ea. do.			7	4
		1 labourer 1/4 day do.				9
	12	1 man 1 day 2 hrs. fencing + make jambs + frames				
					4	6
		1 man 1 day do. do.			3	8
	13	2 men 1 day ea. making frames			7	4
		1 pair hooks + trust for stable door			4	0
		1.10 x 1/2 bolt, + 1 iron for wall post				8
		1 Norfolk Handle complete stable				8
		8. 2 screws. 2. 3x 3/8 bolts "				3 1/2
		18.6 of 3x 3/4 stops "			1	0
		2 lbs. priming				10
		5.9 of 9x3 lintel	6 1/2		3	1
		6 lbs. nails	2			10
		2 8.0 sheet galvzd: iron	40 lbs 2.10		5	8 6
		1 8.0 narrow piece	7 lbs 1.5		1	5 6
	31	7.0 sheets galvzd: iron	27 1/2	4	1	5 x
		2 lb galvzd: screws + washers	4 1/6 pms			6 9
		carried forward	£	11	12	0 1/2

1903

Food

	amt. brot. forward:		11	12	0 $\frac{1}{2}$
	17.0 of 4 $\frac{1}{2}$ x 3 jambs for W.C.	3 $\frac{1}{2}$		4	11 $\frac{1}{2}$
	16.6 of 4 x 3 2 frames for do.	3 $\frac{1}{4}$		4	10 $\frac{1}{2}$
	4.0 of hoop iron	1		..	4
E	25.6 of 4 $\frac{1}{2}$ x 3 deal large frame	3 $\frac{1}{2}$		7	5
	224.0 of 4 $\frac{1}{2}$ x 2 rails for fence	2 $\frac{1}{4}$	2	2	0
June 15	1 man 3 $\frac{1}{2}$ hrs. make casements			1	5 $\frac{1}{2}$
16	1 man 1 day 2 hrs. fix frames put in joist			..	..
"	in joist			4	6
17	1 man 1 day cut off joist ease door & make & fix lintel			..	..
"	1 man 3 hrs. make casements			3	8
18	2 men 1 day ea. fix jambs put in post, make doors & casements			..	..
				7	4
19	1 man 1 day ea. do.			3	8
"	1 man 1 day 2 hrs. help plumbers fix cistern & make doors			4	6
20	1 man 1 day make & paint doors			..	..
"	1 man 5 hrs. do. do.			3	8
	1 staple for walling in			2	1
	4. $\frac{1}{2}$ bolts for wall in jambs			..	4
	1 bolt			1	2
	10.6 of 4 x 2 joist	1 $\frac{1}{4}$		..	4
	3.9 of 4 x 2 $\frac{1}{2}$ turning pieces	2		1	1 $\frac{1}{2}$
	8.0 of 4 x 5 $\frac{1}{2}$ lintel over coalhouse	5 $\frac{1}{4}$		..	7 $\frac{1}{2}$
	8.0 of 3 x 5 $\frac{1}{2}$ "	3 $\frac{3}{4}$		3	6
	1.6 of 2 x 4 "	1 $\frac{1}{4}$		2	6
	11.6 of 4 x 2 $\frac{1}{2}$ wall plate	2		..	2
	1 piece line 8.0 long 2 $\frac{1}{2}$ wide			1	11
	2.3 of 4 $\frac{1}{2}$ x 3/8 slips			..	0
	3.9 of 9 x 1 $\frac{1}{2}$ W.C. & H. casements	3 $\frac{1}{2}$		..	1 $\frac{1}{2}$
	9.3 of 9 x 1 $\frac{1}{2}$ large do.	3 $\frac{1}{2}$		3	9 $\frac{1}{2}$
	carried forward	£	17	0	4



1903

£ o d

	amt. brok. forward		17	0	4
	8 panes of 9x7 H-R. glass			1	4
	18 " glass 10 $\frac{1}{8}$ x8 $\frac{1}{4}$	1 $\frac{3}{4}$		2	7 $\frac{1}{2}$
	4 lbs. putty			"	6
	8.0 of 9x2 deal for cistern	4 $\frac{1}{2}$		3	0
	18.0 of 7x1 floor do.	14		1	10 $\frac{1}{2}$
	1 lb. nails do.	2		"	2
	5 lbs. red lead for plumber	4		"	2
	2 gutter bolts	5		"	1
	12.0 of 4x3 loft door jambs	3 $\frac{1}{4}$		3	3
	112.0 of 7x1 match large doors	1 $\frac{1}{2}$		14	0
	28.6 of 7x1 $\frac{1}{4}$ ledges "	2		4	9
	12.0 of 7x3 $\frac{1}{4}$ braces "	1		1	0
	3 lbs. nails "	2		"	6
	5 lbs. priming "	6		2	6
	27.0 of 7x1 match W.C. doors	1 $\frac{1}{2}$		3	4 $\frac{1}{2}$
	6.9 of 7x1 ledges "	1 $\frac{3}{4}$		1	0
	1 lb. nails "	2		"	2
£	23.6 of 7x1 match top door	1 $\frac{1}{2}$		2	11
"	7.0 of 7x1 $\frac{1}{4}$ ledge "	2		1	2
	3.6 of 7x3 $\frac{1}{4}$ brace "	1		"	3 $\frac{1}{2}$
	1 lb. nails "	2		"	2
	2 pairs of hooks & twist for large doors			7	8
June 24	1 man 1 day make gates			3	8
"	1 man 5 hrs. help plumbers			2	1
25	2 men 1 day ea make gates			7	4
" 26	2 men 1 day 2 hrs. ea. hang gates, doors, casements "			"	"
				9	0
27	2 men 1 day 2 hrs. ea. hang gates + glass casements.			"	"
				9	0
	repair ironwork from old doors for new gates			"	"
				2	8
	Carried forward	£	21	6	5

1903

21 16 5  
£ o d

	amt. brok. forward		21	6	5
	2 new hooks, 1 guide and 10 4 x 1/2" bolts		"	"	2 10
	1 haap + 2 staples for left door		"	"	"
	2 window stays for W.C. + U		"	"	8
June 29	* 2 men 1 day ea. hang doors		7	4	
30	2 men 1 day 2 hrs. ea. hang doors + gates + make netting frames		"	"	9 0
July 1	1 man 1 day alter kitchen window put sill to door		"	"	3 8
	1 man 4 hrs. make netting frames				1 8
	1 man 9 1/2 hrs. painting	6	4	9	
4	1 man - 6 hrs. do.		3	0	
	ring handle, plates, latch, catch and plate, 1 guide		"	"	2 6
	2 iron harness pegs		"	"	6
£	1 man 21.0 of 7 x 1 floor	1 1/2	2	7 1/2	
	8.0 of 3 x 1 stops for doors	1	"	8	
	1.6 of 4 1/2 x 1 1/4 for bolts			3	
40 <del>50</del>	1 1/2", 2 <del>1/2</del> 1", 12. 2 1/2", 8. 2"		"	"	
	<del>8. 1"</del> 8. 3/4 screws.		1	1	
	8. 3 x 3/8 bolts			10	
	10.6 of 4 x 2 stud in stable	1 1/4	1	1	
	4 lbs. nails	2	"	8	
	3.6 of 3 1/2 x 3/4 deal		"	2	
	10.0 of 9" feather edge	1 3/4	1	5 1/2	
	1 doz. copper clouts		"	1	
	15.3 of 4 x 2 deal	1 1/4	1	7	
	1 pane glass 9 1/4 x 10 1/2 garden W.C.			2	
	3.0 of 3 x 1 for sill oak			2	
	6.0 of 6 1/2 x 1 pales	1 3/4	"	10 1/2	
	4.0 of 3 x 2 rails	1	"	4	
	carried forward	£	23	14	4 1/2

1903

£ s d

	amt. brok. forwd.		23	14	4½
	7'3 of 1x9 netting frames for Kitchen	2¾		1	8
	2 iron buttons, 2 iron knobs			"	4
	10'0 of 1½x½ stop for kitchen window			"	3
	3 yds. of 3'0 x ¾ mesh netting	}		"	"
	3 yds of 2'0 x ¾ do.			"	"
	staples			2	1
	24½ lbs. paint	6		12	3
	4½ lbs. putty	1½		"	6
July	6 1 man 9 hrs. painting			4	6
	7 1 man 3½ hrs. do.			1	9
	" 1 man 4 hrs. fix netting frames, & gate & door stays			"	"
	3 hooks & 6 staples for doors & gates			1	8
	4½ lbs. paint	6		1	0
	15. 2" screws for frames			<del>6</del>	3
	2 padlocks			3	0
			£	25	7 4½

Paid September 8<sup>th</sup> 1903

Mr. Charles Stamp, Butcher

L o a

1903

Feb. 12	making whippletree, 1 staple		. 9
24	5.0 of 1x11 for ironing board planing		1 9
Mar. 2	1 man + 1 lad 1 day ea. make 3 sash frames + sashes		6 2
3	1 man + 1 lad 1 day ea.	do	6 2
4	1 man + 1 lad 1 day ea.	do.	6 2
5	1 man + 1 lad 1 day ea.	do.	6 2
6	1 man + 1 lad 1 day ea.	do.	6 2
7	1 man + 1 lad 1 day ea.	do.	6 2
9	1 man + 1 lad 6 1/2 hrs. ea.	do.	4 7 1/2
	36.0 of glass	3 5/8	9 0
	6 1/2 lbs. putty	1 1/2	. 10
	19.3 of 9x1 deal	2 3/4	4 5
	13.6 of 11x1 "	3	3 4 1/2
	13.3 of 9x 1/2 "	3 3/4	. "
	13.6 of 11x 3/8 backs		. "
	4.0 of 9x 3/8 slips	30.9	4 5 1/2
	12.0 of 5 1/2 x 3 sills	4 1/2	4 6
	48.0 of 3/4 bead	4-	2 0
	32.0 of 1x 3/8 parting slips	3/6	1 1 1/2
	2.0 of 4x2 blocks	1 1/4	. 2 1/2
	12 sash pulleys, 2 doz. 3/4 screws		2 6
	1 lb. nails	2	. 2
	16.0 of 9x 1 1/2	3 1/2	4 8
	4.6 of 9x1	2 3/4	1 0 1/2
	2 lbs. priming	6	1 0
	To making 12 sash weights		5 0
	12 cords	1 1/2	1 6
	3 brass sash fasteners + screws		2 0
	2 doz. clouts	(1 1/4 = 9.7)	2
	To making 3 fasteners + sashes glazed + hung complete 3.9 x 4.10 ea. = 54.0		5 8 6
	carried over	£	5 11 0
			5 " 0

1903

15 11 0  
£ s d

			£	s	d
		amount brok. over	5	11	0
Mar.	16	1 man $\frac{1}{2}$ day fix frames		1	10
	17	1 man 2 hrs. make soilboards 1 <sup>st</sup>		..	10
	18	1 man 6 $\frac{1}{2}$ hrs. fix & hang sashes		2	8 $\frac{1}{2}$
	19	1 man 2 hrs. fixing frame		..	10
	20	1 man 8 hrs. fixing frames & sashes spit up brackets & rollers		3	4
	21	1 man 3 hrs. fix soilboards		1	3
		12.9 of 7x1 soilboards	1 $\frac{3}{4}$		19 $\frac{1}{2}$
		11.6 of galv'd: hoop iron	1		11 $\frac{1}{2}$
		1 lb. red lead	4		4
		3.6 of 4x2 $\frac{1}{2}$ turning piece	1 $\frac{1}{2}$		5 $\frac{1}{2}$
		4.0 of 3x2 bearers	1		4
		1 doz. screws for roller brackets		..	1 $\frac{1}{2}$
	24	1 man 4 hrs. paint windows		1	8
	25	1 man 7 $\frac{1}{2}$ hrs. do.		3	1 $\frac{1}{2}$
	26	1 man 4 $\frac{1}{2}$ hrs. do.		1	10 $\frac{1}{2}$
		3 qlbs. paint	6		46
		putty		..	1 $\frac{1}{2}$
	28	17 $\frac{3}{4}$ lbs. paint	6		810 $\frac{1}{2}$
	30	9 lbs. paint	6		46
April	16	1 man 1 day paint windows		3	8
	17	1 man 7 $\frac{1}{2}$ hrs. do.		3	1 $\frac{1}{2}$
June	2	putting on a new hinge on door		..	6
May	28	1 $\frac{1}{2}$ pint. Linseed Oil		..	9 $\frac{1}{2}$
			£	7	184 $\frac{1}{2}$

Paid July 29<sup>th</sup> 1903

7184 $\frac{1}{2}$

1903

Mr. Robert Channon

£ s d

		To acc. rendered (page 251)	£	s	d
			1	4	0
Jan	5	4 shoes		2	4
	20	2 staples, 1 hand pin iron		"	4
	29	wedges for scythe		"	3
Feb.	5	2 shoes		1	2
	12	2 shoes		1	2
	23	2 shoes		1	2
	"	3 hooks & 2 twist		1	4
Mar.	3	1 man $\frac{1}{4}$ day make barrow wheel	-	-	-
	4	1 man 1 day do.		3	8
	5	1 man 2 hrs. do.		"	9 $\frac{1}{2}$
		1 tyre 7 lbs		1	9
		1 axle		"	3
		spokes, felloes & stock		-	-
	12	4 shoes		2	4
	28	riveting pick stem		"	2
Apr.	1	2 shoes		1	2
	"	2 staples		"	3
	4	1 shoe		"	7
	9	make new eye for twobill		1	6
	11	2 shoes		1	2
	14	2 shoes		1	2
	23	1. K3 share		"	7 $\frac{1}{2}$
May	2	2 shoes		1	2
	"	repair twobill		"	2
	16	4 shoes		2	4
June	11	4 shoes		2	4
	12	2 seat board irons & fixing		2	1
	16	2 shoes		1	2
	26	setting scythe		"	3

forward to page 334  $\frac{1}{2}$  2 17 8 $\frac{1}{2}$

Mr. John Dew

1903

£ s d

Jan.	2	1 man 8 hrs. repair waggon		32
	3	1 man 1 day do.		38
	5	1 man 1 day do.		38
	6	1 man 4 hrs. do.		17
		1. 4 x 3/8, 4. 3 1/2 x 3/8 bolts		6 1/2
		6. 10 x 1/2 bolts		13
		3 keys		4 1/2
		8' 0" of 6 x 3 ash for 2 sweeps	6	40
		4' 6" of 6 x 3 1/4 ash for front sweeps	6 1/2	25
		paint		4
			<del>£1.1.0.</del>	24
	9	4 shoes		6
	15	1 eye & crook for cart		16
Feb.	16	new spreader <sup>3 hrs</sup>		9
	26	rusting spade put in handle		12
Mar.	13	2 shoes		24 1/2
	14	1 man 6 hrs. boxing cart wheel		2
		1 key		10
	20	screwing long bolt + 4 7/8 nuts		12
April	3	2 shoes		6
	7	make 2 plates own iron		12
	23	2 shoes		3
	27	1 staple & sharp 1 large one		4
May	16	2 new nuts & screw drag line		7 1/2
June	2	1. 114 share		12
	4	2 shoes		12
	8	2 shoes		8
	19	sharp 2 scuffle knives		2
		2 small S		3
	23	put in pick stem		

carried to page 332 ~~£ 116 7~~

1181

Mr. John Bastin.

1903

£ s d

Jan.	3	1 shoe			6
	10	3 shoes			16
Mar.	26	1 shoe & fasten 2			8
Apr.	20	1 shoe			6
	27	1 man 2 1/2 hrs. put bottom to mawn			10
		2.6 of 2 x 3 1/2 elm	} 1 1/2		6
		2.0 of 2 x 1 1/2 "			
		nails			2
May	4	2 shoes			8
May	9	repairs withy skinner			6
June	22	2 removes			20
	27	4 shoes			10
Aug	31	2 shoes			6
Sep.	7	1 shoe			3
	15	fitting lamp socket-			6
Oct	30	1 shoe			10
Nov.	7	2 shoes			41
	20	1 man 1 day 1 hr. repairing door			38
	21	1 man 1 day hang door			9
		7.3 of 3/4 match	1 1/4		9
		9.0 of 3/4 x 7 floor	1		9
		5.0 of 9 x 1 1/2 deal	3 3/4		17
		3.3 of 11 x 1 "	3		10
		nails 10 1/2 lb. paint			4
Dec.	23	repairing stove 3 hrs & 4 screws			110
	24	1 plate			6
	30	1 shoe			

£ 168

Paid Feb 23<sup>rd</sup> 1904



1903 Messrs. Ware &amp; Sons.

£ s d

Jan	5	1 man 2 hrs. <sup>preparing</sup> <del>put out</del> elm plank			9½
		15.0 of 13" x 1½ elm	4		50
		7.6 of 14" x 1½ elm	4½		210
	5	1 man 4½ hrs. make plunger (stopper)			19½
		1.9 of 5" x 5" elm plunger	5		8½
		8.0 of 1½" x 1½" stem "	½		.. 4
	19	one old Bell Rope 75 ft.			20
* May	16	1 hr. cut out elm plank			" "
		9.0 of 11" x 3½ elm	9½		57½
	26	1 man 6 hrs. make hanging door			24½
	27	1 man 1 hr. do			.. 5
		41.9 of 7" x ¾" match	1¼		44
		7.3 of 9" x 1" ledges	2¾		18
		3.6 of 7" x 1" do.	1½		.. 5
		nails 1.0 9. 1½" screws 1½			.. 2½
		2 twists for door			18
* Mar	13	put handles on skin knife			13

£ 1 11 5.

Settled October 8<sup>th</sup> 1903

1903 Mr. Henry Ware.

		£	s	d
May 21	2 men 7½ hrs ea. painting bedroom	6	0	
23	1 man 8½ hrs. e do. do.	3	4½	
25	1 man 5 hrs. do. do.	2	0	
..	1 man 1 day, papering do.	3	8	
26	1 man 3½ hrs. put on lock	1	5	
	1, 2" butt hinge screws }		2	
	12, 1" screws }		1½	
	1. 6 rim lock handles, brace	2	9	
	2 brass turnbuckles		9	
	putty, 1, ½ lbs. size, 4. paste 6		11	
	11 lbs. paint	5	6	
June 13	1 man 6 hrs. painting bedroom	2	4½	
15	1 man 8½ hrs. do. r			
	putting in sash cord	3	4½	
16	1 man 1 day, paper room	3	8	
18	1 man 2½ hrs. do.	1	0	
	1 sash cord, 2, 1" screws		4½	
	1 bucket paste		6	
	5½ lbs. paint	2	9	
	½ lb. size, putty 1		5½	
		£	2	1
				2.

Settled October 8<sup>th</sup> 1903

1903 Mr. James Glanville Rydon

£ s d

		To balance due on a/c rendered	2	2	8
Feb.	12	6 stroke nails & putting on			6
	19	1 man 1 day hanging gates			3 8
	20	1 man 1 day do.			3 8
	21	1 man 1 day do.			3 8
		repairing gate irons, hooks & thrust			1 6
		new gate iron			3 4
		2 doz. gate nails, 6, 4 x 3/8 bolts &			" "
		repair gate ironwork. 1 staple			2 0
Mar.	25	binding wheel			2 8
June	19	1 man 6 hrs. ring barrow wheel			2 4 1/2
		wheelbarrow tyre			1 9
		felloes & paint			1 1 1/2
	26	1 man 4 hrs. put in pick stems			1 4
		5 hay pick stems			3 2
	27	1 man 1 1/2 hrs. put hinge on window			4
		1. 2 1/2" butt. hinge & screws			3

£ 3 14 4

1903

Mr. Henry Pile. Bagmoor Farm.

£ s d

To account rendered~~3 5 41~~

Feb. 9	1 man 4½ hrs. repair trap	1 10
	3:0 of ½" x 5" elm dash board	2
	paint + bolts	" 3
	1 plate + 2 rivets	" 4
12	2½ hrs. making 2 drafts	1 0
"	2 large staples	6

£ 3 10 0Received £ 3.5.11 August 1<sup>st</sup> 1903

4 1

Received the <sup>s d</sup> 4.1 August 12<sup>th</sup> 1903

Mr. James George,

1903

£ s d

Feb.	21	2 shoes			10
	28	2 shoes		10	10
June	4	1 shoe			6
	10	1 shoe			6
	22	binding two trap wheels			40
			£		70

Paid August 19<sup>th</sup> 1903

1903 Mr. Henry Glanville.

£ s d

		acc. rendered		1	7	0
Jan.	2	2 shoes			1	2
	5	1 man 4 hrs. repair cart, put in new front & tail boards				
					1	7
	7	1 man 1 day do			3	8
	8	1 man 1 day do			3	8
	9	1 man 4 hrs. do			1	7
		4.3 of 3 1/4 x 2 1/4 ash	2 1/2			10 1/2
		4.3 of 2 x 3 ash	1 3/4			7 1/2
		3.6 of 1 x 11 elm	2 1/2			" "
		4.0 of 1 x 12 elm	2 1/2		1	5 1/2
		15.0 of 1 x 9 elm	2		2	6
		2. 3 1/2 x 3 1/8 bolts, 1 lb. nails.				4 1/2
		1 lb. paint				6
		12 rivets for cart				6
		6 rivets, alter tail irons				6
	9	1 man 4 1/2 hrs. make new barrow & singing barrow wheel				19 1/2
	10	1 man 1 day do			3	8
	12	1 man 1 day do			3	8
	13	1 man 1 day do			3	8
	16	1 man 2 1/2 hrs. do			1	0
		timber for barrow				" "
		felloes for " wheel	17 1/2		2	0
		paint				8 1/2
		put tyre on wheel				6
	28	2 shoes & 2 removes			1	9
Feb.	9	2 shoes			1	2
	16	1 new plate & 2 bolts for hanger of cart & fix do.				13
Mar.	2	1 man 1 day felloeing waggon wheel			3	8
		1 man 4 1/2 hrs. do			1	9 1/2
		carried forward			3	72

1903

£ s d

		amt. brought forward.		3	7	2
		paint for wheel				1
		new tyre <u>45 lbs.</u>	16 <sup>0</sup> / <sub>6</sub>		10	4
			-----			2 <sup>3</sup> / <sub>4</sub>
Mar.	4	2 shoes			1	2
	28	2 shoes			1	2
Apr.	4	lying coultter			1	6
	30	2 shoes			1	2
May	11	1 man 2 hrs. hang gate				9 <sup>0</sup> / <sub>2</sub>
		2. 3 <sup>1</sup> / <sub>2</sub> x 3 <sup>3</sup> / <sub>8</sub> bolts				2
		1 clip for twist of gate & sharpen eye				6
	18	4 shoes			2	4
	22	2 shoes			1	2
June	9	putting 2 ends to pigs trough				6
	10	repair spindle of pump				10
	12	1 man 5 <sup>1</sup> / <sub>2</sub> hrs. ring wheel			2	2
	13	1 man 1 day do.			3	8
	15	1 man 1 <sup>1</sup> / <sub>2</sub> hrs. do.				7
	18	1 man 5 hrs. do.			2	0
	23	1 man 1 <sup>1</sup> / <sub>2</sub> hrs. do.				7
	24	1 man 1 hr. do.				5
		spokes				
		paint				8
		new tyre <u>65 lbs.</u>	£ 1-5-0		14	11
				2 <sup>3</sup> / <sub>4</sub>		
		new staple & crook hays for wheel				4
	16	lying 2 horse hoe knives & 1 foot			3	3
	29	2 removes				7
carried to page 335				£	6	4 1 <sup>1</sup> / <sub>2</sub>

Aug. 5-03.

Mr. Matthias Hearn

1903

£ s d

Mar. 5	1 man $\frac{3}{4}$ day new felloe 3 wheels		2	9
6	1 man $7\frac{1}{2}$ hrs.	do.	2	10
9	1 man 1 day	do.	3	8
10	1 man 1 day	do.	3	8
11	1 man $3\frac{1}{2}$ hrs.	do.	1	5
12	1 man $6\frac{1}{2}$ hrs. paint 3 wheels		2	8
13	1 man $2\frac{1}{2}$ hrs.	do.	1	0
14	1 man $2\frac{1}{2}$ hrs.	do.	1	0
	18 new ash felloes	4	6	0
	3 spokes	3		9
	paint			9
	3 new tyres <u>54</u> lbs. at 3 <sup>0</sup>		13	6

£ 2 0 0

Paid August 10<sup>th</sup> 1903



Aug. 5. 03.

1903 Mr. Alfred Stokes.

£ s d

May	19	1 man 1 hr. make wheel for cart			5
	20	1 man 1 day do.			3 8
	21	1 man 1 day 2 hrs. do.			4 5½
	22	1 man 1 day 2 hrs. do.			4 5½
	23	1 man 6 hrs. do.			2 4½
		binding wheel			2 6
	25	1 man 7 hrs. do.			2 9½
	27	1 man 1 hr. do.			5
		1 stock 4 put-on rings			1 9
		14 spokes	4		4 8
		4 ash felloes	£ 1.12.0	4	4 1
		2 lbs. paint			7 0
	29	1 man 1 day papering			3 8
	30	1 man 1 day do.			3 8
		6 pieces paper at 8			3 0
		2 do. at 8			1 4
		1 bucket paste			6
June	2	2 lbs. red lead paint			10

£ 252

Paid August 18<sup>th</sup> 1903

Mr. G. P. Shell, Globe Inn

1903.

£ s d

Feb. 16	1 man 8 hrs. repair skids			3 4
	9' 0" of 3 1/2" x 2 1/2" elm for skids	1 3/4		1 4
	8. 1" screws	5/6		2
	2 plate nails for skids			8
16	1 man 8 hrs. repair frame of drags			3 4
	9' 0" of 3 1/2" x 3" elm	2 1/4		1 8 1/2
	5' 0" of 3 x 1 "	3/4		4
	2. 3 x 3/8" bolts			3
	paint			3
	lying 26 drag lines	4 1/2		8 8
	4 new lines	17 1/6		2 0
	1 ring 2 bolts & 2 keys for drags			1 0
24	1 man 5 1/2 hrs. repair wheelbarrow			2 3 1/2
	6' 6" of 4 x 2" elm	3/6	1 1/2	10
	nails & paint			4 1/2
ap. 3	1 man 2 1/2 hrs. hang door & make whipple tree			1 0
	new part to twist of door			1 4
	1 staple for whipple tree			3
	whipple tree			6

£ 197

Paid Sept 27<sup>th</sup> 1903

Aug. 1. 03.  
Jan. 4. 04

Miss Stogdon, Exton

1903

May 27	1 man 8 hrs. make mantelpiece for S. Burdens		3 2
28	1 man 2 1/2 hrs. fix & paint do. 18.6 of 7x1 floor 1 1/2 lbs. paint nails	1 1/2	1 0 2 3 " 9 " 1
	to ap. rendered		27 3
Oct. 23	1 man 1/2 day repair roofs at S. Burdens		1 10
24	1 man 1/2 day do.		1 10
	88.0 of 2x1 batten		2 8
	10.0 of 4 1/2 x 3 deal		2 9
	22.0 of 3x2 rafter		1 10
	3 lbs. nails		.. 6
		£	18 8

Paid May 20<sup>th</sup> 1904

Rev. Godfrey Bird.

1903

			£	s	d
Jan.	1	4 removes 2 leathers	2	2	
28	5	repair coal scuttle	1	2	
	15	1 square staple	..	3	
	28	1 man 2 hrs. make fowls cover frame		10	
	29	1 man 2 1/2 hrs. do.	1	0 1/2	
	30	1 man 1 1/2 hrs. do.		4 1/2	
		7.0 of 8 x 1 1/4	3	1	4
		18- 1" round headed screws		1 1/2	
		paint	..	2 1/2	
Feb.	10	4 shoes	2	0	
		1 man 2 1/2 hrs. repair floor in bedroom make bath for bed	1	0 1/2	
		1.6 of 5 x 1 deal		1 1/2	
		6.0 of 1 1/2 x 1/2 "		2	
		nails	..	1	
C	14	<del>4</del> new part-10 Dutch hoe		7	
	21	fitting 2 roller castors	..	4	
Mar.	12	4 removes	1	2	
	14	3 small S	..	2	
	20	repair bottom of grate	..	9	
Apr.	17	4 removes & 2 leathers	2	2	
	29	1 man 3 hrs. fix leg to chair, ease front door fix lock to hall door new spring to lock	1	8	
		1 turned leg & screw for bed chair		8	
			1	0	
May	18	4 shoes	2	0	
	30	1 roller bracket & plate	..	10	
June	16	4 removes		12	
			£	1	3
			£	3	

Aug. 5.03.

1903 Mr. Fred Stamp, Butcher

June	9	1 man 3 hrs. make pigs trough		1	3
		9' 0" of 9 x 1 1/2 elm		1	6
		1 1/2 lbs. nails	3/0		3
	17	1 man 3 hrs. make pigs trough		1	3
		13' 6" of 7 x 1 elm		1	1
		1 lb. nails	2/6		2

---

£ 5 6

---

Paid. Aug. 18. 1903

1903 Mrs. Langdon Fulford. The Priory.

		£	p	d
April 29	1 man 1½ hrs. repair lock of bedroom door 1 spring			10
28	pumping out well			20
Aug 6	repair looking glass tray			6
19	1 man 2 hrs. repair fascia board of house			10
Dec. 7	3 lbs. spikes for weir in garden			10
	5 ripped Oak stakes, 3" dia.			18
	1 piece elm 10" 6 long 1 1/2" 9"			50
	chopping stakes boring holes			6
15	to putting new boiler in Kitchen as per contract	2	2	6
16	time fitting new bottom bars front bars and fire cheek			48
	new bottom bars. front bars & cheek			59
18	repair handle of bedroom door & 1 screw			6
23	½ hrs. repairing two chairs			9
28	new plate to side of grate. 2 screws fixing			20

£ 3 8 8

Paid February 5<sup>th</sup> 1904

less £1.7.6 for Rent of Garden.

Aug. 5. 03.

## W-Josias Down

1903				
Jan	12	5 <sup>3</sup> / <sub>4</sub> <sup>lbs</sup> - Paint		2 10 <sup>1</sup> / <sub>2</sub>
		1 sheet glass paper		<sup>1</sup> / <sub>2</sub>
1902 Dec	22	1 man 1 day paper parlour		3 8
1903 Nov.	7	2 sash cords	⌋	<del>2 11</del>
Dec	5	1 do.		.. 3
	7	4 do.		1 0
			⌋	8 4

Paid February 6<sup>th</sup> 1904

The churchwardens of Horison blyot

1903

June 4 <sup>th</sup> & 5 <sup>th</sup>	For repairs to the Bells & Bell Frame	3 0 0
---	---------------------------------------	-------

Paid July 30<sup>th</sup> 1903



July 27<sup>th</sup>/03

H. Sellwood Geop. - Bullington

1903

Jaws	21	2 <sup>3</sup> / <sub>4</sub> <sup>lbs</sup> - chime cord	32
		9 ft - tubing	46
			<hr/>
			78

Paid Oct-7<sup>th</sup> 1903

Rec'd A. V. Cox, Stockland

1903

Jan <sup>ry</sup>	29	8 <sup>3</sup> / <sub>4</sub> <sup>lbs</sup> - chime cord Parcel Post	od 1-2	10.3	11
				11.2	

Settled October 9<sup>th</sup> 1903

July 31<sup>st</sup> 1903

1903		Greenleaf & Triolram Grove Road. Hereford		£	s	d
July	21	1-	5-0 - Bell Wheel	1	2	6
		1-	5-2 do	1	3	6
		1-	5-4 do	1	4	6
		1-	5-6 do	1	5	6
		1-	5-9 do	1	6	6
		1-	6-1 do	1	8	0
	24	1-	4-9 do	1	2	6
				£	8	13 0
Carriage to G. W. Rail. Exeter by conveyance P. & O. instead of to Woodbury R. & L. W. Rail						3 6
				£	8	16 6

Paid August 12<sup>th</sup> 1903

W. E. Munday

1903

In the Twatou Society of Ringers

May 25 <sup>14</sup>	2 men 36 hours each at Twatou over			
to 27	hauling the St. Peter's 8 bells		1	19 8
"	2 mens fares to Twatou & back		3	6 )
	Lodgings		4	0
	Oil			2
	Self to Twatou & back		12	0
			<hr/>	
			3	2 10

Paid March 16<sup>th</sup> 1904

## The Churchwardens of Stoke Gabriel

1903			
April	1 <sup>st</sup>	2 mens time 8½ hrs each 17 hrs at ½ <sup>d</sup>	10 3
		Alter Staple of Bell	. 6
		Trap here out & back	5 0
			15 9
May	30	1 mans time, 23½ hrs <sup>unchanging Bell and</sup> taking off head from Bell and drilling holes through her and hanging her again	13 9
		Trap to W. R. twice with chain blocks	2 6
		W. R. to Exeter & back	1 2
		lab at Exeter twice	2 0
		Exeter to Prigaton & back	4 6
		Smith for bolts	4 6
		Lodgings	. 6
			<hr/> 1 9 0
			15 9
			<hr/> 2 4 9

Paid January 16<sup>th</sup> 1904

Aug 5<sup>th</sup> 1903  
6427 103Rev<sup>d</sup> W. T. Wellacott  
Bradwenty

1903

June 29

Mans train fare to Holowenty & back  
Conveyance to Bradwenty from Holowenty

8 10

5 0

---

13 10Paid Novembe 13<sup>th</sup> 1903

Mr. Wm. Summerfield

1903

£ s d

		To balance due on acc. rendered		50	14	8½
		" <del>Perry building</del>		<del>3</del>	<del>12</del>	<del>0</del>
		<del>To acc. due on Mr. S. Lindsey, house</del>		<del>9</del>	<del>19</del>	<del>4½</del>
Jan.	13	For work done at Lackington, Farm. Withycombe Raleigh as per contract of Dec. 12. 1902.		2	15	0
Jan.	15	34.0 of 1x7 floor board	15	3	6½	
Feb.	2	4 shoes		2	0	
Mar.	9	1 man 1½ hrs. put in lintel repair cupboard at Mr. Northcotes				9½
	10	1 man 1 day repair cupboard do.				
	12	1 man 1½ hrs. paint do. do.				
	13	1 man 1½ hrs. paint do. do.				
		24.0 of 2x1 batten				
		8.6 of 9x3 lintel	6½	4	7½	
		75.0 of 5½x¾ match for cupboard				
		9.0 of ¾x9 deal for repairing cupboard				
		9.0 of ¾x7 new shelves re at Mr Northcotes. as per estimate of Jan. 27. 1903				
		2 lbs. nails		14	6	
	12	1 man 1½ hrs. repair door at Miss Kenwoods				7
		1 pair 16" Tee Hinges + 18 screws				10
	11	2 pipe holdfasts				9
	18	sharp iron bar				2
		4 shoes		2	0	
		1 load brick from Otterton to Hitchcocks				40
	19	1 load brick do do.		4	0	
	20	1 load brick from Exmouth to Shed.		3	0	
	21	1 load brick from Otterton to Hitchcocks		4	0	
		sharp 2 hammers + 1 bar				4
	24	1 load brick from Otterton to Hitchcocks		4	0	
	25	binding cart wheel		2	6	
		carried forward	£	56	14	

1903

£ o d

	amt. brok. forward	56	1	4
Mar. 25	1 load squares <del>from</del> tiles from Otterton to shed		..	..
			4	0
29	1. 6" length of 4 1/2" shuting red lead		1	9
			..	2
April 2	New pair of stairs at Mr. Wheaton as per estimate of Jan. 27. 1903		..	..
		3	0	0
<del>Apr</del> 20	2 load brick from Exmouth to <del>Otterton</del> <sup>Boston</sup>		6	0
23	1 load brick from Exmouth to Sanctuary		4	6
May 2	make turning bar		..	8
12	4 shoes		2	0
23	For putting on roof + new doors at Sanctuary Farm. as per estimate of Nov. 22. 1902		..	..
		31	14	0
June 9	binding cart wheel		2	6
	1 plate + 3 rivets for wheel		..	6
	putting 2 blocks in wheels		1	0
16	4 shoes		2	0
20	sharp hammer		..	1

£ 92 0 6

105 11 19

December 23<sup>rd</sup> 1903 Received on account - £20 =

20 0 0

to page 344 balance due

£ 72 0 6



Mr. C. Summerfield.

1903

£ p d

Apr. 25	1 man 2 hrs varnish chair 10. 2" black head screws varnish	}	16
---------	--	---	----

Paid - Jan. 5<sup>th</sup> 1904.

# The Vicar & Churchwardens of Calmstock

1903 April to August	20 <sup>th</sup> 13		£	s	d
		For lowering down the 6 Bells in Calmstock Church Tower, taking out the old fittings and frame, and providing and fixing in the Tower, a new iron cage <sup>for the 6 Bells</sup> and hoisting and hanging the 6 Bells with all new fittings complete, according to specification and estimate of February 26 <sup>th</sup> 1902	140	18	0
		For taking out the old beams from the Tower and providing and fixing new Oak beams, and a new floor, according to estimate of February 26 <sup>th</sup> 1902	28	14	0
			£	169	12 0

September 3<sup>rd</sup> 1903 Received on account - £120 =

do - 10<sup>th</sup> 1903 Received on account - £25 =

February 4<sup>th</sup> 1904 Received the balance of £24 = 12/

Sept 10<sup>th</sup>

W<sup>c</sup> Hanning

1903

£ s d

August 23

For making a coffin for his son the late W<sup>c</sup> John Hanning

2 7 0

Paid Sept 12<sup>th</sup> 1903  
less 4-

Recd of L Hulford

1903

Sept 8 <sup>th</sup>	For making and fixing a New Lych	£ 0 1
-	Gate to Woodbury Churchyard according	" " "
	to plans & specification by Rev. R. M. Hulford	" " "
	and according to estimate of January 9 <sup>th</sup> 1903	58 18 0

Received by Cheque Sept 9<sup>th</sup> 1903

Jan 4<sup>th</sup> 1904

Rev. R. C. W. Atkins

1903

Sept<sup>r</sup> 4<sup>th</sup> For taking down the 1<sup>st</sup> Bell from  
Rame Church Tower, and recasting her,  
and taking down the other 2 Bells, and  
taking out the old woodwork &c from Tower  
Providing and fixing in the Tower new  
oak Framework for the 3 Bells, and  
hoisting and hanging the Bells in the  
Tower with all new fittings complete  
according to estimates of October 24<sup>th</sup> 1901  
and February 23<sup>rd</sup> 1903.

£. 0 0

46 15 0

extra to putting in new floor close under the bells

15 0

£ 44 10 0

September 12<sup>th</sup> 1903 Received on account £55 =

January 29. 1904. Received the balance  
£ 22-10-0.

Rev<sup>d</sup> C R de Benfat

Browan. Vicarage. Camborne

1903

August 15 <sup>th</sup>	For providing and fixing the Ellacombe chiming apparatus to the 6 Bells in Browan Church Tower, according to estimate of April 30 <sup>th</sup> 1903 and amended estimate of May 11 <sup>th</sup> 1903	£	0	0
		"	"	"
		"	"	"
		"	"	"
		9	0	0

Paid Sept<sup>r</sup> 22<sup>nd</sup> 1903

Dec. 30. 02

Oct 7<sup>th</sup> 1903.

March 31<sup>st</sup> 1904

July 1<sup>st</sup> 1904

W. C. Knowles

Cluncharaden, Kingsteigton

£ s d

1903

Sept 26 <sup>th</sup>	For 6 Bell Ropes each 60 ft long for Kingsteigton Cluncharaden at 11 <sup>0</sup> / <sub>6</sub> per rope	3	6	6
-----------------------	--	---	---	---

Paid August 22<sup>nd</sup> 1904

Oct-7<sup>th</sup> 1903  
D.L. 10. 03

Mr. Jonas Bromfield  
Churchwarden Upottery

£ 0 d

1903  
August 28

For 4 Bell Ropes for the 2<sup>nd</sup> 3<sup>rd</sup> 5<sup>th</sup>  
& Ten Bells in Upottery Church Tower at 14/-

" " "  
2 4 0

Settled January 19<sup>th</sup> 1904