

		found		4	3	10 $\frac{1}{2}$
July	30	2 $\frac{1}{2}$ hrs.				13
Aug	7	4 $\frac{1}{2}$ hrs.				23
	9	1 hr.				6
		put in name		4	8	4 $\frac{1}{2}$
July	6	2 hrs. repair ironwork				10
	7	7 $\frac{1}{2}$ hrs. do.				39
	8	9 hrs. do.				46
	9	3 hrs. do.	1-4-9			16
	10	1 $\frac{1}{2}$ hrs. do.	2-17-6			9
		14 lbs. new iron	1-5-7 $\frac{1}{2}$			37 $\frac{1}{2}$
	12	2 hrs.	<u>1-5-7</u>			10
	13	2 hrs.	<u>10<math>\frac{1}{2}</math></u>			10
	16	6 hrs.		1-5-7 $\frac{1}{2}$		30
		new iron plus.		<u>1-5-9-6</u>		10
July	27	9 $\frac{1}{2}$ hrs. repair lades & put plates on shafts + paint to shafts				49
	29	1 $\frac{1}{2}$ hrs. paint wheels				9
	30	3 $\frac{1}{2}$ hrs. paint wheels & shafts				19
Aug	7	2 hrs. paint lades & side boards				10
		5 hrs. do. do.				33
		6 lbs. paint wheel, shafts, lades & do.				7 $\frac{1}{2}$
		3.0 of 3+2 ash points to shafts				7 $\frac{1}{2}$
		7-6 of 2x1 ash lades				20
		2 plates of iron for shafts & lbs.				4
		4 bolts				60
		tyring 2 wheels				6
		cut & shoot stock board		7	1-2-5	6

Aug 9 ~~Leach~~  
 Monday Tolman. 10 hrs. painting shed Mr. C-Davy  
 Tolman. 1 1/2 hrs. put wheels on cart Mr. H. Pile  
 " 4 1/2 hrs. ring cart wheels Mr. T. Glanville  
 " 3 1/2 hrs. put side boards to cart Self  
 X Coles. 9 1/2 hrs. painting at Webbers Farm  
 W Radford, 9 1/2 hrs. clean out and white  
 wash coach house Broadway House  
 Self 1/2 hr. prepare for Farringdon School  
 " 1 hr. about side boards for cart Self  
 " 10 station for Mother R

10 Tuesday Tolman. 3 hrs. put side boards to cart Self  
 " 6 1/2 hrs. ring cart wheels Mr. T. Glanville  
 X Coles. 9 1/2 hrs. alter door Farringdon School (cont.)  
 X Leach. 9 1/2 hrs. do. do.  
 X Rdavey, 9 1/2 hrs. coloring at Webbers Farm  
 + W Radford, 9 1/2 hrs. do. do.  
 Self 3 hrs. at Farringdon School  
 at accounts R

+ 11 Wednesday Tolman. 9 1/2 hrs. ring wheels Mr. T. Glanville  
 Coles. 9 1/2 hrs. contract Farringdon School  
 X Leach. 9 1/2 hrs. do. do.  
 Rdavey, 9 1/2 hrs. put down floor & top in  
 jambs (contract), Farringdon School  
 X W Radford. 9 1/2 hrs. take off top of wall &  
 " picking stones Mr. C-Davy Dr. Stokes  
 Self all work

12 Thursday Tolman. ~~4~~ 4 1/2 hrs. repair cart & harness Self  
 " 5 hrs. ring wheels Mr. T. Glanville  
 X Coles. 9 1/2 hrs. painting at Webbers Farm  
 Leach. 4 hrs. contract Farringdon School  
 " 2 1/2 hrs. repair door lock & hanging  
 windows at Farringdon School

Aug. 12 Leach, 3 hrs. repair windows Farringdon School  
 + RDavey, 3 hrs. coloring at Webbers Farm  
 + WRadford, 2 hrs. do.  
 + .. 7 1/2 hrs. put up orchard wall Mr. C. Davy  
 + RDavey, 6 1/2 hrs. do. do.  
 Self, 2 hrs. at Farringdon School (extra)  
 .. at Mr. Davy's about memorial  
 .. about pine for tent bottom etc.

Friday 13 Tolman, 2 hrs. get out coping boards for wall  
 for Mr. C. Davy  
 .. 1 hr. unload timber  
 + .. 4 hrs. ring wheels Mr. T. Glanville  
 + .. 4 hrs. put shafts on traps Mr. J. Hall  
 + Coles, 8 1/2 hrs. painting at Webbers Farm  
 .. 1 hr. unload timber  
 + Leach, 9 1/2 hrs. repair windows Farringdon School  
 + RDavey, 8 1/2 hrs. build wall Mr. C. Davy  
 + WRadford, 8 1/2 hrs. do. do.  
 Self at reeler etc.

Saturday 14 Tolman, 6 hrs. make tent bottom Mr. W. Abbott  
 Self, 4 hrs. do. do.  
 + Coles, 6 hrs. painting at Webbers Farm  
 + Leach, 2 hrs. repair windows Farringdon School  
 + .. 4 hrs. fix curtain poles Miss B. Martin  
 + Self, 1/2 hr. do.  
 + RDavey, 6 hrs. put up wall Mr. C. Davy's  
 + WRadford, 6 hrs. do.

Mr. J. Hall trap shafts	sent.	
2. 3 1/2 x 7/16 bolts		3
2. 1 1/2 screws		1
oil for wheels	3/-	3
time 4 hrs.		25

\$elf for cart wheel  
 4 spokes  
 12. 3½" ash fellows

Mr. T. Glanville - wheels

X 8-6 of 1¼ x 3" ash for 12 fellows  
 1 spoke

12 Mr. A. Stamp

4 cow boxes 4/3 ea

material in one box

X 7-3 of 12 x 1 elm } 1-8

1-10 x 1-10 x 1" elm } 9

2½ lbs. nails } 1-3

nails } 2½

Miss Edith Martin

5 white curtain poles & rings 6 3

X 1 brass portiere rod & brackets 2 3

2 doz. screws .. 6

10 extra brass rings 10

Mr. C. Davy Orchard wall

credit by 2½ lbs. stone color paint

1 load mortar

2 barrows do.

50 bricks

1 bag cement

1½ pecks do.

4 barrows sand 1/-

carting stone Dr. Stokes

X 16 Mr. W. Newton

re-leather pump sucker paid

20

Broadway House  
 1 bucket lime  
 1 barrow mortar

Farringdon School (contract)

3-0 of 3 1/2 x 1 oak pile

15-0 of 1 1/2 x 1/2 deal stop

70 bricks

1 barrow sand

1/2 pk. cement

3-4 of 2 x 3/4 deal gate pale

Horse Wagon deliver

Extras.

7. coat that pegs screens

1 drive in catch

Pony trap fetch windows

Aug. 16 Monday Tolman, 5 1/2 hrs. make tent bottom Mr. W. Abbott  
 .. 4 hrs. help smith about types

X Coles, 9 1/2 hrs. painting at Webbers Farm

X Leach, 7 1/2 hrs. repair, paint & glass casements  
 for Farringdon School

X .. 1/2 hr. remove chest for Miss E. Martin

X .. 1 1/2 hrs. re-leather pumpucker Mr. W. Newton

X R. Davey, 6 hrs. finish wall at Knoll Cottage

X W. Radford, 6 hrs. do. and tar

shed roof at Knoll Cottage

X Self, 5 1/2 hrs. make tent bottom Mr. W. Abbott

X .. 1/2 hr. remove chest Miss E. Martin

17 Tuesday Tolman, 8 1/2 hrs. help smith type wheels

X .. 1 hr. wash cast wheels Mr. T. Glanville

Coles, 1 1/2 hrs. help smith type wheels

X .. 8 hrs. painting at Webbers Farm

Self Workmen Compensation app

Aug 17 Leach, 6 hrs. hang casements, put up  
 " hat pegs r. Farningdon School  
 X " 3 1/2 hrs. put in glass r. do. Cottage

18 Wednesday Tolman, 3 1/2 hrs. clean off orn r Mr. T.  
 " Glauwills cart wheels  
 " 6 hrs. turning oats  
 + Coles, 9 1/2 hrs. painting Welbers Farm  
 + Leach, 9 1/2 hrs. do. do  
 \$elf 6 hrs. turning oats  
 " 2 hrs. fowlhouse Mr. W. Carter

19 Thursday Tolman, 5 hrs. clean off paint orn r  
 " Mr. T. Glauwills cart wheels  
 " 4 1/2 hrs. housing oats  
 + Coles, 9 1/2 hrs. painting Welbers Farm  
 + Leach, 9 1/2 hrs. do.  
 + RDavey, 5 hrs. repair plaster Welbers Farm  
 " 4 1/2 hrs. housing oats  
 W Radford, 4 1/2 hrs do  
 + " 4 1/2 hrs. clean windows Welbers Farm  
 \$elf housing oats  
 3 hrs. fowlhouse Mr. W. Carter

20 Friday Tolman, 6 hrs. repair cart put in new  
 " bottom Mr. T. Glauwills  
 " 4 hrs. housing wheat  
 + Coles, 6 hrs. painting Welbers Farm  
 + Leach, 6 hrs. do.  
 X RDavey, 2 1/2 hrs. coloring do.  
 " 3 1/2 hrs. housing wheat  
 W Radford, 3 1/2 hrs do.  
 " 5 hrs. take up potatoes in Garden  
 X " 1 hr. put in plants Mother  
 \$elf housing wheat  
 3 hrs. fowlhouse Mr. W. Carter

Aug 21 Tolman, 6 hrs. repair cart & paint wheel  
 Saturday Mr. T. Glanville

- + Coles, 6 hrs. painting at Webbers Farm
- + Leach, 6 hrs. do. do.
- + R Davey, 5 1/2 hrs. coloring do.
- + W Radford, 6 hrs. do.
- Self, 4 hrs. fowl house Mr. W. Carter

19 Mr. H. Rile

sharpen & cut saw

paid

9

4 screws

paid

1/2

Tent bottom

5 lbs. nails

335' 0" of 7x1 floor

Miss Martin

10 curtain rings ~~paid~~

H Leach

2 curtain pole ends

paid

4

Mr. C. Davy

2 lbs. Halls distemper white

2 1/2 pecks cement

2 gallons tar for shed

Farningdon School Windows extra

Pay & trap take up windows

3' 0" of 1 1/2 x 1 3/4 deal

2 lbs. putty

10. 1 1/2" screws

1 lb. paint

2 panes of glass for porch (contract)

Mr. T. Glanville's cart

4 lbs. of iron for plates

2.  $4 \times \frac{3}{8}$  bolts

1.  $2\frac{1}{2} \times \frac{3}{8}$  "

1.  $2 \times \frac{1}{4}$  "

1. 1" screws

1  $\frac{1}{2}$  lbs. nails

17.6 of  $12 \times 1$  elm bottom

5.0 of  $14 \times \frac{1}{2}$  " for sides

2 tyres 124 lbs

3  $\frac{1}{2}$  lbs paint for wheels

2 tail pins

Aug 23 Monday Tolman, 2 hrs. put on wheels on cart's  
Mr. T. Glanville & repair shop

" 1 hr. about own wheels

" 2  $\frac{1}{2}$  hrs. repair dash board of

" trap Mr. J. F. Glanville

" 3 hrs. clean car Col. Bolitho

+ Coles, 9  $\frac{1}{2}$  hrs. painting at Webbers Farm

+ Leach, 6 hrs. do. do.

X R. Davey, 9  $\frac{1}{2}$  hrs. take out doorway

" whiten color kitchen r. at Mother's house

Self at Topsham fetch lime r.

X " 4 hrs. clean motor car Col. Bolitho

24 Tuesday Tolman, 6  $\frac{1}{2}$  hrs. clean motor car Col. Bolitho

" 3 hrs. fowl house Mr. W. Carter

+ Coles, 9  $\frac{1}{2}$  hrs. painting at Webbers Farm

+ Leach, 6 hrs. do. do.

X R. Davey, 4  $\frac{1}{2}$  hrs. at Mother's house

+ " 5 hrs. coloring at Webbers Farm

+ W. Radford, 3  $\frac{1}{2}$  hrs. do. do.

X " 5  $\frac{1}{2}$  hrs. clean motor car Col. Bolitho

X Self, 5  $\frac{1}{2}$  hrs. do.

" 3 hrs. fowl house Mr. W. Carter



Aug. 25 Tolman, 9 $\frac{1}{2}$  hrs. painting car Col. Bolitho  
 Wednesday Self 9 $\frac{1}{2}$  hrs. do. do.  
 Coles, 1 hr. help about door post at Webbers Farm  
 + " 8 $\frac{1}{2}$  hrs. painting at Webbers Farm  
 + Leach, 6 hrs. do. do.  
 X R Davey, 9 $\frac{1}{2}$  hrs. coloring do.  
 + W Radford, 9 $\frac{1}{2}$  hrs. do. do.

26 Tolman, 6 hrs. paint motor car Col. Bolitho  
 Thursday " 3 $\frac{1}{2}$  hrs. fowlhouse Mr. W. Carter  
 X Coles, 9 $\frac{1}{2}$  hrs. painting at Webbers Farm  
 + Leach, 9 $\frac{1}{2}$  hrs. do. do.  
 R Davey, 9 $\frac{1}{2}$  hrs. concrete in post, repair  
 X " brickwork r. of steps Webbers Farm  
 + W Radford, 9 $\frac{1}{2}$  hrs. do. do.  
 X Self 6 hrs. paint motor car Col. Bolitho  
 " 3 $\frac{1}{2}$  hrs. fowlhouse Mr. W. Carter

27 Tolman, 9 $\frac{1}{2}$  hrs. fowl house Mr. W. Carter  
 Friday X Coles, 9 $\frac{1}{2}$  hrs. painting at Webbers Farm  
 + Leach, 4 hrs. do. do.  
 X " 2 hrs. clean off table for Mother  
 X R Davey, 9 $\frac{1}{2}$  hrs. repair plating r. Webbers Farm  
 + W Radford, 9 $\frac{1}{2}$  hrs. do. do.  
 X Self, 10 hrs. varnish motor car Col. Bolitho

28 Tolman, 2 hrs. repair change gate Thom Meadow  
 Saturday " 4 hrs. fowlhouse Mr. W. Carter  
 X Coles, 6 hrs. painting at Webbers Farm  
 X Leach, 1 $\frac{1}{2}$  hrs. fix curtain poles Miss B. Martin  
 X " 2 hrs. fix blinds r. at Mother's House  
 X " 2 hrs. painting at Webbers Farm  
 X R Davey, 6 hrs. repair manhole, roof r. do.  
 X W Radford, 6 hrs. do. do.  
 + Self 4 hrs. about car Col. Bolitho

Mr. J. F. Glanville for Crup

10.  $\frac{3}{4}$  screws

1 piece sheet iron  $8 \times 5$

Mrs. H Stokes Gen. at House

6 lbs. Halls white

7 lbs. do. buff

$\frac{1}{4}$  peck plaster

$\frac{1}{2}$  bucket mortar

1 bucket whitewash

Webbers Farm Contract

X 14 lbs. white paint

X 14 lbs. lead color

X 1 quart Linseed Oil

X 28 lbs ochre

X 1 bag lime

X putty

X glasspaper

Webbers Farm extras

7.  $11 \times 22$  slate roof.

10.  $12 \times 24$  do. "

50 slate nails "

5 lbs. strip lead "

2  $\frac{1}{2}$  pecks cement porch

2 barrows gravel "

1. 4" collar pipe "

12 bricks

3 barrows buckets mortar

2 pieces iron for manhole

2 buckets sand "

1 barrow stone "

Aug 29 Tolman, 9 hrs make coffin late Mrs Jane Knott  
 Monday Leach, 9 hrs. do. do.  
 Sunday Self, 9 hrs. do. do.  
 Hawkins Buy & Trap to better for furniture

30 Tolman, 9 hrs. prepare chimes Landkey  
 Monday Leach, 6 hrs. make coffin late Mrs. Jane Knott  
 X Coles, 9 1/2 hrs. painting at Webber's Farm  
 R Davey, 6 hrs. white wash washhouse Self  
 " 3 1/2 hrs. put up stable wall Broadway House  
 W Radford, 9 1/2 hrs. do. dig out floor do.  
 Self with Road Foreman about bridge Rydon Lane  
 " 5 1/2 hrs. foul house Mr. W. Carter

31 Tolman, 6 1/2 hrs. chime rack Landkey  
 Tuesday " 3 hrs. about motor car Col. Bolitho  
 X Coles, 9 1/2 hrs. painting at Webber's Farm  
 + Leach, 8 1/2 hrs. do. do.  
 " 1 hr. take off measurements of  
 Cottage at T. Shole with Mr. Toomer  
 R Davey, 9 1/2 hrs. about stable wall Broadway House  
 W Radford, 9 1/2 hrs. do. do.  
 Self, 3 1/2 hrs. about car Col. Bolitho  
 " at Rydon Lane

Sep. 1 Tolman, 9 1/2 hrs. Landkey chimes  
 Wednesday X Coles, 9 1/2 hrs. painting at Webber's Farm  
 + Leach, 8 1/2 hrs. do. do.  
 " 1 hr. coffin screw down Mrs. J. Knott  
 R Davey, 5 hrs. stable wall Broadway House  
 W Radford, 5 hrs. do. do.  
 Self 2 hrs about car Col. Bolitho  
 " 6 hrs. foul house Mr. W. Carter

- Sep. 2 Tolman,  $\frac{1}{2}$  hr. repair tent-pole Col. Bolitho  
 Thursday ..  $\frac{1}{2}$  hr. fowl house Mr. W. Carter  
 ..  $8\frac{1}{2}$  hrs. Landkey chimneys  
 + Coles,  $9\frac{1}{2}$  hrs. painting at Webbers Farm  
 + Leach, 5 hrs. do. do.  
 X -  $4\frac{1}{2}$  hrs. repair floor & fix door  
 at Bakehouse Mrs Stokes. Gen  
 Rdavey,  $9\frac{1}{2}$  hrs. about wall of floor at  
 " Stable Broadway House  
 W Radford,  $9\frac{1}{2}$  hrs. do.  
 Self  $7\frac{1}{2}$  hrs fowl house Mr. W. Carter
- 3 Tolman,  $2\frac{1}{2}$  hrs. Landkey chimneys  
 Friday ..  $\frac{1}{2}$  hr. help smith put stork  
 .. bonds on mill wheels Self  
 .. 3 hrs. get out posts & mangers  
 for Stable Broadway House  
 X Coles, 6 hrs. painting at Webbers Farm  
 Leach, 6 hrs. do. do.  
 X ..  $4\frac{1}{2}$  hrs. make stops & architrave  
 for door at Bakehouse  
 ..  $1\frac{1}{2}$  hrs. measure painting at Priory  
 Rdavey,  $9\frac{1}{2}$  hrs put in floor Broadway Stable  
 W Radford,  $9\frac{1}{2}$  hrs. do. do.  
 Self measure painting at Priory  
 attend funeral late Mrs. Jane Knott
- 4 Tolman, 6 hrs. make mangers Broadway House  
 Saturday + Coles, 6 hrs. painting at Webbers Farm  
 X Leach, 6 hrs. hang door at Bakehouse  
 Rdavey, 6 hrs. put in floor Broadway Stable  
 - W Radford, 6 hrs. do. do.  
 Self at apcs R.  
 2 hrs. fowl house Mr. W. Carter

Mr. T. Pykes Cottage  
 + 1 sanitary bucket

Mrs. Wildes Cottage  
 + 1 furnace door frame

Mr. S. Miller  
 X 600 bricks rearing  
 2 loads gravel rearing

Bakelhouse (Trustees)

6-0 of 11x2 studs

3-0 of 7x1 floor

3-0 of 3½x2 joist

4- 1½" screws

4- 1" do.

1- 6" rim lock complete

1 hasp & 2 staples

1 old 4 panel door

Lt. Col. Bolitho motor car

1 quart Varnish 10/-

Paint

1 button screws.

Sep. 6 Tolman, 2 hrs. make manger Broadway  
 Monday " 5 hrs. moving furniture Mother  
 " and fix curtain poles.

X " 2 hrs. prepare rail for Rydas Bridge RDE.

X Coles, 9 hrs. painting Welbers Farm

X Leach, 6 hrs. piping shelves. Mother

R Daver, 9 hrs. put in stable floor Broadway

W Radford, 9 hrs. do. do.

X Self 5 hrs. move furniture. Mother

Sep 7 Tolman 11 hrs. fix chimneys at Landkey  
 Tuesday X Coles, 9 1/2 hrs. painting Webber's Farm  
 X Leach, 9 1/2 hrs. fix up shelves in Mother  
 RDavey, 9 1/2 hrs. put in drain gutters  
 " " at Broadway Stable  
 W Radford, 9 1/2 hrs. do  
 + Self 1 hr. prepare rail Rydon Bridge

8 Tolman, 11 1/2 hrs. at Landkey  
 Wednesday X Coles, 9 1/2 hrs. painting at Webber's Farm  
 X Leach, 7 1/2 hrs. do do  
 X " 2 hrs. paint door Mother's house  
 X RDavey, Self 2 1/2 hrs. make draft. Mr. S. Miller

9 Tolman, 11 1/2 hrs. at Landkey  
 Thursday Coles, 5 hrs. ceiling Broadway ceiling  
 X " 9 hrs. fix up bridge & rails  
 at Rydon Lane R.D.C.  
 X Leach, 9 hrs. do do  
 " 1/2 hr. stable ceiling Broadway  
 X RDavey, 9 1/2 hrs. fix meal bin Mr. S. Miller  
 X W Radford, 9 1/2 hrs. do do  
 X Self put down canvas in Mother  
 Postlake sale

10 Tolman, 2 hrs. put on nit wheels &  
 Friday " sharp saw Self  
 " 7 1/2 hrs. stable partition Broadway  
 Coles, 9 1/2 hrs. stable ceiling do  
 Leach, 9 1/2 hrs. do do  
 X RDavey, 9 1/2 hrs. meal bin Mr. S. Miller  
 X W Radford, 9 1/2 hrs. do do  
 X Self at Exciter about Oddfellows work

Sep 11 Tolman, bhs. stable ~~along~~ <sup>carriage</sup> Broadway  
 Saturday Coles, bhs. stable ceiling do.  
 Leach, 2 hrs. do. do.  
 RDavey, bhs. put new door pipe box  
 to furnace Mrs. Wildes Cottage  
 + WRadford, bhs. grass out garden Mother  
 + J-Lark, bhs. do. do.  
 Self Ringing (Garniss)

Mrs. Wildes Cottage

1 peck cement  
 1 bucket gravel  
 1/2 barrel mortar  
 16 bricks  
 3 pieces iron 7 lbs.  
 1 furnace door frame

Mrs. H. Stokes Sen. at our house

21-6 of 7 x 3/4 shelves  
 1 lb. paint  
 1/4 peck cement  
 nails

Webber Farm

opened 2<sup>nd</sup> pot of white

Mr. S. Miller

3-0 of 2 1/2 x 2 1/2 ash drop  
 2 washers  
 3 1/2 bags cement  
 2 barrels mortar  
 2 barrels sand  
 4 holdfasts 4 lbs.  
 360 bricks

## Ryder Lane Bridge RD. Council

2. 19-0 of 3x2 rails
3. 3-0 of 4x3 deal posts
- 4-0 of 9x8 oak beams
- 6-0 of 3x2 oak plates (2)
6. 4 1/2 x 3/8 bolts
- 3 spikes
- 2 lbs. nails
- 3-0 of 2x3 rail
- 2 lbs. paint
- 5-0 of 14x1 elm

Sep. 13 Tolman, 9 1/2 hrs. make hang door w/it  
Monday mangers Broadway Stable

Coles, 9 1/2 hrs. do.

Leach, 9 1/2 hrs. do.

RDavey, 2 1/2 hrs. repairs at Broadway House

WRadford, 2 hrs. do.

X " 7 1/2 hrs. ship furniture Mother

X RDavey, 7 1/2 hrs. do. do.

Self do. do.

14 Tolman, 8 1/2 hrs. Broadway Stable

Tuesday - 1 hr. fix window at R. Davey's

+ for Rolle Estate

X RDavey, 8 hrs. do.

" 1 1/2 hrs. Broadway Stable

Leach, 9 1/2 hrs. do.

Coles, 9 1/2 hrs. do.

X Self fix curtain poles, furniture r. Mother

X 15 Tolman, 9 1/2 hrs. painting Welbers Farm X

Wednesday Leach, 9 1/2 hrs. Broadway Stable

Coles, 8 hrs. do.

" 1 hr. repair office drawers Self



Sep 15 RDavey, 9 $\frac{1}{2}$  hrs. repair walls Broadway House  
 Wednesday WRadford, 2 hrs. pick stone for paving Welbers Farm  
 X " 7 $\frac{1}{2}$  hrs. tarring at do.  
 + Self fit coat that pegs Mother

16 Tolman, 9 $\frac{1}{2}$  hrs. painting at Welbers Farm +  
 Thursday WRadford, 9 $\frac{1}{2}$  hrs. tarring do. X  
 X Coles, 9 $\frac{1}{2}$  hrs. painting do. contract  
 Leach, 5 hrs. repair Broadway Stable  
 " 1 hr. help take down fowl house  
 " 3 $\frac{1}{2}$  hrs. make signal box Mr. W. Abbott  
 RDavey, 9 $\frac{1}{2}$  hrs. repair walls Broadway H  
 Self, 3 hrs. take down fowl house  
 X " 2 hrs. repairs at Mother's house

17 Tolman, 9 $\frac{1}{2}$  hrs. painting at Welbers Farm +  
 Friday WRadford, 9 $\frac{1}{2}$  hrs. tarring do.  
 X Coles, 9 $\frac{1}{2}$  hrs. painting do. contract  
 Leach, 9 $\frac{1}{2}$  hrs. make signal box Mr. W. Abbott  
 RDavey, 9 $\frac{1}{2}$  hrs. repair walls Broadway H  
 X Self, 4 hrs. repair trap Mr. W. Sage  
 " Excite at Army shoe meeting

18 Tolman, 6 hrs. painting Welbers Farm +  
 Saturday Coles, 4 hrs. do. do.  
 X " 2 hrs. do. do. finish contract  
 X WRadford, 2 hrs. tarring do.  
 " 4 hrs. clear up at Broadway H  
 RDavey, 6 hrs. repair walls do.  
 Leach, 6 hrs. signal box Mr. W. Abbott  
 Self, 1 $\frac{1}{2}$  hrs. do. do.

R Davey's Cottage

Rolle Estate

20 bricks

1 peck cement

1 bucket sand

2 buckets mortar

4-0 of 2x1/2 deal

4-0 of 2x1  
nails

Webbers Farm extra

28-lb. lead color

2-lb. putty

X 8 buckets tar about 20 gals.

X 2 loads sand

Mr. W. Abbott Signal box

9-9 of 11x1 deal

5-6 of 9x1 ..

5-6 of 7x1 1/2 ..

8-0 of 9x1/2 ..

6-0 of 2x1 ..

1 lb. nails

4 shoes 11-

4 toes 9<sup>0</sup>4 plates 4<sup>0</sup>1 pair box handles 8<sup>0</sup>1 sharp staple 7<sup>0</sup>1 pair strap hinge 8<sup>0</sup>3 doz. 3/4 screw 6<sup>0</sup>1. 1 1/2 x 1/4 bolt 1<sup>0</sup>

time 25 1/2 hrs.

4<sup>5</sup>3 1/2  
2 3/4

38

17 1/2  
13  
20

4 1/2

2 1/2

10

9

4

8

7

8

6

1

129

165 1/2

## Mr. W. Carter Fowl House

336-0 q 7x3/4 match

142-0 q 2x2 deal

65-0 q 2x1 battens

13-0 q 7x1 floor

85-6 q 7x3/4 floor

5-9 q 9x3/4

14-9 q 11x3/4

18-0 q 1 1/2 x 1 1/2

1-6 q 11x3/4

3-6 q 7x3/4

1-5" dead lock

2 cupboard locks

1 pair 12" tee hinges &amp; screws

2 pair back flaps &amp; screws

1 piece chain

8. 3/8 pegs

2 hooks &amp; eyes

12. 5/2 + 3/8 bolts &amp; washers

6. 2 x 1/4 bolts

18. 2" screws

Creosote

3 lbs. nails

3 wheels &amp; axles

time 6 hrs.

Sep. 20 Tolman, 9 hrs. painting Welles Farm

Monday Coles, 9 hrs. do. do.

Leach, 5 hrs make signal box Mr. W. Abbott

" 4 hrs. painting at Priory

R Davey, 9 hrs. repair paving in yard at

X Welles Farm

X W Radford, 9 hrs. do. do.

See at S. Marychurch.

- Sep. 21 X Tolman, 9½ hrs. ring trap wheels Mr. W. Sage  
 Tuesday X Coles, 9½ hrs. do. do.  
 Leach, 9½ hrs. painting at Priory  
 R Davey, 4½ hrs. repair paving and  
 drinking trough Webbers Farm  
 X W Radford, 4½ hrs. do. do.  
 X .. 5 hrs. put up water tank Mrs. Stokes  
 X R Davey, 5 hrs. do. do.  
 X Self, 5 hrs. repair paint trap Mr. W. Sage
- 22 X Tolman, 6 hrs. ringing wheels Mr. W. Sage  
 Wednesday X .. 3½ hrs. painting Webbers Farm  
 X Coles, 6 hrs. ring wheel Mr. W. Sage  
 .. 4½ hrs. help put on tyres Mr. W. Sage  
 Leach, 9½ hrs. painting at Priory  
 X R Davey, 9½ hrs. put up water tank Mrs. Stokes  
 X W Radford, 6 hrs. do. do.  
 X .. 3½ hrs. tarring at Webbers Farm  
 X Self, 6 hrs. repair varnish trap Mr. W. Sage
- X 23 Tolman, 9½ hrs. painting at Webbers Farm  
 Thursday X Coles, 7½ hrs. do. do.  
 X .. 2 hrs. clean off wheels Mr. W. Sage  
 Leach, 9½ hrs. painting at Priory  
 X R Davey, 8 hrs. build tank make good  
 gutter at Mrs. Stokes  
 .. 1½ hrs. whitewash cowsheds  
 X W Radford, 7 hrs. tank Mrs. Stokes  
 X .. 2½ hrs. tar top of wall Mr. C. Davy  
 X Self, 2 hrs. fix bell rope at Clyst S. George  
 X .. 6 hrs. varnish trap Mr. W. Sage

Sep 24 Tolman, 9 1/2 hrs painting at Webber Farm

Friday Coles, 7 1/2 hrs do.

X " 2 hrs varnish trap Mr. W. Sage

Leach, 9 1/2 hrs painting at Priory

X R. Davey, 9 1/2 hrs repair piggers Bridgepit

X W. Radford, 9 1/2 hrs do do.

Self screw up bells at Hemlock Clayhidon

25 Tolman not to work

Saturday Coles, 6 hrs painting at Webber Farm

Leach, 6 hrs painting at Priory

X R. Davey, 6 hrs repair piggers Bridgepit

X W. Radford, 6 hrs do do.

X Self 4 hrs varnish trap Mr. W. Sage

Mr. H. Glanville

X 1 1/2 pecks cement trough

X 10 bricks

X 1 bucket gravel

3. 14 lbs. of lead color

3 pints linseed Oil

6 sheets glass paper

C. Davy Esq

X 1 bucket tar

Rev. Dr. Fulford, Priory

14 lbs. light purple brown

2 pints linseed Oil

5 sheets glass paper

23 Clept S. George

X 1. 60.0 bell rope + piping

## Mr. W. Sage Trap

1 pint varnish

2 tins enamel 1/2

9 screws

2. 2 x 1/4, 1. 1 x 1/4 bolts

3-3 of 1 x 5/16 iron

2. 1 1/2 x 3/8, 2 - 2 x 3/8 bolts

1 brass shaft stop screw

14. 2" ash felloes

## Mrs. H. Stokes Tank

250 bricks

single rds.

3 bags cement

3 barrows sand

1 barrow washed gravel

1. 3/4" brass tap, 1.0 of 3/4" pipe

1. 3/4" connection

10" of 1 1/2" pipe

1/2 load concrete

## Broadway Home Hall

1 barrow mortar

1 bucket lime

1/2 pk. plaster

2 buckets coloring

6-0 of 3 x 2 rafter stable

2. 13-0 of 4 x 2 "

1. 13-0 of 3 x 2 "

2. 17-0 of 2 x 1

3 lbs nails

4-3 of 7 x 3/4 floor

Sep. 27 Tolman, 9½ hrs. painting Webber Farm  
 Monday Coles, 9½ hrs. do.  
 Leach, 9½ hrs. painting at Priory  
 + RDavey, 9½ hrs. pigger at Bridgepit  
 + WRadford, 9½ hrs. do.  
 Self at accounts r., 5 hrs. trap Mr. W. Sage

28 Tolman, 1 hr. repairing plating Webber Farm  
 Tuesday .. 8½ hrs. painting at do.  
 + Coles, 9½ hrs. do. do.  
 Leach, 9½ hrs. painting at Priory  
 + RDavey, 5 hrs. pigger at Bridgepit  
 + WRadford, 5 hrs. do.  
 + Self, 2 hrs. take off, put on lock Miss Martin  
 + " 2 hrs. trap Mr. W. Sage  
 " all sorts

29 Tolman, 9½ hrs. painting at Webber Farm  
 Wednesday Coles, 5½ hrs. help smith tyre wheels  
 " for Mr. W. Newton  
 " 4 hrs. take off wheels & rebox wheel  
 " for Mr. W. Newton  
 Leach, 9½ hrs. painting at Priory  
 + RDavey, 9½ hrs. pigger at Bridgepit  
 + WRadford, 9½ hrs. do.  
 Self making paint  
 + 2 hrs. making hat rail Mrs. Stokes

30 Tolman, 9½ hrs. painting at Webber Farm  
 Thursday Coles, 4 hrs. box trap wheels Mr. W. Newton  
 " 5½ hrs. threshing Self  
 Leach, 5½ hrs. do.  
 " 1 hr. measure painting at Public Hall  
 " 3 hrs. painting at Priory  
 Self threshing and about Public Hall Carriage

Sep. 30 R Davey, 6 hrs. - threshing self  
 X " 4½ hrs. remove furniture Archer, Cowley, Co.  
 X W Radford, 4½ hrs. do. do.  
 " 6 hrs. threshing self

Oct. • Tolman, 9½ hrs. painting at Webbers Farm  
 Friday Coles, 7½ hrs. do. do  
 " 2 hrs. make plumb rule &  
 X straight edge Rural D Council  
 Leach, 9½ hrs. painting at Priory  
 X R Davey, 7½ hrs. remove furniture  
 Archer, Cowley Co  
 X W Radford, 6 hrs. do.  
 " 3½ hrs. pick over potatoes  
 X Self 2 hrs. fit hat rail & put  
 X " down canvas Mrs. Stokes  
 " at parlour apr. for Rydon

2 Tolman, 6 hrs. painting at Webbers Farm  
 Saturday Coles, 6 hrs. prepare jambs, rail for  
 X steps & board for door Webbers Farm  
 X Leach, 1½ hrs. repair school desk Woodbury School  
 X " 1½ hrs. about yard door Priory  
 X " 1½ hrs. repair table Kilmaster  
 " 1½ hrs. make paint  
 W Radford, 6 hrs. about potatoes

Miss Martin  
 X repair lock

10

Mrs. Stokes pen.  
 X 8-9 of 3x1 coat rail  
 11 coat hooks & screws



## Bridgepit Piggery

- + 1 bag cement
- + 1 load mortar
- + 1 load sand

## Webbers Farm

- + 3 shut screws
- + 12 nails
- + 6-4 of 3x2 1/2 deal rail
- + 3-0 of 9x1 deal
- + 3-0 of 4x3 1/4 oak for jambs

- Oct. 4<sup>th</sup> Tolman, 7 hrs painting Webbers Farm  
 Monday + .. 2 1/2 hrs. repair yard door posts do.  
 + Coles, 9 1/2 hrs. repair door on landing do.  
 Leach, 9 1/2 hrs. painting at Priory  
 R Davey, 9 1/2 hrs. whitewash cottage late Mrs. Taylor  
 W Radford, 9 1/2 hrs. do. do.  
 X Self, 2 hrs. take out gudgeon of roller thru R side  
 clear out cottage r.

5<sup>th</sup> Tolman, 9 1/2 hrs. painting at Webbers Farm

- Tuesday Coles, 9 1/2 hrs. repair rail of steps + put  
 X .. piece on door at Webbers Farm  
 Leach, 10 hrs. repair stairs, put in rush  
 cord in window + repair apple loof  
 floor Mr. E. Ware  
 R Davey, 1 1/2 hrs. strip in jambs + color wall  
 at Webbers Farm  
 X .. 8 hrs. Bridgepit Piggery  
 X W Radford, 9 1/2 hrs. do.  
 X Self, 2 hrs. repair rail Webbers Farm

Oct. 6 X Tolman,  $9\frac{1}{2}$  hrs. painting at Webbers Farm  
 Wednesday Coles,  $9\frac{1}{2}$  hrs. piggeries at Bridgepit  
 Leach,  $9\frac{1}{2}$  hrs. painting at Priory  
 X R Davey,  $9\frac{1}{2}$  hrs. piggeries at Bridgepit  
 X W Radford,  $9\frac{1}{2}$  hrs. do do  
 Self picking in apples  
 X " 2 hrs. Mr. R. Pile's roller

X Tolman, 4 hrs. help put in gudgeon  
 Thursday " and repair roller frame Mr. R. Pile  
 X "  $5\frac{1}{2}$  hrs. painting at Webbers Farm  
 X Coles,  $9\frac{1}{2}$  hrs. piggeries at Mr. T. Woods  
 Leach,  $9\frac{1}{2}$  hrs. painting at Priory  
 X R Davey,  $9\frac{1}{2}$  hrs. piggeries Bridgepit  
 X W Radford,  $9\frac{1}{2}$  hrs. do do  
 Self see boarding at Mr. W. Glanville  
 " help put in winter oats  
 X " 2 hrs. paint roller frame Mr. R. Pile

X Tolman,  $9\frac{1}{2}$  hrs. painting at Webbers Farm  
 Friday X Coles,  $9\frac{1}{2}$  hrs. piggeries at Bridgepit  
 X Leach, 2 hrs. repair shutters W.C. casement  
 " at Priory  
 "  $7\frac{1}{2}$  hrs. painting at Priory  
 X R Davey,  $9\frac{1}{2}$  hrs. piggeries Bridgepit  
 X W Radford,  $9\frac{1}{2}$  hrs. do do  
 X Self  $1\frac{1}{2}$  hrs. paint roller frame Mr. R. Pile  
 " at Exeter "

X Tolman, 6 hrs. painting at Webbers Farm  
 Saturday Coles, 6 hrs. piggeries at Bridgepit  
 Leach, 4 hrs. painting at Priory  
 X R Davey, 6 hrs. piggeries at Bridgepit  
 W Radford, 1 hr. do do  
 " 3 hrs. put up scapled at Priory

Oct 9 - W Radford, 2 hrs. picking apples  
 Self 3 hrs. make stay for bell at  
 X Topsham for Mr. Swain  
 apples & apes

X Mr Swain, Topsham  
 1 stay for bell 3/-

Mr. J. Ware

4-3 of 21x1 elm

6-6 of 13x1 elm

4-3 of 14x1 elm

5-0 of 2x3 deal

1 lb nails

2 sack cords rebolt

Mr. R. Pile

X 3 1/2 lbs paint

1 false link

Self at Cottage

1 bucket plaster lime

1/2 pk. plaster

4 lbs. calcarium

Webbers Farm

X 1-3 x 1-3 of zinc

36. 1" clouts

5-0 of 7 x 3/4 deal

3-0 of 8 x 3/4 - stop

1-6 of 3 1/2 x 1 1/2 deal

2-2 1/2" screws

1/4 peck cement embars

~~Bridgepit Farm~~

5 plate iron

1 load mortar

600 bricks

300 single round

14½ lb. nails

X 29-0 of 3"x¾" deal extra

+

Oct. 11 X Tolman, 9½ hrs. painting Webbers Farm

Monday Leach, 9½ hrs. do. Priory

X Coles, 9½ hrs. piggery at Bridgepit

X R Davey, 9½ hrs. do.

X W Radford, 9½ hrs. do.

X Self ½ hr. repair tailboard Mr. B. Stamp

X " 3 hrs. put sill on frame for  
Piggery at Bridgepit (extra)

X 12 Tolman, 9½ hrs. painting Webbers Farm

Tuesday Leach, 9½ hrs. painting at Priory

X Coles, 9½ hrs. piggery at Bridgepit

X R Davey, 9½ hrs. do.

X W Radford, 6 hrs. do.

" 3½ hrs. make mortar

Self at Exmouth Market 15.

13 Tolman, 3 hrs. repair orchard gate

~~Wednesday~~ " orchard door post Webbers Farm

X " 6½ hrs. painting do.

Leach, 9½ hrs. do. Priory

X Coles, 9½ hrs. piggery at Bridgepit

X R Davey, 9½ hrs. do.

X W Radford 3½ hrs. do.

" 6 hrs. make mortar

Self pick apples 15

- Oct. 14) Tolman, 9½ hrs. painting at Welbers Farm  
 Thursday Leach, 9½ hrs. do. Priory  
 X Coles, 3½ hrs. put new shaft in water  
 " east for District Council  
 + " 6 hrs. piggery at Bridgepit  
 X R Davey, 9½ hrs. do. do.  
 X W Radford, 9½ hrs. do. do.  
 X Self 2½ hrs. repair electric bells &  
 " ease bedroom door C. Davy log.
- 15) Tolman, 9½ hrs. painting at Welbers Farm  
 Friday Leach, 9½ hrs. do. Priory  
 X Coles, 9½ hrs. put in new shaft in  
 watercart District Council  
 + R Davey, 6 hrs. piggery at Bridgepit  
 + " 3½ hrs. dig out floors & put walls do. extra  
 + W Radford, 9½ hrs. do. do.  
 X Self 5 hrs. put in 2 panes glass, put  
 new leather to spindle Mr. R. Pile
- 16) Tolman, 6 hrs. painting at Welbers Farm  
 Saturday Leach, 6 hrs. do. Priory  
 X Coles, 6 hrs. piggery at Bridgepit  
 + R Davey, 6 hrs. about floors in piggery do.  
 + W Radford, 6 hrs. do. do.  
 Self all sorts

C. Davy log.

Salamoniae

3 zincs

4' 6" 1½ x ½ deal

nails 1?

Mr. B. Stamp

X 4. 2 x ¼ bolts for tailboard

Mr. R. Pile

1 pane glass  $14\frac{1}{4} \times 18\frac{1}{2}$  2102

1 do  $10\frac{3}{8} \times 11\frac{3}{4}$  "

1 lb. putty

1 spindle leather

Rural District Council

1 ash shap.  $8\text{'-}6\text{'}$  of  $4\text{'}$  x  $3\text{'}$

1 screw.

$\frac{1}{2}$  lb. paint

3 washers.

Bridgepit

3-10 of  $7 \times 3$  deal counterpill extra

6.  $4\text{'}$  cuts. paint

$6\frac{1}{2}$  lbs nails

1 load mortar

300 bricks

Webbers Farm extra

24.  $2\text{'}$  pat. nails

2.  $1\frac{1}{2}\text{'}$  screws

4 doz.  $1\text{'}$  clout

1 piece zinc  $14 \times 12$

$4\text{'-}0\text{'}$  x  $4\text{'}$  sheet iron

Prory

8 lbs. paint

- Oct. 18<sup>x</sup> Tolman, 8 $\frac{1}{2}$  hrs. painting at Webbers Farm  
 Monday X " 1 hr. repair plumbing do.  
 Leach, 9 $\frac{1}{2}$  hrs. painting at Priory  
 X Coles, 9 $\frac{1}{2}$  hrs. Woods Piggery Contract  
 Rdavey, 9 $\frac{1}{2}$  hrs. take out old floors, put  
 X up walls, put up partition walls  
 & put in concrete Woods Piggery  
 W Radford, 9 $\frac{1}{2}$  hrs. do.  
 Self, 2 $\frac{1}{2}$  hrs. painting at Priory
- 19<sup>x</sup> Tolman, 1 $\frac{1}{2}$  hrs. repair plumbing Webbers Farm  
 Tuesday Leach, 8 $\frac{1}{2}$  hrs. painting at Priory  
 X Coles, 9 $\frac{1}{2}$  hrs. Woods Piggery Contract  
 1 $\frac{1}{2}$  hrs. prepare ledge partition do.  
 X Rdavey, 6 hrs. do. extras  
 W Radford, 6 hrs. do. do.  
 Self, 2 hrs. painting at Priory  
 3 hrs. tar barge boards Mr. Skilles  
 Role X
- 20<sup>x</sup> Tolman, 1 hr. repair plumbing Webbers Farm  
 Wednesday X " 8 $\frac{1}{2}$  hrs. painting at do.  
 X Leach, 9 $\frac{1}{2}$  hrs. put up cake house Mr. W. Glanville  
 X Coles, 9 $\frac{1}{2}$  hrs. Woods Piggery Contract  
 X Rdavey, 9 $\frac{1}{2}$  hrs. do. extras  
 W Radford, 9 $\frac{1}{2}$  hrs. do. do.  
 Self at Dexter with Mrs. Taylor
- 21<sup>x</sup> Tolman, 3 $\frac{1}{2}$  hrs. repair <sup>making shed</sup> ~~bandon~~ Webbers Farm  
 Thursday X " 6 hrs. painting do.  
 X Leach, 9 $\frac{1}{2}$  hrs. put up cake house Mr. W. Glanville  
 X Coles, 6 hrs. contract Woods Piggery  
 X " 3 $\frac{1}{2}$  hrs. repair partition do.  
 W Radford, 9 $\frac{1}{2}$  hrs. Woods Piggery extras  
 W Radford, 9 $\frac{1}{2}$  hrs. do.  
 Self

Oct. 22 Tolman, 4 hrs. repair barn door Webbers Farm

Friday .. 5 1/2 hrs. painting do.

X Leach, 9 1/2 hrs. build cake house Mr. W. G. Lawill

X Coles, 2 1/2 hrs. fix partitions Woods Piggery

X .. 7 hrs. contract do.

+ P. Davey, 3 1/2 hrs. extras do

+ W. Radford, 9 1/2 hrs. do. do.

Self at Exeter market

23 Tolman, 2 hrs. unload ash plank

Saturday X .. 2 1/2 hrs. repair barn door Webbers Farm

X .. 1 1/2 hrs. painting do.

Leach, 1 1/2 hrs. unload timber

X .. 4 hrs. enlarging door for  
Rev. Dr. Fulford

Coles, 2 hrs. unload ash plank

.. 4 hrs. help smith shoot up  
types of wheels

+ P. Davey, 6 hrs. extras Woods Piggery

+ W. Radford, 6 hrs. do.

Webbers Farm extras

2-0 of 3x1 deal machine shed  
nails 1<sup>0</sup> ..

4-3 of 11x1 deal drift barn

4-3 x " 6" of sheet iron "

4 doz. 1" clouts ..

nails 1<sup>0</sup> ..

6 phute screws

1. 4 1/2" stop end

1-6 of 5" 1/2 rd. gutter

2 plates of iron 6" barn

6. 1" screws ..

Roll Mr. S. Miller 2 quarts varnish



Mr. W. Glauert

2. 17.0 of 3x2 rafter

1. 14.0 of 3x2 "

7 lbs nails

1. 5" dead lock screws

1 pair 14" Tee hinges screws (18)

Prory

1. 4 $\frac{1}{2}$ " stop end

1 gutter bolt

3.0 of 7x1 ledge for door

6.6 of 4 $\frac{1}{2}$ x1 $\frac{1}{2}$  to enlarge door

Woods Piggery extra

1 load mortar

11 bags cement 11m

30 single rd. bricks

4 lbs. nails

6.0 of 7x3/4 deal stops

Oct. 25 Tolman. 9 $\frac{1}{2}$  hrs. painting at Welbers Farm

Monday Coles. 6 hrs. help smith tyre 3 wheels

" take off put on wheels

X Leach. 2 hrs. widening door Prory

X " 7 $\frac{1}{2}$  hrs. repair eavches Mr. A. Stamp

X R Davey. 9 $\frac{1}{2}$  hrs. put in piggery floors. r

" put blocks to panels. Pipe in wall

" at Bridgepit

X W Radford. 9 $\frac{1}{2}$  hrs do do

Coles. 3 $\frac{1}{2}$  hrs. take off hooks + twists from

X doors at Bridgepit

X Self 3 hrs. put down canvas Mother  
at Mr. H. Ware. Bridgepit r.

Oct. 26 Tolman, 9½ hrs. painting at Webbers Farm  
 Tuesday Coles, 9½ hrs. do.

X Leach, 9½ hrs. repair cowshed Mr. A. Stamp

X R Davey, 6½ hrs. floors. Bridgepit pigger

X " 3 hrs. take out grate Mr. C. Davy

Self 3½ hrs. repair grate do.

" 1 hr. put board in kitchen S. Seales Cottage

X " 1½ hrs. put up boards for harness Miss Martin  
 " 1 hr. fit canvas Mrs. Taylor

27 Tolman, 9½ hrs. painting at Webbers Farm  
 Wednesday Coles, 9½ hrs. do. do.

X Leach, 9½ hrs. repair cowshed Mr. A. Stamp

X R Davey, 7 hrs. cutting fire blocks fixing

" grate Mr. C. Davy

" 2½ hrs. put step to door Mrs. Pomeroy.

X Self 2 hrs. fit grate & examine chimney,  
 Mr. C. Davy

" 2 hrs. clean paint garden frame

X " Mr. H. Ware

X " 1½ hrs. repair glass in light. Mr. H. Ware

28 Tolman, 9½ hrs. scarf jamb put in new  
 Thursday sill counter sill at barn Webbers Farm

X Coles, 9½ hrs. do. do.

X Leach, 9½ hrs. repair cowshed Mr. A. Stamp

X R Davey, 9½ hrs. put in floors Bridgepit

Self all sorts. 1 hr. find water T. Sloth  
 wrapped 1 hr. do.

29 Tolman, 9½ hrs. repair barn jamb floor Webbers Farm  
 Friday Coles, 9½ hrs. do. do.

X Leach, 9½ hrs. repair cowshed Mr. A. Stamp

X R Davey, 8 hrs. put up brickwork do.

X " 1½ hrs. finish floors Bridgepit

X Self 3 hrs. clean off & repair lights Mr. H. Ware

Oct. 30 Tolman, hrs. repair barn floor r. Webbers farm  
 Saturday Coles. hrs. do. do.

X J. Davey, hrs. fill in between beam. make  
 " good brick quoin at barn Webbers farm  
 X Leach, hrs. repair cowshed Mr. A. Stamp  
 Self 1 hr. examine window Miss L. Martin  
 X " 2 hrs. glass light Mr. H. Ware

C. Davy Esq.

50 bricks

2 barrels mortar

3 fire bricks,

5.6 of copper wire

1/4 pk. plaster

Mrs. Ponerry's step.

1 peck cement

2 buckets gravel

Bridgemit

X 1.4" collar pipe

Miss S. Martin

X 15.0 of 7x3/4 floor paid 1/10<sup>5</sup>

Mr. Alfred Stamp

34.0 of 2x3 rafter

14.0 of 2x4 do

11.6 of 7x1 floor

7 lbs. nails

2 lbs. galv. screws washers

2. 3/2 x 3/8 bolts

2 barrels mortar

1 peck cement

Mr. Harold Ware

2-7 x 2-7 of glass

8-0 x -10 of glass

5 $\frac{1}{2}$  lbs. putty

Webbers Farm

1 barrow mortar barn

$\frac{1}{2}$  peck cement "

5 single rd. bricks "

2-6 of 4x1 deal

1-9 of 7x2 - floor

5 lbs. nails

1-6 x -4 $\frac{1}{2}$ " zinc

18-  $\frac{3}{4}$ " clout

3 7" spikes

10-6 of 2 $\frac{1}{2}$  x 1 stops

8-9 of 4x1 "

Nov. 1 Tolman, 5 $\frac{1}{2}$  hrs. put new bottom<sup>rs</sup> in  
Monday " car Mr. H. G. Lawell

3 $\frac{1}{2}$  hrs. repair floor mill in  
stable loft Webbers Farm

+ Coles, 9 $\frac{1}{2}$  hrs. hang doors Bridgepit

+ Leach, 9 $\frac{1}{2}$  hrs. repair cowshed Mr. A. Stamp

+ R. Davey, 9 hrs. cowshed floors do

+ W. Radford, 9 hrs. do. do.

+ H. Stokes, 4 $\frac{1}{2}$  hrs. paint lights Mr. H. Ware

2 Tolman, 9 $\frac{1}{2}$  hrs. repair waggon shafts  
Tuesday " for Mr. G. Ware

+ Coles, 7 $\frac{1}{2}$  hrs. hang doors Bridgepit

+ " 2 hrs. boarding do.

+ Leach, 9 $\frac{1}{2}$  hrs. repair cowshed Mr. A. Stamp

+ R. Davey, 1 $\frac{1}{2}$  hrs. do. do.

+ W. Radford, 1 $\frac{1}{2}$  hrs. do. do.

- Nov. 2 R Davey, 8 hrs. repair tiles on Cottage  
 " Mr. H. Ware
- X W Radford, 8 hrs. do. do.  
 Self 1 1/2 hrs. paint frame Mr. H. Ware  
 X " 3 hrs. paint lights do.
- X 3 Tolman, 1 hr. put on waggon shafts Mr. G. Ware  
 Wednesday " 1 hr. put in glass Miss Stoneman  
 X " 8 hrs. painting at Webbers Farm  
 X Coles, 9 1/2 hrs. boarding at Bridgepit  
 X Leach, 9 1/2 hrs. repair of jambs of  
 door + rehang door Mr. H. Ware  
 X R Davey, 2 1/2 hrs. put new bottom to  
 stove at Mrs. Wildes Cottage  
 X " 7 hrs. tar roof + repair W.E.  
 X " ceiling for C. Davy Esq.  
 X Self 1 hr. take down garden lights  
 " Mr. H. Ware.  
 X " 1 hr. make pill Bridgepit  
 " 1 hr. fowl house Mr. J. Glanville
- 4 X Tolman, 9 1/2 hrs. painting at Webbers Farm  
 Thursday X Coles, 5 hrs. boarding at Bridgepit  
 X " 4 1/2 hrs. repair partition do.  
 X Leach, 9 1/2 hrs. hang paint down +  
 repair bridge rails Mr. H. Ware  
 X R Davey, 8 hrs. repair roofs Tanyard do.  
 X W Radford, 8 hrs. do. do.  
 " 1 1/2 hrs. cut up wood  
 X Self 5 hrs. make fowl house Mr. J. Glanville
- 5 X Tolman, 9 1/2 hrs. painting at Webbers Farm  
 Friday X Coles, 9 1/2 hrs. fit up door board up end  
 at Bridgepit X hrs  
 X Leach, 9 1/2 hrs. put head to post gates Mr. H. Ware

Nov. 5 / R Davey, 5½ hrs. repair roops Tanyard  
 + W Radford, 5½ hrs. do. do.  
 " 4 hrs. cut up logs  
 Self 6 hrs. poultry house Mr. J. Glanville

6 / Tolman, 1½ hrs. repair poultry roost for  
 Saturday .. Mr. H. Glanville  
 + - 4 hrs. painting at Webber's Farm  
 X Coles, 5½ hrs. board up end Bridgepit  
 Leach, 5½ hrs. repair front gates  
 X for Mr. H. Ware  
 X R Davey, 5½ hrs. repair roops at Tanyard  
 X W Radford, 5½ hrs. do.  
 Self 3 hrs. poultry house Mr. J. Glanville

Mr. S. Ware

2-10 of 8x3 ash  
 4-1" screws, 2 C-S nails  
 2-3½x3/8 bolts  
 paint

Mr. H. Ware (Own)

+ 6 lbs. white paint lights  
 3-6 of 4x3 jambs  
 7-0 of 2x3 prop.  
 1-9 of 3½x3 oak stake  
 1 drive in cable  
 1 coil spring  
 2 bolts  
 38 pan tiles  
 2 double roll tiles  
 ½ barrow mortar  
 1 peck cement

Mr. H. Ware (Own)

4' 9" of 4x4 deal gate head

1 lb. wire

12 staples

4 iron stands for wire

Tan Yard

20. 24x12 plates

3. 22x11 "

6. 20x10 "

75 nails plate

8 lbs. lead strips

90 pantiles

1/2 barrow mortar

Mr. H. Glanville

7' 0" of 2x3 deal perch

nails 1<sup>p</sup>.

2 crooks for shafts

Miss Stoneham

1 pane glass 9<sup>3</sup>/<sub>4</sub> x 7<sup>3</sup>/<sub>4</sub> pulley & time paid .. 9

Mr. A. Stamp

1/4 peck cement

2 loads sand

4 lbs. nails

Mrs. Wildes Cottage

2 fire bricks

1 bucket mortar

1 bottom bar

1 front bar

C. Davy. Eq.

2 gals. of tar

1/2 peck cement

2 barrows gravel

10. 3/4 laths

1/2 lb. lath nails

1/4 peck cement

1/2 bucket putty lime

1 pane tile

Webbers Farm

1 lb. nails for stable floor

6-0 of 2x4 deal

Bridgepit Farm

28. 2" screws

2. 1" do. 2 C.S. nails

4. 3 1/2 x 3/8 bolts

7-0 of 1 1/4 x 7 deal & ledgers

13 lbs nails

3-6 of 7 x 2 1/2 deal sill

Nov. 8 Tolman, 6 hrs. repair & rehang orchard  
Monday " gates & put stop block Webbers Farm

3 1/2 hrs. paint gates do

3 hrs. board end & fit up door  
at Bridgepit Piggery

3 1/2 hrs. repair & paint front  
gates Mr. H. Ware

3 hrs. repair roof Mrs. H. Stokes

6 1/2 hrs. put in gutter Bridgepit

H. Stokes, see elm trees with Mr. Stamp.

4 hrs. make poultry house Mr. J. Glanville



Nov 9 x Tolman, 1½ hrs. painting gates Webbers Farm  
 Tuesday .. 8 hrs. repair barn floor & put in  
 posts at machine shed Webbers Farm  
 X Coles, 2 hrs. board up end of piggeny Bridgepit  
 Y .. 7 hrs. repair inside partitions do.  
 Leach, 4 hrs. repair bridge & stop posts  
 X .. Mr. H. Ware  
 - 5½ hrs. putting in sack cords  
 X & repair door Priory  
 f RDavey, 9 hrs. put in gutter, brick up  
 .. under manger & stop in walls Bridgepit  
 H Stokes, 7½ hrs. prol house Mr. J. Glanville

10 Tolman, 9½ hrs. put in posts & rehang  
 Wednesday X .. doors manure shed Webbers Farm  
 Coles, 9 hrs. fix manger & repair & repair  
 X .. partitions at Bridgepit  
 Leach, 9½ hrs. repairing & hanging  
 X .. doors at Priory  
 X RDavey, 9 hrs. finish gutter & Bridgepit  
 H Stokes, 7½ hrs. make prol house Mr. J. Glanville

11 x Tolman, 7½ hrs. painting Webbers Farm  
 Thursday X .. 2 hrs. prepare stop posts do.  
 X Coles, 9 hrs. fix rack, manger & Bridgepit  
 X Leach, 5½ hrs. make fix door cap Priory  
 - 2 hrs. paint doors do.  
 - 2 hrs. put new stile to garden  
 X .. door Webbers Farm  
 RDavey, 9 hrs. take out grate, repair  
 fire place, whiten ceilings Self  
 H Stokes, 3 hrs. prol house Mr. J. Glanville  
 make paint &

Nov 12 Tolman, 9½ hrs. put new frame  
 Friday " to roller Mr. R. Pile  
 Coles, 9 hrs. make change partition  
 + door at Bridgepit  
 Leach, 6 hrs. repair garden door  
 X " at Welbers Farm  
 " 3½ hrs. put bottom back  
 + to manger Mr. E. Ware  
 Rdavey, 7½ hrs. clean out slates &  
 repair tiles on linhay at  
 X Globe Hill & fix fire check to  
 stove at E. Hawkins  
 Self, 1 hr. poulhouse Mr. J. Glanville  
 " at Exeter see Mrs. Thomas  
 at Exeter with mother

13 Tolman, 3½ hrs. put legs on barrow Self  
 Saturday " 2 hrs. paint roller frame &  
 + put on chain Mr. R. Pile  
 Coles, 4½ hrs. creosote woodwork  
 X " at Bridgepit  
 " 1 hr. creosote poulhouse  
 X Leach, 5½ hrs. hang door Welbers Farm  
 + Rdavey, 5½ hrs. pave pigger, Mr. A. Stamp  
 Self 1 hr. poulhouse

Miss Rose Edith Martin

X 76-0 of 7 x ¾ inch board

Mr. Kilmaster

X 1 pane glass 24 x 20 pictures 1½ hrs. cut

1 do. 10 x 8½ " put in

1 pane do. 13½ x 10½ putty

1 hr. put in

Rev. Dr. Hulford

2 sack cuds.

6 clmb

1 pair 16" Heavy Tee Triggs

18. 1 1/4 screws

1 1/2 lbs. paint extract

Mr. Harold Ware

12-0 of 6x1 elm for bridge

2-1 of 3x1 oak gate catches

1/2 lb. nails

lbs. paint for gates & door

Mr. Edgar Ware

6-3 of 10x1 elm manger

6-3 of 9x1/2 elm "

1/2 lb. nails "

Mr. Robert Pile

6-0 of 4 1/2 x 3 oak bar roller frame

4-6 of 7 x 4 oak ends "

2 lbs. paint "

1 long bar

2 bolts

2 copers & bolts

Mr. A. Stamp

1/2 peck cement

1 borrow mortar

30 bricks

## Bridgeport Piggery extras

788 bricks for partitions &amp; gutter

22.0 of 2x1 stops

2 lbs nails contract

6.0 of 7x1 $\frac{1}{4}$  deal ledges (inside door)

4.9 x 3.0 of 1" elm "

1 pair 14" Heavy Tee hinges "

18. 1 $\frac{1}{2}$ " screws "

1 staple "

4 $\frac{1}{2}$  lbs nails

## Webbers Farm

iron plates for gates 3 $\frac{1}{2}$  lbs.3 $\frac{1}{2}$  lbs nails for barn

2. spikes machine shed

1. 3/4" dowel "

1 staple for stop block "

5.0 of 5 $\frac{1}{2}$  x 2

## Self parlors

25 bricks

1 barrow mortar

6 lbs. Halls distemper

## Mrs. Stokes

1 fire lump Mr. Hawkins

3 fire bricks "

1 bucket mortar "

5 pieces wallpaper Mrs. Davey

1 top lap round Mr. G. Nutters

1 set front bars "

20 pantiles Globe Hill Linhay

3. 22x11 slates on W.C.

2 shiphead nails "

1/2 peck cement "

1 bucket gravel "

5.0 of 3 $\frac{1}{2}$  x 1 deal "

- Nov. 15 Tolman. 5 hrs. put in paint stuy  
 Monday X .. posts to yard doors Webbers Farm  
 X .. 4 hrs. paint orchard gates do.  
 X Leach, 9 hrs. repair stable Mr. A. Stamp  
 X Coles, 7 1/2 hrs. put in sash cords, ease  
 X .. doors r. Dr. Furnival  
 .. 1 1/2 hrs. pick up nails, create  
 .. fowl house r. Self  
 X R. Davey, 9 hrs. paring styes Mr. A. Stamp  
 X W. Radford, 9 hrs. do. do.  
 Self all over
- 16 X Tolman, 9 hrs. painting Webbers Farm  
 Tuesday Leach, 9 hrs. repairs Mr. A. Stamp  
 X Coles, 6 1/2 hrs. put in sash cords  
 .. r. Dr. Furnival  
 .. 1 hr. fix iron over cupboard  
 + .. for Mrs. Stokes  
 X .. 1 1/2 hrs. make whippetree Mr. B. Stamp  
 X R. Davey, 9 hrs. dig out floors Mrs. Thomas  
 X W. Radford, 9 hrs. do. do.  
 Self at Mrs. Thomas  
 .. at Vermont (Tax Commissioners)
- 17 X Tolman, 9 hrs. painting Webbers Farm  
 Wednesday Leach, 9 hrs. repairs Mr. A. Stamp  
 X Coles, 9 hrs. put up shed Mr. W. Glanville  
 X R. Davey, 9 hrs. dig out concrete floors  
 .. for Mrs. Thomas  
 X W. Radford, 9 hrs. do.  
 Self Rolle State Rent. at Mrs. Thomas  
 .. at T. Short's & Bridgeport with Mr. Foster  
 Mr. B. Stamp  
 X 1 large staple for whippetree

Nov. 18  
 Thursday Tolman, 1 hr. make pit stop to garden  
 .. door Webbers Farm  
 X .. 2 hrs. paint garden door do  
 X .. 5 1/2 hrs. fit fencing in orchard  
 at Webbers Farm  
 .. 1/2 hr. get out battens for floor Mrs. Thomas  
 + Leach, 9 hrs. repairs Mr. A. Stamp  
 X Coles, 9 hrs. put up shed Mr. W. Glanville  
 X Rdavey, 9 hrs. concrete floors Mrs. Thomas  
 X W Radford, 9 hrs. do do  
 Self, all sorts paint bedroom

19  
 Friday Tolman, 9 hrs. fit orchard fencing  
 at Webbers Farm  
 X Leach, 9 hrs. put up shed Mr. A. Stamp  
 X Coles, 9 hrs. repair shed Mr. S. Miller  
 X Rdavey, 9 hrs. put in floors Mrs. Thomas  
 X W Radford, 9 hrs. do do  
 Self, at Shepherds, about greenhouse  
 with Mr. G. Pyne  
 at Exton at Mrs. Thomas  
 .. 2 hrs. fit fowl house at Rydon

20  
 Saturday Tolman, 3 1/2 hrs. repair barn Mr. E. Ware  
 .. 1 hr. paint garden door Webbers Farm  
 X .. 1 hr. get out leathers for Thorverton  
 X Leach, 5 1/2 hrs. put up shed Mr. E. Ware Stamp  
 X Coles, 5 1/2 hrs. repair shed Mr. S. Miller  
 X Rdavey, 5 1/2 hrs. put in floors Mrs. Thomas  
 X W Radford, 5 1/2 hrs. do do  
 Self sowing wheat

Mr. W. Glanville

X 5 lbs. cut nails

X 1 door knob screw

Dr. Furnivall

X 9 sash cords

4 doz. clouts

20. 2" screw

Mrs. Thomas Eaton Farm

X 4" 0' of 2x1 batten

3" 0' of 4x1 "

2 plates of iron for jambs 4 lbs.

4. C.S. nails

Mr. Jim Glauwill

X 1 hay knife handle

put on do. 1 lb.

Mr. John Glauwill

(19) X 1 fowl house

Dr. Fulford

X 1 fire check boiler side

take off plate from stand 3'

Mr. Edgar Ware barn

X 3-0 of 12x1 elm

3-6 of 12x1/2 "

1-6 of 2x2 ash

nails 2'

Webber's Farm Fencing

X 5 lbs. nails

4 lbs. of iron pegs

2 lbs wire staple

1 roll of 3-0 x 2' netting

Webber's Farm

of doorstop

Mr. Alf Stamp

2 plates of old iron 11 lbs.

4 pipe nails

1 load sand

5 lbs nails

8-0 of 4x3 deal post stable

8-0 of 3½x2 " rail "

13-0 of 3x2 bars "

4. 12-0 of 4x2 old joints slye

13-0 of 3x2 deal

24 galv'd. screws washers

2. 14-0 of 4x2 shed

3. 8-0 of 3x2 "

Mr. J. Glanville Bowl house

312-0 of 7x¾ match

105-0 of 7x¾ floor

12-3 of 7x1 "

69-4 of 2x1 batten

101-0 of 2x2

10-0 of 1½x1¼ ends

2. 13¼ back flaps screws

1 cupboard lock

1 pair 10" Tee hinges screws

1. 5" dead lock screws

2 hooks &amp; eyes

1 chain &amp; ring

creosote

nails



Mr. S. Miller

5 lbs. nails

3 doz.  $\frac{1}{2}$  screws

Nov 22 Tolman, 13 hrs. overhaul & screw up bell  
Monday at Thorverton

X Coles, q hrs. repaired shed, trap & pulper box  
for Mr. S. Miller

X Leach, q hrs. putting up shed Mr. A. Stamp

X R Davey, q hrs. putting in concrete floor

" cementing ends Mrs. Thomas

X W Radford, q hrs. do do

H. Stokes, at Mrs. Thomas,

.. paint bedroom r.

X 23 Tolman, q hrs. make burrow Mr. B. Stamp

Tuesday Coles, q hrs. brace roof, paint window

X put in stop post Mr. T. Woods

X Leach, q hrs. put up shed Mr. A. Stamp

X R Davey, q hrs. floors r. Mrs. Thomas

X W Radford, q hrs. do

H Stokes, remove markers

X 24 Tolman, q hrs. make burrow Mr. B. Stamp

Wednesday Coles, 7 hrs. cut & hang stable door Mr. T. Woods

" 2 hrs. put bar & glass in window

of pool house Mr. T. Wood

X Leach, 7 hrs. paint front gates door Mr. H. Ware

X " 2 hrs. prepare window sill r. Mrs. Thomas

X R Davey, q hrs. floors r. Mrs. Thomas

X W Radford, q hrs. do

H Stokes, at Mrs. Thomas, paint bedroom self

at Hill Fields

Nov. 25 Tolman, 9 hrs. make barn - Mr. B. Stamp  
 Thursday Coles, 5 hrs. put in bar & glass in  
 fowl house Mr. T. Wood  
 + .. 1 hr. finish stable door at Mr. Woods  
 X .. 3 hrs. fix shed Mothers  
 X Leach, 1 1/2 hrs. prepare sill & and  
 stakes & straight edge for Mrs. Thomas x  
 .. 4 1/2 hrs. paint doors Priory (contract)  
 .. 1/2 hr. pick up things Mrs. Thomas x  
 .. 2 1/2 hrs. make parlor mantelpiece Self  
 X R. Davey, 9 hrs. floors & Mrs. Thomas  
 X W. Radford, 9 hrs. do.  
 J. Stokes, 2 hrs. paint bedroom  
 .. plan for greenhouse

26 Tolman, 3 hrs. paint barn & fix &  
 Friday clean off wheel Mr. B. Stamp  
 + .. 1 hr. repair lades Mr. E. Ware  
 .. 5 hrs. paint porch Mr. Dary (contract)  
 X Coles, 9 hrs. put up shed Mothers  
 X Leach, 9 hrs. repair stable window Mrs. Thomas  
 X R. Davey, 9 hrs. floors & Mrs. Thomas  
 X W. Radford, 9 hrs. do.  
 Self fetch mangel. 10 Exeter

+ 27 Tolman, 3 1/2 hrs. repair lades Mr. E. Ware  
 Saturday .. 2 hrs. paint porch Mr. Dary, (contract)  
 X Coles, 5 1/2 hrs. put up shed Mother  
 Leach, 5 1/2 hrs. mantelpiece Self  
 X R. Davey, 1 hr. floors & Mrs. Thomas  
 X W. Radford, 1 hr. do.  
 Self farming

## Bridgepit Rolle.

2. 15 ft. of 7x1 braces for roof  
1 lb. nails

4-3 of 5 $\frac{1}{2}$ x1 $\frac{1}{4}$  ledge for stable door  
2 twists, 2 hooks,

1 latch, catch & guide

4. 3x3/8 bolts

4. 1 $\frac{1}{2}$ " screws, 1. 1 $\frac{1}{2}$ x1/4 bolt

1 catch & 1 guide

## Mr. T. Wood

2-3 x 1-6 of glass 3-4 $\frac{1}{2}$  at 6 $\frac{1}{2}$

19

2 lbs. putty

3

2-2 of 2x1 $\frac{1}{4}$  bar

3

1 pane glass 15 $\frac{1}{2}$ x8 $\frac{5}{8}$

6

7 hrs.

36

## Mrs Thomas. Ixton

1 load sand

4-3 of 3 $\frac{1}{2}$ x3 deal sill

2-6 of 3 $\frac{1}{2}$ x3

2-0 of 2x1 battens

5-0 of 3 $\frac{1}{2}$ x1 straight edge

stakes

screws

## Mr. J. Miller

1. 2" butt. 6. 1 $\frac{1}{4}$ " screws trap

5-6 of 15x1 elm pulper

3-0 of 4x1 elm. "

nails

1. 6" Tower bolt screw

8. 3/4" screw

1 Suffolk handle complete

Mr. Alf Stamp

30-0 q of  $2 \times 3/4$  floor door

8-9 q of  $2 \times 1$  floor

14-1/4 screws

1 lb. nails

1 lb. galv. screws washers

1 pint creosote

Mr. H. Ware

7 lbs. paint galv. door bridge green

Shed at Mother's home

18-0 q of  $2 \times 3$  deal

4 lbs. galv. nails

3 lbs. nails

tar

Nov 29 Tolman, 2 1/2 hrs. take home board from Orchard

Monday X .. 6 1/2 hrs. repair lades Mr. E. Ware

Coles, 2 1/2 hrs. take home board from Orchard

X .. 6 1/2 hrs. put up shed Mother

Leach, 1 1/2 hrs. make mantelpiece Self

X .. 8 hrs. take up dining room floor

at Mr. E. Ware

X R Davey, 9 hrs. concrete yard Mrs. Thomas

X to Radford, 9 hrs. do. do.

Self pack board. at Hawkins Wages R.

30 Tolman, 4 hrs. repair lades Mr. E. Ware

Tuesday X .. 5 hrs. put sides back to cart Mr. F. Woods T-Jennings

X Coles, 9 hrs. tarring at Bridge pit

Leach, 8 hrs. make mantelpiece Self

X .. 1 hr. get out sill bot Mrs. Thomas

X R Davey, 9 hrs. concrete yard Mrs. Thomas

X to Radford, 9 hrs. do.

- Dec. 1 Tolman, 3½ hrs. repair cart Mr. T. Jennings  
 Wednesday X " 1 hr. paint barn Mr. B. Stamp  
 X " 4½ hrs. repair lades Mr. G. Ware  
 Coles, 1½ hrs. oil four wheel  
 X " 7½ hrs. finish shed at Mother  
 Leach, 9 hrs. make mantelpiece Self  
 X R. Davey, 2½ hrs. put in concrete Mrs. Thomas  
 " 6½ hrs. put in grate for Self  
 Self paper bedroom r.
- 2 Tolman, 1 hr. put link in hames Self  
 Thursday " 3 hrs. repair lades Mr. G. Ware  
 " 1 hr. put round in ladder Self  
 " 2½ hrs. paint porch at Mr. Davey's (contract)  
 X " 1½ hrs. make jamb for wall Mr. G. Pyne  
 Coles, 9 hrs. oil trap wheels, fit up calves  
 " 1 hr. make calves hay rack Self  
 Leach, 9 hrs. fit mantelpiece, repair  
 cupboards r. Self  
 X R. Davey, 9 hrs. put in concrete at Mrs. Thomas  
 Self finish bedroom r.
- X 3 Tolman, 9 hrs. make greenhouse Mr. G. Pyne  
 Friday X Leach, 1½ hrs. do.  
 " 8 hrs. repair parlor cupboards r. Self  
 Coles, 4½ hrs. packing board  
 X " 4½ hrs. tarring at Bridgepit  
 X R. Davey, 9 hrs. put in cement r. Mrs. Thomas.  
 Self at Exeter
- X 4 Tolman, 5½ hrs. make greenhouse Mr. G. Pyne  
 Saturday X Leach, 5½ hrs. do.  
 X Coles, 3½ hrs. tarring at Bridgepit  
 " 2 hrs. packing board  
 X R. Davey, 2 hrs. put in cement at Mrs. Thomas

Mrs. Thomas Belmont Farm

4-3 of 2x3 deal for pill box

4-3 of 3 1/2 x 1 " "

4-3 of 1" hoop iron tongue

3. 1 1/4" screws

3 gratings frames

plaster

putty line

Mr. T. Jennings cart

4 lbs. iron for plates

18. 1 x 1/4 bolts

6-6 of 10 x 3/4 elm board

2 square staples

3 ring staples

8. 3/4 screws

Mr. Edgar Ware lade

11-0' of 9x1 elm

5-3 of 6x1 elm

4-0 of 4 x 1/2 elm

1 lb. nails

3. 3 1/2 x 3/8 bolts

5-3 of 3x1 elm

4-0 of 6 x 1/2 elm

1/2 lb. nails

paint

1/2 lb. nails drawing room floor

Mr. Dawey

2 piece wood 6'

- Dec. 6<sup>th</sup> Tolman, 9 hrs. greenhouse Mr. G. Pyne  
 Monday Leach, 9 hrs do.  
 X Coles, 2½ hrs tarring at Bridgepit  
 X .. 1½ hrs put in glass Mr. Kilmaster  
 .. 1½ hrs repair yard doors Self  
 X .. 3½ hrs make manger Mr. T. Jennings  
 X R. Davey, 9 hrs concrete yard Mrs. Thomas  
 Self at T. Jennings rallies
- X 7 Tolman, 9 hrs. greenhouse Mr. G. Pyne  
 Tuesday Leach, 4 hrs do.  
 X Coles, 9 hrs <sup>make r.</sup> fix manger track Mr. T. Jennings  
 X R. Davey, 9 hrs. concrete yard Mrs. Thomas  
 X W. Radford, 5 hrs. washing concrete do.  
 Self at Exton, & at T. Jennings
- X 8 Tolman, 10 hrs. unload monument Mr. Davy  
 Wednesday .. 8 hrs. greenhouse Mr. G. Pyne  
 X Leach, 8 hrs. do.  
 X .. 1 hr. unload monument Mr. Davy  
 X Coles, 9 hrs. tarring at Bridgepit  
 X R. Davey, 9 hrs. concrete yard Mrs. Thomas  
 Self at apt
- X 9 Tolman, 9 hrs. greenhouse Mr. Pyne  
 Thursday Leach, 9 hrs. do.  
 Coles, 6 hrs. pack board Self  
 X .. 3½ hrs. take off car axle & straighten  
 it & screw up trap Mr. T. Jennings  
 X R. Davey, 6½ hrs. put in sill, & stop up  
 holes in house Mrs. Thomas  
 Self at Mrs. Thomas, to bill for hay

Dec. 10 Tolman, 9 hrs. greenhouse Mr. G. Pyne

Friday Leach, 8 hrs. do do

X .. 1 hr. make curtain rods Mother

X Coles, 6 hrs. alterable Mr. T. Jennings

.. 3 hrs. make barrow H.C.

Rdavey not to work

Self Lord Derby

11 Tolman, 5½ hrs. greenhouse Mr. G. Pyne

Saturday Leach, 5½ hrs. do.

Coles, 5½ hrs. barrow H.C.

X Rdavey, 5½ hrs. finish yard & path

on well cover Mrs. Thomas

Self clear up paint job r.

Mr. Kilmaster

1 pane glass 13½ x 10¾

X petty

X Mrs. Thomas

1 well cover

Mr. T. Jennings (trap)

X 1. 2 x ¼ bolts, 1. 4 x ¾ bolts, 3 screws

2-6 of 12 x 1 elm manger 2-6

2-6 of 10 x 1 elm " 2-1

2-6 of 16 x 1 elm " 3-4

2-6 of 11 x 1 elm " 2-6 10-5

6-0 of 18 x ½ " rack 9-0

12-0 of 9 x ½ " " 9-0 18-0

6-0 of 4 x 2 " rail "

7-6 of 3½ x 2 oak posts "

nails

pony & trap deliver



Dec. 13 Mr. L. Stoneman  
104-0 of 2x1 battens paid 3/8

Dec. 13 Monday Tolman, q hrs. greenhouse Mr. G. Pyne  
Leach, q hrs. do  
x Coles, q hrs. tarring at Bridgepit  
RDavey, 1 hr. repair plaster in parlor Self  
x " 8 hrs. fix monument Mr. C. Davy  
Self at Churchyard  
paint parlor

14 Tuesday Tolman, q hrs. greenhouse Mr. G. Pyne  
Leach, q hrs. do  
x Coles, q hrs. tarring at Bridgepit  
x RDavey, q hrs. fix monument Mr. C. Davy  
x W. Radford, q hrs. help do. rapturf do.  
Self at Churchyard r.

15 Wednesday Tolman, 4 hrs. greenhouse Mr. G. Pyne  
.. 5 hrs. hang yard gates Webbers Farm  
x Coles, 5 1/2 hrs do.  
.. 1 1/2 hrs. make barrow H Clotworthy  
.. 2 hrs. repair tailboard of cart Self  
x Leach, q hrs. greenhouse Mr. G. Pyne  
RDavey, 1 hr. whiten parlor ceiling Self  
x .. 6 1/2 hrs. fix monument Mr. C. Davy  
Self alle etc

16 Thursday Tolman, 2 hrs. make ironwork for gates Webbers Farm  
.. 7 hrs. hang gates do.  
x Coles, 8 hrs. do. do.  
x .. 1 hr. repair roof Mr. H. Ware  
x Leach, q hrs. greenhouse Mr. G. Pyne  
x RDavey, q hrs. repair roof Mr. H. Ware  
x G. Stamp, q hrs. do. do.

Dec-16 Self at Mrs. Thomas see chimney cow  
 .. at Mr. Ware's

17 Tolman.  $\frac{1}{2}$  hr. paint barn H. Clotworthy  
 Friday .. 8 hrs. greenhouse Mr. G. Pyne  
 X Leach. q hrs. do. do.  
 X Coles. q hrs. repair roof motor shed  
 .. at Mr. H. Ware  
 X Rdavey.  $5\frac{1}{2}$  hrs. do.  
 X E. Stamp.  $5\frac{1}{2}$  hrs. do.  
 ..  $3\frac{1}{2}$  hrs rifting gravel Self  
 Self paint parlor r.

18 Tolman.  $5\frac{1}{2}$  hrs. greenhouse Mr. G. Pyne  
 Saturday Leach.  $5\frac{1}{2}$  hrs. do.  
 Coles.  $5\frac{1}{2}$  hrs. repair roof motor  
 X house Mr. H. Ware  
 X Rdavey.  $5\frac{1}{2}$  hrs. do.  
 X E. Stamp.  $5\frac{1}{2}$  hrs. do.  
 Self all sorts

Mr. H. Ware

14-0 of 2x1 battens

9-0 of 4x2 rafter

9-0 of springing

4 lbs. nails

100 triple roll tiles

7 pan tiles

10 ridge tiles

2 barrow motor

3-0 of  $4\frac{1}{2}$ x3 joists motor house

3.  $1\frac{1}{2}$  screws

## Webber Farm. Rolfe Estate

14.  $4 \times \frac{1}{2}$  bolts  
 3 long spikes 3 lbs.  
 1 lb. catch staple 3 lbs  
 12.  $1 \frac{1}{2}$  screws  
 12. 1" do.  
 1. 2" coach screws  
 2-3 of  $2 \times 1 \frac{1}{2}$  deal  
 2-0 of  $2 \times 3$  oak  
 " of  $4 \times 3$  oak  
 1 lb. nails

## Mr. C. Davy. Monument

2 barrows mortar  
 125 bricks  
 2 pecks cement

## Mr. G. Pyes Greenhouse

9 lbs. iron bars  
 14 lbs. priming with pot  
 9-3 of  $7 \times 3$  deal } home  
 16-0 of  $11 \times 2$  " }

## Self Parlor Mantelpiece

4-3 of  $7 \times 1 \frac{1}{2}$   
 4-3 of  $9 \times 1$   
 3-6 of  $11 \times 1$   
 4-6 of  $7 \times 1$   
 $\frac{1}{2}$  lb. nails  
 12-0 of  $7 \times \frac{3}{4}$  match  
 priming  
 2 lbs. 1 falls white  
 plaster mortar  
 1 grate  
 concrete mortar 2 barrows

Dec. 20 Tolman 8 hrs. make barge caps Mr. H. Ware  
 Monday .. 1 hr. make ladder Mr. A. Stamp  
 X Leach, 1½ hrs. put in pane of glass  
 Mr. Kilmaster  
 2 hrs. ease windows at do. Self  
 X .. 5½ hrs. greenhouse Mr. G. Pyne  
 X Coles. 9 hrs. repair roop motorhouse Mr. H. Ware  
 R. Davey, 1½ hrs. repair parlor plaster &  
 sift sand Self  
 X .. 7½ hrs. repair roop Mr. H. Ware  
 X E. Stamp. 7½ hrs. do. do.  
 .. 1½ hrs. sift sand Self  
 Self

21 Tolman 1½ hrs. make ladder Mr. A. Stamp  
 Tuesday X .. 7½ hrs. fix barge boards Mr. H. Ware  
 X Coles. 9 hrs. do & repair roop do.  
 X R. Davey. 9 hrs. do. do.  
 X E. Stamp 9 hrs. do. do.  
 X H. Leach, 9 hrs. greenhouse Mr. G. Pyne  
 Self at Exeter

22 Tolman, 9 hrs. make ladder Mr. A. Stamp  
 Wednesday Coles. 9 hrs. repair motorhouse & fix  
 X shuting & Mr. H. Ware  
 X Leach. 9 hrs. greenhouse Mr. G. Pyne  
 X R. Davey, & E. Stamp. 4 hrs. each  
 Take off chimney cowl Mrs. Thomas  
 R. Davey & E. Stamp 3½ hrs. ea. repair  
 plaster at Bridgepit  
 R. Davey & E. Stamp 1½ hrs. ea. bore for  
 water at J. Georges field  
 Self

Dec 23 Tolman, 2½ hrs. finish ladder Mr. A. Stamp  
~~Thursday~~ .. 2 hrs. make stakes R. D. Council  
~~Friday~~ .. 2 hrs. put in afe stem Mr. Jim Glauwill  
 .. 2½ hrs. fix post house afe. Mr. John Glauwill  
 X Leach, q hrs. greenhouse Mr. G. Pyne  
 X Coles, q hrs. repair phuting Mr. H. Ware  
 X Rdavey, q hrs. bore for well J. Georges field  
 X E. Stamp, q hrs. do. do.  
 Self

24 Tolman, 1½ hrs. fix post house afe. Mr. J. Glauwill  
 Friday .. 1 hr. paint ladder Mr. A. Stamp  
 .. ½ hr. packing board Self  
 Coles, 7 hrs. do. do.  
 X .. 2 hrs. finish phuting Mr. H. Ware  
 X Leach, q hrs. greenhouse Mr. G. Pyne  
 X Rdavey, q hrs. bore well J. Georges field  
 X E. Stamp, q hrs. do. do.  
 Self

25 Xmas Day

X Mr. Kilmaster  
 1 pane glass 13¼ x 10¾ putty

Rural District Council

X 6 stakes 7 ft long ea. sap  
 13 feet of slabs

Greenhouse

X 9-6 of 9 x 1½ deal hung  
 14-0 of 9 x 2 " "

Mr. T. Woods. Bridgepit

X 2 barrows hair mortar

Mr. H. Ware

50 pan tiles

50 triple roll tiles

47-0 of 7x3/4 cappings }  
47-0 of 7x1 barges }  
2 1/2 lbs. paint }

19-0 of 3x2 rafter

47-0 of 2x1 battens

9-9 of 9x3/4 bottom of door

3-6 of 3x1 do.

1-6 of 3x2 "

3-9 of 3x5/8 stop "

1 Norfolk handle + 6 screws "

4 lbs nails

2-0 of 4 1/2" 1/2 rd. gutter

9 phunk screws

1 lb putty

piece zinc 1-0 x 6

Mother's Home

1. rim lock complete

Dec. 28 Tolman, 9 hrs. get stocks re-spokes for Cart

Tuesday, X Coles, 9 hrs. tarring at Mr. T. Woods

X Leach, 6 1/2 hrs. greenhouse Mr. G. Pyne

X " 2 1/2 hrs. repair table Dr. Telford

R Davey, 1 1/2 hrs. repair roof Broadway House

X " 3 hrs. do. Bakehouse

" 1 hr. do. Shop

" 3 1/2 hrs. make scaffold S. Coles

B. Stamp, same as R. Davey

Self allent

9  
9  
9  
27

Dec-29 Tolman, 1 hr. turn out plank  
 Wednesday . 8 hrs. make cart wheels  
 Coles, ~~4~~ 3½ hrs. do.  
 .. 3½ hrs. make large cap for T. Locks  
 - 2 hrs. borrow H.C.  
 X Leach, 9 hrs. greenhouse Mr. G. Pyne  
 R. Davey, 3½ hrs. repair plastering &  
 X .. & roughcast at Mr. T. Woods  
 .. 1½ hrs. measure roof at Mr. T. Jennings  
 .. & 1½ hrs. repair roof Broadway Home  
 X .. & 2½ hrs. do. Mr. James  
 E. Stamp, ~~+~~ ~~+~~ same as R. Davey  
 .. 1½ hrs. cut up firewood  
 Self at Mr. T. Jennings & apc

30 Tolman, 9 hrs. make cart wheels  
 Thursday Coles, 8 hrs. make cart wheel  
 .. 1 hr. turn out plank  
 X Leach, 9 hrs. greenhouse Mr. G. Pyne  
 R. Davey, 4 hrs. repair tiles on wall  
 .. between Mr. James Miss Martins &  
 X .. 1½ hrs. repair roof Mrs. Wildes  
 .. 3½ hrs. make up greenhouse  
 X at Shepherds Farm  
 E. Stamp, 4 hrs. repair tiles at Miss Martins.  
 X .. 1½ hrs. repair roof Mrs. Wildes  
 .. 3½ hrs. making mortar  
 Self at Postlake & at Shepherds Farm

31 Tolman, 9 hrs. make cart  
 Friday Coles, 9 hrs. do.  
 X Leach, 7 hrs. greenhouse Mr. G. Pyne  
 .. 2 hrs. put in glass at Miss Martins  
 E. Stamp, 7½ hrs. make mortar  
 Self at Reeler &

9  
 9  
 9  
 75  
 345

Dec. 28 R. Davey (Roll estate)

1 fire lump  
50 bricks  
5 fire bricks  
1 barrow mortar

T-Loeks

10-6 of 7x1 barge cap  
10-6 of 4 $\frac{1}{2}$ x3 $\frac{1}{4}$  "  
nails, paint

Miss Lucy Martin

1 pane glass 13 $\frac{1}{2}$ x10.5 putty

Mr T. Woods. Roll estate

1 barrow hair mortar  
1 $\frac{1}{2}$  pecks cement  
1/2 barrow gravel

Broadway House

3. 24x12 plates  
3 strips lead nails  
30 pantiles

Mr. James

14 pantiles

Mrs. Wildes

14 pan tiles  
1 bucket mortar  
2. 9x18 slate, lead nails

Bakehouse

1. 11x22 plate, 2 strips lead nails  
7 double roll tiles



Miss Martin, Mr. James

5 double roll tiles

4 ridge crease

$\frac{1}{2}$  barrel mortar

Mr. Pynes Greenhouse (home)

X 11-0 of 7x 1 $\frac{1}{2}$  deal

1916

758

Jan. 1 Tolman. 5 $\frac{1}{2}$  hrs. cart work  
Saturday Coles. 5 $\frac{1}{2}$  hrs. do  
Leach. 3 $\frac{1}{2}$  hrs. greenhouse Mr. G. Pyne  
.. 2 hrs. take up carpets for  
Mr. C. Dairy  
Self





